

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9279M - AXA**ROEL***Not Authored
11 Sep 8*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9279M - ROEL**KL1LA69RJBBO67020****CHEVROLET****EPICA 2.0****16.06.16****AXA****PART****LIST**

1	1	Front Bumper	\$	<i>Bur</i> 1,202.00 ✓
2	1	Front Bumper Reinforcement	\$	<i>Bt</i> 295.25 ✓
3	1	Front Bumper Lower Absorber	\$	<i>CM</i> 180.00 ✓
4	1	Front Bumper Lower Grille	\$	<i>CM</i> 78.00 ✓
5	1	Front Bumper Retainer RH	\$	<i>Sn</i> 102.00 X
6	1	Front Bumper Retainer LH	\$	<i>Sn</i> 102.00 X
7	1	Front Bumper Lower Stiffener	\$	<i>R</i> 134.37 X
8	1	Front Headlamp RH	\$	<i>CM</i> 816.00 ✓
9	1	Front Headlamp LH	\$	<i>ng/CM</i> 816.00 ✓
10	1	Front Bumper Fog Lamp Outer Cover LH	\$	<i>Sn</i> 32.40 X
11	1	Front Bumper Fog Lamp Outer Cover RH	\$	<i>Sn</i> 32.40 X
12	1	Front Support Panel Assy (Panel A-Frt)	\$	<i>Rt</i> 1,222.32 ✓
13	1	Bonnet (Panel A-Hood)	\$	<i>Bur</i> 1,250.00 ✓
14	1	Centre 'CHEVROLET' Logo Badge	\$	<i>na</i> 144.30 ✓
15	1	Bonnet Moulding	\$	<i>CM</i> 257.00 ✓
16	1	Bonnet Insulator	\$	<i>Sn</i> 84.63 X
17	1	Bonnet hinge RH	\$	<i>R</i> 36.00 X
18	1	Bonnet hinge LH	\$	<i>R</i> 36.00 X
19	1	Bonnet cable	\$	<i>Sn</i> 150.00 X
20	1	Bonnet lock	\$	<i>Dis</i> 200.00 ✓
21	2	HORN LH	\$	<i>Sn</i> 320.00 X
22	1	Radiator Grille (Grille A-Rad)	\$	<i>Bur</i> 367.00 ✓
23	1	Radiator Assembly (Radiator A)	\$	618.00 ?
24	1	Radiator upper hose	\$	30.00 ?
25	1	Radiator lower hose	\$	120.00 ?
26	1	Aircon Condenser (Condenser A)	\$	<i>At/Pn</i> 600.00 ✓
27	1	Aircon hose - condenser to compressor	\$	215.40 ?
28	1	Aircon hose - compressor to evaporator	\$	316.20 ?
29	1	Aircon hose - condenser to evaporator	\$	332.10 ?
30	1	Aircon compressor - pump	\$	<i>Sn</i> 1,847.95 X
31	1	Aircon compressor bracket	\$	<i>Sn</i> 245.30 X
32	1	Front Centre Member	\$	<i>Sn</i> 265.63 X
33	1	Air Intercooler	\$	652.00 ?

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9279M - AXA

34	1	Fan Blade (Small)	\$	CRT	536.00	✓
35	1	Fan Blade (Big)	\$		634.00	7
36	1	Front Fender LH	\$	R	837.60	X
37	1	Front Fender RH	\$	R	837.60	X
38	1	Fender Insulation RH	\$	Sn	39.00	X
39	1	Front Fender Liner RH	\$	Sn	47.00	X
40	1	Front Fender Liner LH	\$	Sn	47.00	X
41	1	Rear Bumper	\$	Mis	1,202.00	✓
42	1	Rear Bumper Beam	\$	Bt	239.94	✓
43	1	Rear Bumper Centre Absorber	\$	Mis	260.00	✓
44	1	Rear Bumper Side Retainer RH	\$	CRT	68.76	✓
45	1	Rear Bumper side support RH	\$	Mis	25.00	✓
46	1	Rear Bumper Reflectors RH	\$	Mis	119.74	✓
47	1	Rear Bumper stay RH	\$	Mis	35.00	✓
48	1	Rear Bumper Tow Hook Cover	\$	Mis	93.00	✓
49	1	Rear End Panel Inner	\$	Bt	336.84	✓
50	1	Rear End Panel Outer	\$	Bt	623.76	✓
51	1	Rear End Panel Inner Trim	\$	Dis/In	263.84	✓
52	1	Bootlid	\$	Bt	973.00	✓
53	1	Bootlid inner trim board	\$	Reform	400.00	✓
54	1	Bootlid Weatherstrip	\$	@17.14/m	344.28	50% Sn
55	1	Bootlid Lock - Top	\$	Re	466.56	✓
56	1	Bootlid lock - bottom	\$	Dis	39.40	✓
57	1	Bootlid 'CHEVROLET' Badge	\$	Mis	120.62	✓
58	1	Bootlid Logo	\$	Mis	138.84	✓
59	1	Bootlid 'EPICA LT' Badge	\$	Mis	119.84	✓
60	1	Bootlid inner handle	\$	Sn	45.55	X
61	1	Bootlid Reflector Centre	\$		217.97	7
62	1	Bootlid Reflector RH	\$	CRT	128.40	✓
63	1	Bootlid Reflector LH	\$	Bt	128.40	✓
64	1	Bootlid Hinge RH	\$	R	120.00	X
65	1	Bootlid Hinge LH	\$	R	120.00	X
66	1	Rear Gas T/Gate Spring RH	\$	Sn	286.90	X
67	1	Rear Gas T/Gate Spring LH	\$	Sn	286.90	X
68	1	Rear number plate lamp RH	\$	Sn	25.00	X
69	1	Rear number plate lamp LH	\$	Sn	25.00	X
70	1	Rear Tail Lamp RH	\$	Bt	479.30	✓
71	1	Rear Tail Lamp Panel RH	\$	Bt	359.00	✓
72	1	Rear Tail Lamp LH	\$	CRT	479.30	✓
73	1	Rear Tail Lamp Panel LH	\$	Bt	359.00	✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9279M - AXA

74	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	R 1,110.00 X
75	1	Centre Exhaust Pipe	\$	R 403.00 X
76	1	Rear Fender RH	\$	Bu 1,145.00 ✓
77	1	Rear Fender Inner Cowling RH	\$	CRM 298.00 ✓
78	1	Rear Fender Inner Trim RH	\$	CRM 418.44 ✓
79	1	Rear Fender Inner Wheel House Panel RH	\$	R 2,556.35 X
80	1	Rear Fender LH	\$	R 1,145.00 X
81	1	Rear Fender Inner Cowling LH	\$	CRM 298.00 ✓
82	1	Rear Door RH (Panel A-RR DR RH)	\$	R 1,133.00 X
83	1	Rear Door weatherstrip - Inner RH	\$	SR 41.40 X

TOTAL	\$	33,557.78
10%	\$	3,355.78
	\$	30,202.00

Special Nett

1	1Set	Front Bumper Fastener Clip	\$	NR 24.00 ✓
2	1Set	Front Licence Plate With Holder	\$	Bu 192.00 455AN ✓
6	1Set	Bonnet Insulator Clip	\$	NR 40.00 X
7	1Set	Radiator Grille Clip	\$	NR 18.00 ✓
8	1Set	Radiator Grille Top Cover Clip	\$	NR 10.00 X
9	1Set	Front Fender Liner Clip LH	\$	NR 40.00 X
10	1Set	Front Fender Liner Clip RH	\$	NR 40.00 X
11	1Set	Engine Splash Cover Clip RH	\$	NR 12.00 X
12	1Set	Rear Bumper Parking Sensor	\$	MIS 300.00 ✓
13	1Set	Rear Bumper Fastener Clip	\$	NR 30.00 ✓
14	1Set	Rear Fender inner cowling clip RH	\$	NR 30.00 ✓
15	1	Rear Boot Sticker 'Trans-cab'	\$	NR 30.00 ✓
16	1	Rear Boot Sticker '6555-3333'	\$	NR 30.00 ✓
18	1	Rear Door Sticker '6555-3333' RH	\$	NR 30.00 X
18	1	Rear Door Sticker '6555-3333' LH	\$	NR 30.00 X
20	1	Front Tyre RH	\$	SR 180.00 X
21	1	Front Wheel Rim RH	\$	SR 126.74 X
22	1	Rear Tyre RH	\$	SR 180.00 X
23	1	Rear Wheel Rim RH	\$	SR 126.74 X
24	2	Rear Windscreen Sealant	\$	NR 80.00 405N ✓
25	1	Rear Windscreen Inner Sponge Seal	\$	NR 100.00 305N ✓

TOTAL	\$	1,649.48
TOTAL PARTS	\$	31,851.48

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9279M - AXA**ROEL**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	16,800.00 <i>2600</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>40</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 ✓
Putty And Spray Painting Of The Affected Portion.	\$	16,200.00 <i>1800</i>
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00 <i>240</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>60</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 <i>250</i>
To transfer of Fender fittings, attachments and perform water seepage test.	\$	170.00 <i>120</i>
Towing Fees.	\$	120.00 <i>50</i>
To check steering geometry and computer wheel alignment	\$	220.00 <i>60</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nr</i> 170.00 <i>X</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 <i>120</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>nr</i> 120.00 <i>X</i>
To check ABS brake efficiency, final checking and testing.	\$	<i>nr</i> 380.00 <i>X</i>

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9279M - AXA**ROEL**To replace, refix and top up coolant for radiator \$ 170.00 *50%*To vacuum, replace, refix and recharge Air
Intercooler \$ 170.00 *50%*

	\$	35,960.00
TOTAL	\$	67,811.48

Repair Days*60 Days**21 days***LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: