

# EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SJG 7191E  
Vehicle Model : HONDA STREAM  
Accident Date : 24.06.2016  
Original Reg Date : 14.07.2008

Date : 24.06.2016  
Chassis : RN61069801  
TP Ins. AXA

## ESTIMATE

|    |       |                                       |     |        |          |
|----|-------|---------------------------------------|-----|--------|----------|
| 1  | 1 pc  | Tailgate Assy                         | dt. | ✓      | 982.60   |
| 2  | 1 pc  | Tailgate Badge                        | NLM | X      | 58.00    |
| 3  | 1 pc  | Tailgate Emblem (STREAM)              | ue  | ✓      | 60.00    |
| 4  | 1 pc  | Tailgate Windscreen Moulding          | ue  | ✓      | 82.10    |
| 5  | 1 pc  | Tailgate Windscreen Inner Seal        | ue  | ✓      | 60.00    |
| 6  | 1 set | Tailgate Windscreen Clips             | ue  | ✓      | 30.00    |
| 7  | 1 pc  | Tailgate Inner Lock                   | bst | ✓      | 186.40   |
| 8  | 1 pc  | Tailgate Lock Catch                   | R.  | X      | 36.20    |
| 9  | 1 pc  | Tailgate Lock Actuator                |     | ?      | 175.50   |
| 10 | 1 pc  | Tailgate Weatherstrip                 | dis | ✓      | 173.30   |
| 11 | 1 pc  | Tailgate Inner Trim                   |     | ?      | 312.60   |
| 12 | 1 set | Tailgate Inner Trim Clips             | ue  | ✓      | 40.00    |
| 13 | 1 pc  | Tailgate Pocker Holder                | dis | ✓      | 39.60    |
| 14 | 2 pcs | Taillamps OS LRA NSWC                 | ✓   | 395.20 | X 790.40 |
| 15 | 2 pcs | Taillamps Inner Sealer ue             |     | 30.00  | ✓ 60.00  |
| 16 | 2 set | Taillamps Clips ✓                     |     | 25.00  | 40 50.00 |
| 17 | 2 pcs | Taillamps Lower Retainers dis         |     | 36.20  | ✓ 72.40  |
| 18 | 1 pc  | End Panel (Bottom)                    |     | ?      | 269.30   |
| 19 | 1 pc  | End Panel (Outer)                     |     | ?      | 453.20   |
| 20 | 1 pc  | End Panel Top Trim                    | dis | ✓      | 189.50   |
| 21 | 1 set | End Panel Top Trim Clips              | ue  | ✓      | 30.00    |
| 22 | 1 pc  | Vehicle Jack Cover                    | dis | ✓      | 96.30    |
| 23 | 1 set | Vehicle Jack Cover Clips              | ue  | ✓      | 25.00    |
| 24 | 2 pcs | Rear Fender Inner Trim NSWC OSdis     | ✓   | 348.20 | X 696.40 |
| 25 | 2 set | Rear Fender Inner Trim Clips ue       |     | 30.00  | ✓ 60.00  |
| 26 | 2 pcs | Rear Floor Panel Top Board OSdis NSWC | ✓   | 159.20 | X 318.40 |
| 27 | 1 pc  | Rear Bumper dt                        |     |        | ✓ 796.30 |
| 28 | 2 pcs | Rear Bumper Side Retainers dis        |     | 42.00  | ✓ 84.00  |
| 29 | 2 pcs | Rear Bumper Stay                      |     | 22.00  | ?        |
| 30 | 1 set | Rear Bumper Clips ue                  |     |        | ✓ 50.00  |

C/F

6,321.50

# EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SJG 7191E

B/F

6,321.50

|   |       |                         |       |   |        |
|---|-------|-------------------------|-------|---|--------|
| 1 | 1 pc  | Spare Tyre Carrier      |       | 7 | 226.70 |
| 2 | 1 pc  | Spare Tyre Carrier Bolt | 2pc   | 8 | 86.50  |
| 3 | 1 pc  | Spare Tyre Carrier Nut  | ave   | 8 | 38.70  |
| 4 | 1 pc  | Rear Exhaust Silencer   | 1st   | ✓ | 659.30 |
| 5 | 2 pcs | Rear Exhaust Mountings  | 48.00 | 7 | 96.00  |
| 6 | 1 pc  | Rear Exhaust Gasket     | 1st   | ✓ | 46.50  |

7,475.20

Less 20% 1,495.04

5,980.16

## Special Nett

|   |       |                              |     |     |          |        |
|---|-------|------------------------------|-----|-----|----------|--------|
| 1 | 1 pc  | Rear Windscreen Sealant      | 1st | ✓   | 60.00    | 460    |
| 2 | 1 pc  | Rear Number Plate with Cover | 1st | ✓   | 70.00    | 460    |
| 3 | 1 set | Body Panel Joint Sealant     | 1st | ✓   | 120.00   | 80     |
| 4 | 1 set | Reverse Sensor               | 2nd | 220 | 250.00   | ✓      |
| 5 | 1 set | Reverse Camera               | 2nd | 250 | 450.00   |        |
| 6 | 1 pc  | Rear Bumper Lower Spoiler    | 2nd | ✓   | 1,100.00 |        |
| 7 | 1 pc  | Rear Exhaust Chrome Pipe     | 1st | ✓   | 100      | 140.00 |

## Labour charge

|                                           |          |      |
|-------------------------------------------|----------|------|
| Panel Beating                             | 1,200.00 | 1000 |
| Spray painting                            | 1,200.00 | 1000 |
| Check Wiring                              | 50.00    | 30   |
| Anti rust                                 | 100.00   | 60   |
| Remove and install rear winscreen.        | 140.00   | 120  |
| Remove and install tailgate parts.        | 90.00    | 60   |
| Remove and install carpet and seat.       | 120.00   | 80   |
| Remove and install reverse sensor         | 90.00    | 60   |
| Remove and install reverse camera.        | 150.00   | 80   |
| Remove and install rear exhaust silencer. | 120.00   | 80   |

\$ 11,430.16

29/6/2016  
Not Authorized  
HS Rep  
8w/ days  
H/S Rep  
Ltko M/T