

RESTRICTED

ANNEX C  
BB72-1/1-15  
DATED 27 JUN 16

**STATEMENTS OF TRANSPORT OPERATOR AND WITNESSES**

**STATEMENT OF DRIVER/WITNESS**

STATEMENT OF:	LCP HARIZ FITRI BIN JAUHARI			PES STATUS	A1L1
NRIC NO	S9241354C	AGE	24	MARITAL STATUS	SINGLE
TOS	NSF	DOE	091215	NATIONALITY	SINGAPOREAN
EDU LVL	"N" LEVEL	ORD	081216	TEL NO	97263879

I, LCP HARIZ FITRI BIN JAUHARI, S9241354C, driving a GP car (MID41539), was on my way to send sample for urine regime to Jalan Kilang Barat with my front passenger REC Kathirvel. At the filter lane (roundabout) of Pioneer Road North, directions towards AYE, I was waiting at the filtering lane before merging to the main road, direction towards AYE. I thought the front vehicle had already moved off. And therefore after checking there wasn't any vehicle I moved off. And when I proceeded then I realize the front vehicle had jammed brake and I couldn't stop in time. As I was manoeuvring out from the filtering lane, Civilian Vehicle(SGM7256G) had jammed brake at the end of the filtering lane lane and i did not have enough time to react and came into contact with a Civilian Vehicle (SGM7256G)- Subaru Grey. I then alighted from my vehicle and check for damage, it was then I realise that the Civilian Vehicle (SGM7256G) in front of me had already came into contact with front Civilian Vehicle (SJJ9005G)- Toyota, resulting in a chain-collision accident.

That's all I have to say.

Date: 27 JUN 16

Signature : <Sent via Email>

# RESTRICTED

## STATEMENT OF DRIVER/WITNESS

STATEMENT OF:	REC Kathirvel Periasamy			PES STATUS	-
NRIC NO	S9775477B	AGE	19	MARITAL STATUS	SINGLE
TOS	-	DOE	-	NATIONALITY	SINGAPOREAN
EDU LVL	-	ORD	-	TEL NO	-

I, REC Kathirvel Periasamy, S9775477B, would like to explain the incident happened on 27/06/2016, at 2.00pm at the roundabout on Pioneer Road North. I was the Vehicle Commander of GP car (MID 41539) on my way with Transport Operator LCP Hariz Fitri to send sample of urine regime to Jalan Kilang Barat. At the filtering lane (roundabout) of Pioneer Road North, direction towards AYE, LCP Hariz was waiting at the filtering lane before emerging to the main road, direction towards AYE.


As he was manoeuvring out from the filtering lane, (2) Civilian Vehicle(SGM7256G)-Subaru Grey had jammed brake at the end of the filtering lane and MID 41539 came into contact with a Civilian Vehicle (SGM7256G). LCP Hariz and I then alighted from the vehicle to check for damages, it was then we realise that (2) Civilian Vehicle (SGM7256G) had already came into contact with front (1) Civilian Vehicle (SJJ9005G) - Toyota, resulting in a chain-collision incident.

This information is based on my knowledge and observation of the incident.

Date: 27 JUN 16      Signature      : <Sent via Email



**DAMAGE TO STORES AND EQUIPMENT INVESTIGATION REPORT**

<b>A. General</b>		Reference Number: BB72/PLC/060/16			
Date/Time Of Damage	270616 1400HRS	Report To	3WO SUNNY TOH	Reported By	2LT SENG ZHI YUAN
Place Occurred	PIONEER ROAD NORTH	Date/Time Reported	270616 1400HRS	Repair Cost	\$3,569.77
<b>B. Nature of Damage</b> (in full details) (use continuation sheet if necessary.)					
<p><u>Vehicle involved:</u></p> <p>MID 41539</p> <ul style="list-style-type: none"> <li>- FRONT BONNET ASSEMBLY SLIGHTLY DENTED</li> <li>- FRONT NUMBER PLATE DENTED</li> <li>- BOTH LEFT AND RIGHT BUMPER DENTED</li> <li>- FRONT BONNET MISALIGNMENT</li> </ul>					
<b>C. Circumstances of the Damage</b> (use continuation sheet if necessary) (For Vehicle Accident, sketch of the accident is to be made on reverse page).					
<p>LCP HARIZ FITRI BIN JAUHARI, S9241654C WAS DRIVING AROUND A SAF GP CAR MID 41539, MET AN ACCIDENT WITH A CIVILIAN VEHICLE SGM7256G AT 1400HRS WHILE TRAVELLING ALONG THE FILTERING LANE (ROUNDAABOUT) OF PIONEER ROAD NORTH. HE WAS DRIVING ALONG WITH THE INTENTION OF MANOEUVRING OUT FROM THE FILTERING LANE WHILE A CIVILIAN VEHICLE, GREY SUBARU IMPREZA (SGM7256G) PERFORMED A SUDDEN BREAK AT THE EXIT OF THE FILTERING LANE. THE SAF GP CAR (MID 41539) CAME INTO DIRECT COLLISION WITH CIVILIAN CAR (SGM7256G).</p> <p>WHEN LCP HARIZ FITRI BIN JAUHARI ALIGHTED TO CHECK FOR DAMAGES, HE NOTICED THE CIVILIAN VEHICLE HAD COME IN CONTACT WITH ANOTHER FRONT VEHICLE (SJJ9005G) RESULTING IN A DOMINO THEORY ACCIDENT EFFECT.</p>					
<b>D. Comments &amp; Recommendations of the Investigating Officer(s)</b> (To be completed after receipt of SAF 1223 from Log Base)					
NIL					
Signature and Date		 WTA LEE JIE YING			
Rank/Name		Rank/Name			



GOM NO 301-03

**E. Decision/Comments & Recommendations of CO***Please tick appropriate box and state reason.*☐ Negligence is not involved☒ Negligence is involved

(see extent of negligence and disciplinary action taken of each errant person in Part F)

Where gross negligence is involved but cost recovery is not recommended to be made from errant servicemen, please state reason below:

Other Comments / Recommendations (if any):

S7707746D  
MAJ ELTON TAN BOON WOON  
HD TPT HUB WEST

Signature and Date

Rank/Name

**F. Particulars of Individuals if Negligence is Involved**

NRIC NO	RANK AND NAME	SERVICE STATUS (NSF/NSmen/ Regular)	ORD (ddmm/yyyy)	APPOINTMENT	EXTENT NEGLIGENCE (Slight/ Moderate/Gross)	OF DISCIPLINARY ACTION TAKEN	COST RECOVERY (\$) (Fill up only if CO is the Approving Authority)
S9241354C	LCP HARIZ FITRI BIN JAUHARI	NSF	081216	Transport Operator	Slight	7 days SOL 4 demerit points	

SAF 1222 (2008)

**PARTICULARS REQUIRED FOR VEHICLE ACCIDENTS**

PARTICULARS REQUIRED FOR VEHICLE ACCIDENTS							
VEHICLE NO	TYPE OF VEHICLE	DATE OF LAST OVERHAUL	DATE OF LAST TEST	DRIVER RANK & NAME	SERVICE STATUS	DRIVING EXPERIENCE	NO OF PREVIOUS ACCIDENT INVOLVED
INVOLVEMENT OF INJURY			FATAL/SERIOUS/SLIGHT/NO INJURY*				



SMRT Automotive Services Pte Ltd  
6 ANG MO KIO STREET 62  
SINGAPORE 589140

Contract Ref No :  
**8016100475**

**HQ Maintenance Engineering Support**  
151, Choa Chu Kang Way, Singapore 688248  
Blk 822, #02-14, Kranji Camp 3

Dear Sir,

Quotation Ref No : **MAY18/QY2/038**  
Quotation Request Date : **08/05/2018 (04/07/2016)**  
Quotation Submission Date : **08/05/2018 (04/07/2016)**

TPT HUB : West Hub  
UNIT : Pasir Laba Camp

Vehicle Number : **MID 41539** Vehicle Grouping: A / B  
Vehicle Type/Model : FORD FOCUS 1.6A  
Type of Repair : Accident / Damaged / Modification

We hereby submit the quote for repair for the above-mentioned vehicle in accordance to the job description attached:

Job carried out by SMRT Automotive Services Pte Ltd

Total Repair Labour Cost : \$ 650.81 21.5 @ \$ 30.27 per hr  
Spares Cost : \$ 2,795.10  
Transportation Cost : \$ 123.86  
**Grand Total Cost : \$ 3,569.77** (Excluding GST)  
GST @ 7% \$ 249.88  
Grand Total Cost : \$ 3,819.65 (Including GST)

Delivery Period: 14 Days from date of Purchase Order (PO) Approval

Validity Period: 90 Days from the date of quotation

Spares purchased by Vendor's Name are subjected to mark-up and overseas items based on CIF price.  
The grand total repair cost of labour and spare(s) materials(s) used are subjected to Good and Services Tax.

Yours Faithfully

SMRT Automotive Services Pte Ltd

Name : Tan Yu Kok

Appointment : Executive

For Authority Use Only :

PO / PR NUMBER	DATE CREATED	DATE RELEASED	RELEASED BY	SIGNATURE
			GR on	

68662670



Particulars of Vehicle

Quotation Ref. No.:	MAY18/QY2/038
Vendors Coy Job No.:	
TPT HUB:	West Hub
Unit:	Pasir Laba Camp

Quotation Req Date: 08/05/2018 (04/07/2016)  
 Inspected By: Robin Koh  
 Date Inspected: 04/07/2016  
 Date quotation Submitted: 08/05/2018 (04/07/2016)

Delivery Period: 14

Transportation/ Towing Service: 2

Legend: REP- Repair, RPL - Replace, INFO - Information Only

Particulars of Vehicle

Type of Repair:	Accident / Damaged / Modification
Contract Ref No:	8016100475
Vehicle No. :	MID 41539
Vehicle Model:	FORD FOCUS 1.6A
Vehicle Grouping:	A / B
Chassis Number:	WF0WXXGCDW7U77415
Engine Number:	-
Odometer Reading:	45836

Total Spare Price:	\$	2,795.10
Mark Up Price:	\$	254.10
Max Allowable Mark Up:	\$	254.10

68662670







4 Jul. 2016 3:50

RECEIVED 04/07/2016 08:53 68662670  
Indeco PLC

KDYMINDEF  
No. 5294 P. 2/2

RESTRICTED

Received on 4/7/16 @ 08:53

GENERAL ADMIN VEHICLE MAINTENANCE CONTRACT  
(CN: 8013100564)

SMRT SERVICE REQUEST

Attention: MR HONG (Fax: 68662670)





Contacted: \_\_\_\_\_ (Hotline: 93227386)

Date : 04/07/2016




Requestor's Info	
Vehicle No.	M/D 41539
Unit:	TPT HUB WEST - PASIR LABA NODE
Rank & Name:	DXO 6 SEGARAN
Contact No.	91083924
Activated Time (24hr Format):	0800hrs
Job Requests	
	REQUEST FOR QUOTATION
1)	FRONT BONNET ASSEMBLY SLIGHTLY DENTED.
2)	FRONT NUMBER PLATE DENTED.
3)	BOTH FRONT LEFT AND RIGHT BUMPER DENTED.
4)	FRONT BONNET MISALIGNMENT.
	*REMARKS: VEHICLE AT PLC MT LINE.

Approved By: DXO 6 SEGARAN  
(Rank & Name)

Signature: 



20 plate holder fixed  
24-25-26 fixed  
27 Bump fixed  
28 Bumper lower body bent  
29 Bumper bent

Unit / Camp:	Qasir Lohar An	Vehicle Number:	41539 MIN
MT Staff Rank & Name:		Model / Type:	Ford Focus
Signature & Unit Stamp:	 	Mileage	6836
	04-JULY-2016 (1200PM)	Date / Time:	4/7/2016 1150

X - Scratches  
O - Dents  
Δ - Missing



Kan Khin Chye  
Snr Engr Supervisor (Assessor)  
Fleet Maintenance

