CITY CAB PTE LTD REPAIR ESTIMATE*

VEHICLE NO: SHB 3883T

DATE: 12/7/2016 15:30



Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bumper Assy, Frt CYU			\$ 1,345.00
	Bumper Bracket, Frt/RH N C			\$ 41.80
	Head Lamp Assy (RH)5			\$ 976.60
	Fender, Frt/RH dented			\$ 878.50
	Fender Splashshield, Frt/RH (Front) ton			\$ 133.00
	Wheel Rim			\$ 552.50
	Tyre 205/60R16 Yokohama RH SLC			\$ 310.00
	Tyle 203/00KT0 Tokonama Kt1 \$22			
	SUB TOTAL			\$ 4,237.4
	LESS 20%			\$ 847.4
	DISCOUNTED TOTAL			\$ 3,389.9
	Labour Charge Panel Beating		(7)n	\$ 650.0
	_		300	\$ 500.0
	Spray Painting Charge		400	\$ 50.0
	Wiring Charge		400 400 30	\$ 50.0
	Tuff Kote		×	\$ 50.0
	TOTAL LABOUR			\$ 1,250.0
	Z Jan LJ S ESTIMATE TOTAL			\$ 4,639.9
	3 day 45 LKK Henry 9788 4060 12/7/16 1600hs.			
	LKK Helig			
	9796 4060			
	7/88 9000			
	12/7/16 1600MB.			
	This is an initial estimate based on a visual inspection of			1

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.