



AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120
Tel : 65-6419-3000
Fax : 65-6835-7416
www.AIG.com.sg
CLAIMS DEPARTMENT
Co. Reg. No. 201009404M

Claim No: 1845724197SG **Date of Survey:** 11/07/2016
Repairer: CYCLE & AMP; CARRIAGE INDUSTRIES PTE LTD

REFERENCE

Insured/Claimant: [REDACTED] **Policy No:** [REDACTED]
Date of Loss: 07/07/2016 **Nature of Claim:** OD

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg. No: SDE2200C
Make & Model: MERCEDES-BENZ B180, 1.6
STYLE (R16 LED) (A) **Reg. Date:** 29/05/2015
Engine No: [REDACTED] **Chassis No:** [REDACTED]

CONDITION OF TYRES

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	5 mm	Rear Left Side:	5 mm
Front Right Side:	5 mm	Rear Right Side:	5 mm

The above values represent the remaining tyre treads depth

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Footbrake (Serviceable):	Yes	Engine Modification:	No
Handbrake (Serviceable):	Yes	Steering (Serviceable):	Yes
		Pre-accident Condition:	

TOTAL OFFER

Offer Authorized By:	CHANG, LOIS-KL on 07 Sep 2016 14:11
Offer Initiated By:	MERIMEN ADMINISTRATOR on 13 Jul 2016 11:44 (Rec. Offer Amount: S\$3,902.01)
Subrogation:	Yes
Rep. Gross Total:	S\$5,288.01 [Diff: S\$1,385.99, 26.21%]
Approved Gross Total:	S\$3,902.02
- Excess:	S\$800.00 [Remarks: Not Applicable]
	S\$3,102.02
+ GST (7.00%):	S\$217.14
Approved Nett Amount:	S\$3,319.16 (No Betterment/Depreciation)

COST OF CLAIMS	Repairer's	Our Offer	Difference	Diff %
Parts	228.01	228.02	-0.01	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,060.00	3,674.00	1,386.00	27.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,288.01	3,902.02	1,385.99	26.21

- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	4,488.01	3,102.02	1,385.99	30.88
+ GST 7.00/7.00% (S\$)	314.16	217.14	97.02	30.88
Nett Amount (S\$)	4,802.17	3,319.16	1,483.01	30.88

SURVEYOR'S REMARKS

This inspection is conducted on a "Without Prejudice Basis"

Estimated repair period : 6.0 days

Authorised Repair : Yes

Inspection conducted by : Chang, Lois-KL (AIG Claims Dept)

Signature : _

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT COVER MOLDING		59.44 FL	*59.45 FL
2	1		*RIGHT MIRROR HOUSING		193.91 FL	*193.91 FL
					Sub Total (\$\$)	253.35
					- List Item Discount on L Items 10.00/10.00% (\$\$)	25.34
					Total Parts (\$\$)	228.01

F=Franchise part. L=ListItemDisc.

AIG Asia Pacific Insurance Pte. Ltd./SDE2200C/07/09/2016 14:11

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STD SETTINGS. NETT	New	380.00	380.00
2	REMOVE, REPAIR & INSTALL RIGHT FRONT FENDER, RIGHT FRONT DOOR, RIGHT REAR DOOR, RIGHT REAR FENDER, RING WING MIRROR	New	1,680.00	1,344.00
3	RESPRAY ON RIGHT FRONT FENDER, RIGHT FRONT DOOR, RIGHT REAR DOOR, RIGHT REAR FENDER, RING WING MIRROR	New	3,000.00	1,950.00
Gross Labour Cost (\$)			5,060.00	3,674.00

AIG Asia Pacific Insurance Pte. Ltd./SDE2200C/07/09/2016 14:11

< END OF REPORT >