

15/5/2016

INS. CASE OWNER:

(Chan

CC3 /AIG160

13480 / Kim

LKK:

IDAC:

ASSIGNMENT

Surveyor:

Kathin

DOI:

19/7/16

Date / Time:

19/7/16

Registered in Merimen:

20/7/16

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKT1204L

Name of Insured:

Lion Ze Ping

Insured Tel No.:

HP:

9788814

Excess Sec II :SS

D.O.A.:

15/7/16

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

47176911 457

Policy No.:

2100414078

Make / Model:

Citroen C4 Grand Picasso 1.6i

Place of Accident:

15km towards back 24.5km

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Sme7 CWY



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

26/7/16 @ 5:

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	SS 35,400/-	(12 days)	Reduction: 32%
FINAL SETTLEMENT		Date/Time: 16/11/16	Confirm with: Tan Lee Gok
Final Liability:	% 100	(Agreed / Assessed)	BOLA S/N No.: 27
Repair Cost:	SS 35,400.00		
Loss of Rental (LOR):	SS 3,738.05	(25.5 days)	12 days + 3.5 days in police compound + 1 day inspection
Loss of Use (LOU):	SS -	(3 - x - days)	2 weeks waiting time + 2 days waiting + 2 half day of SA
Loss of Income (LOI):	SS -	(3 - x - days)	
LOR only	☒ LOR only	☐ LOR + LOU	☐ LOR + LOI
GIA/LTA Search	SS 5.00		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost	SS -		
Total:	SS 39,143.05	Global Sum SS:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	SS 39,143.05	Name 1:	SMART TAXIS
Payee 2: (Strike if N.A.)	SS -	Name 2:	
Payee 3: (Strike if N.A.)	SS -	Name 3:	

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call 01:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

(08/11/13) wef

ASS. REC. BY:

Kq/vin

REF:

ASSIGNMENT

From:

Date:

19/7/16

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHD1156Y

at Workshop m/s

SARIN

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHD1156Y

Yr Regn:

12 May 2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chrysler 200

c.c

2981

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

1C3C96CM2AY108633

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225 / 60 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

15/7/16

D.O.I.

19/7/16 1045hrs

Survey held at

SARIN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Veh cannot start

max 1.7/16/21x6
CHK

AZG / SKT 1204C

C LIS : \$ 35,400 | Red \$ 16,535.15 | 321.1

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG16013480/K1yg3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 20-07-2016



Code : AIG

Policy Particulars :- THIRD PARTY CLAIM

1.	Insured Veh.	SKT 1204L	Veh. Inspected	SHB 1156Y
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	20/07/2016

Vehicle Particulars & Condition

2.	Make & Model	c.c	0
	Engine No.	HIDDEN	Year of Reg.
	Chassis No.		Colour
	Odometer	-	Steering
	Brakes		Modification
	General		

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

Description of Damages

4.	
----	--

General Information

5.	Accident Date	15/07/2016	Inspection Date	19/07/2016
	Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

Remarks

5a.	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
-----	---



Camera (NO) +

Attached
Supplementary

Guan +4Days

SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg No : SHB1156Y
 Ref. No : TAX/07/16/2146
 Reg. Date : 12/05/2010
 Vehicle Type : TAXI
 Make : CHRYSLER
 Model : C300
 Name of Driver : LOH PENG YAM
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 15/07/2016 05:45:00 PM
 Accident Reported Date / Time : 16/07/2016 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : kalvin
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024083543
 Special Instruction to ARC, if any :

Towed to TP compound / SKT1204L / Towed \$100 - AIG - LKK
 AFTER REPAIR PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR KALVIN (LKK) /
 Email: kalvinang@lkkauto.com
 LUMPSUM REPAIR

Prepared Date : 18/07/2016 10:29:36 AM



1730 17/8/16 Rejet R/C exhaust retit no gas
 14-00 18/8/16 Pass

Vehicle to Wega Date In: 22/07	Towing: _____
Time In: _____	Driver: _____
Wega Job No: 12090/07	
Vehicle sent to SMRT Date In: 17/8/16	Towing: _____
Time In: 1505	Driver: chr
Received by (SMRT): _____	

E 1/2 F
 KM 7.32581

Chassis No : 1C3C96CM2AY108633

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,859.00	1,800.00
Total Spray Painting Charges	: 2,972.00	1,100.00
Total Material Charges	: 38,365.82	31,598.30
Other Charges	: 2,460.00	910.00
TOTAL	: 45,656.82	35,408.30
Lum Sum Total	: 45,650.00	35,400.00
No. of Repair Days	: 13.00	12.00
Prepared / Adjusted By	:	KALVIN (LKK)
Arc / Surveyor Sing Off Date	: 19/07/2016 02:19:17 AM	19/07/2016 04:01:17 AM

f

LKK

Prepared / Adjusted Date :

Remarks :

Prepared Date : 19/07/2016 02:18:01 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

: QN-1608-0716

Invoice No

:

Quotation Date

: 23/8

Invoice Date

:

Invoice Amount

:

Prepared Date

:

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,859.00	1,800.00
Total Labour	1,859.00	1,800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	473.00	200.00
TO RESPRAY REAR PANEL	180.00	100.00
TO RESPRAY REAR BOOT LID	473.00	200.00
TO RESPRAY REAR SPARE TYRE PANEL	180.00	100.00
TO RESPRAY REAR CHASSIS LH	180.00	50.00
TO RESPRAY REAR CHASSIS RH	180.00	0.00
TO RESPRAY REAR FENDER RH	473.00	200.00
TO RESPRAY TAIL LAMP PANEL LH	180.00	50.00
TO RESPRAY REAR FENDER LH	473.00	200.00
TO RESPRAY BATTERY PANEL	180.00	0.00
Total Spray Painting & Panel Beating	2,972.00	1,100.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	140.00	100.00
TO CHECK WIRING AND SYSTEM FUNCTION	120.00	30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	80.00
TO REMOVE / REFIT SEAT	120.00	50.00
TO REMOVE & REFIT EXHAUST	120.00	50.00
TO REMOVE & REFIT FUEL TANK	120.00	50.00
TO ALIGN CHASSIS	350.00	150.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	50.00
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	100.00
TO REMOVE AND REFIT WIRE HARDESS	120.00	0.00
TO TRANSFER DOOR MECHANISM	120.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	50.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00
TO REMOVE AND REFIX UNDERCARRIAGE	450.00	200.00
Total Other Costs	2,460.00	910.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
	REAR		REAR BUMPER ASSY <i>Rebuilt</i>	1	2,120.00	10.00	1,908.00	Replace	Replace	No ☒
	REAR		REAR BUMPER CLIP BIG <i>LC</i>	6	10.00	10.00	54.00	Replace	Replace	No ☒
	REAR		REAR BUMPER CLIP SMALL <i>LC</i>	6	20.00	10.00	108.00	Replace	Replace	No ☒
04806257 AA	REAR		ENERGY ABSORBER - REAR BUMPER <i>CR9</i>	1	373.00	10.00	335.70	Replace	Replace	No ☒
	REAR		REAR BUMPER REINFORCEMENT <i>Rebuilt</i>	1	600.00	10.00	540.00	Replace	Replace	No ☒
04805940 AA	REAR		REAR BUMPER STRIP CHROME <i>CR9</i>	1	430.00	10.00	387.00	Replace	Replace	No ☒
	REAR		REAR NUMBER PLATE <i>Plat</i>	1	35.00	0.00	35.00	Replace	Replace	No ☒
	REAR		REAR NUMBER PLATE FRAME <i>CR</i>	1	35.00	0.00	35.00	Replace	Replace	No ☒
04805846 AA	COMMON		LAMP LISCENSE <i>CR9</i>	2	31.00	10.00	55.80	Replace	Replace	No ☒
	COMMON		REAR REVERSE CAMERA <i>CR9</i>	1	320.00	10.00	288.00	Replace	Replace	No ☒
56054049 AE			REAR REVERSE SENSOR MODULE <i>SC</i>	1	470.00	10.00	423.00	Replace	Check	No ☒
	REAR		REVERSE SENSOR <i>CR9</i>	4	420.00	10.00	1,512.00	Replace	Replace	No ☒
	REAR		REAR EXHAUST PIPE LH <i>Rebuilt</i>	1	3,800.00	10.00	3,420.00	Replace	Replace	No ☒
	COMMON		REAR EXHAUST PIPE RH <i>SC</i>	0	6,600.00	10.00	0.00	Replace	Not given	No ☒
	REAR		REAR BOOT LID ASSY <i>Rebuilt</i>	1	1,620.00	10.00	1,458.00	Replace	Replace	No ☒
	COMMON		WEATHERSTRIP - REAR BOOT <i>Rebuilt</i>	1	580.00	10.00	522.00	Replace	Replace	No ☒
			HINGE REAR BOOTLID LH <i>Rebuilt</i>	1	120.00	10.00	108.00	Replace	Replace	No ☒
			HINGE REAR BOOTLID RH <i>Repair</i>	1	120.00	100.00	0.00	Replace	Repair	No ☒
			DAMPER REAR BOOTLID LH <i>SC</i>	0	152.40	10.00	0.00	Replace	Not given	No ☒
			DAMPER REAR BOOTLID RH <i>SC</i>	0	152.40	10.00	0.00	Replace	Not given	No ☒
	REAR		LOCK ASSY RR LID <i>CR9</i>	1	450.00	10.00	405.00	Replace	Replace	No ☒
	REAR		EMBLEM - "300C" <i>Rebuilt</i>	1	150.00	10.00	135.00	Replace	Replace	No ☒
	REAR		EMBLEM - "CHRYSLER" <i>Rebuilt</i>	1	180.00	10.00	162.00	Replace	Replace	No ☒
	REAR		EMBLEM - "CRD" <i>Rebuilt</i>	1	120.00	10.00	108.00	Replace	Replace	No ☒
	REAR		EMBLEM - SYMBOL MARK <i>Rebuilt</i>	1	60.00	10.00	54.00	Replace	Replace	No ☒
	COMMON		SMRT LOGO <i>Rebuilt</i>	1	7.80	0.00	7.80	Replace	Replace	No ☒
	COMMON		STICKER PRESTIGE <i>Rebuilt</i>	1	60.00	0.00	60.00	Replace	Replace	No ☒
	COMMON		REAR WINDSCREEN MOULDING <i>Rebuilt</i>	1	150.00	10.00	135.00	Replace	Replace	No ☒
	COMMON		SEALANT W/SCREEN <i>Rebuilt</i>	2	37.00	0.00	74.00	Replace	Replace	No ☒
	REAR		REAR PANEL <i>Rebuilt</i>	1	1,080.00	10.00	972.00	Replace	Replace	No ☒

Number			Part Name	Qty	Unit Price (\$)	Discount (%)	Final Price (\$)	Recommend	Surveyor Approved	Notes
			GARNISH REAR END PANEL <i>cm</i>	1	390.00	10.00	351.00	Replace	Replace	No ✓
	COMMON	4006314	SEALANT SIKAFLEX <i>net</i>	1	37.00	0.00	37.00	Replace	Replace	No ✓
	REAR		SPARE TYRE PANEL <i>net</i>	1	5,333.33	10.00	4,800.00	Replace	Replace	No ✓
	COMMON		TYRE <i>see</i>	0	395.00	10.00	0.00	Replace	Not given	No X
	REAR		REAR MAIN CHASSIS LH ASSY <i>repair</i>	1	7,500.00	100.00	0.00	Replace	Repair	No R
	COMMON		REAR MAIN CHASSIS RH ASSY <i>see</i>	0	7,500.00	10.00	0.00	Replace	Not given	No X
			TRIM LH REAR FENDER <i>cm</i>	1	227.50	10.00	204.75	Replace	Replace	No ✓
			TRIM RH REAR FENDER <i>see</i>	0	227.50	10.00	0.00	Replace	Not given	No X
	COMMON		COVER SPARE TYRE <i>cm</i>	1	250.00	10.00	225.00	Replace	Replace	No ✓
			FUSE BOX ASSY - REAR <i>cm</i>	1	3,500.00	10.00	3,150.00	Replace	Replace	No ✓
			BATTERY <i>see</i>	1	150.00	10.00	135.00	Replace	Check	No X
			BATTERY TRAY REAR <i>see</i>	1	580.00	0.00	580.00	Replace	Check	No X
	COMMON		BREAKDOWN SIGN <i>see</i>	1	35.00	0.00	35.00	Replace	Check	No X
04806372 AB	REAR		TAILLAMP ASSY - REAR RH <i>see</i>	1	680.00	10.00	612.00	Replace	Check	No X
05135906 AI	COMMON		FENDER ASSY - REAR RH <i>see</i>	0	3,440.00	10.00	0.00	Replace	Not given	No X
			LINER RH REAR FENDER <i>see</i>	0	227.50	10.00	0.00	Replace	Not given	No X
04806373 AB	REAR		TAILLAMP ASSY - REAR LH <i>cm</i>	1	680.00	10.00	612.00	Replace	Replace	No ✓
			TAIL LAMP PANEL LH <i>net</i>	1	334.75	10.00	301.27	Replace	Replace	No ✓
05135907 AL	LEFT		FENDER ASSY - REAR LH <i>net</i>	1	3,440.00	10.00	3,096.00	Replace	Replace	No ✓
			LINER LH REAR FENDER <i>see</i>	1	227.50	10.00	204.75	Replace	Replace	No ✓
			FUEL TANK NECK <i>cm</i>	1	460.00	10.00	414.00	Replace	Replace	No ✓
05134177 AN	LEFT		DOOR ASSY - REAR LH <i>repair</i>	1	3,800.00	100.00	0.00	Replace	Repair	No R
04575893 AA	LEFT		LOCK ASSY - REAR DOOR LH <i>see</i>	0	315.00	10.00	0.00	Replace	Not given	No X
05166093 AA	LEFT		HINGE - REAR DOOR LOWER LH <i>see</i>	0	115.00	10.00	0.00	Replace	Not given	No X
04575751 AC	LEFT		HINGE - REAR DOOR UPPER LH <i>see</i>	0	265.00	10.00	0.00	Replace	Not given	No X
04780259 AD	LEFT		STRIKER ASSY - REAR DOOR LH <i>see</i>	0	40.00	10.00	0.00	Replace	Not given	No X
	COMMON		SMRT LOGO <i>net</i>	0	7.80	0.00	0.00	Replace	Not given	No X
	COMMON		STICKER PRESTIGE <i>net</i>	0	60.00	0.00	0.00	Replace	Not given	No X
			LH REAR TENSION LINK <i>see</i>	1	1,560.00	10.00	1,404.00	Replace	Replace	No ✓
			LH REAR TOE LINK <i>net</i>	1	1,250.00	10.00	1,125.00	Replace	Replace	No ✓
04766866 AA			STABILIZER LINK BAR <i>net</i>	1	83.00	10.00	74.70	Replace	Replace	No ✓

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	Recommended	Surveyor Approved	Attached
04726035 AD	COMMO N	REAR DRIVE SHAFT ASSY LH <i>Bar</i>	1	525.00	10.00	472.50	Replace	Replace	No ☒
04782587 AD		REAR LH KNUCKLE <i>Bar</i>	1	1,563.00	10.00	1,406.70	Replace	Replace	No ☒
04593650 AF		PROP SHAFT FRT & REAR <i>Bar</i>	1	2,240.00	10.00	2,016.00	Replace	Replace	No ☒
04578084 AC		REAR SUBFRAME BUSHES - LH/RH <i>Bar</i>	2	55.00	10.00	99.00	Replace	Replace	No ☒
		REAR AXLE DIFFERENTIAL <i>sun</i>	1	7,416.00	10.00	6,674.40	Replace	Check	No ☒
68241573 AB		CAMBER LINK LHR <i>Bar</i>	1	981.00	10.00	882.90	Replace	Replace	No ☒
5170306 AA		Rear axle subframe <i>Bar</i>	1	6,000.00	10.00	5,400.00	Replace	Replace	No ☒
04895513 AC	COMMO N	REAR SHOCK ABSORBER ASSY <i>Bar</i>	1	380.00	10.00	342.00	Replace	Replace	No ☒
TOTAL MATERIALS						47,957.27	39,497.87		
TOTAL MATERIALS(Discounted)						38,365.82	31,598.30		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
		LH REAR TENSION LINK	1	1,560.00	10.00	1,404.00	Replace	Replace	No ☒
		LH REAR TOE LINK	1	1,250.00	10.00	1,125.00	Replace	Replace	No ☒
04766866 AA		STABILIZER LINK BAR	1	83.00	10.00	74.70	Replace	Replace	No ☒
04726035 AD	COMMO N	REAR DRIVE SHAFT ASSY LH	1	525.00	10.00	472.50	Replace	Replace	No ☒
04782587 AD		REAR LH KNUCKLE	1	1,563.00	10.00	1,406.70	Replace	Replace	No ☒
04593650 AF		PROP SHAFT FRT & REAR	1	2,240.00	10.00	2,016.00	Replace	Replace	No ☒
04578084 AC		REAR SUBFRAME BUSHES - LH/RH	2	55.00	10.00	99.00	Replace	Replace	No ☒
		REAR AXLE DIFFERENTIAL	1	7,416.00	10.00	6,674.40	Replace	Check	No ☒
68241573 AB		CAMBER LINK LHR	1	981.00	10.00	882.90	Replace	Replace	No ☒
5170306 AA		Rear axle subframe	1	6,000.00	10.00	5,400.00	Replace	Replace	No ☒
04895513 AC	COMMO N	REAR SHOCK ABSORBER ASSY	1	380.00	10.00	342.00	Replace	Replace	No ☒
TOTAL SUPPLEMENTARY MATERIALS						19,897.20			

39,497.87
 - 202
 31,598.30
 + 1,800.00
 + 2,010.00
 35,408.30
 45 \$35,400/-
 29/8/16
 cash
 11

Supplementary Parts

Contractor	WEGA ENGINEERING PTE LTD		
Accident Case Number	TAX/07/16/2146 ①	Date of Collection	29/7/16
Vehicle No	SHB1156Y	Date of Request	29/7/16
Vehicle Model	Chrysler	Number of Days to Extend	10 Days 4 Days.

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	1923, 26, 27	Rear Exhaust pipe LH ✓	1	\$3800.00
2	1914, 1936, 35	Rear Main chassis Assy LH	1	\$7500.00 X repair
3	1917, 18	Fuse Box Assy - Rear ✓	1	\$3500.00
4	1919, 20, 21	Fuel Tan Neck ✓	1	\$460.00
5	1929	Rear shock Absorber LH ✓	1	\$700.00
6	1936, 35, 34	Rear Subframe Axle ✓	1	\$6000.00
7	1928	Rear Camber Link LH ✓	1	\$1000.00
8	1937	Rear Tension Link LH ✓	1	\$1370.00

<<<Please submit photographs for damaged parts>>>

(Name) GUAN

(Position) ADVISOR

I do solemnly and sincerely declare that - Supplementary Parts are raised for replacement for the aforesaid vehicle

(Signature)

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation Number
Photo Submitted	Date of submission	

For SMRT Staff

[Handwritten signature]

Contractor	WEGA ENGINEERING PTE LTD		
Accident Case Number	TAX/07/16/2146 ②	Date of Collection	22/7/16
Vehicle No	SHB1156Y	Date of Request	29/7/16
Vehicle Model	Chrysler	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	1942	None Toe Link LH	1.	\$502.00
2	1929	Rear stabilizer	1.	\$83.00
3	1936	Rear Drive shaft LH	1.	\$455.00
4	1939, 40	Rear Knuckle LH	1.	\$1563.00
5	1933	Long shaft	1.	\$2240.00
6	1929	Rear stabilizer Bar Bushes	2	\$30.00
7	1932	Rear Axle Differential	1.	\$12360.00 ? check
8	1912	To Repair Rear Trندر RH		\$378.00 \$200

<<<Please submit photographs for damaged parts>>>

(Name) GUAN

(Position) ADVISOR

I do solemnly and sincerely declare that - Supplementary Parts are raised for replacement for the aforesaid vehicle

(Signature)

Signature of person making this declaration

(To be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PC / WOC / Reservation Number
Photo Submitted For SMRT Staff	Date of submission	

Contractor		WEGA ENGINEERING PTE LTD	
Accident Case Number	TAX/07/16/2146 (3)	Date of Collection	22/7/16
Vehicle No	SHB1156Y	Date of Request	29/7/16
Vehicle Model	Chrysler	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	1912	To Repair Rear Fender Rt & }		\$ 600
2	1905, 06, 07	Accident Portion To Low }		\$ 1200.00
3	1913, 14	To Remove & Refix undercarriage)		\$ 450.00
4				\$ 200
5				
6				
7				
8				

<<<Please submit photographs for damaged parts>>>

Name: GUAN

Position: ADVISOR

I do solemnly and sincerely declare that - Supplementary Parts are raised for replacement for the aforesaid vehicle

(Signature)

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation Number
Photo Submitted		Date of submission
For SMRT Staff		

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1156Y
 Ref. No : TAX/07/16/2146
 Reg. Date : 12/05/2010
 Vehicle Type : TAXI
 Make : CHRYSLER
 Model : C300
 Name of Driver : LOH PENG YAM
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 15/07/2016 05:45:00 PM
 Accident Reported Date / Time : 16/07/2016 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024083543
 Special Instruction to ARC, if any :
 Towed to TP compound / SKT1204L / Towed \$100 - AIG - LKK
 Prepared Date : 18/07/2016 10:29:36 AM



After Repair
 LCC Repair
 Check Back

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants hence notify the Repairer of:

Signature: _____
 Date: _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : 1C3C96CM2AY108633

Mileage :

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,859.00	0.00
Total Spray Painting Charges	: 2,972.00	0.00
Total Material Charges	: 44,994.15	44,994.15
Other Charges	: 2,010.00	0.00
TOTAL	: 51,835.15	0.00
Lum Sum Total	: 51,850.00	0.00
No. of Repair Days	: 13.00	0.00 <i>8 Days.</i>
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 19/07/2016 02:19:17 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 19/07/2016 02:18:01 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,859.00	0.00
Total Labour	1,859.00	0.00 1200

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	473.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 100
TO RESPRAY REAR BOOT LID	473.00	0.00 250
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 100
TO RESPRAY REAR CHASSIS LH	180.00	0.00 50
TO RESPRAY REAR CHASSIS RH	180.00	0.00 X
TO RESPRAY REAR FENDER RH	473.00	0.00 X
TO RESPRAY TAIL LAMP PANEL LH	180.00	0.00 50
TO RESPRAY REAR FENDER LH	473.00	0.00 200
TO RESPRAY BATTERY PANEL	180.00	0.00 X
Total Spray Painting & Panel Beating	2,972.00	0.00 900

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	140.00	0.00 X
TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 80
TO REMOVE / REFIT SEAT	120.00	0.00 50
TO REMOVE & REFIT EXHAUST	120.00	0.00 50
TO REMOVE & REFIT FUEL TANK	120.00	0.00 50
TO ALIGN CHASSIS	350.00	0.00 150
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 50
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 100
TO REMOVE AND REFIT WIRE HARDESS	120.00	0.00 X
TO TRANSFER DOOR MECHANISM	120.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 50
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 X
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 X
Total Other Costs	2,010.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
	REAR		REAR BUMPER ASSY	1	2,120.00	10.00	1,908.00	Replace	Replace ✓	No
	REAR		REAR BUMPER CLIP BIG	6	10.00	10.00	54.00	Replace	Replace ✓	No
	REAR		REAR BUMPER CLIP SMALL	6	20.00	10.00	108.00	Replace	Replace ✓	No
04806257 AA	REAR		ENERGY ABSORBER - REAR BUMPER	1	373.00	10.00	335.70	Replace	Replace ✓	No
	REAR		REAR BUMPER REINFORCEMENT	1	600.00	10.00	540.00	Replace	Replace ✓	No
04805940 AA	REAR		REAR BUMPER STRIP CHROME	1	430.00	10.00	387.00	Replace	Replace ✓	No
	REAR		REAR NUMBER PLATE	1	35.00	0.00	35.00	Replace	Replace ✓	No
	REAR		REAR NUMBER PLATE FRAME	1	35.00	0.00	35.00	Replace	Replace ✓	No
04805846 AA	COMMON		LAMP LICENSE	2	31.00	10.00	55.80	Replace	Replace ✓	No
	COMMON		REAR REVERSE CAMERA	1	320.00	10.00	288.00	Replace	Replace ✓	No
56054049 AE			REAR REVERSE SENSOR MODULE	1	470.00	10.00	423.00	Replace	Replace x Leak	No
	REAR		REVERSE SENSOR	4	420.00	10.00	1,512.00	Replace	Replace ✓	No
	REAR		REAR EXHAUST PIPE LH	1	3,800.00	10.00	3,420.00	Replace	Replace x repair	No
	COMMON		REAR EXHAUST PIPE RH	1	6,600.00	10.00	5,940.00	Replace	Replace x	No
	REAR		REAR BOOT LID ASSY	1	1,620.00	10.00	1,458.00	Replace	Replace ✓	No
	COMMON		WEATHERSTRIP - REAR BOOT	1	580.00	10.00	522.00	Replace	Replace ✓	No
			HINGE REAR BOOTLID LH	1	120.00	10.00	108.00	Replace	Replace ✓	No
			HINGE REAR BOOTLID RH	1	120.00	10.00	108.00	Replace	Replace x repair	No
			DAMPER REAR BOOTLID LH	1	152.40	10.00	137.16	Replace	Replace x	No
			DAMPER REAR BOOTLID RH	1	152.40	10.00	137.16	Replace	Replace x	No
	REAR		LOCK ASSY RR LID	1	450.00	10.00	405.00	Replace	Replace ✓	No
	REAR		EMBLEM - "300C"	1	150.00	10.00	135.00	Replace	Replace ✓	No
	REAR		EMBLEM - "CHRYSLER"	1	180.00	10.00	162.00	Replace	Replace ✓	No
	REAR		EMBLEM - "CRD"	1	120.00	10.00	108.00	Replace	Replace ✓	No
	REAR		EMBLEM - SYMBOL MARK	1	60.00	10.00	54.00	Replace	Replace ✓	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓	No
	COMMON		STICKER PRESTIGE	1	60.00	0.00	60.00	Replace	Replace ✓	No
	COMMON		REAR WINDSCREEN MOULDING	1	150.00	10.00	135.00	Replace	Replace ✓	No
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace ✓	No
	REAR		REAR PANEL	1	1,080.00	10.00	972.00	Replace	Replace ✓	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
			GARNISH REAR END PANEL	1	390.00	10.00	351.00	Replace	Replace ✓	No
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ✓	No
	REAR		SPARE TYRE PANEL	1	5,333.33	10.00	4,800.00	Replace	Replace ✓	No
	COMMON		TYRE	1	395.00	10.00	355.50	Replace	Replace X	No
	REAR		REAR MAIN CHASSIS LH ASSY	1	7,500.00	10.00	6,750.00	Replace	Replace X repair	No
	COMMON		REAR MAIN CHASSIS RH ASSY	1	7,500.00	10.00	6,750.00	Replace	Replace X	No
			TRIM LH REAR FENDER	1	227.50	10.00	204.75	Replace	Replace ✓	No
			TRIM RH REAR FENDER	1	227.50	10.00	204.75	Replace	Replace X	No
	COMMON		COVER SPARE TYRE	1	250.00	10.00	225.00	Replace	Replace ✓	No
			FUSE BOX ASSY - REAR	1	3,500.00	0.00	3,500.00	Replace	Replace X	No check
			BATTERY	1	150.00	10.00	135.00	Replace	Replace X	No check
			BATTERY TRAY - REAR	1	580.00	0.00	580.00	Replace	Replace X	No check
	COMMON		BREAKDOWN SIGN	1	35.00	0.00	35.00	Replace	Replace X	No check
04806372 AB	REAR		TAILLAMP ASSY - REAR RH	1	680.00	10.00	612.00	Replace	Replace X	No check
05135906 AI	COMMON		FENDER ASSY - REAR RH	1	3,440.00	10.00	3,096.00	Replace	Replace X	No X
			LINER RH REAR FENDER	1	227.50	10.00	204.75	Replace	Replace X	No
04806373 AB	REAR		TAILLAMP ASSY - REAR LH	1	680.00	10.00	612.00	Replace	Replace ✓	No
			TAIL LAMP PANEL LH	1	334.75	10.00	301.27	Replace	Replace ✓	No
05135907 AL	LEFT		FENDER ASSY - REAR LH	1	3,440.00	10.00	3,096.00	Replace	Replace ✓	No
			LINER LH REAR FENDER	1	227.50	10.00	204.75	Replace	Replace ✓	No
			FUEL TANK NECK	1	460.00	10.00	414.00	Replace	Replace X	No check
05134177 AN	LEFT		DOOR ASSY - REAR LH	1	3,800.00	10.00	3,420.00	Replace	Replace X	No repair
04575893 AA	LEFT		LOCK ASSY - REAR DOOR LH	1	315.00	10.00	283.50	Replace	Replace X	No
05166093 AA	LEFT		HINGE - REAR DOOR LOWER LH	1	115.00	10.00	103.50	Replace	Replace X	No
04575751 AC	LEFT		HINGE - REAR DOOR UPPER LH	1	265.00	10.00	238.50	Replace	Replace X	No
04780259 AD	LEFT		STRIKER ASSY - REAR DOOR LH	1	40.00	10.00	36.00	Replace	Replace X	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓	No
	COMMON		STICKER PRESTIGE	1	60.00	0.00	60.00	Replace	Replace ✓	No
TOTAL MATERIALS							56,242.69	56,242.69		
TOTAL MATERIALS(Discounted)							44,994.15	44,994.15		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
-------------	---------	-----------	-----	-----------------	--------------	------------------	-----------	----------------	----------

Kalim 10/14
M 19/7/16

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 5369K

Vehicle Details

Vehicle No.: SHB1156Y

Vehicle to be Exported: No

Intended De-registration
Date: 19 Jul 2016

Vehicle Make: CHRYSLER

Vehicle Model: 300C 3.0L AT ABS D/AIRBAG HID 2WD 4DR

Primary Colour: Black

Manufacturing Year: 2010

Engine No.: AY106980

Chassis No.: 1C3C96CM2AY108633

Maximum Power
Output: 160.0 kW (214 bhp)

Open Market Value: \$41,370.00

Original Registration
Date: 12 May 2010

First Registration Date: 12 May 2010

Transfer Count: 0

Actual ARF Paid: \$41,370.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 11 May 2018

PARF Rebate Amount: \$26,890.00

Intended COE Rebate Details

COE Expiry Date: 11 May 2018

COE Category: A - Car (1600cc & below)

COE Period(Years): 8

PQP Paid: \$20,470.00

COE Rebate Amount: \$4,631.00

Total Rebate Amount: \$31,521.00**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 19 Jul 2016

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2016 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 6259
www.police.gov.sg

Our Ref : TP/IP/35919/2016
Date : 3rd August 2016

Loh Peng Yam
Apt Blk 220 Serangoon Avenue 4
#10-226
Singapore 550220

Dear Sir/ Mdm,

TRAFFIC ACCIDENT INVOLVING SHB1156Y AND SKT1204L ON 15TH JULY 2016 AT ABOUT 6.43PM ALONG PIE(TUAS) 25.4KM

I refer to the above accident.

2 We have completed investigation into the case. Our investigation shows that an offence of Careless Driving Under Rule 29 Road Traffic Rules was disclosed against the driver of motor car SKT1204L. Action will be initiated against the driver for the said offence.

3 This is for your information only.

Yours Sincerely,

**FAKHRUR RAZI , SSGT
for HEAD INVESTIGATION
TRAFFIC INVESTIGATION BRANCH**

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	20 Jul 2016 19:04	Clim Veh Model Changed	(201965) CHRYSLER 300C 3.0 D (A).		[A] Agnes Lim Su Hoon
2	20 Jul 2016 19:04	Clim Created	Reg No: SHB1156Y. Acct Date: 2016/07/15. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). TP Insurer: First Capital Insurance Ltd (HQ). Workshop: SMRT Automotive Services Pte Ltd (Woodlands)		[A] Agnes Lim Su Hoon
3	20 Jul 2016 19:04	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] Agnes Lim Su Hoon
4	20 Jul 2016 19:04	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2016/07/29		[A] Agnes Lim Su Hoon
5	20 Jul 2016 19:04	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.		[A] Agnes Lim Su Hoon
6	20 Jul 2016 19:04	Clim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)		[I] Merimen Administrator
7	20 Jul 2016 19:05	Label Added	(23):Express.		[A] Agnes Lim Su Hoon
8	20 Jul 2016 19:05	Adj Adjuster Assigned	[None] -> KALVIN ANG WEI KUN		[A] Agnes Lim Su Hoon
9	09 Nov 2016 11:15	Adj Rpt Initiated			[A] NUR SHAQILAH BTE ABDOL WAHAB
10	09 Nov 2016 11:15	Clim Details Notified			[A] NUR SHAQILAH BTE ABDOL WAHAB
11	21 Jan 2017 16:52	Adj Mandate Request	Cur,Req:40315.77:FOR YOUR APPROVAL PLEASE		[A] Jasmine Khine Phoo Wai
12	23 Mar 2017 15:14	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2016/07/29. Mandate Remarks: From: Chan, Kian-Chuan Sent: Monday, January 23, 2017 1:49 PM To:		[I] Chan, Kian-Chuan
13	23 Mar 2017 15:14	Adj Mandate Set	Approved:0.00:From: Chan, Kian-Chuan Sent: Monday, January 23, 2017 1:49 PM To: 'Jas Khine (LKKAuto)' Subject:		[I] Chan, Kian-Chuan
14	25 Sep 2017 11:41	Adj Mandate Request	Cur,Req:40315.77:RE-SEEK MANDATE		[A] Jasmine Khine Phoo Wai
15	24 Oct 2017 09:41	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2016/07/29. Mandate Remarks: Please kindly provide us with a detail chronological events for the LOR claimed our review on the matter. We are not agreeable to the email from SMRT dated 19/9/17. We are of the view that the		[I] Chan, Kian-Chuan
16	24 Oct 2017 09:41	Adj Mandate Set	Approved:0.00:Please kindly provide us with a detail chronological events for the LOR claimed our review on the matter. We are not agreeable to the email from SMRT dated 19/9/17. We are of the view that the days taken to check (hidden parts, stock		[I] Chan, Kian-Chuan
17	09 Jul 2019 17:38	Adj Mandate Request	Cur,Req:40315.77:\$40,315.77		[A] Khanchna Pothuraj
18	26 Jul 2019 23:28	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2016/07/29. Mandate Remarks: subject to final repair bill & ATA		[I] Syed-Yusoff, Saliha
19	26 Jul 2019 23:28	Adj Mandate Set	Approved:39143.40:subject to final repair bill & ATA		[I] Syed-Yusoff, Saliha
20	26 Jul 2019 23:34	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2016/07/29. Mandate Remarks: subject to final repair bill & ATA ** LOU from 21.5 days - 25.5 days [12 days (recommendation) + 4 weekends + 5.5 days - 9.5 days (downtime for parts)]		[I] Syed-Yusoff, Saliha
21	26 Jul 2019 23:34	Adj Mandate Set	Approved:39243.40:subject to final repair bill & ATA ** LOU from 21.5 days - 25.5 days [12 days (recommendation) + 4 weekends + 5.5 days - 9.5 days (downtime for parts)]		[I] Syed-Yusoff, Saliha
22	09 Oct 2019 17:28	Insured Phone No Updated	[None] -> [+6597998121]		[A] CHEW HSIAO TONG
23	09 Oct 2019 18:33	Adj Mandate Request	Cur,Req:39802.70:Our offer was rejected. Third party repairer counter proposed global sum of \$39,800.00 all in and wants loss of rental for 30 days. Your approval please. Thank you.		[A] Khanchna Pothuraj

Date From



Date To



Audit Type None



Go

ACTIVITY

[20/07/2018 14:19] OLIVIA LAU WAN YEE:

AIG instruction on LOR. Reseek mandate. 19/06/2018.

[26/07/2016 17:20] Jasmine Khine Phoo Wai:

CALL OI ..HAND UP THE PHONE....ACC SCENARIO...OI REAR ENDED TP VEH...SERIOUS DAMGED BOTH PARTY...BOLA 27 LIAB 100%

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1300691	09 Nov 2016 11:15:34	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SHB1156Y		10.70