

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1156Y
 Ref. No : TAX/07/16/2146
 Reg. Date : 12/05/2010
 Vehicle Type : TAXI
 Make : CHRYSLER
 Model : C300
 Name of Driver : LOH PENG YAM
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 15/07/2016 05:45:00 PM
 Accident Reported Date / Time : 16/07/2016 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024083543
 Special Instruction to ARC, if any :
 Towed to TP compound / SKT1204L / Towed \$100 - AIG - LKK
 Prepared Date : 18/07/2016 10:29:36 AM



*After repair plz
 Loh Peng Yam
 Check Book value*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants hence notify the Repairer of:

Repairer's Name: _____
 Repairer's Address: _____
 Repairer's Phone: _____
 Repairer's Email: _____
 Repairer's Insurance: _____
 Repairer's License: _____
 Repairer's Signature: _____
 Repairer's Date: _____

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : 1C3C96CM2AY108633

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates**Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges : 1,859.00
Total Spray Painting Charges : 2,972.00
Total Material Charges : 44,994.15
Other Charges : 2,010.00

0.00

0.00

44,994.15

0.00

TOTAL : 51,835.15**0.00****Lum Sum Total : 51,850.00****0.00**

No. of Repair Days : 13.00

~~0.00~~ 8 Days.

Prepared / Adjusted By :

Arc / Surveyor Sing Off Date : 19/07/2016 02:19:17 PM

01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 19/07/2016 02:18:01 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable	
TO REPAIR REAR PORTION	1,859.00	0.00	
Total Labour	1,859.00	0.00	1 200

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable	
TO REPSRAY REAR BUMPER	473.00	0.00	200
TO RESPRAY REAR PANEL	180.00	0.00	100
TO RESPRAY REAR BOOT LID	473.00	0.00	250
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00	100
TO RESPRAY REAR CHASSIS LH	180.00	0.00	50
TO RESPRAY REAR CHASSIS RH	180.00	0.00	X
TO RESPRAY REAR FENDER RH	473.00	0.00	X
TO RESPRAY TAIL LAMP PANEL LH	180.00	0.00	50
TO RESPRAY REAR FENDER LH	473.00	0.00	250
TO RESPRAY BATTERY PANEL	180.00	0.00	X
Total Spray Painting & Panel Beating	2,972.00	0.00	900

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable	
TOWING CHARGE	140.00	0.00	X
TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0.00	30
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00	80
TO REMOVE / REFIT SEAT	120.00	0.00	50
TO REMOVE & REFIT EXHAUST	120.00	0.00	50
TO REMOVE & REFIT FUEL TANK	120.00	0.00	50
TO ALIGN CHASSIS	350.00	0.00	150
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00	50
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00	100
TO REMOVE AND REFIT WIRE HARDESS	120.00	0.00	X
TO TRANSFER DOOR MECHANISM	120.00	0.00	X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00	50
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00	X
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00	X
Total Other Costs	2,010.00	0.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
	REAR		REAR BUMPER ASSY	1	2,120.00	10.00	1,908.00	Replace	Replace ✓	No
	REAR		REAR BUMPER CLIP BIG	6	10.00	10.00	54.00	Replace	Replace ✓	No
	REAR		REAR BUMPER CLIP SMALL	6	20.00	10.00	108.00	Replace	Replace ✓	No
04806257 AA	REAR		ENERGY ABSORBER - REAR BUMPER	1	373.00	10.00	335.70	Replace	Replace ✓	No
	REAR		REAR BUMPER REINFORCEMENT	1	600.00	10.00	540.00	Replace	Replace ✓	No
04805940 AA	REAR		REAR BUMPER STRIP CHROME	1	430.00	10.00	387.00	Replace	Replace ✓	No
	REAR		REAR NUMBER PLATE	1	35.00	0.00	35.00	Replace	Replace ✓	No
	REAR		REAR NUMBER PLATE FRAME	1	35.00	0.00	35.00	Replace	Replace ✓	No
04805846 AA	COMMON		LAMP LISCENSE	2	31.00	10.00	55.80	Replace	Replace ✓	No
	COMMON		REAR REVERSE CAMERA	1	320.00	10.00	288.00	Replace	Replace ✓	No
56054049 AE			REAR REVERSE SENSOR MODULE	1	470.00	10.00	423.00	Replace	Replace X <i>check</i>	No
	REAR		REVERSE SENSOR	4	420.00	10.00	1,512.00	Replace	Replace ✓	No
	REAR		REAR EXHAUST PIPE LH	1	3,800.00	10.00	3,420.00	Replace	Replace X <i>repair</i>	No
	COMMON		REAR EXHAUST PIPE RH	1	6,600.00	10.00	5,940.00	Replace	Replace X	No
	REAR		REAR BOOT LID ASSY	1	1,620.00	10.00	1,458.00	Replace	Replace ✓	No
	COMMON		WEATHERSTRIP - REAR BOOT	1	580.00	10.00	522.00	Replace	Replace ✓	No
			HINGE REAR BOOTLID LH	1	120.00	10.00	108.00	Replace	Replace ✓	No
			HINGE REAR BOOTLID RH	1	120.00	10.00	108.00	Replace	Replace X <i>repair</i>	No
			DAMPER REAR BOOTLID LH	1	152.40	10.00	137.16	Replace	Replace X	No
			DAMPER REAR BOOTLID RH	1	152.40	10.00	137.16	Replace	Replace X	No
	REAR		LOCK ASSY RR LID	1	450.00	10.00	405.00	Replace	Replace ✓	No
	REAR		EMBLEM - "300C"	1	150.00	10.00	135.00	Replace	Replace ✓	No
	REAR		EMBLEM - "CHRYSLER"	1	180.00	10.00	162.00	Replace	Replace ✓	No
	REAR		EMBLEM - "CRD"	1	120.00	10.00	108.00	Replace	Replace ✓	No
	REAR		EMBLEM - SYMBOL MARK	1	60.00	10.00	54.00	Replace	Replace ✓	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓	No
	COMMON		STICKER PRESTIGE	1	60.00	0.00	60.00	Replace	Replace ✓	No
	COMMON		REAR WINDSCREEN MOULDING	1	150.00	10.00	135.00	Replace	Replace ✓	No
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace ✓	No
	REAR		REAR PANEL	1	1,080.00	10.00	972.00	Replace	Replace ✓	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
			GARNISH REAR END PANEL	1	390.00	10.00	351.00	Replace	Replace ✓	No
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ✓	No
	REAR		SPARE TYRE PANEL	1	5,333.33	10.00	4,800.00	Replace	Replace ✓	No
	COMMON		TYRE	1	395.00	10.00	355.50	Replace	Replace X	No
	REAR		REAR MAIN CHASSIS LH ASSY	1	7,500.00	10.00	6,750.00	Replace	Replace X repair	No
	COMMON		REAR MAIN CHASSIS RH ASSY	1	7,500.00	10.00	6,750.00	Replace	Replace X	No
			TRIM LH REAR FENDER	1	227.50	10.00	204.75	Replace	Replace ✓	No
			TRIM RH REAR FENDER	1	227.50	10.00	204.75	Replace	Replace X	No
	COMMON		COVER SPARE TYRE	1	250.00	10.00	225.00	Replace	Replace ✓	No
			FUSE BOX ASSY - REAR	1	3,500.00	0.00	3,500.00	Replace	Replace X	No check
			BATTERY	1	150.00	10.00	135.00	Replace	Replace X	No check
			BATTERY TRAY - REAR	1	580.00	0.00	580.00	Replace	Replace X	No check
	COMMON		BREAKDOWN SIGN	1	35.00	0.00	35.00	Replace	Replace X	No check
04806372 AB	REAR		TAILLAMP ASSY - REAR RH	1	680.00	10.00	612.00	Replace	Replace X	No check
05135906 AI	COMMON		FENDER ASSY - REAR RH	1	3,440.00	10.00	3,096.00	Replace	Replace X	No X
			LINER RH REAR FENDER	1	227.50	10.00	204.75	Replace	Replace X	No
04806373 AB	REAR		TAILLAMP ASSY - REAR LH	1	680.00	10.00	612.00	Replace	Replace ✓	No
			TAIL LAMP PANEL LH	1	334.75	10.00	301.27	Replace	Replace ✓	No
05135907 AL	LEFT		FENDER ASSY - REAR LH	1	3,440.00	10.00	3,096.00	Replace	Replace ✓	No
			LINER LH REAR FENDER	1	227.50	10.00	204.75	Replace	Replace ✓	No
			FUEL TANK NECK	1	460.00	10.00	414.00	Replace	Replace X	No check
05134177 AN	LEFT		DOOR ASSY - REAR LH	1	3,800.00	10.00	3,420.00	Replace	Replace X	No repair
04575893 AA	LEFT		LOCK ASSY - REAR DOOR LH	1	315.00	10.00	283.50	Replace	Replace X	No
05166093 AA	LEFT		HINGE - REAR DOOR LOWER LH	1	115.00	10.00	103.50	Replace	Replace X	No
04575751 AC	LEFT		HINGE - REAR DOOR UPPER LH	1	265.00	10.00	238.50	Replace	Replace X	No
04780259 AD	LEFT		STRIKER ASSY - REAR DOOR LH	1	40.00	10.00	36.00	Replace	Replace X	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓	No
	COMMON		STICKER PRESTIGE	1	60.00	0.00	60.00	Replace	Replace ✓	No
TOTAL MATERIALS							56,242.69	56,242.69		
TOTAL MATERIALS(Discounted)							44,994.15	44,994.15		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
-------------	---------	-----------	-----	-----------------	--------------	------------------	-----------	----------------	----------

Kalvin 10/14
H 19/7/16