

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHB 7512M -

ROEL

Not Notified
11/10/16 @ 2900h

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHB7512M - ROEL
 KL1LA69RJBB065097
 CHEVROLET
 EPICA 2.0
 01.07.16
 EQ

PART

LIST

1	1	Front Bumper	\$	<i>RM</i> 1,202.00 ✓
2	1	Front Bumper Reinforcement	\$	<i>R</i> 295.25 X
3	1	Front Bumper Lower Absorber	\$	<i>Sm</i> 180.00 X
4	1	Front Bumper Lower Grille	\$	<i>Sm</i> 78.00 X
5	1	Front Bumper Retainer RH	\$	<i>Sm</i> 102.00 X
6	1	Front Bumper Retainer LH	\$	<i>Sm</i> 102.00 X
7	1	Front Bumper Lower Stiffener	\$	<i>R</i> 134.37 X
8	1	Front Headlamp RH	\$	<i>R</i> 816.00 X
9	1	Front Headlamp LH	\$	<i>R</i> 816.00 X
10	1	Front Support Panel Assy (Panel A-Frt)	\$	<i>R</i> 1,222.32 X
11	1	Bonnet (Panel A-Hood)	\$	<i>R</i> 1,250.00 X
12	1	Centre 'CHEVROLET' Logo Badge	\$	<i>Sm</i> 144.30 X
13	1	Bonnet Moulding	\$	<i>Sm</i> 257.00 X
14	1	Radiator Grille (Grille A-Rad)	\$	<i>CM</i> 367.00 ✓
15	1	Radiator Assembly (Radiator A)	\$	<i>Sm</i> 618.00 X
16	1	Aircon Condenser (Condenser A)	\$	<i>Sm</i> 600.00 X
17	1	Air Intercooler	\$	<i>Sm</i> 652.00 X
18	1	Fan Blade (Small)	\$	<i>Sm</i> 536.00 X
19	1	Fan Blade (Big)	\$	<i>Sm</i> 634.00 X
20	1	Front Fender LH	\$	<i>R</i> 837.60 X
21	1	Front Fender RH	\$	<i>R</i> 837.60 X
22	1	Rear Bumper	\$	<i>Sm</i> 1,202.00 ✓
23	1	Rear Bumper Beam	\$	<i>R</i> 239.94 X
24	1	Rear Bumper Centre Absorber	\$	<i>Sm</i> 260.00 X
25	1	Rear Bumper Side Retainer RH	\$	<i>CM</i> 68.76 ✓
26	1	Rear Bumper Side Retainer LH	\$	<i>Sm</i> 68.76 X
27	1	Rear Bumper side support RH	\$	<i>Sm</i> 25.00 X
28	1	Rear Bumper side support LH	\$	<i>Sm</i> 25.00 X
29	1	Rear Bumper Reflectors RH	\$	<i>CM</i> 119.74 ✓
30	1	Rear Bumper Reflectors LH	\$	<i>Sm</i> 119.74 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 7512M -

31	1	Rear Bumper Tow Hook Cover	\$	Sh 93.00 X
32	1	Rear Luggage Floor Panel	\$	R 973.00 X
33	1	Rear Luggage Floor Panel Insulator	\$	Sh 63.50 X
34	1	Rear Luggage Floor Panel Trim Board	\$	Sh 378.00 X
35	1	Rear End Panel Inner	\$	R 336.84 X
36	1	Rear End Panel Outer	\$	R 623.76 X
37	1	Rear End Panel Inner Trim	\$	Sh 263.84 X
38	1	Bootlid	\$	R 973.00 X
39	1	Bootlid inner trim board	\$	Sh 400.00 X
40	1	Bootlid Weatherstrip	\$	Sh 344.28 X
41	1	Bootlid Lock - Top	\$	R 466.56 X
42	1	Bootlid lock - bottom	\$	R 39.40 X
43	1	Bootlid 'CHEVROLET' Badge	\$	un 120.62 X
44	1	Bootlid Logo	\$	un 138.84 X
45	1	Bootlid 'EPICA LT' Badge	\$	un 119.84 X
46	1	Bootlid inner handle	\$	Sh 45.55 X
47	1	Bootlid Reflector Centre	\$	Sh 217.97 X
48	1	Bootlid Reflector RH	\$	Sh 128.40 X
49	1	Bootlid Reflector LH	\$	Sh 128.40 X
50	1	Bootlid Hinge RH	\$	R 120.00 X
51	1	Bootlid Hinge LH	\$	R 120.00 X
52	1	Rear Tail Lamp RH	\$	Sh 479.30 X
53	1	Rear Tail Lamp Panel RH	\$	R Sh 359.00 X
54	1	Rear Tail Lamp LH	\$	Sh 479.30 X
55	1	Rear Tail Lamp Panel LH	\$	R 359.00 X
56	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	R 1,110.00 X
57	1	Rear Fender RH	\$	R 1,145.00 X
58	1	Rear Fender Inner Cowling RH	\$	Sh 298.00 X
59	1	Rear Fender Inner Trim RH	\$	Sh 418.44 X
60	1	Rear Fender LH	\$	R 1,145.00 X
61	1	Rear Fender Inner Cowling LH	\$	Sh 298.00 X
62	1	Rear Fender Inner Trim LH	\$	Sh 418.44 X

TOTAL	\$	26,414.66
10%	\$	2,641.47
	\$	23,773.19

Specical Nett

1 1Set Front Bumper Fastener Clip

\$

un 24.00 ✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 7512M -**ROEL**

2	1Set	Front Licence Plate With Holder	\$	<i>Per</i> 192.00 ²⁵ⁱⁿ
3	1Set	Bonnet Insulator Clip	\$	<i>nn</i> 40.00 X
4	1Set	Radiator Grille Clip	\$	<i>nn</i> 18.00 ✓
5	1Set	Bootlid inner trim board Clip	\$	<i>nn</i> 40.00 X
6	1Set	Radiator Grille Top Cover Clip	\$	<i>nn</i> 10.00 X
7	1Set	Front Fender Liner Clip	\$	<i>nn</i> 40.00 X
8	1Set	Rear Bumper Parking Sensor	\$	<i>nn</i> 300.00 X
9	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i> 30.00 ✓
10	2Set	Rear Fender inner cowl clip	\$	<i>nn</i> 30.00 X
11	1Set	Rear Fender Inner Trim Clip RH	\$	<i>nn</i> 30.00 X
12	1Set	Rear Fender Inner Trim Clip LH	\$	<i>nn</i> 30.00 X
13	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i> 30.00 X
14	1	Rear Boot Sticker 'Trans-cab'	\$	<i>nn</i> 30.00 X
15	1	Rear Boot Sticker '6555-3333'	\$	<i>nn</i> 10.00 X
16	1	Rear Exhaust Mounting	\$	<i>nn</i> 80.00 X
17	1	Rear Bumper End Sealant	\$	<i>nn</i> 80.00 X
18	2	Rear Windscreen Sealant	\$	<i>nn</i> 100.00 X
19	1	Rear Windscreen Inner Sponge Seal	\$	

TOTAL	\$	1,144.00
TOTAL PARTS	\$	24,917.19

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 5,400.00 *4000*

To Check Electrical Lighting Concerned.

\$ 170.00 *300*

To Rust-Proofing Of The Affected Areas.

\$ *nn* 170.00 X

Putty And Spray Painting Of The Affected
Portion.

\$ 5,350.00 *4000*

To drop rear exhaust box, renew the same, to
repair and realign centre exhaust pipe.

\$ *nn* 170.00 X

To reinstall rear bumper parking sensor.

\$ 170.00 *600*

To transfer of end panel fittings and conduct
water seepage test.

\$ *nn* 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHB 7512M -

ROEL

Towing fees	\$	<i>nn</i> 120.00 X
To transfer of boot fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00 X
To check ABS brake efficiency, final checking and testing.	\$	<i>nn</i> 380.00 X
	\$	13,000.00
TOTAL	\$	37,917.19

Repair Days

~~20 Days~~

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: