

INS. CASE OWNER:

CC 4/AXA1601

LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A:

Nature of Accident:

Driver Name / Age:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	STAGE	DATE / PIC
7/10/16	Non-Reporting ltr (1st):	
7/10/16	Non-Reporting ltr (2nd):	
7/10/16	Non-Reporting ltr (Final):	
7/10/16	Notification ltr (if non-pickup):	
7/10/16	Call OI:	
7/10/16	After call ltr to OI:	
7/10/16	Documentation Check List:	
7/10/16	Notification ltr (if non-pickup):	
7/10/16	After call ltr to OI:	
7/10/16	Authorisation To Act:	
7/10/16	Release Voucher:	
7/10/16	Final Repair Bill:	
7/10/16	Car Rental Invoice:	
7/10/16	Towing Invoice:	
7/10/16	LTA / GIA:	
7/10/16	Medical Bill:	
7/10/16	PIR:	
7/10/16	Mandate/Reject Instruction:	
7/10/16	LOD:	
7/10/16	Payment Breakdown Form:	
7/10/16	Post-Repair Photos:	
7/10/16	Others:	
7/10/16	Confirm with:	
7/10/16	Confirm by:	
7/10/16	Repair Cost:	
7/10/16	Final Liability:	
7/10/16	Repair Cost:	
7/10/16	Loss of Rental (LOR):	
7/10/16	Loss of Use (LOU):	
7/10/16	Loss of Income (LOI):	
7/10/16	LOR only	
7/10/16	LOU only	
7/10/16	GIA/LTA Search	
7/10/16	Medical:	
7/10/16	Disbursement:	
7/10/16	Legal Cost	
7/10/16	Total:	
7/10/16	Global Sum SS:	
7/10/16	FINAL PAYMENT	
7/10/16	Payee 1:	
7/10/16	Payee 2: (Strike if N.A.)	
7/10/16	Payee 3: (Strike if N.A.)	

REF:

ASS. REC. BY: Adrian Ling**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 16 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLC2858X Yr Regn: 2008 / MayType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Odyssey cc 2354Colour: Black A/C: _____ Insured / Std / NI / NASp. Reading: 164/10 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMIRB/8508C204116Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/55R17R: 215/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 17/08/06Survey held at NSIDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPAXAUS\$14000 cred # 18362-94 559

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE SINGAPORE PTE LTD		Ref : CC4/AXA16015334/Ayb3		
8 SHENTON WAY #27-01 SINGAPORE 068811		Date : 17-08-2016		
		Code : AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 7227L	Veh. Inspected	SLC 2858X	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	17/08/2016	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/08/2016	Inspection Date		
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

15334 / Ag 13

2008 May

SHAJAHAN S/O PEER MOHD
7 DAIRY FARM HEIGHT #10-13
SINGAPORE 677669

TPA XA
Joe.

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

Contact : 98579363, 93212348

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
PETROL TANK	1	680.00	680.00 ✓
PETROL TANK BRACKET	2	45.00	90.00 ✓
PETROL TANK FLOAT	1	143.70	143.70 ✓
PETROL TANK NECK	1	110.00	110.00 ✓
PETROL TANK NECK HOSE	1	50.00	50.00 ✓
PETROL TANK PUMP	1	535.00	535.00 ✓
REAR 3RD ROLL AUTO FOLDING SEAT ASSY	1	1850.00	1850.00 ✓
REAR 3RD ROLL RH PASSENGER SAFETY BELT	1	300.00	300.00 ✓
REAR BUMPER	1	705.80	705.80 ✓
REAR BUMPER REFLECTOR L/R	2	42.10	84.20 ✓
REAR BUMPER REINFORCEMENT	1	89.70	89.70 ✓
REAR BUMPER REINFORCEMENT BRACKET L/R	2	58.40	116.80 ✓
REAR BUMPER SCREW COVER L/R	4	9.50	38.00 ✓
REAR BUMPER SIDE RETAINER L/R	2	18.30	36.60 ✓
REAR BUMPER SIDE SUPPORT L/R	2	60.80	121.60 ✓
REAR BUMPER TOW HOOK COVER	1	18.00	18.00 ✓
REAR END PANEL	1	427.30	427.30 ✓
REAR END PANEL INNER TOP GARNISH	1	172.70	172.70 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
 7 DAIRY FARM HEIGHT #10-13
 SINGAPORE 677669

Contact : 98579363, 93212348

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

REAR END PANEL INNER TOP GARNISH CLIPS <i>new</i>	6	6.50	39.00 15
REAR END PANEL LOCK STRIKER <i>new</i>	1	24.70	24.70 +
REAR END PANEL LOCK STRIKER COVER <i>new</i>	1	8.60	8.60 -
REAR LH EXHAUST ALUMINIUM HEAT SHIELD <i>new</i>	1	31.50	31.50 +
REAR LH EXHAUST END CHROME PIPE <i>new</i>	1	89.70	89.70 +
REAR LH EXHAUST GASKET <i>new</i>	1	13.60	13.60 +
REAR LH EXHAUST RUBBER MOUNTING <i>new</i>	2	10.80	21.60 +
REAR LH EXHAUST SILENCER BOX <i>new</i>	1	474.80	474.80 +
REAR LH FENDER <i>new</i>	1	901.50	901.50 +
REAR LH FENDER GLASS INNER GARNISH	1	105.00	105.00 +
REAR LH FENDER GLASS INNER GARNISH CLIPS	6	6.50	39.00 +
REAR LH FENDER GLASS WITH MOULDING ASSY <i>new</i>	1	534.60	534.60 -
REAR LH FENDER INNER AIR VENT	1	29.10	29.10 +
REAR LH FENDER INNER SHIELD	1	97.10	97.10 +
REAR LH FENDER INNER TRIM BOARD <i>new</i>	1	489.90	489.90 -
REAR LH FENDER INNER TRIM BOARD COVER <i>new</i>	1	642.70	642.70 215
REAR LH FENDER PROTECTOR <i>new</i>	1	19.00	19.00 +
REAR RH DOOR <i>Buckled</i>	1	943.80	943.80 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
7 DAIRY FARM HEIGHT #10-13
SINGAPORE 677669

Contact : 98579363, 93212348

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

REAR RH DOOR BLACK FRAME STICKER 'HORIZONTAL'	1	52.80	52.80 ✓
REAR RH DOOR BLACK FRAME STICKER 'VERTICAL'	1	45.40	45.40 ✓
REAR RH DOOR CHECKER	1	40.00	40.00 ✗
REAR RH DOOR HINGES (TOP & LOWER)	2	39.50	79.00 ✗
REAR RH DOOR INNER LOCK HANDLE	1	50.60	50.60 ✗
REAR RH DOOR INNER TRIM BOARD	1	621.50	621.50 ✗
REAR RH DOOR LOCK STRIKER	1	20.00	20.00 ✗
REAR RH DOOR MECHANISM LOCK	1	290.00	290.00 ✓
REAR RH DOOR OUTER CHROME LOCK HANDLE	1	121.50	121.50 ✗
REAR RH DOOR OUTER CHROME LOCK HANDLE COVER	1	12.00	12.00 ✗
REAR RH DOOR PILLAR WEATHER STRIP	1	92.50	92.50 ✗
REAR RH DOOR PROTECTOR	1	88.00	88.00 ✗
REAR RH DOOR QUATER GARNISH 'INNER'	1	65.00	65.00 ✗
REAR RH DOOR QUATER GARNISH 'OUTER'	1	55.00	55.00 ✗
REAR RH DOOR QUATER GARNISH CLIPS	2	6.50	13.00 ✗
REAR RH DOOR RUBBER GUIDE STOPPER	2	6.00	12.00 ✗
REAR RH DOOR STEP GARNISH	1	35.00	35.00 ✗
REAR RH DOOR STEP GARNISH CLIPS	3	6.50	19.50 ✗

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
 7 DAIRY FARM HEIGHT #10-13
 SINGAPORE 677669

Contact : 98579363, 93212348

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

REAR RH DOOR SWITCH	1	18.00	18.00 +
REAR RH DOOR WEATHER STRIP	1	109.40	109.40 +
REAR RH DOOR WIRE HARNESS - SET	1	110.00	110.00 +
REAR RH EXHAUST ALUMINIUM HEAT SHIELD	1	31.50	31.50 ✓
REAR RH EXHAUST END CHROME PIPE	1	89.70	89.70 ✓
REAR RH EXHAUST GASKET	1	13.60	13.60 ✓
REAR RH EXHAUST RUBBER MOUNTING	3	10.80	32.40 +
REAR RH EXHAUST SILENCER BOX	1	906.40	906.40 ✓
REAR RH FENDER	1	841.30	841.30 ✓
REAR RH FENDER AIRCON AIR DUCT	1	65.00	65.00 ✓
REAR RH FENDER AIRCON COOLING PIPE	1	220.10	220.10 ✓
REAR RH FENDER AIRCON DISCHARGE PIPE	1	248.10	248.10 ✓
REAR RH FENDER AIRCON EVAPORATOR UNIT	1	794.50	794.50 ✓
REAR RH FENDER GLASS INNER GARNISH	1	105.00	105.00 ✓
REAR RH FENDER GLASS INNER GARNISH CLIPS	6	6.50	39.00 ✓
REAR RH FENDER GLASS WITH MOULDING ASSY	1	534.60	534.60 ✓
REAR RH FENDER INNER PANEL	1	558.00	558.00 ✓
REAR RH FENDER INNER SHIELD	1	105.10	105.10 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
7 DAIRY FARM HEIGHT #10-13
SINGAPORE 677669

Contact : 98579363, 93212348

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

REAR RH FENDER INNER TRIM BOARD <i>ok</i>	1	455.70	455.70 ✓
REAR RH FENDER PROTECTOR <i>new</i>	1	19.00	19.00 ✓
REAR RH SUB CHASSIS FRAME <i>new</i>	1	1150.00	1,150.00 ✓
REAR RH WHEEL HOUSE PANEL ASSY <i>new</i>	1	690.00	690.00 ✓
REAR TAILGATE <i>Distorted</i>	1	1072.50	1,072.50 ✓
REAR TAILGATE 3RD BRAKE LAMP <i>ok</i>	1	340.40	340.40 ✓
REAR TAILGATE DAMPER L/R <i>new</i>	2	107.90	215.80 ✓
REAR TAILGATE HINGES L/R <i>new</i>	2	34.60	69.20 ✓
REAR TAILGATE INNER HANDLE <i>new</i>	1	93.90	93.90 ✓
REAR TAILGATE INNER TRIM BOARD <i>ok</i>	1	198.80	198.80 ✓
REAR TAILGATE MECHANISM LOCK <i>ok</i>	1	165.60	165.60 ✓
REAR TAILGATE NUMBER PLATE LAMP COVER L/R <i>ok</i>	2	12.00	24.00 ✓
REAR TAILGATE NUMBER PLATE LAMP L/R <i>ok</i>	2	50.70	101.40 ✓
REAR TAILGATE OUTER CHROME GARNISH <i>ok</i>	1	756.80	756.80 ✓
REAR TAILGATE OUTER CHROME GARNISH CLIPS <i>new</i>	6	6.50	39.00 ✓
REAR TAILGATE OUTER GARNISH <i>ok</i>	1	425.30	425.30 ✓
REAR TAILGATE OUTER LOCK HANDLE <i>new</i>	1	53.40	53.40 ✓
REAR TAILGATE REFLECTOR LAMP CLIPS L/R <i>new</i>	2	6.50	13.00 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
 7 DAIRY FARM HEIGHT #10-13
 SINGAPORE 677669

Contact : 98579363, 93212348

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

REAR TAILGATE REFLECTOR LAMP L/R <i>ambd.</i>	2	328.10	656.20 ✓
REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>per</i>	2	7.80	15.60 ✓
REAR TAILGATE SPOILER <i>ambd.</i>	1	523.90	523.90 ✓
REAR TAILGATE WEATHER STRIP <i>lt</i>	1	125.60	125.60 ✓
REAR TAILGATE WINDSCREEN <i>shattered.</i>	1	1103.50	1103.50 ✓
REAR TAILGATE WINDSCREEN INNER GARNISH 'TOP' <i>per on</i>	1	33.80	33.80 ✓
REAR TAILGATE WINDSCREEN INNER GARNISH L/R <i>RH cut</i>	2	30.30	60.60 30.3 ✓
REAR TAILGATE WIPER ARM <i>lt</i>	1	158.30	158.30 ✓
REAR TAILGATE WIPER ARM COVER <i>lt</i>	1	49.50	49.50 ✓
REAR TAILGATE WIPER ARM RUBBER SEAL <i>per</i>	1	46.20	46.20 ✓
REAR TAILGATE WIPER BLADE <i>lt</i>	1	41.30	41.30 ✓
REAR TAILGATE WIPER MOTOR <i>2yd.</i>	1	226.60	226.60 ✓
REAR TAILGATE WIPER NOZZLE <i>2yd</i>	1	18.70	18.70 ✓
REAR TAILGATE WIPER NOZZLE HOSE <i>per on</i>	1	10.00	10.00 ✓
REAR TAILGATE WIRE HARNESS - SET <i>per on</i>	1	115.00	115.00 ✓
REAR TAILLAMP CLIPS L/R <i>per</i>	4	6.50	26.00 ✓
REAR TAILLAMP INNER PANEL L/R <i>RH Sented</i>	2	151.10	302.20 151.1 ✓
REAR TAILLAMP L/R <i>ambd.</i>	2	376.60	753.20 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
7 DAIRY FARM HEIGHT #10-13
SINGAPORE 677669

Contact : 98579363, 93212348

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

REAR TAILLAMP LOWER BRACKET L/R <i>RH Set</i>	2	15.00	30.00 15
REAR TAILLAMP WIRE HARNESS L/R - SET <i>new</i>	2	335.50	671.00 x
SPARE TYRE PANEL <i>Deleted</i>	1	1118.50	1,118.50 ✓
SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD <i>deleted</i>	1	303.80	303.80 ✓
SPARE TYRE RETAINER LOCK <i>Byrd</i> <i>15601-40 SN-800</i>	1	25.00	25.00 ✓
SPARE TYRE SIDE PANEL L/R <i>Byrd</i> <i>12481-12</i>	2	80.00	160.00 x
Subtotal before discount			29,067.40
Percentage discount 20%			5,813.48
Sub-total 1			23,253.92
REAR BUMPER CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR BUMPER REVERSE SENSOR - SET <i>changed</i>	1	350.00	350.00 250
REAR LH FENDER GLASS SEALANT <i>new</i>	1	60.00	60.00 ✓
REAR LH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR LH FENDER INNER TRIM BOARD CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR RH DOOR INNER L.E.D BULB <i>new</i>	1	90.00	90.00 ✓
REAR RH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR RH DOOR L.E.D LAMP <i>new</i>	1	190.00	190.00 ✓
REAR RH DOOR SPEAKER <i>new</i>	1	180.00	180.00 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
 7 DAIRY FARM HEIGHT #10-13
 SINGAPORE 677669

Contact : 98579363, 93212348

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

REAR RH FENDER GLASS SEALANT <i>new</i>	1	60.00	60.00 0
REAR RH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR RH FENDER INNER TRIM BOARD CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR TAILGATE 'LOGO' EMBLEM (RED COLOR) <i>new</i>	1	180.00	180.00 50
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR TAILGATE NUMBER PLATE <i>2 new</i>	1	25.00	25.00 ✓
REAR TAILGATE NUMBER PLATE HOLDER	1	50.00	50.00 ✓
REAR TAILGATE NUMBER PLATE LAMP BULB L/R <i>new</i>	2	10.00	20.00 ✓
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR TAILGATE SPOILER CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR TAILGATE WINDSCREEN 3M SOLAR FILM <i>new</i>	1	380.00	380.00 180
REAR TAILGATE WINDSCREEN INNER GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00 10
REAR TAILLAMP 'BRAKE' BULB L/R	2	12.00	24.00 ✓
REAR TAILLAMP 'REVERSE' LED BULB L/R - SET	1	250.00	250.00 ✓
REAR TAILLAMP 'SIGNAL' BULB L/R <i>new</i>	2	15.00	30.00 ✓
SPARE TYRE <i>new</i>	1	280.00	280.00 ✓
SPARE TYRE PANEL INNER BREAK DOWN SIGN	1	150.00	150.00 ✓
SPARE TYRE PANEL INNER JACKING TOOL	1	180.00	180.00 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
 7 DAIRY FARM HEIGHT #10-13
 SINGAPORE 677669

Contact : 98579363, 93212348

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

SPARE TYRE PANEL INSULATOR MAT	1	350.00	350.00 200
	Subtotal before discount		3,149.00
Percentage discount 0%			0.00
	Sub-total 2		3,149.00
	Parts-total		26,402.92

LABOUR

To remove, replaced aircon evaporator unit, aircon blower motor and etc to vacuum system and top up gas.	280.00 180
To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	150.00 80
To remove, reinstall window glass. (to FR)	120.00 40
To remove, reinstall tailgate windscreen	150.00 120
To remove, reinstall fender glass	120.00 60
To remove, reinstall rear suspension and undercarriage part. (to FR)	280.00 20
To road test driving, check and resetting wheel alignments system.	180.00 20
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00 100
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	160.00 80
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel, rear bumper, rear doors (L/R), and roof top panel.	2,000.00 140
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	160.00 100
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2,500.00 1800
To mount vehicle on to Car 'O' Liner.	400.00 300

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
7 DAIRY FARM HEIGHT #10-13
SINGAPORE 677669

Contact : 98579363, 93212348

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

To apply anti-rust chemical on repaired and replaced panel.

4300

120.0080

Labour Total**6,760.00****Parts & Labour Total****33,162.92**

*** This is a computer-generated document which requires no signature.***

page 10

total 18501.12

1/5 14.8K

16 Apr

14.8K

16 Apr

Olivia Lau (LKKAUTO)

To: Sabrina (N-51)
Cc: Hsiao Tong (LKKAUTO); Mei Kwan (LKKAUTO)
Subject: [AXA]: SLC 2858X (TP) / PC 7227L (AXA) / DOA 14.08.2016

LKK Ref: CC4/AXA16015334/Amb3

Without Prejudice

SAVE AS TO COSTS

Hi Sabrina,

Apologies for the delay in our reply.

On SLC 2858X below, our Principal AXA is prepared to make a global sum offer of **\$18,000.00 (all-in) (incl. GST)**.

For your kind acceptance please.

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: olivialau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

*Make
good
use of
Today*

From: Mei Kwan (LKKAUTO)

Sent: Monday, 9 July, 2018 5:29 PM

To: Sabrina (N-51) <sabrina@n51.com.sg>

Cc: Vic (LKKAUTO) <vicalpeh@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Pending offer/update from 3rd party.

Dear Sabrina,

We refer to the below email and the contents were duly noted.

Our respective case handler will look into the matter and revert to you in due course.

1) SJG 1451 U - LOD email on 22/06/2017 *** LKK REF: CC4/AXA16017537/Ahb3 // **PIC - VIC**

2) SJK1702A - LOD email on 13/03/2017 and re-send on 01/08/2017 *** LKK REF: CC4/AXA16017241/Aha3 // **PIC - VIC**

3) SLC 2858 X - LOD email on 22/06/2017 *** LKK REF: CC4/AXA16015334/Amb3 // **PIC - TBA**

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	16 Aug 2016 11:40	Cim Veh Model Changed	(202355) HONDA ODYSSEY 2.4 (A).	[I] Paras Gaikwad
2	16 Aug 2016 11:40	Cim Created	Reg No: SLC2858X, Policy No: P1743728, Acct Date: 2016/08/14, Claim Type: TP, Insurer: AXA Insurance Singapore Pte Ltd (HQ), Workshop: N-51 Automotive Pte Ltd (HQ), Ins.Status => Incoming Claim	[I] Paras Gaikwad
3	16 Aug 2016 14:29	Adj Co Assigned	AJAX Inspection Services Pte Ltd (HQ):	[I] Ruth Chua
4	16 Aug 2016 14:29	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2016/08/25	[I] Ruth Chua
5	16 Aug 2016 14:29	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[I] Ruth Chua
6	16 Aug 2016 14:38	Adj Assignment Cancelled		[I] Ruth Chua
7	16 Aug 2016 14:38	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Ruth Chua
8	16 Aug 2016 15:37	Adj Co Assigned	AJAX Inspection Services Pte Ltd (HQ):Adrian Ling (LKK) appointed as SJE. Pls conduct PRS.	[I] Ruth Chua
9	16 Aug 2016 15:37	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2016/08/25	[I] Ruth Chua
10	16 Aug 2016 15:37	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[I] Ruth Chua
11	16 Aug 2016 17:47	Assignment 1st Accessed		[A] Joey Ng
12	17 Aug 2016 10:28	Adj Assignment Cancelled		[I] Ruth Chua
13	17 Aug 2016 10:28	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Ruth Chua
14	17 Aug 2016 10:28	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Adrian Ling (LKK) appointed as SJE. Pls conduct PRS.	[I] Ruth Chua
15	17 Aug 2016 10:28	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2016/08/26	[I] Ruth Chua
16	17 Aug 2016 10:28	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[I] Ruth Chua
17	17 Aug 2016 10:37	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
18	17 Aug 2016 10:40	Label Removed	(62):PRI.	[A] CATHERINE CHONG KAI LING
19	17 Aug 2016 14:41	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Lau Shu Pei
20	18 May 2017 12:06	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2016/08/26	[A] HOW MEI KWAN
21	21 Jul 2017 15:00	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
22	21 Jul 2017 15:00	Cim Details Notified		[A] JOANNE LEE KHANG MIN
23	21 Jul 2017 18:37	Adj Mandate Request	Cur.Req:19361.35:(a) Liability : 100% OI rear ended TP vehilce (BOLA 27 applies) (b) Quantum COR W/GST : \$15,836.00 Loss of Rental : \$ 80.00.00 (\$180 x 19 days) LTA Search : \$ 5.35 Towing Fee	[A] Jasmine Khine Phoo Wal
24	07 Oct 2018 17:07	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2016/08/26	[I] Richard Ang
25	07 Oct 2018 17:07	Adj Mandate Set	Approved:18000.00.	[I] Richard Ang

Date From Date To Audit Type

ACTIVITY

[10/10/2016 11:33] Vasanthi D/O Rengliyan:
11/10/2016 @ 1026AM - CONTACTED OI/OID , MR NASAR. CONFIRMED ACCIDENT DETAILS , OID REAR ENDED TP , INFORMED TP CLAIM - AGREED TO SETTLE , INFORMED NCD ISSUES - AWARE, INFORMED EXCESS AMT TO BE PAID TO AXA - INFORMED OID TO CALL ABT PAYMENT MODE, TO CALL OI ABT CLAIM AMT - LETTER SENT TO OI
[10/10/2016 11:33] Vasanthi D/O Rengliyan:
7/10/16@ 2.32PM - CONTACTED OI /OID MR NASAR BIN ALI @ 81866911 - NO RESPONSE
[16/08/2016 17:57] Joey Huang:
Workshop has selected LKK.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
-------------	-----------	----------	----------	------------------	-------	-------	--------

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 4 May 2019 9:13 AM
To: Sabrina (N-51)
Cc: Admin A
Subject: Your Ref: CLM13658/ Aug34 (2016) – SLC2858X *Our Ref: CC4/AXA16015334/Amb3
[ACCIDENT INVOLVING PC 7227L(AXA) & SLC 2858X ON 14/08/2016]

Your Ref: **CLM13658/ Aug34 (2016) – SLC2858X**
Our Ref: CC4/AXA16015334/Amb3

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING PC 7227L(AXA) & SLC 2858X ON 14/08/2016

We refer to the above matter.

We have our principal instruction to offer at a global sum of **\$18,000.00(all-in)**.

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Sabrina (N-51) <sabrina@n51.com.sg>
Sent: Thursday, 9 May 2019 4:44 PM
To: Hsiao Tong (LKKAUTO)
Cc: Admin A
Subject: Re: Your Ref: CLM13658/ Aug34 (2016) – SLC2858X *Our Ref: CC4/AXA16015334/Amb3 [ACCIDENT INVOLVING PC 7227L(AXA) & SLC 2858X ON 14/08/2016]

Dear Hsiao Tong,

We refer to the above matter.
We unable to accept the offer.
We proposed \$19,000.00 (all in).
Kindly re-consider our proposal and re-offer us again.

Regards,

Sabrina
N-51 Automotive Pte Ltd
Office : 6842 0051 Fax : 6744 0510
www.n51.com.sg



On Sat, May 4, 2019 at 9:13 AM Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:
Your Ref: **CLM13658/ Aug34 (2016) – SLC2858X** Without Prejudice
Our Ref: CC4/AXA16015334/Amb3

Dear Sirs/Madam,

ACCIDENT INVOLVING PC 7227L(AXA) & SLC 2858X ON 14/08/2016

We refer to the above matter.

We have our principal instruction to offer at a global sum of **\$18,000.00(all-in)**.

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Print Sent Message

This mail is associated with :

***SLC2858X (C0396138)
[PC7227L]**

TP
SHAJAHAN S/O PEER MOHD
Aug 14 2016 5:00AM
[N & K TRANSPORT SERVICES]
N-51 Automotive Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 11/05/2019 10:35 AM.
To richard.angbs@axa.com.sg
CC AXA_SG; chewht@lkkauto.com; admin-a@lkkauto.com
Subject <SEEK MANDATE>C0396138

Hi Richard,

We refer to the above matter.

Third party rejected our offer at \$18K(all-in) and proposed \$19K(all-in).

Kindly let us have your further mandate/ instruction.

Thank you.

Hsiao Tong

<-- Original Message -->

From: AXA_SG
To: LKK_HQ; sur@lkkauto.com; assignments@lkkauto.com
CC: vicalpeh@lkkauto.com
Sent On: 16/02/2019 09:45 PM
Subject: REVIEW STATUS

Hi,

PLS UPDATE US THE STATUS OF THIS MATTER.



AXA INSURANCE PTE LTD
3 Maxwell Way, #04-01 AXA Tower
Singapore 068911
Incorporated in Singapore
Tel: (65) 6640 8800
Fax: (65) 6319 5127
www.axa.com.sg
GST Reg No.: U99063222M
In. Reg No.: U99063222M

<-- Original Message -->

From: LKK_HQ
To: AXA_SG; sawtheng.khor@axa.com.sg; ernest.tay@axa.com.sg; jas.tan@axa.com.sg; ruth.chua@axa.com.sg
CC: vicalpeh@lkkauto.com; bevanlim@lkkauto.com
Sent On: 23/05/2018 03:25 PM
Subject: MANDATE REQUEST

Dear Sir/Madam,

We refer the above subject.

Kindly let us have your mandate approval for our necessary action.

thank you.

BEVAN LIM
LKK AUTO CONSULTANTS PTE LTD

Print Received Message

This mail is associated with :

***SLC2858X (C0396138)**

[PC7227L]

TP

SHAJAHAN S/O PEER MOHD

Aug 14 2016 5:00AM

[N & K TRANSPORT SERVICES]

N-51 Automotive Pte Ltd

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 15/05/2019 09:34 AM.
To LKK_HQ
Subject Alert - Adj Mandate Maintained - SLC2858X - Claim Handler: Khor Saw Theng

Maintained: Please maintain offer at \$18k(all-in). Thank you.

Print Sent Message

This mail is associated with :

***SLC2858X (C0396138)**
[PC7227L]
TP
SHAJAHAN S/O PEER MOHD
Aug 14 2016 5:00AM
[N & K TRANSPORT SERVICES]
N-51 Automotive Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 01/06/2019 10:16 AM.
To sawtheng.khor@axa.com.sg; sashe.goms@axa.com.sg
CC AXA_SG; chewht@lkkauto.com; admin-a@lkkauto.com
Subject RE: <SEEK MANDATE>C0396138

Dear Sirs/Mdm,

We refer to the above matter.

We maintained our offer at \$18K(all-in). However third party insisted for \$19K(all-in).

Kindly let us have your further mandate/ instruction.

Thank you.

Hsiao Tong

<-- Original Message -->

From: LKK_HQ
To: richard.angbs@axa.com.sg
CC: AXA_SG; chewht@lkkauto.com; admin-a@lkkauto.com
Sent On: 11/05/2019 10:35 AM
Subject: C0396138

Hi Richard,

We refer to the above matter.

Third party rejected our offer at \$18K(all-in) and proposed \$19K(all-in).

Kindly let us have your further mandate/ instruction.

Thank you.

Hsiao Tong

<-- Original Message -->

From: AXA_SG
To: LKK_HQ; sur@lkkauto.com; assignments@lkkauto.com
CC: vicalpeh@lkkauto.com
Sent On: 16/02/2019 09:45 PM
Subject: REVIEW STATUS

Hi,

PLS UPDATE US THE STATUS OF THIS MATTER.



AXA INSURANCE PTE LTD
8 Shenton Way, #04-01 AXA Tower
Singapore 068811
Customer Service 400-000000
☎ (Toll Free) 4000 4000
✉ axa@axa.com.sg
187 Reg No.: 199601012M
In Reg No.: 199601012M

Print Received Message

This mail is associated with :

***SLC2858X (C0396138)**

[PC7227L]

TP

SHAJAHAN S/O PEER MOHD

Aug 14 2016 5:00AM

[N & K TRANSPORT SERVICES]

N-51 Automotive Pte Ltd

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 03/06/2019 09:55 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$18250.00) - SLC2858X - Claim Handler: Khor Saw Theng

Approved:18250.00:Please revise offer to \$18,250/- (all-in, max). Thank you.

Hsiao Tong (LKKAUTO)


From: Sabrina (N-51) <sabrina@n51.com.sg>
Sent: Tuesday, 11 June 2019 12:41 PM
To: Hsiao Tong (LKKAUTO)
Cc: Admin A
Subject: Re: Your Ref: CLM13658/ Aug34 (2016) – SLC2858X *Our Ref: CC4/AXA16015334/Amb3 [ACCIDENT INVOLVING PC 7227L(AXA) & SLC 2858X ON 14/08/2016]

Dear Hsiao Tong,

We refer to the above matter.
We agreed as per offer as per recommended \$18,250.00 (all in).
Do we need to sign any DV?

Regards,

Sabrina
N-51 Automotive Pte Ltd
Office : 6842 0051 Fax : 6744 0510
www.n51.com.sg



On Wed, Jun 5, 2019 at 9:35 AM Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Without Prejudice

(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to improve our offer at global sum of **\$18,250.00(all-in).**

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sabrina (N-51) <sabrina@n51.com.sg>

Sent: Friday, 31 May 2019 12:55 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Re: Your Ref: CLM13658/ Aug34 (2016) – SLC2858X *Our Ref: CC4/AXA16015334/Amb3 [ACCIDENT INVOLVING PC 7227L(AXA) & SLC 2858X ON 14/08/2016]

Dear Hsiao Tong,

Refer to the subject above.

Understand we maintain our offer of \$19,000.00 (all in).

Are we agreed in it?

Kindly advise me.

Regards,

Sabrina

N-51 Automotive Pte Ltd

Office : 6842 0051 Fax : 6744 0510

www.n51.com.sg



On Sat, May 18, 2019 at 10:27 AM Sabrina (N-51) <sabrina@n51.com.sg> wrote:

Dear Hsiao Tong,

We refer to your email.

We maintain our proposal as \$19,000.00 (all in).


Regards,

Sabrina

N-51 Automotive Pte Ltd

Office : 6842 0051 Fax : 6744 0510

www.n51.com.sg



On Sat, May 18, 2019 at 8:41 AM Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

Without Prejudice

(save as to costs)

Dear Sirs/Mdm,

We refer to your below email.

We have our principal instruction to maintain our offer at a global sum of \$18,000.00(all-in).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sabrina (N-51) <sabrina@n51.com.sg>

Sent: Thursday, 9 May 2019 4:44 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Re: Your Ref: CLM13658/ Aug34 (2016) – SLC2858X *Our Ref: CC4/AXA16015334/Amb3 [ACCIDENT INVOLVING PC 7227L(AXA) & SLC 2858X ON 14/08/2016]

Dear Hsiao Tong,

We refer to the above matter.

We unable to accept the offer.

We proposed \$19,000.00 (all in).

Kindly re-consider our proposal and re-offer us again.

Regards,

Sabrina

N-51 Automotive Pte Ltd

Office : 6842 0051 Fax : 6744 0510

www.n51.com.sg

Error! Filename not specified.Error! Filename not specified.Error! Filename not specified.

On Sat, May 4, 2019 at 9:13 AM Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Your Ref: CLM13658/ Aug34 (2016) – SLC2858X
Our Ref: CC4/AXA16015334/Amb3

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING PC 7227L(AXA) & SLC 2858X ON 14/08/2016

We refer to the above matter.

We have our principal instruction to offer at a global sum of **\$18,000.00(all-in).**

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921
Tel No.: +65 6744 0510 / 6842 0051 Fax No.: +65 6741 0510
Email: sales@n51.com.sg
Company Reg. No.: 200616038C
GST Registration No.: 200616038C

21 June 2017

Our Ref: CLM13658 / Aug-34 (2016)

AXA INSURANCE SINGAPORE PTE LTD ✓
8 SHENTON WAY
#27-01/02 AXA TOWER
SINGAPORE 068811

ATTN: MOTOR CLAIMS DEPARTMENT

Dear Sir @ Mdm,

Re: Accident involving SLC 2858 X & PC 7227 L on 14/08/2016
Along Infront of Blk 420 Clementi Ave 1 ✓

We refer to the above accident which was caused due to the negligence of your insured driver of vehicle No: PC 7227 L whose vehicle was insured with you at the material date of the accident.

We are proposing for a direct settlement on the claims as following exclude personal injury in respect of claim arising out of the abovementioned accident.

Cost of Repairs	\$ 15,838.00 (Include 7% GST)
Car Rental	\$ 3,420.00
Towing fee	\$ 100.00
LTA search fee	\$ 5.35
	<u>S \$ 19,361.35</u>

We enclosed herein the following documents for your necessary attention.

- 1) Our Final Repair Bill No: CLM13658
- 2) Win Win Car Rental - Invoice No.: WWIN0000939 , VHA No.: 31699
- 3) Autobay Towing - Towing receipt (SLC2858X)
- 4) LTA search fee
- 5) Letter of Authorisation

We look forward to your prompt reply.

Yours faithfully,



.....
N-51 Automotive Pte Ltd
S.Y. NEO
Managing Director





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

11 OCTOBER 2016

N&K TRANSPORT SERVICES
BLK 422 CLEMENTI AVE 1
09-333
Singapore 120422
ATTN: MR MOHAMAD NASAR BIN ALI

Dear Sir/Mdm,

YOUR REF : PC 7227L
OUR REF : CC4/AXA16015334/Ayb3

ACCIDENT INVOLVING PC 7227L & SLC 2858X ALONG CLEMENTI AVENUE 1 ON 14/08/2016

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from N-51 AUTOMOTIVE PL acting on behalf of the owner SLC 2858X against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had rear-ended the Third Party vehicle SLC 2858X. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We also wish to advise that there is an excess of **S\$ 1,500.00** attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim. The applicability of the excess is as follows:

- (1) Any settlement equal to or above the excess, you shall be liable to make the payment of **S\$ 1,500.00**; or
- (2) Any settlement below the excess, you shall be liable for the amount settled.

AXA shall keep you informed of the third party claim settlement and thereafter kindly let AXA have the excess payment in your cheque payable to "AXA Insurance Singapore Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

Notwithstanding the excess being applied and/or received by AXA for the above subject matter, AXA expressly reserves all their rights under the policy to refund the excess payment in the event that there arises any known policy breach and or exclusion material to coverage.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to AXA immediately. You may email it to vicalpeh@lkkauto.com or deliver it by hand to AXA's Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 8625 or email us at vicalpeh@lkkauto.com. Please quote our claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

R. Vasanthi

R. Vasanthi
Case Handler
DID: 6841 2132
FAX: 6741 4108
EMAIL: vicalpeh@lkkauto.com

Cc Motor Claims Department
AXA Insurance Singapore Pte Ltd

LETTER OF AUTHORISATION

To: M/s N-51 Automotive Pte Ltd
Singapore

RE: ACCIDENT INVOLVING VEHICLE NOS: SLC 2858 X & PC 7227 L
ALONG IN FRONT OF BLK 430 CLEMENTI AVE 1 ON 14/08/2016 @ 06:00hrs

I/We SHAJAHAN S/O PEER MOHD NRIC/Passport No: S 1745044 A
of 7 DAIRY FARM HEIGHT #10-13 S (67A669)
the owner of vehicle no. SLC 2858 X hereby authorise you to commence repair to the said vehicle forthwith. In consideration of you repairing my/our vehicle at my/our request.

- a) I/We hereby irrevocably authorise you to demand claim settle receive whatever amount settled/payable by the insurance and/or third party or to commence legal proceeding, if necessary, in my name, for the costs of repair and loss of use, etc and to you appointing any Solicitor to act for me in respect of the accident claim and all an any amount claimed, received and/or settled shall belong absolutely to you. I/We agree to assign the whole proceeds of my/our third party claim to you and my/our Solicitors (to be appointed by you on my/our behalf) shall accept this as my/our irrevocable authorisation to pay the amount compensated direct to you after deduction of their costs on a Solicitor & Client basis. I/We undertake to co-operate fully with you and my/our Solicitors to see the claim to a successful conclusion.
- ~~b) If the third party claim is unsuccessful or in your discretion inappropriate for any reason, I/we hereby instruct and authorise you to claim direct from my/our insurance company on my/our behalf for all monies due to you. I undertake to pay you for the Excess applicable under my policy and to reimburse you all costs, fees and expenses incurred by you in pursuing the claim on my behalf.~~
- ~~c) If the own insurers' claim is not applicable and/or the third party claim fails and/or either of the aforesaid is inadequate, I/we undertake to pay you for your expenses, costs and fees immediately.~~

I/We also irrevocably authorise you to sign all discharge vouchers/indemnity forms and all necessary papers in connection with the above claim in my/our absence. I/We irrevocable authorise you to appoint such a firm of Solicitors on my/our behalf as you shall deem fit for the purpose of the third party/own insurer's claim.

I/We undertake to inform you and/or the Solicitors appointed by you on my behalf in the event the third party's insurance company communicate with me/us directly, orally or in writing and I/we further undertake not to accept any monies or offer of settlement from the third party's insurers without first communicating with you and obtaining your consent.

Upon settlement of the third party claim and in case the settlement monies was sent to me/us by the third party's insurers, I/we undertake to pay you and my/our solicitor the cost of repairs settled and related expenses and disbursement incurred.

My/Our insurer is/are _____
Policy No. _____ Expiry Date: _____

Date: _____ Excess: _____

X 
Owner's Signature/Co's stamp (if applicable)

Witness Signature/Name



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	PC 7227L (Insd veh)	Model: Honda Odyssey (2354cc)
	SLC 2858X (TP veh)	
Date of Accident/ Time:	14/08/2016	

Repair Estimate	: \$	35,454.32			
Final Repair Cost	: \$				
Loss of Use	: \$		days at \$ per day		
Rental (if any)	: \$		days at \$ per day		
LTA / GIA Search Fee	: \$				
Others:	: \$				
Final Settlement Sum (Global Sum)	: \$	18,250.00			
Payee Name : N-51 AUTOMOTIVE PTE LTD					
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly Indicate below)					
A)	For Non GIA Registered Workshop:	Agreed Liability 100 (%)			
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____			
	BOLA Liability: _____ (%)	Assessed Liability (*) : _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks:					

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/i confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp

Name of Representative: SHU BUA

Date: 13/6/2019

Signature of Witness / Workshop stamp (if applicable)

Name of Witness: CHIN HUI XIN

Date: 13/06/2019

Signature of AXA's surveyor/representative:

Name of AXA's surveyor /Representative:

Date: 15/6/19

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921

Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
7 DAIRY FARM HEIGHT #10-13
SINGAPORE 677669

Contact : 98579363, 93212348

TAX INVOICE

Date : 12/06/2017

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Make/Model : HONDA ODYSSEY 2.4 A-2008

Chassis/Eng# : JHMRB18508C204116/K24A65004116

Accident Date : 14/08/2016

Claim No : CLM13658

Reference : AUG-34/2016

Policy No. : 5080556300 (24/05/2017)

LUMPSUM REPAIR BILL

REF : CLM13658 - N51 DATED 17/08/2016

BY LKK

Amount S\$
14,800.00



E. & O.E.	Sub S\$:	14,800.00
	Add GST (7%) S\$:	1,036.00
	Total Amount S\$:	15,836.00

for N-51 AUTOMOTIVE PTE LTD



bizSAFE₃



WIN WIN CAR RENTAL

Invoice

SLC2858X
SHAJAHAN S/O PEER MOHD
7 DAIRY FARM HEIGHT
#10-13
S(677669)

Invoice No : WWIN0000939
Invoice Date : 10/9/2016
Due Date : 10/9/2016
VHA No : 31699
Referral ID : N001

Description :	Amount
Rental for 19 Day/s @ \$180 per Day	\$3,420

Vehicle No : SJJ 3985 S

Vehicle Description : Toyota Wish 1.8 A

Rental Period : 14/08/2016 to 02/09/2016

Total Amount Payable : \$3,420

WIN WIN CAR RENTAL

Blk 257B, Compassvale Road #15-521 Singapore 542257

Tel: 6315 8479 H/P: 9833 0807

WWIN 939.

VHA No: 31699

SEC 2850 (R20)

ROC No: 52987763E

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULAR

Name: (as in I/C) SHAJAHAN S/O PEER MOHD

NRIC/PASSPORT No: DAIRY FARM HEIGHT

Address (Res): #10-13 S(67669)

S 145044 A

Name & Address of Employer

Occupation: Driving Exp:

Driving Licence No: S145044A D/L Type: Local / International

Issue Date: 16/12/2002 Date of Birth: 20/08/1966

Tel: (O) (R) HP/PG 9833 9363

ADDITIONAL DRIVER'S PARTICULARS

Name: (as in I/C) SIAM ALI BIN SHAJAHAN

NRIC/PASSPORT No: S9419679E

Address (Res): DAIRY FARM HEIGHT

#10-13 S(67669)


Driving License No: S9419679E D/L Type: Local / International

Issue Date: 21/03/2013 Date of Birth: 30/05/1994

Occupation: Driving Exp:

VEHICLE CHECK LIST

INDICATE:
D - DENTS
S - SCRATCHES
A - ACCIDENTS



ACCESSORIES CHECK

- ☐ Ashtray ☐ Cig Lighter ☐ S/Tyre
- ☐ STD Tools ☐ Jack ☐ Hub Caps
- ☐ Radio/Cass ☐ CD ☐ Cartridges

Vehicle No: SSJ3985 Replace Veh No:

Mileage Out: Mileage Out:

Make & Model: Tajet van Auto / Manual Group:

Out : Date 14/8/16 Time: 12:45 pm

HIRE / PERIOD EXPIRY Time:

NON-WAIVER EXCESS=\$ 3000/-

CHARGES

Daily 19 @ \$ 180 per day \$3420

Weekly @ \$ per week

Monthly @ \$ per month

Hours @ \$ per hour

Others @ \$

CDW @ \$ per day/month

PAI @ \$ per day/month

Delivery/Collection Service

SUB-TOTAL \$

PETROL LEVEL

Out E 1/4 1/2 3/4 F

In E 1/4 1/2 3/4 F

EXTENSION

Misc.

TOTAL CHARGES \$

Hirer's Signature

Additional Driver's Signature

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given WIN WIN CAR RENTAL in connection with this agreement is true.

*IMPORTANT

- ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE AUTHORIZED LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY WIN WIN CAR RENTAL.

RETURN OF VEHICLE. THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SINGAPORE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO WIN WIN CAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
12/08/16	11:00				

AUTOBAY TOWING

1 Kaki Bukit Avenue 6
#01-55 AutoBay @ Kaki Bukit
Singapore 417883
Tel: 9015 8585 (Ah Boon)

CASH SALE

(N-51)

No. _____

Sold to: SLC 2858 X

Date: 15/8/16

Item	Quantity	Description	Unit Price	Amount
		Auto Hub to U6: DRC		100
/		Reporting Two Trips		
E. & O. E.			Sub Total :	
			GST Tax :	
			Total :	100

Issued by: _____

CROWN



Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 15 Aug 2016 / 15:57:05

Receipt Date/Time : 15 Aug 2016 / 15:57:05

Tax Invoice/Receipt

Receipt No. : ITNET-00000-160815-001215

Previous Receipt No. :

**S/N Item Description/
Business Transaction
Reference No.**

Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
--------------------------------	-------------------------	-------------------------------

Result of Insurance Enquiry - PC7227L

As at 14 Aug 2016/06:00:00

Insurance Co: AXA INSURANCE SINGAPORE PTE LTD

1 Insurance Enquiry - PC7227L
Enquiry Fee
20160815155559453295

5.00	0.35	5.35
------	------	------

Sub-Total	5.00	0.35	5.35
-----------	------	------	------

Total Before Rounding	5.00	0.35	5.35
-----------------------	------	------	------

Rounding Difference			0.00
---------------------	--	--	------

Total Amount Payable			5.35
----------------------	--	--	------

Paid By

xxxxxxxxxxxx2392	Credit Card: Visa/MasterCard	5.35
------------------	---------------------------------	------

Total			5.35
-------	--	--	------

Cash Change			0.00
-------------	--	--	------

Tendered Amount			5.35
-----------------	--	--	------

Excess Refundable Amount			0.00
--------------------------	--	--	------

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Proceed Direct Settlement

































CLAIM SUBFOLDER TRACKING



















































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Aug 2016		17 Aug 2016 10:28 Edit Adj Rpt	S\$14,800.00 Edit Estimates	S\$14,800.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	N & K TRANSPORT SERVICES , Co. Reg. No.: 53328158W, Tel: +6581866911								
Main Claimant:	SHAJAHAN S/O PEER MOHD , ID: S1745044A								
Vehicle Reg. No.:	SLC2858X	Date of Loss:	14/08/2016 05:00 - :59 [98 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0396138	Policy/Cover Note No.:	P1743728 (Comprehensive)						
Vehicle Reg. No. (Insured):	PC7227L	Policy No. (Claimant):	508055600						
		Excess:	S\$1,500.00						
Reparer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Khor Saw Theng - 6880 4754]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/08/2016]								
Driver/Custodian (Insured):	MOHAMAD NASAR BIN ALI (35), NRIC: S8103086C, Tel: +6581866911 Email:								
Adj Asg. Remarks:	Adrian Ling (LKK) appointed as SJE. Pls conduct PRS.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AXA_SG (03/06/2019): Alert - Adj Mandate Approved (S\$18250.00) - SLC2858X - Claim Handler: Khor Saw T... AXA_SG (15/05/2019): Alert - Adj Mandate Maintained - SLC2858X - Claim Handler: Khor Saw Theng AXA_SG (16/02/2019): REVIEW STATUS AXA_SG (07/10/2018): Alert - Adj Mandate Approved (S\$18000.00) - SLC2858X - Claim Handler: Richard An... AXA_SG (06/10/2016): TP settlement - C0396138/P1743728 AXA_SG (17/08/2016): WP/ PRI Assignment - C0396138/P1743728 AXA_SG (17/08/2016): WP / New TP Assignment - C0396138/P1743728 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									
































Claim Documents

*SLC2858X (C0396138)
[PC7227L]
TP
SHAJAHAN S/O PEER MOHD
Aug 14 2016 5:00AM
[N & K TRANSPORT SERVICES]
N-51 Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print					
1	(Draft)		Third Party Express Settlement – Payment Breakdown												Edit					
Assessment Reports															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print					
1	18/05/17 12:06		Adjuster Immediate Advice												Load HTM					
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print						
1	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
2	18/05/17 09:24	Chassis Number												Load JPG		<input checked="" type="checkbox"/>				
3	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
4	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
5	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
6	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
7	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
8	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
9	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
10	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
11	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
12	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
13	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
14	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
15	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
16	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
17	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
18	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
19	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
20	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
21	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
22	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
23	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
24	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
25	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
26	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
27	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
28	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
29	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				
30	18/05/17 09:24	General View												Load JPG		<input checked="" type="checkbox"/>				

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
32	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
33	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
34	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
35	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
36	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
37	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
38	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
39	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
40	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
41	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
42	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
43	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
44	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
45	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
46	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
47	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
48	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
49	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
50	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
51	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
52	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
53	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
54	18/05/17 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
55	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
131	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	18/05/17 09:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	16/08/16 11:46	CO-CLAIMANT_ABS	 Load PDF	
2	16/08/16 11:46	PC7227L INSD GIA REPORT_ABS	 Load PDF	
3	16/08/16 11:46	SLC2858X TP GIA REPORT_ABS	 Load PDF	
4	16/08/16 11:48	EMAIL_ABS	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/10/16 10:38	LETTER TO OI	 Load PDF	
2	18/05/17 12:03	TP ESTIMATE - MARKED	 Load PDF	
3	21/07/17 15:49	TOWING FEE	 Load PDF	
4	21/07/17 15:49	RENTAL RECEIPT	 Load PDF	
5	21/07/17 15:49	LTA SEARCH	 Load PDF	
6	20/06/19 07:58	WORKSHOP INVOICE	 Load PDF	
7	20/06/19 07:58	AUTHORISATION TO ACT FORM	 Load PDF	
8	20/06/19 07:58	PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	PC7227L (Insd veh)	Model:	HONDA ODYSSEY 2.4 (A)
	SLC2858X (TP veh)		
Date of Accident:	14/08/2016		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	: \$	35,484.32		
Final Repair Cost	: \$	15,836.00		
Loss of Use	: \$	days at \$0.00 per day		
Rental (if any)	: \$	3,420.00	19	days
LTA / GIA Search Fee	: \$	5.35		
Others: Towing Fee	: \$	100.00		
	: \$			
Final Settlement Sum (Global Sum)	: \$	18,250.00		
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)				
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ 100 _____ (%)		
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	N-51 Automotive Pte Ltd	: \$	18,250.00
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

20 Jun
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA16015334/APB3Q2

Date: 20/06/2019

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1743728

Claimant Vehicle
No : SLC2858X

Insured Vehicle No :

PC7227L

Date of Loss: 14/08/2016

Nature of Claim:

TP

Claim No: C0396138

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLC2858X

Make & Model: HONDA ODYSSEY, 2.4 (A)

Engine No: K24A65004116

Reg. Date: 21/05/2008 (Man. Year: 2008)

Chassis No: JHMRB18508C204116

Colour: Black

Odometer: 164110 km

Engine Capacity: 2354 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size:

215/55 R17

Front Left Side: Maxxis 6 mm

Rear Left Side:

Maxxis 6 mm

Front Right Side: Maxxis 6 mm

Rear Right Side:

Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,402.92	14,281.12	12,121.80	45.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,760.00	4,300.00	2,460.00	36.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,162.92	18,581.12	14,581.80	43.97
Approved Total (Overridden) (S\$)		14,800.00		
(S\$)	33,162.92	14,800.00	18,362.92	55.37
+ GST 7.00/7.00% (S\$)	2,321.40	1,036.00	1,285.40	55.37
Nett Amount (S\$)	35,484.32	15,836.00	19,648.32	55.37
+ Car Rental (19.0 x S\$180.00/day) (S\$)		3,420.00		
+ Doc/Search Fee (S\$)		5.35		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		19,361.35		
Global Sum Settlement (S\$)		18,250.00		

INSPECTION

Date of Assignment: 17/08/2016

Date Inspected: 17/08/2016 Inspected At: N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI
BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 16.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Jul 2017)	
Parts: M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLC2858X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PETROL TANK (CONSISTENT)	Not Necessary	680.00 FL	*- FL
2	2		*PETROL TANK BRACKET (CONSISTENT)	Not Necessary	90.00 FL	*- FL
3	1		*PETROL TANK FLOAT (CONSISTENT)	Not Necessary	143.70 FL	*- FL
4	1		*PETROL TANK NECK (CONSISTENT)	Not Necessary	110.00 FL	*- FL
5	1		*PETROL TANK NECK HOSE (CONSISTENT)	Not Necessary	50.00 FL	*- FL
6	1		*PETROL TANK PUMP (CONSISTENT)	Not Necessary	535.00 FL	*- FL
7	1		*REAR 3RD ROLL AUTO FOLDING SEAT ASSY (CONSISTENT)	Damaged	1,480.00 FS	*800.00 FS
8	1		*REAR 3RD ROLL RH PASSENGER SAFETY BELT (CONSISTENT)	Not Necessary	300.00 FL	*- FL
9	1		*REAR BUMPER (CONSISTENT)	Distorted	705.80 FL	*705.80 FL
10	1		*REAR BUMPER REFLECTOR L/R (CONSISTENT)	O/S Cracked	84.20 FL	*42.10 FL
11	1		*REAR BUMPER REINFORCEMENT (CONSISTENT)	Bent	89.70 FL	*89.70 FL
12	2		*REAR BUMPER REINFORCEMENT BRACKET L/R (CONSISTENT)	Not Necessary	116.80 FL	*- FL
13	4		*REAR BUMPER SCREW COVER L/R (CONSISTENT)	Not Necessary	38.00 FL	*- FL
14	2		*REAR BUMPER SIDE RETAINER L/R (CONSISTENT)	Necessary	36.60 FL	*36.60 FL
15	2		*REAR BUMPER SIDE SUPPORT L/R (CONSISTENT)	Not Necessary	121.60 FL	*- FL
16	1		*REAR BUMPER TOW HOOK COVER (CONSISTENT)	Deformed	18.00 FL	*18.00 FL
17	1		*REAR END PANEL (CONSISTENT)	Distorted	427.30 FL	*427.30 FL
18	1		*REAR END PANEL INNER TOP GARNISH (CONSISTENT)	Deformed	172.70 FL	*172.70 FL
19	6		*REAR END PANEL INNER TOP GARNISH CLIPS (CONSISTENT)	Necessary	39.00 FL	*15.00 FL
20	1		*REAR END PANEL LOCK STRIKER (CONSISTENT)	Not Necessary	24.70 FL	*- FL
21	1		*REAR END PANEL LOCK STRIKER COVER (CONSISTENT)	Damaged	8.60 FL	*8.60 FL
22	1		*REAR LH EXHAUST ALUMINIUM HEAT SHIELD (CONSISTENT)	Not Necessary	31.50 FL	*- FL
23	1		*REAR LH EXHAUST END CHROME PIPE (CONSISTENT)	Not Necessary	89.70 FL	*- FL
24	1		*REAR LH EXHAUST GASKET (CONSISTENT)	Not Necessary	13.60 FL	*- FL
25	6		*REAR LH EXHAUST RUBBER MOUNTING (CONSISTENT)		21.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*REAR LH EXHAUST SILENCER BOX (CONSISTENT)	Not Necessary	474.80 FL	*- FL
27	1		*REAR LH FENDER (CONSISTENT)	Not Necessary	901.50 FL	*- FL
28	1		*REAR LH FENDER GLASS INNER GARNISH (CONSISTENT)	Not Necessary	105.00 FL	*- FL
29	6		*REAR LH FENDER GLASS INNER GARNISH CLIPS (CONSISTENT)	Not Necessary	39.00 FL	*- FL
30	1		*REAR LH FENDER GLASS WITH MOULDING ASSY (CONSISTENT)	Not Necessary	534.60 FL	*- FL
31	1		*REAR LH FENDER INNER AIR VENT (CONSISTENT)	Not Necessary	29.10 FL	*- FL
32	1		*REAR LH FENDER INNER SHIELD (CONSISTENT)	Not Necessary	97.10 FL	*- FL
33	1		*REAR LH FENDER INNER TRIM BOARD (CONSISTENT)	Deformed	489.90 FL	*489.90 FL
34	1		*REAR LH FENDER INNER TRIM BOARD COVER (CONSISTENT)	Deformed	642.70 FL	*285.00 FL
35	1		*REAR LH FENDER PROTECTOR (CONSISTENT)	Not Necessary	19.00 FL	*- FL
36	1		*REAR RH DOOR (CONSISTENT)	Buckled	943.80 FL	*943.80 FL
37	1		*REAR RH DOOR BLACK FRAME STICKER HORIZONTAL (CONSISTENT)	Necessary	52.80 FL	*52.80 FL
38	1		*REAR RH DOOR BLACK FRAME STICKER VERTICAL (CONSISTENT)	Necessary	45.40 FL	*45.40 FL
39	1		*REAR RH DOOR CHECKER (CONSISTENT)	Not Necessary	40.00 FL	*- FL
40	2		*REAR RH DOOR HINGE (TOP & LOWER) (CONSISTENT)	Not Necessary	79.00 FL	*- FL
41	1		*REAR RH DOOR INNER LOCK HANDLE (CONSISTENT)	Not Necessary	50.60 FL	*- FL
42	1		*REAR RH DOOR INNER TRIM BOARD (CONSISTENT)	Not Necessary	621.50 FL	*- FL
43	1		*REAR RH DOOR LOCK STRIKER (CONSISTENT)	Not Necessary	20.00 FL	*- FL
44	1		*REAR RH DOOR MECHANISM LOCK (CONSISTENT)	Damaged	290.00 FL	*290.00 FL
45	1		*REAR RH DOOR OUTER CHROME LOCK HANDLE (CONSISTENT)	Not Necessary	121.50 FL	*- FL
46	1		*REAR RH DOOR OUTER CHROME LOCK HANDLE COVER (CONSISTENT)	Not Necessary	12.00 FL	*- FL
47	1		*REAR RH DOOR PILLAR WEATHER STRIP (CONSISTENT)	Not Necessary	92.50 FL	*- FL
48	1		*REAR RH DOOR PROTECTOR (CONSISTENT)	Not Necessary	88.00 FL	*- FL
49	1		*REAR RH DOOR QUARTER GARNISH INNER (CONSISTENT)	Not Necessary	65.00 FL	*- FL
50	1		*REAR RH DOOR QUARTER GARNISH OUTER (CONSISTENT)	Not Necessary	55.00 FL	*- FL
51	2		*REAR RH DOOR QUARTER GARNISH CLIPS (CONSISTENT)	Not Necessary	13.00 FL	*- FL
52	2		*REAR RH DOOR RUBBER GUIDE STOPPER (CONSISTENT)	Not Necessary	12.00 FL	*- FL
53	1		*REAR RH DOOR STEP GARNISH (CONSISTENT)	Not Necessary	35.00 FL	*- FL
54	3		*REAR RH DOOR STEP GARNISH CLIPS (CONSISTENT)	Not Necessary	19.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*REAR RH DOOR SWITCH (CONSISTENT)	Not Necessary	18.00 FL	*- FL
56	1		*REAR RH DOOR WEATHERSTRIP (CONSISTENT)	Not Necessary	109.40 FL	*- FL
57	1		*SET REAR RH DOOR WIRE HARNESS (CONSISTENT)	Not Necessary	110.00 FL	*- FL
58	1		*REAR RH EXHAUST ALUMINIUM HEAT SHIELD (CONSISTENT)	Crumpled	31.50 FL	*31.50 FL
59	1		*REAR RH EXHAUST END CHROME PIPE (CONSISTENT)	Bent	89.70 FL	*89.70 FL
60	1		*REAR RH EXHAUST GASKET (CONSISTENT)	Necessary	13.60 FL	*13.60 FL
61	3		*REAR RH EXHAUST RUBBER MOUNTING (CONSISTENT)	Not Necessary	32.40 FL	*- FL
62	1		*REAR RH EXHAUST SILENCER BOX (CONSISTENT)	Bent	906.40 FL	*906.40 FL
63	1		*REAR RH FENDER (CONSISTENT)	Buckled	841.30 FL	*841.30 FL
64	1		*REAR RH FENDER AIRCON AIR DUCT (CONSISTENT)	Not Necessary	65.00 FL	*- FL
65	1		*REAR RH FENDER AIRCON COOLING PIPE (CONSISTENT)	Not Necessary	220.10 FL	*- FL
66	1		*REAR RH FENDER AIRCON DISCHARGE PIPE (CONSISTENT)	Not Necessary	248.10 FL	*- FL
67	1		*REAR RH FENDER AIRCON EVAPORATOR UNIT (CONSISTENT)	Cracked	794.50 FL	*794.50 FL
68	1		*REAR RH FENDER GLASS INNER GARNISH (CONSISTENT)	Not Necessary	105.00 FL	*- FL
69	6		*REAR RH FENDER GLASS INNER GARNISH CLIPS (CONSISTENT)	Not Necessary	39.00 FL	*- FL
70	1		*REAR RH FENDER GLASS WITH MOULDING ASSY (CONSISTENT)	Not Necessary	534.60 FL	*- FL
71	1		*REAR RH FENDER INNER PANEL (CONSISTENT)	Repair	558.00 FL	*- FL
72	1		*REAR RH FENDER INNER SHIELD (CONSISTENT)	Deformed	105.10 FL	*105.10 FL
73	1		*REAR RH FENDER INNER TRIM BOARD (CONSISTENT)	Deformed	455.70 FL	*455.70 FL
74	1		*REAR RH FENDER PROTECTOR (CONSISTENT)	Not Necessary	19.00 FL	*- FL
75	1		*REAR RH SUB CHASSIS FRAME (CONSISTENT)	Repair	1,150.00 FL	*- FL
76	1		*REAR RH WHEEL HOUSE PANEL ASSY (CONSISTENT)	Repair	690.00 FL	*- FL
77	1		*REAR TAILGATE (CONSISTENT)	Distorted	1,072.50 FL	*1,072.50 FL
78	1		*REAR TAILGATE 3RD BRAKE LAMP (CONSISTENT)	Cracked	340.40 FL	*340.40 FL
79	2		*REAR TAILGATE DAMPER L/R (CONSISTENT)	Bent	215.80 FL	*215.80 FL
80	2		*REAR TAILGATE HINGES L/R (CONSISTENT)	Not Necessary	69.20 FL	*- FL
81	1		*REAR TAILGATE INNER HANDLE (CONSISTENT)	Not Necessary	93.90 FL	*- FL
82	1		*REAR TAILGATE INNER TRIM BOARD (CONSISTENT)	Deformed	198.80 FL	*198.80 FL
83	1		*REAR TAILGATE MECHANISM LOCK (CONSISTENT)	Jammed	165.60 FL	*165.60 FL
84	2		*REAR TAILGATE NUMBER PLATE LAMP COVER L/R (CONSISTENT)	Damaged	24.00 FL	*24.00 FL
85	2		*REAR TAILGATE NUMBER PLATE LAMP L/R (CONSISTENT)	Damaged	101.40 FL	*101.40 FL
86	1		*REAR TAILGATE OUTER CHROME GARNISH (CONSISTENT)	Cracked	756.80 FL	*756.80 FL
87	6		*REAR TAILGATE OUTER CHROME GARNISH CLIPS (CONSISTENT)	Necessary	39.00 FL	*39.00 FL
88	1		*REAR TAILGATE OUTER GARNISH (CONSISTENT)	Deformed	425.30 FL	*425.30 FL
89	1		*REAR TAILGATE OUTER LOCK HANDLE (CONSISTENT)	Not Necessary	53.40 FL	*- FL
90	2			Necessary	13.00 FL	*13.00 FL
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*REAR TAILGATE REFLECTOR LAMP CLIPS L/R (CONSISTENT)			
91	2		*REAR TAILGATE REFLECTOR LAMP L/R (CONSISTENT)	Cracked	656.20 FL	*656.20 FL
92	2		*REAR TAILGATE RUBBER GUIDE STOPPER L/R (CONSISTENT)	Necessary	15.60 FL	*15.60 FL
93	1		*REAR TAILGATE SPOILER (CONSISTENT)	Cracked	523.90 FL	*523.90 FL
94	1		*REAR TAILGATE WEATHER STRIP (CONSISTENT)	Cut	125.60 FL	*125.60 FL
95	1		*REAR TAILGATE WINDSCREEN (CONSISTENT)	Shattered	1,103.50 FL	*1,103.50 FL
96	1		*REAR TAILGATE WINDSCREEN INNER GARNISH TOP (CONSISTENT)	Not Necessary	33.80 FL	*- FL
97	1		*REAR TAILGATE WINDSCREEN INNER GARNISH L/R (CONSISTENT)	O/S Cut	60.60 FL	*30.30 FL
98	1		*REAR TAILGATE WIPER ARM (CONSISTENT)	Cut	158.30 FL	*158.30 FL
99	1		*REAR TAILGATE WIPER ARM COVER (CONSISTENT)	Cut	49.50 FL	*49.50 FL
100	1		*REAR TAILGATE WIPER ARM RUBBER SEAL (CONSISTENT)	Necessary	46.20 FL	*46.20 FL
101	1		*REAR TAILGATE WIPER BLADE (CONSISTENT)	Cut	41.30 FL	*41.30 FL
102	1		*REAR TAILGATE WIPER MOTOR (CONSISTENT)	Damaged	226.60 FL	*226.60 FL
103	1		*REAR TAILGATE WIPER NOZZLE (CONSISTENT)	Damaged	18.70 FL	*18.70 FL
104	1		*REAR TAILGATE WIPER NOZZLE HOSE (CONSISTENT)	Not Necessary	10.00 FL	*- FL
105	1		*SET REAR TAILGATE WIRE HHARNES (CONSISTENT)	Not Necessary	115.00 FL	*- FL
106	4		*REAR TAILLAMP CLIPS L/R (CONSISTENT)	Necessary	26.00 FL	*26.00 FL
107	1		*REAR TAILLAMP INNER PANEL L/R (CONSISTENT)	O/S Dented	302.20 FL	*151.10 FL
108	2		*REAR TAILLAMP L/R (CONSISTENT)	Cracked	753.20 FL	*753.20 FL
109	1		*REAR TAILLAMP LOWER BRACKET L/R (CONSISTENT)	O/S Bent	30.00 FL	*15.00 FL
110	1		*SET REAR TAILLAMP WIRE HARNESS L/R (CONSISTENT)	Not Necessary	671.00 FL	*- FL
111	1		*SPARE TYRE PANEL (CONSISTENT)	Distorted	1,118.50 FL	*1,118.50 FL
112	1		*SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD (CONSISTENT)	Cracked	303.80 FL	*303.80 FL
113	1		*SPARE TYRE RETAINER LOCK (CONSISTENT)	Damaged	25.00 FL	*25.00 FL
114	2		*SPARE TYRE SIDE PANEL L/R (CONSISTENT)	Repair	160.00 FL	*- FL
115	1		*SET REAR BUMPER CLIPS (CONSISTENT)	Necessary	30.00 FS	*30.00 FS
116	1		*SET REAR BUMPER REVERSE SENSOR (CONSISTENT)	Damaged	350.00 FS	*250.00 FS
117	1		*REAR LH FENDER GLASS SEALANT (CONSISTENT)	Necessary	60.00 FS	*60.00 FS
118	1		*SET REAR LH FENDER INNER SHIELD CLIPS (CONSISTENT)	Not Necessary	30.00 FS	*- FS
119	1		*SET REAR LH FENDER INNER TRIM BOARD CLIPS (CONSISTENT)	Necessary	30.00 FS	*30.00 FS
120	1		*REAR RH DOOR INNER L.E.D BULB (CONSISTENT)	Not Necessary	90.00 FS	*- FS
121	1		*SET REAR RH DOOR INNER TRIM BOARD CLIPS (CONSISTENT)	Not Necessary	30.00 FS	*- FS
122	1		*REAR RH DOOR L.E.D LAMP (CONSISTENT)	Not Necessary	190.00 FS	*- FS
123	1		*REAR RH DOOR SPEAKER (CONSISTENT)	Not Necessary	180.00 FS	*- FS
124	1		*REAR RH FENDER GLASS SEALANT (CONSISTENT)	Necessary	60.00 FS	*40.00 FS
125	1		*SET REAR RH FENDER INNER SHIELD CLIPS (CONSISTENT)	Necessary	30.00 FS	*30.00 FS
126	1		*SET REAR RH FENDER INNER TRIM BOARD CLIPS (CONSISTENT)	Necessary	30.00 FS	*30.00 FS
127	1			Necessary	180.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
128	1		*REAR TAILGATE LOGO EMBLEM (RED COLOR) (CONSISTENT)			
			*SET REAR TAILGATE INNER TRIM BOARD CLIPS (CONSISTENT)	Necessary	30.00 FS	*30.00 FS
129	1		*REAR TAILGATE NUMBER PLATE (CONSISTENT)	Not Necessary	25.00 FS	*- FS
130	1		*REAR TAILGATE NUMBER PLATE HOLDER (CONSISTENT)	Not Necessary	50.00 FS	*- FS
131	2		*REAR TAILGATE NUMBER PLATE LAMP BULB L/R (CONSISTENT)	Not Necessary	20.00 FS	*- FS
132	1		*SET REAR TAILGATE OUTER GARNISH CLIPS (CONSISTENT)	Necessary	30.00 FS	*30.00 FS
133	1		*SET REAR TAILGATE SPOILER CLIPS (CONSISTENT)	Necessary	30.00 FS	*30.00 FS
134	1		*REAR TAILGATE WINDSCREEN 3M SOLAR FILM (CONSISTENT)	Necessary	380.00 FS	*180.00 FS
135	1		*SET REAR TAILGATE WINDSCREEN INNER GARNISH CLIPS (CONSISTENT)	Necessary	30.00 FS	*10.00 FS
136	2		*REAR TAILLAMP BRAKE BULB L/R (CONSISTENT)	Not Necessary	24.00 FS	*- FS
137	1		*SET REAR TAILLAMP REVERSE L.E.D BULB L/R (CONSISTENT)	Not Necessary	250.00 FS	*- FS
138	2		*REAR TAILLAMP SIGNAL BULB L/R (CONSISTENT)	Not Necessary	30.00 FS	*- FS
139	1		*SPARE TYRE (CONSISTENT)	Not Necessary	280.00 FS	*- FS
140	1		*SPARE TYRE PANEL INNER BREAK DOWN SIGN (CONSISTENT)	Not Necessary	150.00 FS	*- FS
141	1		*SPARE TYRE PANEL INNER JACKING TOOL (CONSISTENT)	Not Necessary	180.00 FS	*- FS
142	1		*SPARE TYRE PANEL INSULATOR MAT (CONSISTENT)	Necessary	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **31,846.40** **17,401.40**
 - List Item Discount on L Items 20.00/20.00% (S\$) **5,443.48** **3,120.28**

Total Parts (S\$) 26,402.92 14,281.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,500.00	1,800.00
2	TO REMOVE,REPLACED AIRCON EVAPORATOR UNIT,AIRCON BLOWER MOTOR AND ETC TO VACUUM SYSTEM AND TOP UP GAS	New	280.00	180.00
3	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING ,RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR	New	150.00	80.00
4	TO REMOVE,REINSTALL WINDOW GLASS (TO FR)	New	120.00	0.00
5	TO REMOVE,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
6	TO REMOVE,REINSTALL FENDER GLASS	New	120.00	60.00
7	TO REMOVE,REINSTALL REAR SUSPENSION AND UNDERCARRIAGE PART (TO FR)	New	280.00	0.00
8	TO ROAD TEST DRIVING ,CHECK AND RESETTNG WHEEL ALIGNMENT SYSTEM	New	180.00	0.00
9	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	140.00	100.00
10	TO TRANSFER DOOR GLASS ,REGULATOR GEAR ,MOTOR RAILING ,CHANNEL ,TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	160.00	80.00
11	TO RE-SPRAY PAINTING ON THE REAR BOOTLID ,REAR END PANEL,REAR FENDER (L/R) ,SPARE TYRE PANEL ,REAR BUMPER,REAR DOORS (L/R), AND ROOF TOP PANEL	New	2,000.00	1,400.00
12	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE ,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	160.00	100.00
13	TO MOUNT VEHICLE ON TO CAR O LINER	New	400.00	300.00
14	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	80.00
Gross Labour Cost (S\$)			6,760.00	4,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >