

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
 7 DAIRY FARM HEIGHT #10-13
 SINGAPORE 677669

Contact : 98579363, 93212348

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

REAR TAILGATE REFLECTOR LAMP L/R <i>ambd.</i>	2	328.10	656.20 ✓
REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>new</i>	2	7.80	15.60 ✓
REAR TAILGATE SPOILER <i>ambd.</i>	1	523.90	523.90 ✓
REAR TAILGATE WEATHER STRIP <i>ut</i>	1	125.60	125.60 ✓
REAR TAILGATE WINDSCREEN <i>shattered.</i>	1	1103.50	1,103.50 ✓
REAR TAILGATE WINDSCREEN INNER GARNISH 'TOP' <i>new</i>	1	33.80	33.80 ✓
REAR TAILGATE WINDSCREEN INNER GARNISH L/R <i>RH ut</i>	2	30.30	60.60 30.30 ✓
REAR TAILGATE WIPER ARM <i>ut</i>	1	158.30	158.30 ✓
REAR TAILGATE WIPER ARM COVER <i>ut</i>	1	49.50	49.50 ✓
REAR TAILGATE WIPER ARM RUBBER SEAL <i>new</i>	1	46.20	46.20 ✓
REAR TAILGATE WIPER BLADE <i>ut</i>	1	41.30	41.30 ✓
REAR TAILGATE WIPER MOTOR <i>Byd.</i>	1	226.60	226.60 ✓
REAR TAILGATE WIPER NOZZLE <i>Byd.</i>	1	18.70	18.70 ✓
REAR TAILGATE WIPER NOZZLE HOSE <i>new</i>	1	10.00	10.00 ✓
REAR TAILGATE WIRE HARNESS - SET <i>new</i>	1	115.00	115.00 ✓
REAR TAILLAMP CLIPS L/R <i>new</i>	4	6.50	26.00 ✓
REAR TAILLAMP INNER PANEL L/R <i>RH Dented</i>	2	151.10	302.20 151.10 ✓
REAR TAILLAMP L/R <i>ambd.</i>	2	376.60	753.20 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
 7 DAIRY FARM HEIGHT #10-13
 SINGAPORE 677669

Contact : 98579363, 93212348

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

REAR TAILLAMP LOWER BRACKET L/R <i>RTT Set</i>	2	15.00	30.00 15
REAR TAILLAMP WIRE HARNESS L/R - SET <i>new</i>	2	335.50	671.00 X
SPARE TYRE PANEL <i>Disbld</i>	1	1118.50	1,118.50 ✓
SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD <i>new</i>	1	303.80	303.80 ✓
SPARE TYRE RETAINER LOCK <i>Disbld</i> <i>15601.40 SN:800</i>	1	25.00	25.00 ✓
SPARE TYRE SIDE PANEL L/R <i>Disbld</i> <i>12481.12</i>	2	80.00	160.00 X
Subtotal before discount			29,067.40
Percentage discount 20%			5,813.48
Sub-total 1			23,253.92
REAR BUMPER CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR BUMPER REVERSE SENSOR - SET <i>Disbld</i>	1	350.00	350.00 250
REAR LH FENDER GLASS SEALANT <i>new</i>	1	60.00	60.00 ✓
REAR LH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR LH FENDER INNER TRIM BOARD CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR RH DOOR INNER L.E.D BULB <i>new</i>	1	90.00	90.00 ✓
REAR RH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR RH DOOR L.E.D LAMP <i>new</i>	1	190.00	190.00 ✓
REAR RH DOOR SPEAKER <i>new</i>	1	180.00	180.00 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
 7 DAIRY FARM HEIGHT #10-13
 SINGAPORE 677669

Contact : 98579363, 93212348

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

REAR RH FENDER GLASS SEALANT <i>new</i>	1	60.00	60.00 40
REAR RH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR RH FENDER INNER TRIM BOARD CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR TAILGATE 'LOGO' EMBLEM (RED COLOR) <i>new</i>	1	180.00	180.00 50
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR TAILGATE NUMBER PLATE <i>3 new</i>	1	25.00	25.00 +
REAR TAILGATE NUMBER PLATE HOLDER	1	50.00	50.00 +
REAR TAILGATE NUMBER PLATE LAMP BULB L/R <i>new</i>	2	10.00	20.00 +
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR TAILGATE SPOILER CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR TAILGATE WINDSCREEN 3M SOLAR FILM <i>new</i>	1	380.00	380.00 80
REAR TAILGATE WINDSCREEN INNER GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00 10
REAR TAILLAMP 'BRAKE' BULB L/R	2	12.00	24.00 +
REAR TAILLAMP 'REVERSE' L.E.D BULB L/R - SET	1	250.00	250.00 +
REAR TAILLAMP 'SIGNAL' BULB L/R <i>new</i>	2	15.00	30.00 +
SPARE TYRE	1	280.00	280.00 +
SPARE TYRE PANEL INNER BREAK DOWN SIGN	1	150.00	150.00 +
SPARE TYRE PANEL INNER JACKING TOOL	1	180.00	180.00 +

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
 7 DAIRY FARM HEIGHT #10-13
 SINGAPORE 677669

Contact : 98579363, 93212348

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

SPARE TYRE PANEL INSULATOR MAT <i>new</i>	1	350.00	350.00 200
			3,149.00
Subtotal before discount			3,149.00
Percentage discount 0%			0.00
			3,149.00
			26,402.92

LABOUR

To remove, replaced aircon evaporator unit, aircon blower motor and etc to vaccum system and top up gas.

To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.

To remove, reinstall window glass. (to FR)

To remove, reinstall tailgate windscreen

To remove, reinstall fender glass

To remove, reinstall rear suspension and undercarriage part. (to FR)

To road test driving, check and resetting wheel alignments system.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel, rear bumper, rear doors (L/R), and roof top panel.

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To mount vehicle on to Car 'O' Liner.

~~280.00~~ 180
~~150.00~~ 80
~~120.00~~ +
~~150.00~~ 120
~~120.00~~ 60
~~280.00~~ *
~~180.00~~ *
~~140.00~~ 100
~~160.00~~ 80
~~2,000.00~~ 1400
~~160.00~~ 100
~~2,500.00~~ 1800
~~400.00~~
 300

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
7 DAIRY FARM HEIGHT #10-13
SINGAPORE 677669

Contact : 98579363, 93212348

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

To apply anti-rust chemical on repaired and replaced panel.

4300

120.00

Labour Total

6,760.00

Parts & Labour Total

33,162.92

*** This is a computer-generated document which requires no signature.***

page 10

total: 18,581.12

2/s: 14.8K

162y

14.8K

162y