

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

2008 May.

SHAJAHAN S/O PEER MOHD
 7 DAIRY FARM HEIGHT #10-13
 SINGAPORE 677669

TPAXA
Gas -

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

Contact : 98579363, 93212348

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
PETROL TANK	1	680.00	680.00 ✓
PETROL TANK BRACKET	2	45.00	90.00 ✓
PETROL TANK FLOAT	1	143.70	143.70 ✓
PETROL TANK NECK	1	110.00	110.00 ✓
PETROL TANK NECK HOSE	1	50.00	50.00 ✓
PETROL TANK PUMP	1	535.00	535.00 ✓
REAR 3RD ROLL AUTO FOLDING SEAT ASSY	1	1850.00	1850.00 ✓ <i>200(SW)</i>
REAR 3RD ROLL RH PASSENGER SAFETY BELT	1	300.00	300.00 ✓
REAR BUMPER	1	705.80	705.80 ✓
REAR BUMPER REFLECTOR L/R	2	42.10	84.20 ✓ <i>42.00</i>
REAR BUMPER REINFORCEMENT	1	89.70	89.70 ✓
REAR BUMPER REINFORCEMENT BRACKET L/R	2	58.40	116.80 ✓
REAR BUMPER SCREW COVER L/R	4	9.50	38.00 ✓
REAR BUMPER SIDE RETAINER L/R	2	18.30	36.60 ✓
REAR BUMPER SIDE SUPPORT L/R	2	60.80	121.60 ✓
REAR BUMPER TOW HOOK COVER	1	18.00	18.00 ✓
REAR END PANEL	1	427.30	427.30 ✓
REAR END PANEL INNER TOP GARNISH	1	172.70	172.70 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
 7 DAIRY FARM HEIGHT #10-13
 SINGAPORE 677669

Contact : 98579363, 93212348

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

REAR END PANEL INNER TOP GARNISH CLIPS <i>new</i>	6	6.50	39.00 15
REAR END PANEL LOCK STRIKER <i>new</i>	1	24.70	24.70 +
REAR END PANEL LOCK STRIKER COVER <i>new</i>	1	8.60	8.60 ✓
REAR LH EXHAUST ALUMINIUM HEAT SHIELD <i>new</i>	1	31.50	31.50 +
REAR LH EXHAUST END CHROME PIPE <i>new</i>	1	89.70	89.70 +
REAR LH EXHAUST GASKET <i>new</i>	1	13.60	13.60 +
REAR LH EXHAUST RUBBER MOUNTING <i>new</i>	2	10.80	21.60 +
REAR LH EXHAUST SILENCER BOX <i>new</i>	1	474.80	474.80 +
REAR LH FENDER <i>new</i>	1	901.50	901.50 +
REAR LH FENDER GLASS INNER GARNISH	1	105.00	105.00 +
REAR LH FENDER GLASS INNER GARNISH CLIPS	6	6.50	39.00 +
REAR LH FENDER GLASS WITH MOULDING ASSY <i>new</i>	1	534.60	534.60 +
REAR LH FENDER INNER AIR VENT	1	29.10	29.10 +
REAR LH FENDER INNER SHIELD	1	97.10	97.10 +
REAR LH FENDER INNER TRIM BOARD <i>new</i>	1	489.90	489.90 ✓
REAR LH FENDER INNER TRIM BOARD COVER <i>new</i>	1	642.70	285 642.70 +
REAR LH FENDER PROTECTOR <i>new</i>	1	19.00	19.00 +
REAR RH DOOR <i>new</i>	1	943.80	943.80 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
 7 DAIRY FARM HEIGHT #10-13
 SINGAPORE 677669

Contact : 98579363, 93212348

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

REAR RH DOOR BLACK FRAME STICKER 'HORIZONTAL'	3 per	1	52.80	52.80 ✓
REAR RH DOOR BLACK FRAME STICKER 'VERTICAL'		1	45.40	45.40 ✓
REAR RH DOOR CHECKER	2	1	40.00	40.00 ✗
REAR RH DOOR HINGES (TOP & LOWER)		2	39.50	79.00 ✗
REAR RH DOOR INNER LOCK HANDLE	1	1	50.60	50.60 ✗
REAR RH DOOR INNER TRIM BOARD	1	1	621.50	621.50 ✗
REAR RH DOOR LOCK STRIKER	1	1	20.00	20.00 ✗
REAR RH DOOR MECHANISM LOCK	1	1	290.00	290.00 ✓
REAR RH DOOR OUTER CHROME LOCK HANDLE	2	1	121.50	121.50 ✗
REAR RH DOOR OUTER CHROME LOCK HANDLE COVER		1	12.00	12.00 ✗
REAR RH DOOR PILLAR WEATHER STRIP		1	92.50	92.50 ✗
REAR RH DOOR PROTECTOR	1	1	88.00	88.00 ✗
REAR RH DOOR QUATER GARNISH 'INNER'	1	1	65.00	65.00 ✗
REAR RH DOOR QUATER GARNISH 'OUTER'		1	55.00	55.00 ✗
REAR RH DOOR QUATER GARNISH CLIPS		2	6.50	13.00 ✗
REAR RH DOOR RUBBER GUIDE STOPPER		2	6.00	12.00 ✗
REAR RH DOOR STEP GARNISH		1	35.00	35.00 ✗
REAR RH DOOR STEP GARNISH CLIPS		3	6.50	19.50 ✗

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
 7 DAIRY FARM HEIGHT #10-13
 SINGAPORE 677669

Contact : 98579363, 93212348

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

REAR RH DOOR SWITCH	1	18.00	18.00	+
REAR RH DOOR WEATHER STRIP	1	109.40	109.40	+
REAR RH DOOR WIRE HARNESS - SET	1	110.00	110.00	+
REAR RH EXHAUST ALUMINIUM HEAT SHIELD	1	31.50	31.50	✓
REAR RH EXHAUST END CHROME PIPE	1	89.70	89.70	✓
REAR RH EXHAUST GASKET	1	13.60	13.60	✓
REAR RH EXHAUST RUBBER MOUNTING	3	10.80	32.40	+
REAR RH EXHAUST SILENCER BOX	1	906.40	906.40	✓
REAR RH FENDER	1	841.30	841.30	✓
REAR RH FENDER AIRCON AIR DUCT	1	65.00	65.00	+
REAR RH FENDER AIRCON COOLING PIPE	1	220.10	220.10	+
REAR RH FENDER AIRCON DISCHARGE PIPE	1	248.10	248.10	+
REAR RH FENDER AIRCON EVAPORATOR UNIT	1	794.50	794.50	✓
REAR RH FENDER GLASS INNER GARNISH	1	105.00	105.00	✓
REAR RH FENDER GLASS INNER GARNISH CLIPS	6	6.50	39.00	+
REAR RH FENDER GLASS WITH MOULDING ASSY	1	534.60	534.60	+
REAR RH FENDER INNER PANEL	1	558.00	558.00	+
REAR RH FENDER INNER SHIELD	1	105.10	105.10	✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SHAJAHAN S/O PEER MOHD
 7 DAIRY FARM HEIGHT #10-13
 SINGAPORE 677669

Contact : 98579363, 93212348

ESTIMATE

Repair Code : CLM13658

Date in : 14/08/2016

Vehicle Num. : SLC2858X

Model : HONDA ODYSSEY 2.4 A

Chassis/Eng# : JHMRB18508C204116/K24A65004116

REAR RH FENDER INNER TRIM BOARD <i>del</i>	1	455.70	455.70 ✓
REAR RH FENDER PROTECTOR <i>new</i>	1	19.00	19.00 ✓
REAR RH SUB CHASSIS FRAME <i>new</i>	1	1150.00	1,150.00 ✓
REAR RH WHEEL HOUSE PANEL ASSY <i>new</i>	1	690.00	690.00 ✓
REAR TAILGATE <i>Distorted</i>	1	1072.50	1,072.50 ✓
REAR TAILGATE 3RD BRAKE LAMP <i>del</i>	1	340.40	340.40 ✓
REAR TAILGATE DAMPER L/R <i>new</i>	2	107.90	215.80 ✓
REAR TAILGATE HINGES L/R <i>new</i>	2	34.60	69.20 ✓
REAR TAILGATE INNER HANDLE <i>new</i>	1	93.90	93.90 ✓
REAR TAILGATE INNER TRIM BOARD <i>del</i>	1	198.80	198.80 ✓
REAR TAILGATE MECHANISM LOCK <i>new</i>	1	165.60	165.60 ✓
REAR TAILGATE NUMBER PLATE LAMP COVER L/R <i>del</i>	2	12.00	24.00 ✓
REAR TAILGATE NUMBER PLATE LAMP L/R <i>del</i>	2	50.70	101.40 ✓
REAR TAILGATE OUTER CHROME GARNISH <i>del</i>	1	756.80	756.80 ✓
REAR TAILGATE OUTER CHROME GARNISH CLIPS <i>new</i>	6	6.50	39.00 ✓
REAR TAILGATE OUTER GARNISH <i>del</i>	1	425.30	425.30 ✓
REAR TAILGATE OUTER LOCK HANDLE <i>new</i>	1	53.40	53.40 ✓
REAR TAILGATE REFLECTOR LAMP CLIPS L/R <i>new</i>	2	6.50	13.00 ✓

*** This is a computer-generated document which requires no signature.***