

Your Ref : YL3958H  
Our Ref : 140924/12

**M/s Bukit Batok Driving Centre Ltd**

Postal Address :  
Blk 34 Sin Ming Drive  
#01-114  
Singapore 575708

Date : 16.08.2018

AXA Insurance Singapore Pte Ltd  
Motor Claims Dept  
8 Shenton Way  
#27-01 AXA Tower  
Singapore 068811

Dear Sir/Madam

**ACCIDENT INVOLVING SJR7550U AND YL3958H ALONG SLIP ROAD OF BUKIT  
BATOK ROAD ON 20.12.2014.**

---

I am the owner of the m/vehicle SJR7550U which was involved  
in the above accident.

My vehicle sustained damages as a result of the said accident and  
I am now claiming against you for the followings:-

1. Costs of repairs	.. .. .	\$ 9,844.00
2. Loss of use of vehicle at \$200.00 per day for 14 day(s)	.. .. .	\$ 2,800.00
3. Police documents/Search fees	.. .. .	\$ 2.00
4. Surveyor report fee	.. .. .	\$ -
	Total:	\$ 12,646.00
		=====

Please advise whether you are prepared to settle my claim as  
outlined above. As I have yet to settle my repair bill with my  
repairers, I hereby authorise my repairers and/or their  
representatives to negotiate/compromise settlement of above claim  
on my behalf.

Looking forward to hear from you soon.

Yours faithfully,



encl.

# TAX CLAIM INVOICE



CO. REG. NO: 199402370D  
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6454 9575

Email: service@kkinhin.com.sg

NO: 120872

Accident Date : 20-Dec-2014

Date : 16-Aug-2016

Our Ref : 140924 / ANGIE

PAGE : 1

BUKIT BATOK DRIVING CENTRE LTD  
C/O AXA INSURANCE SINGAPORE PRIVATE LIMITED  
8 SHENTON WAY  
#27-01 AXA TOWER  
Singapore 068811

FINAL REPAIR BILL FOR HONDA JAZZ 1.3L AT (2009) SJR7550U  
=====

To supply spare parts

To remove, cut out damaged parts,  
panel beating, welding, align,  
refix and to renew affected parts.

To remove and renew rear windscreen  
glass and conduct water leak test.

To remove and refit rear upholstery  
trimming, roof lining, seats,  
speaker board in order to  
facilitate repairing works

To check and realignment on chassis  
member.

To apply undersealing

To remove and renew exhaust  
silencer box

To transfer tailgate's fittings

Con't Page 2 ...



CO. REG. NO: 199402370D  
GST NO: M2-0123250-3

AUTO PTE LTD

**金興(龔)汽車私人有限公司**

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

Our Ref : 140924

Page : 2

No. : 21976

To remove and refit petrol/diesel  
tank in order to facilitate  
repairing works.


To putty and respray on affected  
portions.

To focus taillamps. To check rear  
wiring and lighting operation.

	9,200.00
Add 7% GST :	644.00
Total :	S\$ 9,844.00
	=====

Singapore Dollars Nine Thousand Eight Hundred  
and Forty Four Only

金興(龔)汽車私人有限公司  
K. KIM HIN AUTO PTE LTD



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF  
SINGAPORE  
RECORDS MANAGEMENT CENTRE**

10 Anson Road, #06-16 International Plaza, Singapore 079903

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-14-116698

Date of Request: 22/12/2014

Your Ref No: Online Purchase

K Kim Hin Auto Pte Ltd  
Blk 34, #01-114  
Sin Ming Drive  
Singapore 575708

Dear Sir/Madam,

Enquiry Date 22/12/2014

Enquiry By Jane

TP Vehicle No. YL3958H

Accident Date 20/12/2014

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
YL3958H	AXA Insurance Singapore Pte Ltd	19/05/2014-18/05/2015	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF  
SINGAPORE  
RECORDS MANAGEMENT CENTRE**

10 Anson Road, #06-16 International Plaza, Singapore 079903

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-14-116698

Date of Request: 22/12/2014

Your Ref No: Online Purchase

K Kim Hin Auto Pte Ltd  
Blk 34, #01-114  
Sin Ming Drive  
Singapore 575708

Dear Sir/Madam,

Enquiry Date 22/12/2014

Enquiry By Jane

TP Vehicle No. YL3958H

Accident Date 20/12/2014

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Letter of Authorization

To Whom It May Concern

Accident on 20th December 2014 involving SJR7550U and YL3958H

Along Slip Road of Bukit Batok Road

I/We Bukit Batok Driving Centre Ltd NRIC NO. 198801155R of

815 Bukit Batok West Ave 5 S(659085)

owner of Motor Vehicle Registration No. SJR7550U insured by

NTUC INCOME INSURANCE CO-OPERATIVE under Policy No. 0073346186-10

do hereby authorize M/s K. Kim Hin Auto Pte Ltd as my/our  
representative with full authority to write, negotiate and settle claim for damages on my/our  
behalf against the owner and /or driver of Motor Vehicle Regn No. YL3958H  
in regard to the above mentioned accident

I /We also consent to the agreed settlement sum be made in favour of my/our representative,  
M/s K. Kim Hin Auto Pte Ltd and the said  
payment be forwarded to them to be construed as full and final discharge of my/our claim.

BUKIT BATOK DRIVING CENTRE LTD  
815 BUKIT BATOK WEST AVENUE 5  
SINGAPORE 659085  
TEL: 6561 1233 FAX: 6569 0777



Owner's Signature & Company Stamp

16.08.2016

Date