

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 342Y - CHINA**ROEL***Not Authorised*
8

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 342Y - ROEL

VF1ABL15AUC282195

RENAULT

LATITUDE

20.08.16

CHINA**PART****LIST**

1	1	BUMPER COVER FRT	\$	Sn 968.78 ✓
2	1	BUMPER RETAINER FRT LH	\$	Sn 116.47 ✓
3	1	BUMPER BRACKET FRT LH	\$	R 139.81 ✓
4	1	HEADLAMP LH	\$	Sn 911.10 X
5	1	AIR CLEANER LOWER	\$	Sn 271.26 ✓
6	1	AIR CLEANER HOSE	\$	Sn 58.57 X
7	1	LOWER ARM LH	\$	Sn 527.51 X
8	1	KUNCKLE ARM LH	\$	Sn 651.53 X
9	1	KUNCKLE HUB+BEARING LH	\$	R 382.84 ✓
10	1	ABSORBER FRT LH	\$	Sn 277.34 X
11	1	FENDER PANEL FRT LH	\$	B 602.95 ✓
12	1	FENDER WHEELARCH FRT LH (Linner)	\$	Sn 107.33 X
13	1	DOOR FRT LH	\$	B 2,188.20 ✓
14	1	DOOR HINGE UPPER LH	\$	R 211.15 X
15	1	DOOR HINGE LOWER LH	\$	R 231.19 X
16	1	DOOR CHECK FRT LH	\$	Sn 149.83 X
17	1	DOOR LOCK FRT LH	\$	699.04 ?
18	1	DOOR CATCH FRT LH	\$	R 100.95 X
19	1	DOOR HANDLE OUTER FRT LH	\$	Det Sn 198.55 ✓
20	1	DOOR HANDLE CAP FRT LH	\$	Det 20.34 ✓
21	1	DOOR HANDLE SEAL FRT LH	\$	Sn 6.07 X
22	1	DOOR HANDLE COVER FRT LH	\$	Sn 10.17 X
23	1	DOOR HANDLE MODULE FRT LH	\$	Sn 102.77 X
24	1	DOOR REGULATOR FRT LH	\$	388.61 ?
25	1	DOOR REGULATOR MOTOR FRT LH	\$	612.66 ?
26	1	DOOR REGULATOR GUIDE FRT LH	\$	Sn 93.05 X
27	1	DOOR FINISHER FRT LH	\$	Sn 396.20 X
28	1	DOOR MOULDING FRT LH	\$	Sn 136.01 X
29	1	DOOR GRAB HANDLE FRT LH	\$	Sn 162.27 X
30	1	DOOR CASING FRT LH (door inner trim)	\$	Sn 967.35 X
31	1	DOOR GLASS FRT LH	\$	Sn 462.99 X
32	1	DOOR MIRROR LH	\$	C 1,141.08 ✓
33	1	DOOR WHETHERSTRIP FRT LH	\$	Sn 364.78 X
34	1	DOOR SEAL FRT LH	\$	Sn 52.83 ✓

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 342Y - CHINA

35	1	ROCKER PANEL OUTER LH	\$	R 759.61 X
36	1	DOOR REAR LH	\$	B 2,188.20 ✓
37	1	DOOR HINGE UPPER LH	\$	R 211.15 X
38	1	DOOR HINGE LOWER	\$	R 231.19 X
39	1	DOOR SEAL RR LH	\$	Sn 52.83 X
40	1	DOOR GLASS RR LH	\$	Sn 462.99 X
41	1	DOOR HANDLE OUTER REAR LH	\$	Sn 97.31 ✓
42	1	DOOR HANDLE CAP REAR LH	\$	Sn 20.34 ✓
43	1	DOOR HANDLE SEAL REAR LH	\$	Sn 6.07 X
44	1	DOOR HANDLE COVER REAR LH	\$	Sn 10.17 X
45	1	DOOR HANDLE MODULE REAR LH	\$	Sn 102.77 X
46	1	FENDER FINISHER COVER REAR LH	\$	Sn 271.22 X
47	1	FENDER PANEL REAR LH	\$	B 2,537.80 ✓
48	1	FENDER WHEELARCH REAR LH (Linner)	\$	Sn 418.06 X
49	1	BUMPER COVER REAR	\$	R 852.66 X
50	1	BUMEPR BRACKET SIDE LH REAR(Taillamp lov	\$	Sn 104.59 X
51	1	BUMEPR RETAINER LH REAR	\$	Sn 34.61 X

TOTAL	\$	22,073.15
10%	\$	2,207.32
	\$	19,865.84

Special Nett

1	1SET	WHEELARCH CLIP FRT LH	\$	nn 66.00 X
2	1SET	FRONT BUMPER CLIP	\$	nn 66.00 X
3	1	RIM LH FRT	\$	Sn 385.00 X
4	1	TYRE LH FRT	\$	Sn 330.00 X
5	1	DOOR CASING FRT CLIP LH (door inner trim)	\$	nn 45.00 X
6	1	DOOR STICKER "Trans-cab"	\$	nn 80.00 60sn
7	1	DOOR STICKER "Classic"	\$	nn 30.00 15sn
8	1	DOOR STICKER "6555-3333"	\$	nn 80.00 60sn
9	2	Rear Windscreen Sealant	\$	nn 100.00 40sn
10	1	Rear Windscreen Inner Sponge Seal	\$	nn 150.00 30sn
11	1SET	WHEELARCH CLIP RR	\$	nn 15.00 X
12	1	RIM LH RR (spare change)	\$	Sn 385.00 X
13	1	TYRE LH RR (spare change)	\$	Sn 330.00 X
14	1SET	WHEELARCH CLIP RR LH	\$	nn 66.00 X
15	1	FENDER FINISHER COVER CLIP REAR LH	\$	nn 20.00 X
16	1SET	REAR BUMPER CLIP	\$	nn 66.00 X
17	1SET	BUMEPR RETAINER LH CLIP RR	\$	nn 20.00 X

TOTAL	\$	2,234.00
TOTAL PARTS	\$	22,099.84

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 342Y - CHINA

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	5,400.00	1000/
To Check Electrical Lighting Concerned.	\$	170.00	20/
Putty and spray painting of the affected portion.	\$	5,600.00	1200/
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	100/
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
Towing fees	\$	120.00	50/
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	120/
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	120/
To rust-proofing of the affected areas.	\$	170.00	120/

TOTAL	\$	13,160.00
Over All Total	\$	35,259.84

(PARTS BY PARTS) Repair Days

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15 Days

7 days