

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5113P - III**Candy***Not Authorised*
8

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5113P - Candy

VF1ABL15AUC276214

RENAULT

LATITUDE

24.08.16

III**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Buckin</i> 968.79	✓
2	1	BUMPER SPOILER FRT	\$	<i>Sm</i> 139.81	X
3	1	BUMPER ABSORBER FRT	\$	<i>CRA</i> 303.60	✓
4	1	BUMPER RETAINER FRT LH	\$	<i>Div</i> 116.47	✓
5	1	BUMPER SUPPORT FRT LH(Headlamp lower)	\$	<i>Sm</i> 18.37	X
6	1	BUMPER RETAINER FRT RH	\$	<i>Div</i> 115.98	✓
7	1	BUMPER SUPPORT FRT RH(Headlamp lower)	\$	<i>Sm</i> 18.37	X
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sm</i> 363.71	X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Sm</i> 205.23	X
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sm</i> 159.39	X
11	1	BUMPER BEAM FRT	\$	703.14	✓
12	1	RADAI TOR GRILLE	\$	<i>mg</i> 1,313.68	✓
13	1	RADAI TOR GRILLE BADGE 'RENAULT'	\$	<i>Sm</i> 173.36	✓
14	1	RADAI TOR GRILLE FRAME	\$	<i>CRA</i> 1,041.35	✓
15	1	FRAME FULL SUPPORT PANEL	\$	<i>CRA</i> 473.77	✓
16	1	HEADLALMP LH	\$	<i>CRA</i> 911.10	✓
17	1	HEADLALMP RH	\$	<i>mg</i> 911.10	✓
18	1	BONNET	\$	<i>B</i> 1,493.56	✓
19	1	FENDER PANEL FRT LH	\$	<i>R</i> 602.95	X
20	1	FENDER PANEL FRT RH	\$	<i>R</i> 602.95	X
21	1	FENDER WHEELARCH FRT LH (Linner)	\$	<i>Sm</i> 107.32	X
22	1	FENDER WHEELARCH FRT RH (Linner)	\$	<i>Sm</i> 214.49	X
23	1	RADIATOR	\$	<i>Sm</i> 924.77	X
24	1	AIR CLEANER HOSE	\$	<i>Sm</i> 58.57	X
25	1	AIR CLEANER LOWER	\$	<i>Sm</i> 311.95	X
26	1	ENGINE UNDERTRAY	\$	<i>Sm</i> 434.60	X
27	1	A/C CONDENSER	\$	<i>Sm</i> 1,554.13	X
28	1	TRANSMISSION COOLER	\$	<i>Sm</i> 852.66	X
29	1	STEERING PUMP ELECTRIC	\$	<i>Sm</i> 1,543.08	X
30	1	BUMPER COVER REAR	\$	<i>Bu</i> 852.66	✓
31	1	BUMPER BRACKET CTR REAR	\$	<i>Sm</i> 87.29	X
32	1	BUMEPR BRACKET SIDE LH REAR (Taillamp low	\$	<i>Sm</i> 34.61	X
33	1	BUMEPR RETAINER LH REAR	\$	<i>Sm</i> 104.59	X
34	1	BUMEPR BRACKET SIDE RH REAR (Taillamp low	\$	<i>Sm</i> 34.61	X

TRANS-CAB AUTO SERVICES PTE LTD**Candy**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5113P - III

35	1	BUMEPR RETAINER RH REAR	\$	Sn	104.59 X
36	1	BUMPER LOWER REAR	\$	Sn	591.41 X
37	1	BUMPER BEAM REAR	\$	R	598.08 X
38	1	BUMPER BEAM BRACKET LH REAR	\$	R	173.81 X
39	1	BUMPER BEAM BRACKET RH REAR	\$	R	173.81 X
40	1	BUMPER REFLECTOR LH	\$	Sn	33.55 X
41	1	BUMPER REFLECTOR RH	\$	Sn	33.55 X
42	1	BOOT REAR	\$	R	2,209.75
43	1	BOOT FINISHER (Moulding)	\$	Sn	361.58
44	1	BOOT LOCK	\$	R	155.90
45	1	BOOT LOCK CATCH	\$	R	57.23
46	1	BOOT WHEATERSTRIP	\$	Sn	248.50
47	1	BOOT REFLECTOR LAMP LH	\$	R	379.50
48	1	BOOT REFLECTOR LAMP RH	\$	Sn	379.50
49	1	BOOT BADGE 'RENAULT'	\$	nn	173.35
50	1	BOOT BADGE	\$	nn	173.35
51	2	LICENCE PLATE LAMP	\$	Sn	84.00
52	2	BOOT RUBBER PLUG	\$	Sn	170.63
53	1	TAILLAMP LH	\$	CPT	425.04
54	1	TAILLAMP RH	\$	CPT	425.04
55	1	FENDER PANEL REAR LH	\$	R	2,537.80 X
56	1	FENDER PANEL REAR RH	\$	R	2,537.80 X
57	1	FENDER WHEELARCH REAR LH (Linner)	\$	Sn	418.06 X
58	1	FENDER WHEELARCH REAR RH (Linner)	\$	Sn	418.06 X
59	1	OUTER PANEL REAR (End Panel)	\$	R	1,132.13 X
60	1	OUTER PANEL REAR (End Panel)TRIM	\$	Sn	308.48 X
61	1	EXHAUST REAR	\$	R	5,760.00 X
62	1	EXHAUST CAP REAR	\$	R	177.30 X

TOTAL	\$	37,993.79
10%	\$	3,799.38
	\$	34,194.41

Specical Nett

1	1SET	RADAITOR GRILLE FRAME CLIP	\$	nn	52.00 ✓
2	1SET	BUMPER CLIP FRT	\$	nn	66.00 ✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	nn	12.00 X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	nn	10.50 X
5	1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00 X
6	1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50 X
7	1	TOW COVER FRT	\$	Sn	14.50 X
8	1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00 X
9	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00 X

TRANS-CAB AUTO SERVICES PTE LTD**Candy**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5113P - III

10	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	X
11	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
12	1SET	WHEELARCH CLIP FRT LH	\$	na	30.50	X
13	1SET	WHEELARCH CLIP FRT RH	\$	na	29.40	X
14	1SET	BUMPER RR RIVET	\$	na	28.60	X
15	1SET	BUMPER RR CLIP	\$	na	66.00	—
16	1SET	BUMPER BEAM BOLT	\$	na	22.22	X
17	1SET	REFLECTOR SCREW LH	\$	na	25.00	X
18	1SET	PARKING AID	\$	na	600.00	X
19	1	BUMPER BRACKET CLIP CTR REAR	\$	na	15.00	X
20	1	BUMEPR BRACKET SIDE CLIP LH REAR	\$	na	12.00	X
21	1	BUMEPR RETAINER CLIP LH REAR	\$	na	10.40	X
22	1	BUMEPR BRACKET SIDE CLIP RH REAR	\$	na	12.00	X
23	1	BUMEPR RETAINER CLIP RH REAR	\$	na	10.40	X
24	1SET	WHEELARCH CLIP LH RR	\$	na	32.34	X
25	1SET	WHEELARCH CLIP RH RR	\$	na	32.34	X
26	1SET	BOOT FINISHER CLIP	\$	na	25.10	X
27	1	Rear boots sticker "trans-cab"	\$	na	30.00	X
28	1	Rear boots sticker "6555-3333"	\$	na	30.00	X
29	1	EXHAUST MOUNTING REAR	\$	na	65.50	X
30	1	EXHAUST BRACKET REAR	\$	na	22.22	X

TOTAL	\$	1,465.52
TOTAL PARTS	\$	35,659.93

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 *Boof*

To apply paint protection system (PPS) maintain and enhancement

\$ na 380.00 X

Putty and spray painting of the affected portion.

\$ 2,700.00 *301*

To rust-proofing of the affected areas.

\$ 170.00 *301*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ na 380.00 X

To check steering geometry and computer wheel alignment

\$ na 220.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5113P - III**Candy**

To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To check ABS brake efficiency, final checking and testing.	\$	<i>nn</i> 380.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>301</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 280.00 <i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>

TOTAL	\$	8,330.00
Over All Total	\$	43,989.93

< parts by parts > Repair Days

10 DAYS*5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____