

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHD 9653R - CHINA

ROEL

Not Authored
1/1/98

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 9653R - ROEL
KL1LA69RJB101600
CHEVROLET
CHEVROLET EPICA 2.0
05.09.16
CHINA

		PART	LIST	
1	1	Front Bumper	\$	Bu 1,202.00 ✓
2	1	Front Bumper Lower Absorber	\$	SL 180.00 X
3	1	Front Bumper Reinforcement	\$	R 356.00 X
4	1	Front Bumper Retainer RH	\$	Dis 102.00 ✓
5	1	Front Bumper Retainer LH	\$	SL 102.00 X
6	1	Front Bumper Lower Grille	\$	SL 78.00 X
7	1	Front Bumper Lower Stiffener	\$	R 134.37 X
8	1	Bumper Fog Lamp Cover RH	\$	SL 32.40 X
9	1	Front Headlamp RH	\$	Bu 816.00 ✓
10	1	Front Fender RH	\$	Bu 837.60 ✓
11	1	Front Fender Liner RH	\$	CM 47.00 ✓
12	1	Bonnet	\$	Bu 1,250.00 ✓
13	1	Bonnet Moulding	\$	Dis 161.97 ✓
14	1	Bonnet hinge RH	\$	R 36.00 X
15	1	Bonnet hinge LH	\$	R 36.00 X
16	1	Front Support Panel Assy	\$	Bu 1,222.32 ✓
17	1	Windscreen Washer Tank - Filler Neck	\$	SL 4.80 X
18	1	Windscreen Washer Tank	\$	SL 62.00 X
19	1	Windscreen Washer Tank Motor	\$	SL 51.00 X
20	1	Radiator Grille (Grille A-Rad)	\$	SL 367.00 X
21	1	Front Shock Absorber Assy RH	\$	216.17 7
22	1	Front Lower Arm RH	\$	283.00 7
23	1	Front Knuckle Arm RH	\$	230.00 7
24	1	Front Stabilizer Bar Link RH	\$	SL 51.79 X
25	1	Drive Shaft RH	\$	R 900.00 X
26	1	Radiator Assembly	\$	SL 618.00 X
27	1	Aircon Condenser	\$	SL 600.00 X
28	1	Horn Unit (High Tone)	\$	SL 53.46 X
29	1	Air Intercooler	\$	SL 652.00 X
30	1	Front Door RH	\$	R 1,133.00 X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHD 9653R - CHINA

ROEL

31 1 Front Side View Mirror RH

\$ 939.00 X

TOTAL	\$	12,754.88
10%	\$	1,275.49
	\$	11,479.39

Special Nett

1 1 Set Front Bumper Fastener Clip
 2 1 Set Front Fender Liner Clip RH
 3 1 Front Wheel Rim Hub Cap RH
 4 1 Front Tyre RH
 5 1 Front Tyre Rim RH
 6 1 Door Sticker "Trans-cab" RH

\$ 30.00 ✓
 \$ 30.00 ✓
 \$ 166.30 X
 \$ 180.00 ?
 \$ 126.00 505m
 \$ 80.00 X

TOTAL	\$	612.30
TOTAL PARTS	\$	12,091.69

Panel Beating, Knocking And Straightening The
 Necessary Portion, Remove And Renewal Of
 Parts, Adjust And Realign The Same

\$ 2,800.00 600

To Rust-Proofing Of The Affected Areas.

\$ 220.00 60

Putty and Spray Painting Of The Affected
 Portion.

\$ 2,700.00 200

To Check Electrical Lighting Concerned.

\$ 170.00 20

To check steering geometry and computer wheel
 alignment

\$ 220.00 60

To dismantle and refit front end suspension,
 undercarriage parts, final checking and testing.

\$ 380.00 ?

Towing Fees.

\$ 120.00 X

To transfer of tire, rim and on wheel balancing.

\$ 170.00 20

TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO ST 63 SINGAPORE 569111
TEL NO.6287 6666 FAX NO.6257 1330
CO/GST REG NO.201019626G
SHD 9653R - CHINA

ROEL

TOTAL	\$	6,780.00
Over All Total	\$	18,871.69

REPAIR DAYS

~~10 DAYS~~

4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: