

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5860R - AIG**ROEL***Not Noted*
8

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5860R - ROEL

VF1ABL15AUC281455

RENAULT

LATITUDE

07.09.16

AIG

		PART		LIST
1	1	BUMPER COVER FRT	\$	<i>R</i> 968.78 X
2	1	BUMPER ABSORBER FRT	\$	<i>S</i> 303.60 X
3	1	BUMPER BEAM FRT	\$	<i>R</i> 703.14 X
4	1	BUMPER SPOILER FRT	\$	<i>S</i> 139.81 X
5	1	BUMPER FOG LAMP GRILLE RH	\$	<i>S</i> 159.40 X
6	1	BUMPER RETAINER FRT RH	\$	<i>S</i> 116.47 X
7	1	BUMPER SUPPORT FRT RH	\$	<i>S</i> 18.37 X
8	1	BUMPER UNDERTRAY FRT	\$	<i>S</i> 363.71 X
9	1	LOWER ARM RH	\$	527.51 7
10	1	KUNCKLE ARM RH	\$	651.53 7
11	1	ABSORBER FRT RH	\$	277.34 7
12	1	WIPER RESERVOIR	\$	<i>S</i> 173.60 X
13	1	WIPER RESERVOIR MOTOR	\$	<i>S</i> 91.78 X
14	1	BONNET	\$	<i>R</i> 1,493.56 X
15	1	RADAITOR GRILLE	\$	<i>S</i> 1,313.68 X
16	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>rr</i> 173.36 X
17	1	RADAITOR GRILLE FRAME	\$	<i>S</i> 1,041.35 X
18	1	FRAME FULL SUPPORT PANEL	\$	<i>S</i> 473.77 X
19	1	HEADLAMP RH	\$	<i>S</i> 911.10 X
20	1	FENDER PANEL FRT RH	\$	<i>R</i> 602.95 ✓
21	1	FENDER WHEELARCH FRT RH	\$	<i>S</i> 107.33 X
22	1	DOOR MIRROR RH	\$	<i>S</i> 1,141.08 X
23	1	DOOR FRT RH	\$	<i>R</i> 2,188.20 X

TOTAL	\$	13,941.41
10%	\$	1,394.14
	\$	12,547.27

Specical Nett

1	1SET	FRONT BUMPER CLIP	\$	<i>rr</i> 66.00 X
2	1SET	WHEELARCH CLIP RH	\$	<i>rr</i> 66.00 X
3	1	TOW COVER FRT	\$	<i>S</i> 14.50 X
4	1	CAP HUB RH FRT	\$	<i>R</i> 35.00 ✓
5	1	RIM RH FRT	\$	<i>S</i> 385.00 X

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5860R - AIG

6	1	TYRE RH FRT	\$	330.00	X
7	1	DOOR STICKER "Trans-cab"	\$	80.00	X
8	1	DOOR STICKER "Classic"	\$	30.00	X
9	1SET	BUMPER SUPPORT FRT CLIP RH	\$	9.80	X
10	1SET	BUMEPR RETAINER FRT CLIP RH	\$	12.50	X

TOTAL	\$	1,028.80
TOTAL PARTS	\$	13,576.07

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 300/

To Check Electrical Lighting Concerned.

\$ 170.00 10/

Putty and spray painting of the affected portion.

\$ 3,000.00 400/

To check steering geometry and computer wheel alignment

\$ 220.00 60/

To transfer of tire, rim and on wheel balancing.

\$ 170.00 X

To rust-proofing of the affected areas.

\$ 170.00 30/

To transfer of door fittings, attachment and perform water seepage test.

\$ 170.00 X

TOTAL	\$	6,700.00
Over All Total	\$	20,276.07

(PARTS BY PARTS) Repair Days**10 Days**

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: