

ASS. REC. BY:

REF: AG1Kenneth**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Now excel

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 33-35K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 09 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: S77 4833MYr Regn: 10, 09Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy ViosC.C. 1497Colour M. Silver

A/C: Insured / Std / NI / NA

Sp. Reading 198064

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR 053144 9305732248Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 5 mmR/Bal. 6 mmL/Bal. 5 mmL/Bal. 6 mmD.O.A. 12/9/16D.O.I. 15/9/16

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/9Est not ready16/9File pass to Parkson\$7,250/-R (\$5,676.55 / 447)

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

NEW AUTO SPEC APPRAISAL

25 Moonstone Lane #10-02 Singapore 328465

Annex A: Adjustment on Spare Parts

S/No	Qty	Vehicle Parts Description	Condition	Workshop Estimate Before Discount (S\$)	Recommendation (S\$)
1	1	Bootlid	Dented	510.25	510.25
2	1	Bootlid Centre logo	Cracked	61.00	61.00
3	1	Bootlid E emblem	Cracked	58.00	58.00
4	1	Bootlid Vios emblem	Cracked	58.00	58.00
5	1	Bootlid outer moulding assy	Missing	482.50	482.50
6	1	Bootlid lower lock	Dented	89.50	89.50
7	1	Bootlid weatherstrip	Tear	185.60	185.60 <i>50% off</i>
8	2	Bootlid hinges	Bent	180.00	180.00 <i>X</i>
9	2	Taillamps	Cracked	770.40	770.40
10	2	Taillamp panels	Dented	440.00	440.00 <i>2x</i>
11	2	Taillamp clips	Cracked	20.00	20.00
12	1	Rear fenders	Repair	1,640.00	0.00
13	1	Rear fender RH	Bent	820.00	820.00 <i>20% off</i>
14	2	Rear fender inner side trims	Tear	773.00	773.00
15	2	Rear fender undershields	Tear	196.00	196.00
16	1	Rear bumper	Tear	415.60	415.60
17	10	Rear bumper clips	Cracked	35.00	35.00
18	2	Rear bumper side retainers	Cracked	120.00	120.00
19	2	Rear bumper reflectors	Cracked	282.00	282.00
20	1	End panel	Dented	568.90	568.90
21	1	End panel top garnish	Cracked	198.60	198.60
22	1	End panel top latch	Bent	65.00	65.00
23	1	Spare tyre panel	Dented	648.50	648.50
24	1	Spare tyre top board	Cracked	285.00	285.00
25	2	Spare tyre side trays	Cracked	884.00	884.00 <i>X</i>
26	2	Spare tyre side boards	Cracked	448.60	448.60
27	1	Rear exhaust silencer	Dented	689.60	689.60 <i>10% off</i>
TOTAL :				10,925.05	9,285.05
less market discount 10%				1,092.51	928.51
				9,832.55	8,356.55
Special Nett Items					
1	1 set	Reverse sensor	Cracked	280.00	280.00 <i>20% off</i>
2	1	Rear exhaust chrome	Dented	140.00	140.00
TOTAL:				420.00	420.00
TOTAL FOR SPARE PARTS :				10,252.55	8,776.55

NEW AUTO SPEC APPRAISAL


25 Moonstone Lane #10-02 Singapore 328465

Annex B: Adjustment on Labour and Spray Painting

Item	Job Description	Workshop Quote (\$)	Adjusted cost (\$)
1	Labour charges for body repair , replace parts etc	2,200.00	1,400.00 1000/
2	To putty and spray painting on affected areas	2,400.00	1,600.00 1200/
3	Anti rust	200.00	100.00 60/
4	Sealant seal gap , water proofing welding area	280.00	150.00 30/
5	To replace rear exhaust	200.00	100.00 60/
6	Check wiring , replace sensor	200.00	100.00 50/
7	Remove and refix roof lining, carpets, seat cushion, garnishes and etc	380.00	250.00 120/
8	To do rear chassis body alignment	500.00	nw 350.00 X
9	Transfer bootlid parts to another bootlid	200.00	100.00 50/
TOTAL FOR LABOUR & SPRAY PAINTING :		6,560.00	4,150.00
Summary			
TOTAL FOR SPARE PARTS :		10,252.55	8,776.55
TOTAL FOR LABOUR & SPRAY PAINTING :		6,560.00	4,150.00
TOTAL REPAIR COSTS :		16,812.55	12,926.55

Vehicle Surveyed By:

J. day


Ng Ching Chye
New Auto Spec Appraisal



Logout

- Pre repair inspection request - SJT4833M VS SGP837K (OI) DOA 12/9/2016

From: BernardJiQian.Ler@aig.com
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Kristelli.Lopez@chartisinsurance.com, Lily.Tan@aig.com, Andy-SY.Fong@aig.com, KahYin.Leong@aig.com, Kunaseelan.Deivaseelan@aig.com, MingYao.Lee@aig.com, Baljit.L
Sent: Wednesday, 14 September, 2016 11:05:58 AM
Attachments: AVIV-MARS00023287-SJT4833M-GIA.PDF

Hi,

Please refer to the enclosed request from **Autoexcel Engineering Pte Ltd.**

Claim no : 6372121767SG007
Case Owner : Bennie Tan

If you have any queries/concerns, please let us know.
Kindly assist to assign Henry Eng as Single Joint Expert as requested.

Thank you.

Best Regards,

Bernard Ler
AIG
Express Claims Adjuster II
Claims Operations | AIG Shared Services

Level 7, Menara Worldwide, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia.
Tel + 6 03 2719 6000 | Fax 1012123

BernardJiQian.Ler@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: aeexcel@singnet.com.sg
To: BernardJiQian.Ler@aig.com
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGP837K AND SJT4833M ON 12/9/2016
Date: Wed, 14 Sep 2016 02:57:50 +0000
Dear Officer in Charge

We wish to chose Henry Ng from LKK

Please help us arrange

Thank you

Regards
Ryan Soh 93825367 / 64535654

From: Ler, Bernard Ji Qian [mailto:BernardJiQian.Ler@aig.com]
Sent: Wednesday, September 14, 2016 10:31 AM
To: Autoexcel <aeexcel@singnet.com.sg>
Cc: Tan, Lily (AIG) <Lily.Tan@aig.com>; Lopez, Kristelli <Kristelli.Lopez@chartisinsurance.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Lee, Ming Yao <MingYao.Lee@aig.com>; Leong, Kah Yin <KahYin.Leong@aig.com>; Deivaseelan, Kunaseelan <Kunaseelan.Deivaseelan@aig.com>; Hassim, Mohd Fitri <MohdFitri.Hassim@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGP837K AND SJT4833M ON 12/9/2016

Your Reference : SJT4833M
Our Reference : 6372121767SG007

Dear Sir,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd

Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Logout

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards,

Bernard Ler
AIG
Express Claims Adjuster II
Claims Operations | AIG Shared Services

Level 7, Menara Worldwide, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel + 6 03 2719 6000 | Ext. 1012123

Bernard.JiQian.Ler@aig.com | www.AIG.com

From: Autoexcel ([mailto:autoexcel@singnet.com.sg])
Sent: Wednesday, September 14, 2016 10:08 AM
To: 'claims@sg.msig-asia.com' <claims@sg.msig-asia.com>
Cc: 'Ler, Bernard Ji Qian' <Bernard.JiQian.Ler@aig.com>
Subject: PRE REPAIR SURVEY FOR SJT 4833 M
Importance: High

Dear Officer,

Our vehicle : SJT 4833 M

Accident date : 12/09/2016

This is a chain collision and our customer SJT 4833M is the 1st vehicle.

3rd vehicle – EY 9988A (MSIG)

4th vehicle – SGP 837 K (AIG)

Kindly advise us if the 3rd vehicle or 4th coming for the pre repair survey.

Location : Autoexcel Engineering Pte Ltd
Block 19 Sector A Sin Ming Industrial Estate
01 – 05 Singapore 575677

Please help us arrange for surveyor.

Please also let us have the list of surveyor to appoint.

Thank you

Regards

Ryan Soh
Autoexcel Engineering Pte Ltd
Tel 93825367 , 64535654
Fax 64591698

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Vasanthi Rengiyan (LKKAUTO)

To: HSS_MSE HOTMAIL.COM.
Cc: Vic (LKKAUTO); Zayyer (LKKAUTO); Vasanthi Rengiyan (LKKAUTO)
Subject: YOUR REF: SGP837K _ ACCIDENT INVOLVING SGP 837K / SJT 4833M / OTHERS ON 12/09/2016

Our Ref: CC4/AIG16017230/Kza3

03 NOVEMBER 2016

MUHAMED SURESH BIN ZAINOL
914 JURONG WEST ST 91
#03-218
SINGAPORE 640914

Dear Sir/Madam,

ACCIDENT INVOLVING SGP 837K / SJT 4833M / OTHERS ON 12/09/2016

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Best Regards,

R.Vasanthi (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: Vasanthi@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Joy Irene (LKKAUTO)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Saturday, 13 April 2019 7:33 PM
To: Joy Irene (LKKAUTO)
Cc: Olivia Lau (LKKAUTO); Admin A
Subject: RE: Our Ref: 6372121767SG-007 || Accident Involving SGP837K / SJT4833M on 12/09/2016

Hi Joy

Please submit your W/P report to this matter.

Thanks.

Best Regards

Bennie Tan
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1718

Bennie-WZ.Tan@aig.com | www.aig.sg

From: Joy Irene (LKKAUTO) [mailto:JoyIrene@lkkauto.com]
Sent: Friday, April 12, 2019 9:04 AM
To: Tan, Bennie-WZ
Cc: Olivia Lau (LKKAUTO); Admin A
Subject: [EXTERNAL] RE: Our Ref: 6372121767SG-007 || Accident Involving SGP837K / SJT4833M on 12/09/2016

Caution: External Email

Hi Benny,

Can we proceed to submit our report in Meirmen?

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Tan, Bennie-WZ [mailto:Bennie-WZ.Tan@aig.com]
Sent: Thursday, 11 April 2019 11:16 PM

To: Joy Irene (LKKAUTO) <JoyIrene@lkkauto.com>

Cc: Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Our Ref: 6372121767SG-007 || Accident Involving SGP837K / SJT4833M on 12/09/2016

Hi Joy

Please be informed we have received developments from TP lawyer: Mathew Chew & Chelliah on matter.

We have responded to them accordingly with the inclusion of the other insurers.

Thank you.

Best Regards

Bennie Tan

AIG

Senior Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1718

Bennie-WZ.Tan@aig.com | www.aig.sg

From: Joy Irene (LKKAUTO) [<mailto:JoyIrene@lkkauto.com>]

Sent: Tuesday, April 09, 2019 3:02 PM

To: Tan, Bennie-WZ

Cc: Olivia Lau (LKKAUTO); Admin A

Subject: [EXTERNAL] RE: Our Ref: 6372121767SG-007 || Accident Involving SGP837K / SJT4833M on 12/09/2016

Caution: External Email

Dear Bennie,

There is no response from TP solicitors to our 10% contribution. Our last reminder sent to them was on 15/01/2019.

According to Mr. Ryan of Autoexcel, their solicitors are claiming against the Malaysian vehicle and would take a few years before settlement.

In view of indefinite time of waiting, we would like to close this 2016 claim file on wp.

In future, if there are any development, we will inform your accordingly for our further handling.

Please advise if we may proceed.

Thank you.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

MATHEW CHEW & CHELLIAH

advocates & solicitors ♦ commissioner for oaths ♦ notary public

397629

133 New Bridge Road #13-10 Chinatown Point Singapore 059413
Tel: (65) 6533-1123 Fax: (65) 6533-1121 (not for service of Court documents) Email: lawyers@mclegalfirm.com
UEN No: 53131184L

Our Ref LC/4825/17/SML3(A1)N
Your Ref SGP837K

26 January 2017

 **MOTOR CLAIMS DEPARTMENT (THIRD PARTY)**
AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way #09-16
Singapore 079120

**WITHOUT PREJUDICE
BY HAND**

MR MOHAMED SURESH BIN ZAINOL
Blk 914 Jurong West Street 91 #03-218
Singapore 640914

BY POST



Dear Sirs

CLAIMANT: SOON MIN LIANG, CASEY (SUN MINGLIANG, CASEY)
ACCIDENT INVOLVING SGT4833M & SGP837K ON 12-SEP-2016 AT 1230 HOURS
ALONG E LEBUH RAYA UTARA SELATAN, MALAYSIA


We act for Soon Min Liang, Casey (Sun Mingliang, Casey), the owner of car registration no SGT4833M.

We are instructed by the above-named to claim damages against you/your insured in connection with a road traffic accident on 12-Sep-2016 along E Lebuhraya Utara Selatan, Malaysia involving our client's car registration number SGT4833M and vehicle registration number SGP837K driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and/or management of your/your insured vehicle. As a result of the accident, our client's car was damaged and our client has been put to loss and expense.

We have been instructed to quantify our client's claim as follows:-

- (a) Cost of repairs (including GST)
- (b) Loss of Use (16 days x \$80.00)
- (c) Survey Report
- (d) GIA Search/Report
- (e) LTA search
- (f) Costs contribution (at this stage)
- (g) Incidentals
- TOTAL**



S\$
13,831.40
1,280.00
504.00
15.00
8.00
900.00
50.00
16,588.40

Handwritten notes: 720077 - 7757.40, 60x10 = 600, 400-550

Our client's repairer did notify you/your insurer of the accident for pre-repair inspection.

CONFIDENTIALITY: The information contained in this message is confidential information and is also subject to legal professional privilege. If you are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this document in error, please notify us immediately by fax or phone.

MATHEW CHEW & CHEL LAH

advocates & solicitors ❖ commissioner for oaths ❖ notary public

133 New Bridge Road #13-10 Chinatown Point Singapore 059413
Tel: (65) 6533-1123 Fax: (65) 6533-1121 (not for service of Court documents) Email: lawyers@mcclegalfirm.com
UEN No: 53131184L

We enclose hereto double-sided copies of the following for your consideration:-

- (a) Final Repair Bill;
- (b) Survey report together with invoice and receipt;
- (c) Traffic Police report of SJT4833M;
- (d) Traffic Police report of SGP837K;
- (e) Results of Police Investigation, sketch plan and photographs;
- (f) Client's NRIC and Driving Licence;
- (g) Client's Certificate of Insurance, policy schedule and Vehicle Registration;
- (h) LTA Search on SGP837K; and
- (i) Colour Survey photographs of SJT4833M.

For Owner

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter to your insurer. Please take note that copies of the documents in support have been enclosed to your insurer. If you require copies of the documents, please contact our office and furnish your email address to enable us to forward copies of the same to you. Alternatively, you may attend at the office of your insurance company to view the same.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within **14 days** of your receipt of this letter. If you or your insurers wish to have our client examined by your own medical expert, this should be stated in your acknowledgement of receipt.

Please also advise within **14 days** of the acknowledgement of receipt, where and when the examination of our client is to take place so that we may arrange for him to attend.

Should you fail to acknowledge the receipt of this letter within **14 days**, our client can commence court proceedings against you without further notice to you or your insurer.

Please do take note that if you have a counterclaim against our client arising out of the accident, you are required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 6 weeks of your receipt of this letter.

We suggest that communication be carried out by email correspondence. Our email address is lawyers@mcclegalfirm.com. Please confirm the name of your officer handling the file and his/her email address.

Yours faithfully



encs

CONFIDENTIALITY: The information contained in this message is confidential information and is also subject to legal professional privilege. If you are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this document in error, please notify us immediately by fax or phone.

AUTOEXCEL ENGINEERING PTE LTD

BLK 19, SECTOR A, SIN MING INDUSTRIAL ESTATE

01-05 SINGAPORE 575677

TEL : 64591630 FAX : 64591698

PHOTOCOPY

GST Reg. No. 19-9603355 R

DATE : 15/12/2016

INVOICE NO : TP 6057

TO : SOON MIN LIANG CASEY
 BLK 19, SIN MING INDUSTRIAL ESTATE
 SECTOR A #01-05
 SINGAPORE 575677

VEH NO : SJT 4833 M
 MODEL : TOYOTA
 VIOS

S/N	QTY / DESCRIPTION	AMOUNT
Accident Date : 12/09/2016		
1	1 BOOTLID	\$ 510.25
2	1 BOOTLID CENTRE LOGO	\$ 61.00
3	1 BOOTLID E EMBLEM	\$ 58.00
4	1 BOOTLID VIOS EMBLEM	\$ 58.00
5	1 BOOTLID OUTER MOULDING ASSY	\$ 482.50
6	1 BOOTLID LOWER LOCK	\$ 89.50
7	1 BOOTLID WEATHERSTRIP	\$ 185.60
8	2 BOOTLID HINGES	\$ 180.00
9	2 TAILLAMPS	\$ 770.40
10	2 TAILLAMP PANELS	\$ 440.00
11	2 TAILLAMP CLIPS	\$ 20.00
12	1 REAR FENDER	REPAIR
13	1 REAR FENDER RH	
14	2 REAR FENDER INNER SIDE TRIMS	\$ 820.00
15	2 REAR FENDER UNDERSHIELDS	\$ 773.00
16	1 REAR BUMPER	\$ 190.00
17	10 REAR BUMPER CLIPS	\$ 415.60
18	2 REAR BUMPER SIDE RETAINERS	\$ 35.00
19	2 REAR BUMPER REFLECTORS	\$ 120.00
20	1 END PANEL	\$ 282.00
21	1 END PANEL TOP GARNISH	\$ 568.90
22	1 END PANEL TOP LATCH	\$ 198.60
23	1 SPARE TYRE PANEL	\$ 65.00
24	1 SPARE TYRE TOP BOARD	\$ 648.50
25	2 SPARE SIDE TRAYS	\$ 285.00
26	2 SPARE TYRE SIDE BOARDS	\$ 334.00
27	1 REAR EXHUAUST SILENCER	\$ 448.60
		\$ 689.60
	TOTAL :	\$ 9,285.05
	LESS MARKET DISCOUNT 10% :	\$ 928.51
	TOTAL :	\$ 8,356.55
SPECIAL NETT ITEMS		
1	REVERSE SENSOR	\$ 280.00
2	REAR EXHUAUST CHROME	\$ 140.00
	TOTAL S/NETT :	\$ 420.00
	TOTAL PARTS :	\$ 8,776.55

PHOTOCOPY

AUTOEXCEL ENGINEERING PTE LTD

BLK 19, SECTOR A, SIN MING INDUSTRIAL ESTATE

01-05 SINGAPORE 575677

TEL : 64591630 FAX : 64591698

GST Reg. No. 19-9603355 R

DATE : 15/12/2016

INVOICE NO : TP 6057

TO : SOON MIN LIANG CASEY
BLK 19, SIN MING INDUSTRIAL ESTATE
SECTOR A #01-05
SINGAPORE 575677

VEH NO : SJT 4833 M

MODEL : TOYOTA
VIOS

S/N	DESCRIPTION	AMOUNT
	BALANCE B/F	\$ 8,776.55
	<u>LABOUR</u>	
1	Labour charges for bodyrepair, replace parts area.	\$ 1,400.00
2	To putty and spray painting on affected areas.	\$ 1,600.00
3	Anti rust	\$ 100.00
4	Sealant seal gap, water proofing welding area.	\$ 150.00
5	To replace rear exhaust	\$ 100.00
6	Check wiring , replace sensor.	\$ 100.00
7	Remove & refix roof lining, carpets, seat cushion, garnishes and etc.	\$ 250.00
8	To do rear chassis body alignment.	\$ 350.00
9	Transfer bootlid parts to another bootlid.	\$ 100.00
	TOTAL LABOUR :	\$ 4,150.00
	SUB - TOTAL :	\$ 12,926.55
	GST 7 % :	\$ 904.86
	TOTAL PARTS & LABOUR :	\$ 13,831.40

NOTE : All cheques must be crosses and make payable to Autoexcel Engineering Pte Ltd

RECEIVED VEHILCE IN GOOD ORDER

for Autoexcel Engineering Pte Ltd

NEW AUTO SPEC APPRAISAL

25 Moonstone Lane #10-02 Singapore 328465

Annex A: Adjustment on Spare Parts

S/No	Qty	Vehicle Parts Description	Condition	Workshop Estimate Before Discount (S\$)	Recommendation (S\$)
1	1	Bootlid	Dented	510.25	510.25
2	1	Bootlid Centre logo	Cracked	61.00	61.00
3	1	Bootlid E emblem	Cracked	58.00	58.00
4	1	Bootlid Vios emblem	Cracked	58.00	58.00
5	1	Bootlid outer moulding assy	Missing	482.50	482.50
6	1	Bootlid lower lock	Dented	89.50	89.50
7	1	Bootlid weatherstrip	Tear	185.60	185.60
8	2	Bootlid hinges	Bent	180.00	180.00
9	2	Taillamps	Cracked	770.40	770.40
10	2	Taillamp panels	Dented	440.00	440.00
11	2	Taillamp clips	Cracked	20.00	20.00
12	1	Rear fenders	Repair	1,640.00	0.00
13	1	Rear fender RH	Bent	820.00	820.00
14	2	Rear fender inner side trims	Tear	773.00	773.00
15	2	Rear fender undshields	Tear	196.00	196.00
16	1	Rear bumper	Tear	415.60	415.60
17	10	Rear bumper clips	Cracked	35.00	35.00
18	2	Rear bumper side retainers	Cracked	120.00	120.00
19	2	Rear bumper reflectors	Cracked	282.00	282.00
20	1	End panel	Dented	568.90	568.90
21	1	End panel top garnish	Cracked	198.60	198.60
22	1	End panel top latch	Bent	65.00	65.00
23	1	Spare tyre panel	Dented	648.50	648.50
24	1	Spare tyre top board	Cracked	285.00	285.00
25	2	Spare tyre side trays	Cracked	884.00	884.00
26	2	Spare tyre side boards	Cracked	448.60	448.60
27	1	Rear exhaust silencer	Dented	689.60	689.60
TOTAL :				10,925.05	9,285.05
<i>less market discount 10%</i>				1,092.51	928.51
				9,832.55	8,356.55
Special Nett Items					
1	1set	Reverse sensor	Cracked	280.00	280.00
2	1	Rear exhaust chrome	Dented	140.00	140.00
TOTAL:				420.00	420.00
TOTAL FOR SPARE PARTS :				10,252.55	8,776.55

NEW AUTO SPEC APPRAISAL

25 Moonstone Lane #10-02 Singapore 328465

Annex B: Adjustment on Labour and Spray Painting

Item	Job Description	Workshop Quote (\$)	Adjusted cost (\$)
1	Labour charges for body repair , replace parts etc	2,200.00	1,400.00
2	To putty and spray painting on affected areas	2,400.00	1,600.00
3	Anti rust	200.00	100.00
4	Sealant seal gap , water proofing welding area	280.00	150.00
5	To replace rear exhaust	200.00	100.00
6	Check wiring , replace sensor	200.00	100.00
7	Remove and refix roof lining, carpets, seat cushion, garnishes and etc	380.00	250.00
8	To do rear chassis body alignment	500.00	350.00
9	Transfer bootlid parts to another bootlid	200.00	100.00
TOTAL FOR LABOUR & SPRAY PAINTING :		<u>6,560.00</u>	<u>4,150.00</u>
Summary			
TOTAL FOR SPARE PARTS :		10,252.55	8,776.55
TOTAL FOR LABOUR & SPRAY PAINTING :		6,560.00	4,150.00
TOTAL REPAIR COSTS :		<u>16,812.55</u>	<u>12,926.55</u>

Vehicle Surveyed By:


Ng Ching Chye
New Auto Spec Appraisal

NEW AUTO SPEC APPRAISAL

25 Moonstone Lane #10-02 Singapore 328465

Vehicle Inspection Report

Our Reference No.	: SJT4833M12092016	Registration No.	: NASAK1601/2016
Your Reference No.	: Not Advised	Date	: 24/11/2016
Claim Type	: T.P.	Date Of Survey	: 13/09/2016
Assignment Given By	: Soon Min Liang Casey	Date Of Accident	: 12/09/2016
Address	: 326B Anchorvale Road	Survey Conduct At	: Autoexcel Engineering Pte Ltd
	: #13-266 Singapore 542326	Address	: Blk 19 Sin Ming Ind Estate
			: #01-05 Singapore 575677

Particulars of accident vehicle

Vehicle Reg. No.	: SJT4833M	Engine Number	: 1NZX975114
Date Of Registration	: 14/10/2009	Chassis Number	: MR053HY9305132248
Make	: Toyota	Transmission Type	: Auto
Model	: Vios	Vehicle Colour	: Metallic Silver
		Mileage Reading	: 198064

Visual and static test on vehicle during survey

Hand brake condition	: Serviceable	Body Condition	: Good
Foot brake condition	: Serviceable	Paint Work condition	: Good
Steering condition	: Serviceable	Remarks	: None
Modification	: Sport Rim		

Condition of vehicle tyre

	Size	Make / Right Tread	Make / Left Tread
Front Tyre	: 185/60R15	Falken 7MM	Falken 7MM
Rear Tyre	: 185/60R15	Falken 7MM	Falken 7MM

Description on vehicle's point of impact and damages

Rear portion of the vehicle.

(For more detail of the damages, please refer photographs attached)

Remarks

In accordance to your instruction, we have NOT authorised any repairs.

Estimated duration of repairs 12 days

This survey was conducted entirely on a "WITHOUT PREJUDICE" basis.

Point Of Impact



PHOTOCOPY

NEW AUTO SPEC APPRAISAL

25 Moonstone Lane, #10-02 Moonstone Residence, Singapore 328465

INVOICE

Invoice No. ASA K949001

Customer	
Soon Min Liang Casey 326B Anchorvale Road #13-266 Singapore 542326 c/o Autoexcel Engineering Pte Ltd Blk 19, Sin Ming Ind. Estate #01-05 Singapore 575677	Date of Invoice : 24/11/2016 Our Job Ref : SJT4833M001K2016 Your Ref No. : Not Advised Vehicle No. : SJT4833M Reg Form No. : NASAK1601/2016 Date of Survey : 13/09/2016 Date of Accident : 12/9/2016 Survey Conduct at : Autoexcel Engineering PL

S/N	DESCRIPTION	
1	Assessment / Inspection Fee /Survey Fee (including photographs and transport charges)	\$ 504.00
Grand Total \$		\$ 504.00

NEW AUTO SPEC APPRAISAL

Signature /Date

PHOTOCOPY

OFFICIAL RECEIPT

No. ASAK949001

Date: 15/12/2016

Received from

Soon Min Liang Casey

The sum of dollars

Five hundred & four only

\$504 1/2

Cash/Check No.

Being payment of

SJT 4833M





POLIS DIRAJA MALAYSIA

REPOT POLIS

Balai : TRAFIK KULAIJAYA	Pegawai Penyiasat : R114169
Daerah : KULAIJAYA	No Repot Bersangkut : TRAFIK
Kontinjen : JOHOR	KULAIJAYA/007885/16
No Repot : TRAFIK KULAIJAYA/007889/16	
Tarikh : 12/09/2016	
Waktu : 1358 PM	
Bahasa Diterima : B. Malaysia	

Butir-butir Penerima Repot

Nama : ABANG AMIRUL ARRIFFIN BIN ABG. ABDILLAH.	No Personel : R196949	Pangkat : KONST/P
Butir-butir Jurubahasa (Jika Ada)		
Nama : ---	No K/P (Baru) : ---	No Polis/Tentera : ---
No Paspot : ---	Bahasa Asal : ---	
Alamat : ---		

Butir-butir Pengadu

Nama : SOON MIN LIANG		
No K/P (Baru) : ---	No Polis/Tentera : ---	No Paspot : S8434662D
No Sijil Beranak : ---		
Jantina : Lelaki	Tarikh Lahir : 17/11/1984	Umur : 31 tahun 9 bulan
Keturunan : Cina	Warganegara : Singapore	
Pekerjaan : SWASTA		
Alamat Tempat Tinggal : BLOCK 326B ANCHORVALE ROAD #13-266 , SINGAPORE, S542326		
Alamat Ibu/Bapa : ---		
Alamat Pejabat : ---		
No Tel (Rumah) : ---	No Tel (Pejabat) : ---	No Tel (HP) : 91860465
Emel : ---		

Pengadu Menyatakan:-

PADA 12/09/2016 JAM LEBIH KURANG 1230 HRS SAYA MEMANDU M/KAR NO.SJT4833M JENIS T/VIOS DARI KUALA LUMPUR HENDAK KE SINGAPURA, APABILA SAMPAI DI KM 48.7 LEBUH RAYA UTARA SELATAN ARAH SELATAN, TERDAPAT SEBUAH M/KAR TERLIBAT KEMALANGAN DI DEPAN SAYA. SAYA BREK DAN CUBA ELAK, TIBA-TIBA SEBUAH M/KAR NO.JKL9798 JENIS P/WIRA TELAH MELANGGAR BAHAGIAN BELAKANG M/KAR SAYA. SAYA TIDAK CEDERA. KEROSAKAN M/KAR BAHAGIAN BELAKANG BUMPER, BONET, SET LAMPU, SENSOR, MUDGUARD KIRI/KANAN DAN LAIN-LAIN KEROSAKAN BELUM PASTI. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

PEJ. SALINAN REPOT
 TRAFIK JOHOR BAHRU (7)
 SALINAN YANG DISAHKAN BENAR
 (HANYA UNTUK TUNTUTAN CIVIL)

ID Pencetak | Tarikh @ Masa Cetak

: R4131513 | 14/09/2016 10:22:47 AM

KETUA TRAFIK DAERAH JOHOR BAHRU (7)
 TIDAK BOLEH DIGUNAKAN UNTUK TUNTUTAN CIVIL



POLIS DIRAJA MALAYSIA REPOT POLIS

Balai : TRAFIK KULAIJAYA
Daerah : KULAIJAYA
Kontinjen : JOHOR
No Repot : TRAFIK KULAIJAYA/007888/16
Tarikh : 12/09/2016
Waktu : 1342 PM
Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : R114169
No Repot Bersangkut : TRAFIK
KULAIJAYA/007885/16

Butir-butir Penerima Repot

Nama : ASMAN BIN ASRI
Butir-butir Jurubahasa (Jika Ada)
Nama : ---
No Paspot : ---
Alamat : ---
No Personel : R199017
Pangkat : KONST
No K/P (Baru) : ---
No Polis/Tentera : ---
Bahasa Asal : ---

Butir-butir Pengadu

Nama : MOHAMED SURESH BIN ZAINOL
No K/P (Baru) : ---
No Sijil Beranak : ---
Jantina : Lelaki
Keturunan : Melayu
Pekerjaan : JURUTERA
No Polis/Tentera : ---
Tarikh Lahir : 21/06/1961
Umur : 55 tahun 2 bulan
Warganegara : Singapore
Alamat Tempat Tinggal : APT BLK 914 JURONG WEST STREET 91, SINGAPORE , 640914
Alamat Ibu/Bapa : ---
Alamat Pejabat : ---
No Tel (Rumah) : ---
No Tel (Pejabat) : ---
No Tel (HP) : 6590059059
Emel : ---

Pengadu Menyatakan:-

PADA 12/09/2016 JAM LEBIH KURANG 1230HRS SAYA MEMANDU M/KAR NO.SGP837K JENIS P/GEN2 DARI KUALA SELANGOR HENDAK KE SINGAPURA.APABILA SAMPAI DI KM 48.7 LEBUH RAYA UTARA SELATAN ARAH SELATAN.PADA WAKTU ITU HUJAN DAN JALAN RAYA LICIN,SEMASA SEDANG MEMANDU ADA KEMALANGAN YANG TELAH BERLAKU DI HADAPAN LALUAN SAYA.SAYA PUN BREK DAN MEMBERHENTIKAN M/KAR TIBA-TIBA DATANG SEBUAH M/KAR NO.TIDAK PASTI DARI ARAH BELAKANG LALU MELANGGAR BAHAGIAN BELAKANG M/KAR,LALU M/KAR SAYA TELAH BERGANJAK KE HADAPAN DAN MELANGGAR BAHAGIAN BELAKANG M/KAR NO.EY9988 JENIS T/CAMRY YANG BERADA DI HADAPAN SAYA.SAYA TIDAK CEDERA.KEROSAKAN M/KAR SAYA DI BAHAGIAN HADAPAN SET LAMPU KANAN,BUMPER.BAHAGIAN BELAKANG NO.PLAT,BUMPER DAN LAIN-LAIN KEROSAKAN BELUM PASTI.SEKIAN LAPORAN SAYA.

Tandatangan Pengadu:

PEJ. SALINAN REPORT
Tandatangan Jurubahasa (Jika Ada) : JOHOR BAHRU (S)
Tandatangan Penerima Repot:
SALINAN YANG DISAHKAN BENAR
(HANYA UNTUK TUNTUTAN SIVIL)

ID Pencetak | Tarikh @ Masa Cetak

: R4131513 | 14/09/2016 10:22:34 AM
KETUA TRAFIK DAERAH JOHOR BAHRU (S) JOHOR
TIDAK BOLEH DIGUNAKAN UNTUK TUJUAN PERBICARAAN



KETUA POLIS DAERAH
IBU PEJABAT POLIS DAERAH KULAIJAYA
81000 KULAI
JOHOR DARUL TAKZIM

TEL: 07 6632222 Samb

Ruj
Tkh 12/09/2016

MOHAMED SURESH BIN ZAINOL No KP
APT BLK 914 JURONG WEST STREET 91 SINGAPORE
640914 - Motokar SGP837K

KEPUTUSAN PENYIASATAN KES

No. Pengaduan Polis : TRAFIK KULAIJAYA/007888/16
Tkh/Masa Rpt : 12/09/2016 13:42 HRS
Kesalahan : R10 LN166/59
Tkh/Masa Kemalangan : 12/09/2016 12:30 HRS
Tempat Kemalangan : E LEBUH RAYA UTARA SELATAN

Dengan hormatnya saya merujuk kepada pengaduan yang dibuat sepertimana dinyatakan di atas.

2. Untuk makluman, pihak yang bertanggungjawab melakukan kesalahan di atas telah disaman polis (RM 300) pada 12/9/2016 (CARS160071435)

3. Butir-butir pihak yang disalahkan adalah seperti berikut :-
MOHAMED SURESH BIN ZAINOL KP : -
APT BLK 914 JURONG WEST STREET 91 SINGAPORE
640914
SGP837K PEMANDU Motokar

"BERHATI-HATI DI JALAN RAYA"

KETUA BAGIAN PENYIASATAN &
PENGUATKUASAAN TRAFIK
IPD KULAI, JOHOR.

(R114169 - ZULKIFLI B.MD. ZAINI)
AIO TRAFIK
81000 KULAI

s . k KST No :

[Notis ini hanya sebagai makluman anda sahaja]




KETUA BAHAGIAN KETENTERAMAN AWAM/
KETUA TRAFIK DAERAH JOHOR BAHRU SELATAN
JOHOR BAHRU SELATAN
JKR 661 JALAN TEBRAU 80250
JOHOR BAHRU

TEL : 07-2277566 ext 208

No. Pengaduan : TRAFIK KULAIJAYA/007885/16
Tarikh Cetak : 14/09/2016
Dicetak Oleh : R4131513

(Rajah Kasar Tidak Mengikut Skala)



PEJ. SALINAN REPORT
TRAFIK JOHOR BAHRU (S)
SALINAN YANG DISAHKAN BENAR
(HANYA UNTUK TUNTUTAN SIVIL)

KETUA TRAFIK DAERAH JOHOR BAHRU (S) JOHOR
TIDAK BOLEH DIGUNAKAN UNTUK TUJUAN PERBICARAAN

KUNCI RAJAH KASAR KEMALANGAN JALANRAYA
RPT(K)NO: 021699/007885/16 BERTARIKH: 12/09/2016
E0002 - E LEBUH RAYA UTARA SELATAN

TANDA PENGENALAN :-

- A - GARISAN PUTIH BERPANJANGAN DI TEPI JALAN
- A1 - GARISAN PUTIH PUTUS-PUTUS PEMBAHAGI JALAN
- A2 - GARISAN PUTIH BERPANJANGAN DI PEMBAHAGI JALAN
- B - BESI PENGHADANG JALAN
- C - TANDA JARAK DALAM KM "48.7"

UKURAN :-

- | | | | |
|----|----|----|---------|
| A | KE | A1 | = 3.6 M |
| A1 | KE | A2 | = 3.6 M |

PEJ. SALINAN REPORT
TRAFIK JOHOR BAHRU (S)
SALINAN YANG DISAHKAN BENAR
(HANYA UNTUK TUNTUTAN SIVIL)

.....
KETUA TRAFIK DAERAH JOHOR BAHRU (S) JOHOR
TIDAK BOLEH DIGUNAKAN UNTUK TUJUAN PERBICARAAN