

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHF 609T - III

ROEL

Not Authorised
8

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHF 609T - ROEL
 VF1ABL15AUC278448
 RENAULT
 LATITUDE
 09.09.16
III

LIST

		PART		
1	1	BUMPER COVER FRT	\$	<i>Bu</i> 968.78 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Sm</i> 139.81 X
3	1	BUMPER FOG LAMP GRILLE LH	\$	<i>D.V</i> 159.40 ✓
4	1	BUMPER RETAINER FRT LH	\$	<i>cm</i> 116.47 ✓
5	1	BUMPER SUPPORT FRT LH(headlamp lower)	\$	<i>Sm</i> 18.37 X
6	1	AIR CLEANER LOWER	\$	271.26 7
7	1	AIR CLEANER HOSE	\$	58.57 7
8	1	LOWER ARM LH	\$	<i>Sm</i> 527.51 X
9	1	KUNCKLE ARM LH	\$	<i>Sm</i> 651.53 X
10	1	KUNCKLE HUB+BEARING LH	\$	<i>Sm</i> 382.84 X
11	1	ABSORBER FRT LH	\$	<i>Sm</i> 277.34 X
12	1	STEERING PUMP ELECTRIC	\$	<i>Sm</i> 1,543.08 X
13	1	BONNET	\$	<i>R</i> 1,493.56 X
14	1	RADAIOR GRILLE	\$	<i>Sm</i> 1,313.68 X
15	1	RADAIOR GRILLE BADGE 'RENAULT'	\$	<i>Sm</i> 173.36 X
16	1	RADAIOR GRILLE FRAME	\$	<i>Sm</i> 1,041.35 X
17	1	FRAME FULL SUPPORT PANEL	\$	<i>Sm</i> 473.77 X
18	1	HEADLAMP LH	\$	<i>mg,cm</i> 911.10 ✓
19	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 134.59 X
20	1	FENDER PANEL FRT LH	\$	<i>Rt</i> 602.95 ✓
21	1	FENDER WHEELARCH FRT LH (Linner)	\$	<i>cm</i> 107.33 ✓
22	1	DOOR MIRROR LH	\$	<i>Sm</i> 1,141.08 X
23	1	DOOR FRT LH	\$	<i>R</i> 2,188.20 X

TOTAL	\$	14,695.92
10%	\$	1,469.59
	\$	13,226.32

Specical Nett

1	1SET	FRONT BUMPER CLIP	\$	<i>Bu</i> 66.00 ✓
2	1SET	WHEELARCH CLIP LH	\$	<i>Nrc</i> 66.00 ✓
3	1	TOW COVER FRT	\$	<i>Sm</i> 14.50 X
4	1	CAP HUB LH FRT	\$	<i>Sm</i> 35.00 X
5	1	RIM LH FRT	\$	<i>Sm</i> 385.00 X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHF 609T - III

6	1	TYRE LH FRT
7	1SET	BUMPER SUPPORT FRT CLIP LH
8	1SET	BUMPER RETAINER FRT CLIP LH
9	1	DOOR STICKER "Trans-cab"
10	1	DOOR STICKER "Classic"

\$	330.00 X
\$	9.80 X
\$	12.50 X
\$	80.00 X
\$	30.00 X

TOTAL	\$	1,028.80
TOTAL PARTS	\$	14,255.12

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	2,800.00 400
\$	170.00 20

To Check Electrical Lighting Concerned.

Putty and spray painting of the affected portion.

\$	3,000.00 440
----	--------------

To check steering geometry and computer wheel alignment

\$	220.00 X
----	----------

To transfer of tire, rim and on wheel balancing.

\$	170.00 X
----	----------

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.

\$	380.00 X
----	----------

Towing fees

\$	120.00 X
----	----------

To rust-proofing of the affected areas.

\$	170.00 30
----	-----------

TOTAL	\$	7,030.00
Over All Total	\$	21,285.12

(PARTS BY PARTS) Repair Days

10 Days

2 1/2 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: