

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHB 9921C - III

Not Authen
82250h

ROEL

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHB 9921C - ROEL
 VF1ABL15AUC273325
 RENAULT
 LATITUDE
 11.09.16
III

		PART
1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMEPR RETAINER RH REAR
5	1	BUMEPR RETAINER LH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER REFLECTOR LH
8	1	BUMPER BEAM REAR
9	1	BUMPER BEAM BRACKET LH REAR
10	1	BUMPER BEAM BRACKET RH REAR
11	1	BOOT REAR
12	1	BOOT FINISHER (Moulding)
13	1	BOOT WHEATERSTRIP
14	1	BOOT REFLECTOR LAMP RH
15	1	BOOT REFLECTOR LAMP LH
16	1	BOOT BADGE 'RENAULT'
17	1	BOOT BADGE
18	1	TAILLAMP RH
19	1	TAILLAMP LH
20	1	OUTER PANEL REAR (End Panel)
21	1	OUTER PANEL REAR (End Panel)TRIM
22	1	EXHAUST REAR
23	1	EXHAUST CAP REAR

LIST

\$	<i>Per</i>	852.66 ✓
\$	<i>Per</i>	591.41 ✓
\$	<i>Per</i>	87.29 X
\$	<i>Per</i>	34.61 X
\$	<i>Per</i>	34.61 X
\$	<i>Per</i>	33.55 X
\$	<i>Per</i>	33.55 X
\$	<i>Per</i>	598.09 ✓
\$	<i>Per</i>	173.81 X
\$	<i>Per</i>	173.81 X
\$	<i>Per</i>	2,209.75 X
\$	<i>Per</i>	429.90 X
\$	<i>Per</i>	248.50 X
\$	<i>Per</i>	379.50 X
\$	<i>Per</i>	379.50 X
\$	<i>Per</i>	173.35 X
\$	<i>Per</i>	173.35 X
\$	<i>Per</i>	425.04 X
\$	<i>Per</i>	425.04 X
\$	<i>Per</i>	1,132.13 X
\$	<i>Per</i>	311.20 X
\$	<i>Per</i>	5,760.00 X
\$	<i>Per</i>	177.30 X

TOTAL	\$	<u>14,837.94</u>
10%	\$	<u>1,483.79</u>
	\$	<u>13,354.15</u>

Special Nett

1	ISET	PARKING AID	\$	<i>Per</i>	600.00 X
2	ISET	REAR BUMPER CLIP	\$	<i>Per</i>	66.00 ✓
3	ISET	BUMPER BRACKET CTR CLIP	\$	<i>Per</i>	33.00 ✓
4	ISET	BUMEPR RETAINER RH CLIP RR	\$	<i>Per</i>	20.00 X
5	ISET	BUMEPR RETAINER LH CLIP RR	\$	<i>Per</i>	20.00 X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHB 9921C - III

6	1SET	BUMPER LOWER REAR CLIP	\$	na 66.00 ✓
7	1	EXHAUST MOUNTING REAR	\$	sm 17.82 X
8	1SET	BOOT FINISHER CLIP	\$	na 24.20 X
9	1	BOOT STICKER "Trans-cab"	\$	na 30.00 X
10	1	BOOT STICKER "6555-3333"	\$	na 30.00 X
11	1	BOOT INNER TRIM CLIP	\$	na 45.00 X

TOTAL	\$	952.02
TOTAL PARTS	\$	14,306.17

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00 3001
To Rust-Proofing Of The Affected Areas.	\$	na 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na 170.00 X

TOTAL	\$	6,650.00
Over All Total	\$	20,956.17

(PARTS BY PARTS)
Repair Days

10 Days
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date: