

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 7830U -**ROEL***Not Authored
2/1/16*

Vehicle No.:

SHB 7830U - ROEL

Chassis No.:

KL1LA69RJBB097029

Vehicle Make:

CHEVROLET

Vehicle Model:

EPICA 2.0

Date of Accident :

11.09.16

Third Party Insurer :

III

PART		LIST
1	1 Front Bumper	\$ <i>Bur</i> 1,202.00 ✓
2	1 Front Bumper Lower Absorber	\$ 180.00 ?
3	1 Front Bumper Reinforcement	\$ 356.00 ?
4	1 Front Bumper Retainer RH	\$ <i>CM</i> 102.00 ✓
5	1 Front Bumper Retainer LH	\$ <i>Sm</i> 102.00 X
6	1 Front Bumper Lower Grille	\$ <i>Sm</i> 78.00 X
7	1 Front Bumper Lower Stiffener	\$ <i>R</i> 134.37 X
8	1 Front Bumper Bracket LH	\$ <i>R</i> 10.00 X
9	1 Front Bumper Bracket RH	\$ <i>R</i> 10.00 X
10	1 Bumper Fog Lamp Cover RH	\$ <i>MJMT</i> 32.40 ✓
11	1 Bumper Fog Lamp Cover LH	\$ <i>Sm</i> 32.40 X
12	1 Front Windscreen	\$ <i>Sm</i> 1,304.00 X
13	1 Front Windscreen Moulding	\$ <i>nn</i> 196.00 X
14	1 Front Fender LH	\$ <i>R</i> 837.60 X
15	1 Front Fender RH	\$ <i>Bur</i> 837.60 ✓
16	1 Front Fender Liner RH	\$ <i>CM</i> 47.00 ✓
17	1 Front Fender Liner LH	\$ <i>Sm</i> 47.00 X
18	1 Front Fender Inner Wheel House Panel RH	\$ <i>R</i> 1,437.00 X
19	1 Resonator (B/S Fender LH) AIR BOX	\$ <i>Sm</i> 134.67 X
20	1 Resonator Hose	\$ <i>Sm</i> 37.00 X
21	1 Bonnet	\$ <i>Bur</i> 1,250.00 ✓
22	1 Bonnet hinge RH	\$ <i>R</i> 36.00 X
23	1 Bonnet hinge LH	\$ <i>R</i> 36.00 X
24	1 Bonnet Moulding	\$ <i>nc</i> 161.97 ✓
25	1 Bonnet Lock	\$ <i>R</i> 60.00 X
26	1 Bonnet cable	\$ <i>Sm</i> 125.00 X
27	1 Front Support Panel Assy	\$ <i>Bur</i> 1,222.32 ✓
28	1 Headlamp RH	\$ <i>Bur</i> 816.00 ✓
29	1 Headlamp LH	\$ <i>Sm</i> 816.00 X
30	1 Windscreen Washer Tank - Filler Neck	\$ <i>Dd</i> 4.80 ✓

TRANS-CAB AUTO SERVICES PTE LTD

ROEL

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 7830U -

31	1	Windscreen Washer Tank	\$		62.00	?
32	1	Windscreen Washer Tank Motor	\$	Sm	51.00	X
33	1	Washer Tank Hose	\$	Sm	21.00	X
34	1	Radiator Assembly	\$	Sm	618.00	X
35	1	Radiator upper hose	\$	Sm	30.00	X
36	1	Radiator lower hose	\$	Sm	120.00	X
37	1	Radiator Grille (Grille A-Rad)	\$	CM	367.00	✓
38	1	Radiator Grille Top Cover	\$	D.V	45.02	✓
39	1	Fan Blade(A/C)	\$	Sm	536.00	X
40	1	Fan Blade(Radiator)	\$	Sm	634.00	X
41	1	Aircon Condenser	\$	Sm	600.00	X
42	1	Aircon hose - condenser to compressor	\$	Sm	450.00	X
43	1	Aircon hose - compressor to evaporator	\$	Sm	624.00	✓
44	1	Aircon hose - condenser to evaporator	\$	Sm	580.00	X
45	1	Air Intercooler	\$	Sm	652.00	X
46	1	Front Shock Absorber Assy RH	\$	Sm	216.17	X
47	1	Front Lower Arm RH	\$	Sm	283.00	X
48	1	Front Knuckle Arm RH	\$	Sm	230.00	X
49	1	Front Stabilizer Bar Link RH	\$	Sm	51.79	X
50	1	Front Stabilizer Bar Bracket RH	\$	R	105.75	X
51	1	Front Stabilizer Bar Bush RH	\$	Sm	66.00	X
52	1	Drive Shaft RH	\$	R	900.00	X
53	1	Front Door RH	\$	R	1,133.00	X
54	1	Front Side View Mirror RH	\$	Sm	939.00	X

TOTAL	\$	20,959.86
10%	\$	2,095.99
	\$	18,863.87

Special Nett

1	1 Set	Front Bumper Fastener Clip	\$	Mr	24.00	✓
2	2	Front Windscreen Sealant	\$	Mr	100.00	X
3	1	Front Windscreen Inner Sponge Seal	\$	Mr	100.00	X
4	1 Set	Radiator Grille Top Cover Clip	\$	Mr	10.00	✓
5	1 Set	Front licence plate with holder	\$	Mr	192.00	45 Sm
6	1 Set	Radiator Grille clip	\$	Mr	35.00	✓
7	1 Set	Front Fender Liner clip LH	\$	Mr	30.00	X
8	1 Set	Front Fender Liner clip RH	\$	Mr	30.00	✓
9	1 Set	Louver Cowl Top clip	\$	Mr	30.00	X

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 7830U -

10	2	Bonnet stopper	\$	<i>sm</i>	15.00	X
11	1	Door Sticker "Trans-cab"RH	\$	<i>nr</i>	80.00	X
12	1	Front Tyre RH	\$	<i>sm</i>	180.00	X
13	1	Front Tyre Rim RH	\$	<i>sm</i>	126.00	X
14	1	Front Tyre LH	\$	<i>sm</i>	180.00	X
15	1	Front Tyre Rim LH	\$	<i>sm</i>	126.00	X

TOTAL	\$	1,258.00
TOTAL PARTS	\$	20,121.87

To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00	<i>6001</i>
To Remove And Refit Front And Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	440.00	<i>nr</i> X
Putty and spray painting of the affected portion.	\$	2,700.00	<i>8001</i>
Towing Fees.	\$	120.00	<i>501</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	<i>nr</i> X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	<i>nr</i> X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	<i>nr</i> X
To check steering geometry and computer wheel alignment	\$	220.00	<i>nr</i> X
To transfer of tire, rim and on wheel balancing.	\$	170.00	<i>nr</i> X
To replace, refix and top up coolant for radiator	\$	170.00	<i>501</i>

TRANS-CAB AUTO SERVICES PTE LTD

ROEL

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 7830U -

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.

\$

380.00 *100*

To rust-proofing of the affected areas.

\$

170.00 *90*

TOTAL	\$	8,480.00
Over All Total	\$	28,601.87

Repair Days

10 Days

4 days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: