

INS. CASE OWNER:

Sundari

CC 4 / III 160 17469, T139

LKK:

IDAC:

Surveyor:

TAMIKH

DOI:

16/09/16

Date / Time:

16/9/16

Registered in Merimen:

16/9/16

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHB 4413K

Name of Insured:

CTPL

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A.: 10/9/16

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Ho Gng Bang

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

mcom0016

Make / Model:

Hyundai K4

Place of Accident:

Yayn Lebaw Rd 7 Pte (N/A)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

FBK 8652J



INSRS:

WSP:

Tel:

Liability:

RMKS:

Tim Hke



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

FBK 8652J - X: SHB 4413K - X

File review, liability is unclear. 022 said he turn right with green arrow, and TP collided into his vehicle. seek for liability.

File review: b30am accident

31/5/19 - Tamikh called to WSP: Liability & clear. No report - Clear on

13/6/19 - File -> MK to (LTA) (up)

PRELIMINARY ADVICE		Date/Time:	Sent By:	
FINALIZATION				
Repair Cost:	S\$	(days)	Reduction:	%
FINAL SETTLEMENT		Date/Time:	Confirm with:	
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:		Confirm by:
Repair Cost:	S\$			Email ☐ Call ☐
Loss of Rental (LOR):	S\$	(days)		
Loss of Use (LOU):	S\$	(\$ x days)		
Loss of Income (LOI):	S\$	(\$ x days)		
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]			
GIA/LTA Search:	S\$			
Medical:	S\$			
Disbursement:	S\$	(e.g. Tow/ Independent)		
Legal Cost:	S\$			
Total:	S\$	Global Sum S\$:		
FINAL PAYMENT				
Payee 1:	S\$	Name 1:		Email ☐ Call ☐
Payee 2: (Strike if N.A.)	S\$	Name 2:		
Payee 3: (Strike if N.A.)	S\$	Name 3:		

(08/11/13)

Surveyor: Taufik

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: M. Keang Vehicle: IN / OUTVeh No: FBK 8652J Yr Regn: 246, FebType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha FZN150 c.c. 149Colour: Black A/C: Insured / Std / NI / NASp. Reading: 6755 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ME/RG1615F2001631Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim orTyre Size: F: 100/80R17R: 140/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MRF

Front _____ Rear _____

R/Bal. C mm R/Bal. C mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 16/9/14 @ 1230Survey held at: Team HKLDes. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>No finalise, Submit</u>
	<u>P/P # 2960-80 (Ref # 3386.24/877)</u>

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format: _____

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III16017469/T1za3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 16-09-2016		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh. SHB 4413K	Veh. Inspected	FBK 8652J	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	16/09/2016	
2. Vehicle Particulars & Condition				
	Make & Model	c.c	0	
	Engine No. HIDDEN	Year of Reg.		
	Chassis No.	Colour		
	Odometer -	Steering		
	Brakes	Modification		
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	10/09/2016	Inspection Date	16/09/2016
	Survey held at	TEAM HKL RACING PTE LTD BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

①

Team HKL Racing Pte Ltd

Blk 1008 #01-24 Bukit Merah Lane 3 Singapore 159722

Tel: 6275 6566, 6275 6656

Fax: 6272 9291

FRK 8652 J 30

Leaving - 40 ✓

Exhaust pipe - 1100 X R

↳ Cover (Silver) - 60 ant -

↳ " (Black) - 55 ant

Front foot rest PM - 35 b/w -

↳ " bracket PM - 80 b/w -

Brake pedal - 55 bt -

Tap box - 95 ant -

↳ " bracket - 130 X mm

Fuel tank cover PM - 150 ant -

Side cover PM - 80 X mm

Handle bar (protector) - 220 bt -

↳ grip (") - 25 ant -

↳ Release - 60 ant

Brake lever - 20 ant -

↳ pump front - 150 ant -

Brake pedal shield - 25 bt -

Side mirror L - 25 ant -

↳ " R - 25 ant -

Slender switch - 95 dis -

Head light - 160 X mm

↳ " panel PM - 55 ant -

2740

Team HKL Racing Pte Ltd
Blk 1008 #01-24 Bukit Merah Lane 3 Singapore 159722
Tel: 6275 6566, 6275 6656
Fax: 6272 9291

#8652 J

Front Signals - 45 out
 " Hoppers - 12 out
 Motor Assy - 950 \$^{nm}
 Front fender - 80 out
 " Side panel pwr - 180 out
 Lower casing - 150 \$^{nm}
 Front fork Assy - 1150 \$^{nm} btl
 Case bearing - 20 out
 Front Wheel shaft - 35 \$^{nm}
 " Brake disc - 95 \$^{nm}
 Unit - 170 \$^{nm}
 Main Stand - 20 \$^{nm}
 Labor Charge - 580 \$^{nm}

(360)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

1) 2740
 2) 360
 Total \$6340

Tan Jiah 97415749
 16/9/16 @ 1230.
 5 days
 * Resurvey new parts

Hsiao Tong (LKKAuto)

From: Olivia Lau (LKKAuto)
Sent: Tuesday, 19 June 2018 4:58 PM
To: enquiry@teamhklracing.com
Cc: Hsiao Tong (LKKAuto)
Subject: RE: FBK8652J /SHB4413K ON;10,09,2016 LIABILITY // LKK Ref: CC4/III16017469/T1ma3
Attachments: statement of our insured.pdf

Without Prejudice

LKK Ref: CC4/III16017469/T1ma3

Hi Mr. Keong,

I refer to our Zayyer's email dated 20 September 2016.

Please advise if your client is still pursuing the claim against our Insured.

Thank you.

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: olivialau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Make
good
use of
Today

From: Zayyer (LKKAuto)
Sent: Tuesday, 20 September 2016 12:12 PM
To: enquiry
Subject: RE: FBK8652J /SHB4413K ON;10,09,2016 LIABILITY

Dear Keong,

Liability is unclear as this is a conflicting version and our client claimed that your client was coming out from the slip road and collided into the left side of vehicle.

We are now following up with our insured and revert back to you soonest. Meanwhile, kindly provide us evidence, photos, video footage (if any) to support your claim. Thanks.

Best Regards,

Zayer | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841 2409, email: zayer@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: enquiry [<mailto:enquiry@teamhklracing.com>]
Sent: Tuesday, 20 September, 2016 11:34 AM
To: Zayyer (LKKAuto) <zayyer@lkkauto.com>
Subject: FBK8652J /SHB4413K
ON;10,09,2016 LIABILITY

Hi Zayyer

May i know liability for this claim.

Thank You

Keong
Team HKL Racing Pte Ltd
HP 92423895

Print Sent Message

This mail is associated with :

***FBK8652J (MCT16090420)
[SHB4413K]**

TP
SIVES S/O RAVINDRA
Sep 10 2016 6:00AM
[COMFORT TRANSPORTATION PTE LTD]
Team Hkl Racing Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ). sent on 13/06/2019 12:58 PM.
To sundari@iii.com.sg
CC III_SG; chewht@lkkauto.com; admin-a@lkkauto.com
Subject <Submit wp Report> MCT16090420

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that liability is unclear. We have requested evidence(if any) from third party since 20/09/2016(see attached). However there was no response/feedback from third party up-to-date.

In view of non-development from the third-party, we will proceed to temporarily close this 2 years outstanding claim file and submit our survey report to your good-office.

In future, if there are any new developments from the claimant, we will inform you for our further handling.

Thank you.

Hsiao Tong

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Sep 2016 Edit Reg		16 Sep 2016 00:00 Edit Adj Rpt	S\$2,960.80 Edit Estimates	S\$2,960.80 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	SIVES S/O RAVINDRA , ID: S91474200								
Vehicle Reg. No.:	FBK8652J	Date of Loss:	10/09/2016 06:00 - :59 [6 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT16090420	Policy/Cover Note No.:	MCOM0016 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	SHB4413K	Policy No. (Claimant):	-						
		Excess:							
Repairer:	Team Hkl Racing Pte Ltd (HQ) Block 1008 #01-24, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62756656								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	Etiga Insurance Pte Ltd (HQ) - Tel: 63360477								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 27/09/2016]								
Driver/Custodian (Insured):	HO ENG BENG (), NRIC: S0148793J Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
III_SG (21/09/2016): Alert - Adj Mandate Maintained - FBK8652J - Claim Handler: Sundari Nagarajan									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBK8652J (MCT16090420)
[SHB4413K]
TP
SIVES S/O RAVINDRA
Sep 10 2016 6:00AM
[COMFORT TRANSPORTATION PTE LTD]
Team Hkl Racing Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	19/09/16 13:25	General View						Load JPG	☒	
2	19/09/16 13:25	General View						Load JPG	☒	
3	19/09/16 13:25	General View						Load JPG	☒	
4	19/09/16 13:25	General View						Load JPG	☒	
5	19/09/16 13:25	General View						Load JPG	☒	
6	19/09/16 13:25	General View						Load JPG	☒	
7	19/09/16 13:25	General View						Load JPG	☒	
8	19/09/16 13:25	General View						Load JPG	☒	
9	19/09/16 13:25	General View						Load JPG	☒	
10	19/09/16 13:25	General View						Load JPG	☒	
11	19/09/16 13:25	General View						Load JPG	☒	
12	19/09/16 13:25	General View						Load JPG	☒	
13	19/09/16 13:25	General View						Load JPG	☒	
14	19/09/16 13:25	General View						Load JPG	☒	
15	19/09/16 13:25	General View						Load JPG	☒	
16	19/09/16 13:25	General View						Load JPG	☒	
17	19/09/16 13:25	General View						Load JPG	☒	
18	19/09/16 13:25	General View						Load JPG	☒	
19	19/09/16 13:25	General View						Load JPG	☒	
20	19/09/16 13:25	General View						Load JPG	☒	
21	19/09/16 13:26	General View						Load JPG	☒	
22	19/09/16 13:26	General View						Load JPG	☒	
23	19/09/16 13:26	General View						Load JPG	☒	
24	19/09/16 13:26	General View						Load JPG	☒	
25	19/09/16 13:26	General View						Load JPG	☒	
26	19/09/16 13:26	General View						Load JPG	☒	
27	19/09/16 13:26	General View						Load JPG	☒	
28	19/09/16 13:26	General View						Load JPG	☒	
29	19/09/16 13:26	General View						Load JPG	☒	
30	19/09/16 13:26	General View						Load JPG	☒	
31	19/09/16 13:26	General View						Load JPG	☒	
32	19/09/16 13:26	General View						Load JPG	☒	
33	19/09/16 13:26	General View						Load JPG	☒	
34	19/09/16 13:26	General View						Load JPG	☒	
35	19/09/16 13:26	General View						Load JPG	☒	
36	19/09/16 13:26	General View						Load JPG	☒	
37	19/09/16 13:26	General View						Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	19/09/16 13:26	General View	 Load JPG	☒
39	19/09/16 13:26	General View	 Load JPG	☒
40	19/09/16 13:26	General View	 Load JPG	☒
41	19/09/16 13:26	General View	 Load JPG	☒
42	19/09/16 13:26	General View	 Load JPG	☒
43	19/09/16 13:26	General View	 Load JPG	☒
44	19/09/16 13:26	General View	 Load JPG	☒
45	19/09/16 13:26	General View	 Load JPG	☒
46	19/09/16 13:26	General View	 Load JPG	☒
47	19/09/16 13:26	General View	 Load JPG	☒
48	19/09/16 13:26	General View	 Load JPG	☒
49	19/09/16 13:26	General View	 Load JPG	☒
50	19/09/16 13:26	General View	 Load JPG	☒
51	19/09/16 13:26	General View	 Load JPG	☒
52	19/09/16 13:26	General View	 Load JPG	☒
53	19/09/16 13:26	General View	 Load JPG	☒
54	19/09/16 13:26	General View	 Load JPG	☒
55	19/09/16 13:26	General View	 Load JPG	☒
56	19/09/16 13:26	General View	 Load JPG	☒
57	19/09/16 13:26	General View	 Load JPG	☒
58	19/09/16 13:26	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/09/16 15:43	EMAIL TO III DD 160916	 Load PDF	
2	19/09/16 11:51	TP GIA REPORT	 Load PDF	
3	19/09/16 12:00	SAS Alert - Accident involving SHB4413K (OI) and FBK8652J (TP) ON 10.09.2016	 Load PDF	
4	19/09/16 13:39	TP ESTIMATE - MARKED	 Load PDF	
5	13/06/19 12:58	Email to TP dd 190618	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	19/09/16 10:35	Singapore Accident Statement-IV	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III16017469/T1PA3Q2

Date: 19/06/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MC0M0016
Claimant Vehicle FBK8652J **Insured Vehicle No :** SHB4413K
 No :
 Date of Loss: 10/09/2016 Nature of Claim: TP Claim No: MCT16090420

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBK8652J**
 Make & Model: YAMAHA FZN150, 149cc Engine No: G3E3E0011614
 Reg. Date: 24/02/2016 (Man. Year: 2015) Chassis No: ME1RG1615F2001636
 Colour: Black Odometer: 6755 km
 Engine Capacity: 149 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/80 R17 Rear Tyre Size: 140/60 R17
 Front Left Side: MRF 6 mm Rear Left Side: MRF 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,727.00	2,530.80	3,196.20	55.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	620.00	430.00	190.00	30.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,347.00	2,960.80	3,386.20	53.35
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 16/09/2016
 Date Inspected: 16/09/2016 Inspected At: Team Hkl Racing Pte Ltd (HQ)
 Block 1008, #01-24, Bukit Merah Lane 3
 Singapore 159722
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Jun 2019)	
Parts:	N/A	YAMAHA FZN150 149cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK8652J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EXHAUST PIPE	Repair	1,100.00 F	*- FL
2	1		*EXHAUST COVER (SILVER)	Cut	60.00 F	*60.00 FL
3	1		*EXHAUST COVER (BLACK)	Cut	55.00 F	*55.00 FL
4	1		*FRONT FOOT REST RH	Broken	35.00 F	*35.00 FL
5	1		*FRONT FOOT BRACKET RH	Broken	80.00 F	*80.00 FL
6	1		*BRAKE PADEL	Bent	55.00 F	*55.00 FL
7	1		*TOP BOX	Cut	95.00 F	*95.00 FL
8	1		*TOP BOX BRACKET	Not Necessary	130.00 F	*- FL
9	1		*FUEL TANK COVER RH	Cut	150.00 F	*150.00 FL
10	1		*SIDE COVER RH	Not Necessary	80.00 F	*- FL
11	1		*HANDLE BAR (PROTECTOR)	Bent	220.00 F	*220.00 FL
12	1		*HANDLE GROUP (PROTECTOR)	Cut	25.00 F	*25.00 FL
13	1		*HANDLE BALANCER	Cut	60.00 F	*60.00 FL
14	1		*BRAKE LEVER	Cut	20.00 F	*20.00 FL
15	1		*BRAKE PUMP FRONT	Cut	150.00 F	*150.00 FL
16	1		*BRAKE PADEL SHALF	Bent	25.00 F	*25.00 FL
17	1		*SIDE MIRROR LH	Cut	25.00 F	*25.00 FL
18	1		*SIDE MIRROR RH	Cut	25.00 F	*25.00 FL
19	1		*HEAD LIGHT	Not Necessary	160.00 F	*- FL
20	1		*HEAD LIGHT PANEL RH	Cut	55.00 F	*55.00 FL
21	1		*STARTER SWITCH	Distorted	95.00 F	*95.00 FL
22	1		*FRONT SIGNALS	Cut	45.00 F	*45.00 FL
23	1		*FRONT REPLATE	Cut	12.00 F	*12.00 FL
24	1		*METER ASSY	Not Necessary	950.00 F	*- FL
25	1		*FRONT FENDER	Cut	80.00 F	*80.00 FL
26	1		*FRONT FENDER SIDE PANEL RH	Cut	180.00 F	*180.00 FL
27	1		*LOWER COWLING	Not Necessary	150.00 F	*- FL
28	1		*FRONT FORK ASSY	Bent	1,150.00 F	*1,150.00 FL
29	1		*CONE BEARING	Necessary	80.00 F	*80.00 FL
30	1		*FRONT WHEEL SHALF	Dented	35.00 F	*35.00 FL
31	1		*FRONT BRAKE DISC	Not Necessary	95.00 F	*- FL
32	1		*IU UNIT	Not Necessary	170.00 F	*- FL
33	1		*MAIN STAND	Not Necessary	80.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,727.00	2,812.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	281.20
Total Parts (\$\$)	5,727.00	2,530.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE	New	580.00	400.00
2	TOWING	New	40.00	30.00
Gross Labour Cost (S\$)			620.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >