



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592


Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB213Y
Ref. No : TAX/09/16/2177
Reg. Date : 12/09/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : POH SZE LEONG ROGER
Type of Accident : HEAD-ON
Date / Time of Accident : 23/09/2016 06:15:00 AM
Accident Reported Date / Time : 23/09/2016 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024084937
Special Instruction to ARC, if any :
SGV5137H
Prepared Date : 23/09/2016 10:53:45 AM



Before Part p4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AX/09/16/2177

Page: 1

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U905748352

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,314.00	0.00
Total Material Charges	: 7,033.00	7,703.80
Other Charges	: 540.00	0.00
TOTAL	: 9,901.00	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 5.00	0.00 <i>3 Days.</i>
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 23/09/2016 04:00:18 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 23/09/2016 03:58:00 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	1,014.00	0.00
Total Labour	1,014.00	0.00 400

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00
TO RESPRAY FRONT FENDER RH	378.00	0.00
TO RESPRAY RIM	180.00	0.00
TO RESPRAY FRONT DOOR RH	378.00	0.00
Total Spray Painting & Panel Beating	1,314.00	0.00 650

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 40
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 X
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 X
TO TOP UP A/C GAS	120.00	0.00 X
Total Other Costs	540.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommend
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace ✓
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace ✓
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace x check
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace x check
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace x check
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace ✓
81519-47050			BRACKET, FR TURN LOWER RH	1	26.00	25.00	19.50	Replace ✓
81519-47060			BRACKET, FR TURN UPPER RH	1	24.40	25.00	18.30	Replace ✓
81511-47050			LENS & BODY, FR TURN RH	1	511.80	10.00	460.62	Replace ✓
82113-47180			WIRE, ENGINE ROOM, NO.3	1	242.00	10.00	217.80	Replace x
88710-47150			TUBE & ACCESSORY	1	631.90	25.00	473.92	Replace x
85315-47140			WIPER WASHER JAR	1	180.10	25.00	135.07	Replace x
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace ✓
53801-47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace ✓
53875-47030		6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace x
53851-47040			FENDER LINER PAD, FR WHEEL. RH	1	49.30	25.00	36.97	Replace x
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace ✓
		6503707	TYRE	1	126.74	0.00	126.74	Replace x
42611-47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace x repair
45046-49225			TIE ROD END RH	1	159.30	25.00	119.47	Replace x
48510-80574			SHOCK ABSORBER FRT/RH	1	394.20	25.00	295.65	Replace x

48068-47050			LOWER ARM FRT/RH	1	625.90	25.00	469.42	Replace <i>X</i>
43330-49185			JOINT ASSY,LWR BALL	1	195.60	25.00	146.70	Replace <i>X</i>
43201-47030			STEERING KNUCKLE RH FRT	1	580.80	25.00	435.60	Replace <i>X</i>
48820-47020			STABILIZER BAR LINK FRT/RH/LH	1	195.00	25.00	146.25	Replace <i>X</i>
48609-47040			SHOCK ABSORBER MOUNTNG FRT, RH/LH	1	193.80	25.00	145.35	Replace <i>+</i>
67001-47070		6505528	DOOR FRT/RH	1	894.40	25.00	670.80	Repair <i>X repair</i>
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace <i>✓</i>
TOTAL MATERIALS							7,033.04	
TOTAL MATERIALS(Discounted)							7,033.00	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Kalvin / 10/16/16
26/9/16

Replace	No
Replace	No
Replace	No
Replace	No
Replace	No
Replace	No
Replace	No
7,703.80	
7,703.80	