

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHD 5551C - CHINA TAIPING

CANDY

Not Notwork Done 27/10/16
11/10/16
Back Value ??

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 5551C - CANDY
 JTDGJ20W405002526
 TOYOTA
 WISH 2.0 BI-FUEL
 22.09.2016
CHINA TAIPING

		PART		LIST
1	1	Front Bumper	\$	BT/100 585.36 —
2	1	Front Bumper Lower Absorber	\$	MT 130.00 —
3	1	Front Bumper Reinforcement	\$	BT 318.11 —
4	1	Front Bumper Side Support LH	\$	MT 76.20 —
5	1	Front Bumper Side Support RH	\$	MT 76.20 —
6	1	Front Bumper Retainer RH	\$	CM 102.00 —
7	1	Front Bumper Retainer LH	\$	CM 102.00 —
8	1	Front Bumper Bracket RH	\$	BT 108.00 —
9	1	Front Bumper Bracket LH	\$	BT 108.00 —
10	1	Front Bumper Fog Lamp RH	\$	MT 208.00 —
11	1	Front Bumper Fog Lamp Outer Chrome RH	\$	DI 190.00 —
12	1	Front Bumper Fog Lamp Grille RH	\$	DI 150.00 —
13	1	Front Bumper Fog Lamp LH	\$	MT 208.00 —
14	1	Front Bumper Fog Lamp Outer Chrome LH	\$	MT 190.00 —
15	1	Front Bumper Fog Lamp Grille LH	\$	MT 150.00 —
16	1	Front Bumper Fog Lamp Protector Grille	\$	MT 100.00 —
17	1	Front Headlamp RH	\$	BR 672.00 —
18	1	Headlamp RH inner panel	\$	NN 732.00 X
19	1	Front Headlamp LH	\$	BR 672.00 —
20	1	Headlamp LH inner panel	\$	NN 732.00 X
21	1	Front Support Panel Assy	\$	BT 1,222.32 —
22	1	Front Brace Panel	\$	BT 95.49 —
23	1	Horn unit	\$	DI 125.00 —
24	1	Horn high pitch / low pitch	\$	DI 150.00 —
25	1	Bonnet	\$	BT 1,019.16 —
26	1	Bonnet Under Weatherstrip Seal	\$	WT 71.99 —
27	1	Bonnet Hinge RH	\$	BT 81.60 —
28	1	Bonnet Hinge LH	\$	BT 81.60 —
29	1	Bonnet Moulding	\$	NIP 194.36 X
30	1	Bonnet Lock	\$	BT 90.02 —
31	1	Bonnet Centre 'TOYOTA' Logo Badge	\$	MT 115.44 —
32	1	Bonnet Insulator	\$	Q261077 524.06 50/50
33	1	Bonnet Damper Stay	\$	NIP 239.05 X
34	1	Front Fender RH	\$	BR 837.60 —
35	1	Front Fender Liner RH	\$	CM 369.14 —
36	1	Front Fender Indicator Lamp RH	\$	SK 95.80 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 5551C - CHINA TAIPING**CANDY**

37	1	Front Fender Inner Wheel House Panel RH	\$	B ₁	714.86 ✓
38	1	Front Fender LH	\$	B ₁	369.14 —
39	1	Front Fender Liner LH	\$	C _M	369.14 —
40	1	Front Fender Indicator Lamp LH	\$	S _{in}	95.80 X
41	1	Front Fender Inner Wheel House Panel LH	\$	B ₁	714.86 ✓
42	1	Front Windscreen	\$	C _M	1,406.64 ✓
43	1	Front Windscreen Moulding	\$	re	86.40 —
44	1	Radiator Assembly	\$	B ₂	2,268.24 ✓
45	1	Radiator Grille	\$	M ₁	462.48 —
46	1	Radiator Fan Blade	\$	D ₁	223.95 —
47	1	Aircon Fan Blade	\$	N ₁	223.95 X
48	1	Radiator Cowling	\$	C _M	221.73 —
49	1	Radiator Fan Motor	\$	T _{in}	372.76 —
50	1	Aircon Fan Motor	\$	N ₁	372.76 X
51	1	Radiator Expansion Tank	\$	M ₁ C _M	180.76 ✓
52	1	Radiator Y - Pipe	\$	S _{in}	98.50 X
53	1	Aircon Condenser	\$	B ₁	1,375.50 ✓
54	1	Aircon hose - condenser to compressor	\$		389.51 ?
55	1	Aircon hose - compressor to evaporator	\$		521.93 ?
56	1	Aircon hose - condenser to evaporator	\$		216.00 ?
57	1	Aircon compressor - pump	\$		3,200.00 ?
58	1	Windscreen Washer Tank - Filler Neck	\$	D ₁	120.76 —
59	1	Windscreen Washer Tank	\$	D ₁	166.00 —
60	1	Windscreen Washer Tank Motor	\$		266.86 ?
61	1	Fuse Box Top (Cover)	\$		88.44 ?
62	1	Fuse Box Lower	\$		84.24 ?
63	1	Fuse Box Centre	\$		254.04 ?
64	1	Fuse Box Centre Cover	\$		238.32 ?
65	1	Engine Cover (Top)	\$	S _{in}	250.60 X
66	1	Intake Manifold	\$	S _{in}	1,500.08 X
67	1	Air Cleaner Assembly	\$		1,036.44 ?
68	1	Air-Cleaner Intake Duct	\$	C _M	101.57 —
69	1	Air-cleaner intake hose	\$	C _M	199.42 —
70	1	V-belt	\$		146.40 ?
71	1	Front shock absorber assy LH	\$		558.00 ?
72	1	Front shock absorber top mounting LH	\$		159.16 ?
73	1	Front shock absorber assy RH	\$		558.00 ?
74	1	Front shock absorber top mounting RH	\$		159.16 ?
75	1	Front lower arm RH	\$	S _{in}	620.57 X
76	1	Front lower arm LH	\$	S _{in}	620.57 X
77	1	Front knuckle arm RH	\$	S _{in}	490.74 X
78	1	Front knuckle arm LH	\$	S _{in}	490.74 X
79	1	Steering rack & pinion assy	\$	S _{in}	3,167.33 X
80	1	Steering rack end	\$	S _{in}	246.50 X
81	1	Steering rack & pinion bushing	\$	S _{in}	30.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 5551C - CHINA TAIPING**CANDY**

82	1	Bracket-strg rack no 1 (s10/12)	\$	55.14 X
83	1	Bracket-strg rack no 2 (s10/12)	\$	37.42 X
84	1	Steering tie-rod end	\$	127.44 X
85	1	Power steering pump	\$	ASP 5,664.96 X
86	1	Power steering belt	\$	ASP 251.33 X
87	1	Power steering reservoir tank	\$	ASP 394.62 X
88	1	Power steering inlet / outlet pipe	\$	ASP 518.04 X
89	1	Power steering pump pulley	\$	ASP 235.68 X
90	1	Power steering hose - pressure	\$	ASP 361.68 X
91	1	Power steering hose - non pressure	\$	ASP 494.28 X
92	1	Engine block	\$	Sen 9,512.81 X
93	1	Engine main harness wire	\$	R 1,947.93 X
94	1	Engine splash cover RH	\$	CRA 178.20 —
95	1	Engine splash cover LH	\$	CRA 178.20 —
96	1	Engine oil sump	\$	Sen 350.04 X
97	1	Engine oil sump strainer	\$	Sen 115.68 X
98	1	ECU assy	\$	4,584.24 ?
99	1	ABS pump	\$	5,679.60 ?
100	1	ABS pump pipe	\$	Sen 82.08 X
101	1	Alternator assembly	\$	2,657.64 ?
102	1	Gear box assy	\$	Sen 16,629.60 X
103	1	Gear box cross member	\$	1,454.28 ?
104	1	Gear box cross member Center	\$	539.76 ?
105	1	Gear box mountingRR	\$	349.68 ?
106	1	Gear box mounting FRT	\$	189.60 ?
107	1	Engine mounting side LH	\$	209.58 ?
108	1	Engine mounting RH	\$	254.28 ?
109	1	Front Seat Belt RH	\$	Sen 862.20 X
110	1	Front safety belt cover garnish RH	\$	Sen 253.68 X
111	1	Front Seat Belt tension RH	\$	Sen 126.01 X
112	1	Front Seat Belt LH	\$	Sen 862.20 X
113	1	Front safety belt cover garnish LH	\$	Sen 253.68 X
114	1	Front Seat Belt tension LH	\$	Sen 126.01 X
115	1	Battery	\$	Sen 240.00 50/50
116	1	Battery fastener bracket	\$	Q 170 R 37.26 X
117	1	Driver's seat	\$	R 1,454.28 X
118	1	Drivers seat reclining mechanism	\$	R 3,599.76 X
119	1	Longitudinal FRT LH	\$	Sen 556.33 X
120	1	Longitudinal FRT RH	\$	Sen 554.33 X
121	1	Front door LH	\$	R 1,554.00 X
122	1	Front side view mirror LH	\$	Sen 874.43 X
123	1	Front door RH	\$	R 1,554.00 X
124	1	Front side view mirror RH	\$	Sen 874.43 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 5551C - CHINA TAIPING**CANDY**

TOTAL	\$	103,197.74
25%	\$	25,799.44
	\$	77,398.30

Special Nett

1 Set	Front Bumper Fastener Clip	\$	Mr 40.00 —
1	CNG Sticker	\$	Mr 30.00 15sn
1 Set	Front Fender Liner Clip LH	\$	Mr 30.00 —
1 Set	Front Fender Liner Clip RH	\$	Mr 30.00 —
2	Bonnet Stopper	\$	Mr 9.60 —
1 Set	Bonnet Under Weatherstrip Seal Clips	\$	Mr 21.60 —
1 Set	Bonnet Insulator Clip	\$	Mr 42.00 —
1 Set	Bonnet Damper Stay Clip	\$	na 10.00 X
1 Set	Horn High pitch / Low Pitch	\$	Repairs 100.00 X
1 Set	Front Wiper Garnish / Wiper Grille Clips	\$	na 18.50 X
1 Set	Front Wiper Clip	\$	na 10.68 X
1 Set	Radiator Grille Clip	\$	Mr 18.00 —
2 Can	Radiator Coolant	\$	Mr 40.00 20sn
2	Radiator Top Bracket Mounting	\$	X 33.84 X
2	Radiator Lower Mounting Bushing	\$	R 18.43 X
1	Front Licence Plate	\$	Mr's 50.00 25sn
1	Front Door Sticker 'Trans-Cab' LH	\$	na 60.00 X
1	Front Door Sticker 'Trans-Cab' RH	\$	na 60.00 X
1 Set	Front Side Rocker Panel Garnish Clips	\$	na 18.00 X
1	Front Windscreen Sealant	\$	Mr 80.00 40sn
1	Front Windscreen Inner Sponge Seal	\$	Mr 60.00 30sn
1	Front ERP Bracket	\$	Mr 50.00 26sn
1	Front ERP Unit	\$	Sn 200.00 X
2	ERP Sticker	\$	Mr 10.00 —
1	Air Filter	\$	36.00 ?
1 Set	Engine splash cover clip RH	\$	Mr 12.00 —
1 Set	Engine splash cover clip LH	\$	Mr 12.00 —
1	Front tyre LH	\$	Sn 190.00 X
1	Front wheel rim LH	\$	Sn 150.00 X
1	Front tyre RH	\$	Sn 190.00 X
1	Front wheel rim RH	\$	Sn 150.00 X

TOTAL	\$	1,780.65
TOTAL PARTS	\$	79,178.95

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$

5,400.00 200d

To Check Electrical Lighting Concerned.

\$

120.00 40d

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 5551C - CHINA TAIPING**CANDY**

To Rust-Proofing Of The Affected Areas.	\$	200.00	1801
Putty And Spray Painting Of The Affected	\$	5,350.00	1400
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	2501
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	2801
To remove and renew engine and gear box mounting.	\$	380.00	2501
To dismantle and refit engine cross-member and engine mounting.	\$	380.00	?
To lift-up engine with gear box and refit.	\$	Repair 440.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn 440.00	X
To check ABS brake efficiency, final checking and testing.	\$	380.00	} 801
To remove and refit ABS pump relay to enable repair.	\$	380.00	
To Check Steering Geometry And Computer Wheel Alignment.	\$	200.00	601
To Transfer Of Tire, Rim And On Wheel	\$	nn 150.00	X
Towing Fees.	\$	120.00	501
To Vacuum, Replace, Refix And Recharge Air Condenser	\$	350.00	1001
To Transfer Of Door Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00	X
To Replace, Refix And Top Up Coolant For Radiator	\$	170.00	501
To Dismantle And Refit Aircon Assy And Attachment, Vacuum And Charge-In-Gas.	\$	Repair 350.00	X

TRANS-CAB AUTO SERVICES PTE LTD**CANDY**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 5551C - CHINA TAIPING

To Transfer Of Fender Fittings, Attachments
And Perform Water Seepage Test.

\$ *an* 170.00 X**TOTAL \$ 15,910.00****Over All Total \$ 95,088.95****Total Repair Days****30 DAYS***18 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: