

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5720L - AIG**CANDY**

Not Authorised
5338.76
Resing B4 paint

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5720L - CANDY

VF1ABL15AUC281621

RENAULT

LATITUDE

23.09.2016

AIG

PART			LIST		
1	1	BUMPER COVER REAR	\$	<i>Sn</i>	852.66 X
2	1	BUMPER LOWER REAR	\$	<i>Sn</i>	591.41 X
3	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i>	104.59 X
4	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i>	34.61 X
5	1	FENDER PANEL REAR RH	\$	<i>R</i>	2,537.80 X
6	1	FENDER WHEELARCH REAR RH	\$	<i>Sn</i>	418.06 X
7	1	TAILLAMP RH	\$	<i>Sn</i>	425.04 X
8	1	ROCKER PANEL OUTER RH	\$	<i>R</i>	759.61 X
9	1	DOOR REAR RH	\$	<i>Bt</i>	2,188.20 ✓
10	1	DOOR CHECK REAR RH	\$	<i>R</i>	156.20 X
11	1	DOOR HANDLE OUTER REAR RH	\$	<i>R</i>	97.31 X
12	1	DOOR HANDLE MODULE REAR RH	\$	<i>R</i>	102.77 X
13	1	ROCKER PANEL OUTER RH	\$	<i>R</i>	759.61 X
14	1	DOOR MIRROR RH	\$	<i>Sn</i>	1,141.08 X
15	1	DOOR PANEL FRT RH	\$	<i>Bt</i>	2,188.20 ✓
16	1	FENDER PANEL FRT RH	\$	<i>R</i>	602.95 X
17	1	FENDER WHEELARCH FRT RH	\$	<i>Sn</i>	107.33 X

TOTAL	\$	13,067.42
10%	\$	1,306.74
	\$	11,760.68

Specical Nett

1	1SET	PARKING AID	\$	<i>Sn</i>	600.00 X
2	1SET	REAR BUMPER CLIP	\$	<i>nn</i>	66.00 X
3	1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i>	66.00 X
4	1	RIM (ROUE 7J 16H 2547)RH RR	\$	<i>Sn</i>	385.00 X
5	1	TYRE RH RR	\$	<i>Sn</i>	330.00 X
6	1	CAP HUB RH REAR	\$	<i>Sn</i>	35.60 X
7	1	DOOR STICKER "6555-3333"	\$	<i>nn</i>	80.00 <i>6555</i>
8	2	Rear Windscreen Sealant	\$	<i>nn</i>	80.00 X
9	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i>	150.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5720L - AIG**CANDY**

TOTAL	\$	1,792.60
TOTAL PARTS	\$	13,553.28

Putty And Spray Painting Of The Affected Portion.	\$	3,500.00	8601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,200.00	5001
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To transfer of boot fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	1201

TOTAL	\$	7,940.00
--------------	-----------	-----------------

Over All Total	\$	21,493.28
-----------------------	-----------	------------------

Repair Days

3 days ~~10 Days~~
(PARTS BY PARTS)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: