

**LIU'S BROTHER AUTO WORKSHOP**

Invoice/Ref No: YM5389G160922

Block 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROC No. 42674600K . Tel: 6741-1730 / 731 . Fax: 6744-5746 . Email: liusbro@gmail.com

Estimate**Customer**

Name: AIG Asia Pacific Insurance Pte Ltd

Address: Motor Claims Department

78 Shenton Way #07-16

AIG Building Singapore 079120

Date: 30-09-16

Vehicle No: YM5389G

Model/Make: Isuzu NPR71LU5GY

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Box Side Panel	\$ 1,400.00	X
2	Tail Lamp	\$ 198.00	X
3	Safety Bar Rear	\$ 850.00	SN X
4	Safety Bar Bracket	\$ 150.00	SN X
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	450
	To putty & spray painting & including touch up paint on accident affected areas	\$ 400.00	350
	To check all wiring & electrical component for proper function	\$ 50.00	X

Total Parts & Labour of estimate for damaged vehicle

\$ 3,848.00

Total amount in Part By Part / Lump Sum Basis for repaired vehicle

\$ -

SDLS: _____



M/s Liu's Brother Auto Workshop

Not Authorized
Labor
TOTAL \$ 800
2 day.