

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

HITCHCAR.
 BLK 126 PASIR RIS ST 11 #09-363
 SINGAPORE 510126

Contact : 85111991, 82611636

TP Alh.
 J.S.
 BERN

2007 June

ESTIMATE

Repair Code : CLM13722

Date in : 06/10/2016

Vehicle Num. : SGV8227L

Model : TOYOTA RUSH 1.5 A

Chassis/Eng# : J200E0010775/3SZ1739959

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>for</i>	1	980.85	980.85 ✓
REAR BUMPER INNER SIDE SHIELD CLIPS L/R <i>new</i>	8	6.50	52.00 10. ✓
REAR BUMPER INNER SIDE SHIELD L/R <i>RH changed</i>	2	172.40	344.80 172.40 ✓
REAR BUMPER NUMBER PLATE LAMP <i>not new</i>	1	96.30	96.30 X
REAR BUMPER REFLECTOR L/R <i>not new</i>	2	121.30	242.60 X.
REAR BUMPER SIDE RETAINER L/R <i>RH cracked</i>	2	65.90	131.80 65.90 ✓
REAR BUMPER STAY CLIPS <i>new</i>	1	6.50	6.50 ✓
REAR BUMPER TOP RETAINER <i>not new</i>	1	155.10	155.10 X.
REAR BUMPER TOW HOOK COVER <i>not new</i>	1	59.10	59.10 X
REAR RH FENDER <i>Repair</i>	1	806.00	806.00 X
REAR RH FENDER GLASS INNER GARNISH CLIPS	6	6.50	39.00 X
REAR RH FENDER GLASS MOULDING	1	110.00	110.00 X
REAR RH FENDER INNER AIR VENT	2	100.45	200.90 X
REAR RH FENDER PETROL LID MECHANISM LOCK	1	40.10	40.10 X.
REAR RH TAILLAMP	1	404.10	404.10 X
REAR RH TAILLAMP BACK RUBBER GASKET	1	95.50	95.50 X
REAR RH TAILLAMP CLIPS	3	6.50	19.50 X
REAR RH TAILLAMP INNER PANEL	1	126.00	126.00 X

*** This is a computer-generated document which requires no signature. ***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HITCHCAR.
BLK 126 PASIR RIS ST 11 #09-363
SINGAPORE 510126

Contact : 85111991, 82611636

ESTIMATE

Repair Code : CLM13722

Date in : 06/10/2016

Vehicle Num. : SGV8227L

Model : TOYOTA RUSH 1.5 A

Chassis/Eng# : J200E0010775/3SZ1739959

REAR SUSPENSION RH ABS SENSOR <i>Nr Nr</i>	1	251.10	251.10 X
REAR SUSPENSION RH HALF SHAFT ASSY <i>Nr Nr</i>	1	945.50	945.50 X
REAR SUSPENSION RH HALF SHAFT BEARING <i>changed</i>	2	403.10	806.20 <i>35860</i>
REAR SUSPENSION RH HALF SHAFT OIL SEAL	1	19.10	19.10 ✓
REAR SUSPENSION RH SHOCK ABSORBER <i>Nr Nr</i>	1	404.10	404.10 X
REAR WHEEL RH 16" SPORT RIM 'ORIGINAL' <i>lot</i>	1	558.10	558.10 ✓
Subtotal before discount			6,894.25
Percentage discount 25%			1,723.56
Sub-total 1			5,170.69
REAR BUMPER CLIPS - SET <i>Nr</i>	1	30.00	30.00 ✓
REAR BUMPER NUMBER PLATE	1	25.00	25.00 X
REAR BUMPER NUMBER PLATE HOLDER	1	50.00	50.00 X
REAR BUMPER REVERSE SENSOR - SET	1	350.00	350.00 X
REAR RH FENDER GLASS SEALANT	1	60.00	60.00 X
REAR RH FENDER INNER TRIM BOARD CLIPS - SET <i>Nr Nr</i>	1	30.00	30.00 X
REAR WHEEL RH 225/60R16 98V TYRE <i>Nr Nr</i>	1	480.00	480.00 X

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

HITCHCAR .

BLK 126 PASIR RIS ST 11 #09-363

SINGAPORE 510126

Contact : 85111991, 82611636

ESTIMATE

Repair Code : CLM13722

Date in : 06/10/2016

Vehicle Num. : SGV8227L

Model : TOYOTA RUSH 1.5 A

Chassis/Eng# : J200E0010775/3SZ1739959

Subtotal before discount	1,025.00
Percentage discount 0%	0.00
Sub-total 2	1,025.00
Parts-total	6,195.69

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

~~150.00~~ 80

To remove, reinstall fender glass

120.00 X

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

~~550.00~~ 250

To road test driving, check and resetting wheel alignments system.

~~180.00~~ 80

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

1210

140.00 X

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

~~750.00~~ 400

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

~~1,000.00~~ 400

To apply anti-rust chemical on repaired and replaced panel.

120.00 X

Labour Total 3,010.00

Parts & Labour Total 9,205.69

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company



Insurance Company

total 2868.58

4/s: 2.3K

04Days

2310