

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CG/GST REG NO.201019626G

SHD 324A - Lonpac**Candy***Not Authored*
8

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 324A - Candy

VF1ABL15AUC282633

RENAULT

LATITUDE

05.10.16

Lonpac**PART****LIST**

1	1	DOOR PANEL FRT LH	\$	R 2,188.20 X
2	1	ROCKER PANEL OUTER LH	\$	B 759.61 ✓
3	1	DOOR PANEL REAR LH	\$	B 2,188.20 ✓
4	1	DOOR GUIDE REAR LH	\$	107.52 7
5	1	DOOR HINGE UPPER LH	\$	K 166.92 X
6	1	DOOR HINGE LOWER LH	\$	R 182.76 X
7	1	DOOR CHECK REAR LH	\$	S 123.48 X
8	1	DOOR LOCK REAR LH	\$	R 552.60 X
9	1	DOOR HANDLE OUTER REAR LH	\$	S 76.92 X
10	1	DOOR HANDLE CAP REAR LH	\$	S 21.60 X
11	1	DOOR HANDLE SEAL REAR LH	\$	S 4.80 X
12	1	DOOR HANDLE COVER REAR LH	\$	S 8.04 X
13	1	DOOR HANDLE MODULE REAR LH	\$	S 81.24 X
14	1	DOOR REGULATOR REAR LH	\$	B 690.24 —
15	1	DOOR REGULATOR MOTOR REAR LH	\$	T 543.48 ✓
16	1	DOOR FINISHER REAR LH	\$	S 257.28 X
17	1	DOOR MOULDING REAR LH	\$	S 107.52 X
18	1	DOOR CASING REAR LH	\$	S 917.64 X
19	1	DOOR WATER SHIELD REAR LH	\$	S 18.48 X
20	1	DOOR CASING LIGHT	\$	S 29.64 X
21	1	DOOR FINISHER INNER REAR LH	\$	S 196.68 X
22	1	DOOR GRAB HANDLE REAR LH	\$	S 128.28 X
23	1	REAR AXLE	\$	3,205.41 7
24	1	AXLE ARM ROD	\$	90.17 7
25	1	AXLE ARM LH	\$	90.17 7
26	1	KUCKLE ARM REAR LH	\$	566.67 7
27	1	AXLE SPRING ARM LH	\$	289.94 7
28	1	LOWER ARM REAR LH	\$	696.91 7
29	1	LOWER ARM BALANCER REAR LH	\$	26.26 7
30	1	ABSORBER REAR LH	\$	344.78 7

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 324A - Lonpac**Candy**

31	1	FENDER PANEL REAR LH	\$	<i>R</i> 2,537.80 <i>X</i>
32	1	FENDER WHEELARCH REAR LH	\$	<i>R</i> 418.06 <i>X</i>
33	1	TAILLAMP LH	\$	<i>Sn</i> 425.04 <i>X</i>
34	1	BUMPER COVER REAR	\$	<i>R</i> 852.66 <i>X</i>
35	1	BUMPER LOWER REAR	\$	<i>Sn</i> 591.41 <i>X</i>
36	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i> 104.53 <i>X</i>
37	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 33.55 <i>X</i>
38	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 104.59 <i>X</i>

TOTAL \$ 19,729.08

10% \$ 1,972.91

\$ 17,756.17

Specical Nett

1	1	DOOR STICKER "Trans-cab" LH	\$	<i>nn</i> 80.00 <i>6000</i>
2	1	DOOR STICKER "Classic" LH	\$	<i>nn</i> 15.00 <i>✓</i>
3	1	DOOR STICKER "6555-3333" LH	\$	<i>nn</i> 80.00 <i>6000</i>
4	2	Rear Windscreen Sealant	\$	<i>nn</i> 100.00 <i>X</i>
5	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i> 150.00 <i>X</i>
6	1SET	FENDER WHEELARCH CLIP RR	\$	<i>nn</i> 15.00 <i>X</i>
7	1	CAP HUB LH RR	\$	<i>Sn</i> 35.00 <i>X</i>
8	1	RIM LH RR	\$	<i>Sn</i> 385.00 <i>X</i>
9	1	TYRE LH RR	\$	330.00 <i>?</i>
10	1SET	REAR BUMPER CLIP	\$	<i>nn</i> 66.00 <i>X</i>
11	1SET	PARKING AID	\$	<i>Sn</i> 600.00 <i>X</i>

TOTAL \$ 1,856.00

TOTAL PARTS \$ 19,612.17

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$

5,400.00 *8000*

To Check Electrical Lighting Concerned.

\$

170.00 *200*

To Remove And Refit Rear W/Screen Glass To
Facilitate Bodywork Repair.

\$

nn 170.00 *X*

Putty and spray painting of the affected portion.

\$

5,350.00 *11000*

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

Candy**SHD 324A - Lonpac**

To transfer of rear fender fittings, attachment and perform water seepage test.	\$	170.00	<i>sol</i>
To check steering geometry and computer wheel alignment	\$	220.00	<i>bol</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>uu</i> 170.00	<i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	<i>bol</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	<i>7</i>
Towing fees	\$	<i>uu</i> 120.00	<i>X</i>

TOTAL	\$	12,320.00
Over All Total	\$	31,932.17

Repair Days

6 days
15 Days
(PARTS BY PARTS)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: