

ASS. REC. BY: Adrian Ling

REF:

CC3/AZC7160/4175/DH302

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 2166315162Claims No. 2902804432SGSum Insured: _____ Excess: 800

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 115K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10/11/15 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKH 9091E Yr Regn: 2012 Sept.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A6 c.c. 1984Colour: Black A/C: Insured / Std / NI / NASp. Reading: 86026 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ4G4DN023599Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/45R18R: 245/45R18BS / DUN / EXNOVA / GY / FS / LIZA MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 06 mmL/Bal. 06 mmD.O.A. _____ D.O.I. 10/10/16Survey held at PremiumDes. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>OPACG</u>
	<u>RECEIVED 12 JAN 2018</u>
<u>13/10-</u>	<u>Revert. via mailman on lump sum \$25k max</u>
<u>14/10-</u>	<u>Victor authorized 21k lump sum</u>
<u>15/10-</u>	<u>uploaded mv & paper value to prove our market value</u>
<u>20/10-</u>	<u>approve by victor. Global sum \$23k.</u>
<u>29/12-</u>	<u>Finalized final figure @22492.20 (red 14324.80 : 63%)</u>

Date/Time, File Pass to?

☐ : Preli. Report1) 12/1 Typist☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 10Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : ODLump Sum / I.B.I. (\$ 22,492.20)

<u>200</u>
<u>10</u>
<u>210</u>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG16019175/Ath3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 11-10-2016



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKH 9091E
Policy No.	2100315162	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/10/2016

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	05/10/2016	Inspection Date	10/10/2016
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

View Received Message

This mail is associated with :

***SKH9091E (2902894432SG)**

OD

Oct 5 2016 3:00PM

[TAN TENG WEE]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 20/10/2016 14:31 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$23000.00) - SKH9091E - Claim Handler: Chan, Kian Meng

Approved:23000.00:Repairer has agree to repair on Gobal sum \$23,000.00.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 20 October, 2016 2:40 PM
To: Claims
Cc: SUR
Subject: SKH 9091E OWN DAMAGE

Dear Sir/Madam,

As instructed by our client Insurance Company, please proceed to repair the insured vehicle SKH 9091E (excess \$800/-).

If there are any check items or supplementary items please inform our office's Assignment Team at : 6741 8434 to arrange our surveyor for inspection.

As agree between AIG and you repair at Global sum \$23,000.00.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tham, Pauline

Date: 11 Oct 2016

Preliminary Advice

Vehicle No	: SKH9091E	Accident Date	: 05/10/2016
Make	: AUDI A6	Policy No.	: 210003135162-04000
Assignment Date	: 11/10/2016	Excess	: S\$0.00
Date of Inspection	: 10/10/2016	Est. Duration of Repair	: 10.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,877.00
Revised Amount	:S\$	25,073.00
Check Items (Estimated)	:S\$	4,998.00
Total	:S\$	30,071.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	113,000.00
COE / PARF Rebate	:S\$	89,942.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,058.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SGCARMART.COM
 THE ONLY PLACE FOR SMART CAR BUYERS

 SGCARMART
 APP DOWNLOAD

All

Search

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

PRODUCT GUIDE

ARTICLES

FORUM

TOOLS & TIPS



Submit Q



Connect

 * Sign Up New Account
 * Forgot Password

Audi A6

Price Range

2013

Transmission

Vehicle Type

Submit

Advanced
Search

Used Car Comparison

--- Comparing 4 Vehicles ---

Audi A6 2.0A TFSI MU

Audi A6 2.0A TFSI MU

Audi A6 2.0A TFSI MU

Audi A6 2.0A TFSI ML



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Add to Shortlist

Add to Shortlist

Add to Shortlist

CAR DETAILS

	Audi A6 2.0A TFSI MU	Audi A6 2.0A TFSI MU	Audi A6 2.0A TFSI MU	Audi A6 2.0A TFSI ML
Price	\$105,800	\$122,500	\$133,800	\$135,800
Instalment	\$1,165	\$1,150	\$1,242	\$1,247
Road Tax	\$1,194 /yr	\$1,194 /yr	\$1,194 /yr	\$1,194 /yr
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,984 cc	1,984 cc	1,984 cc	1,984 cc
Power	132.0 kW (177 bhp)	132.0 kW (177 bhp)	132.0 kW (177 bhp)	-
Registration Date	27-Jan-2012	21-Feb-2013	15-Apr-2013	10-May-2013
Mileage	73,000 km	64,000 km	68,700 km	42,000 km
Features	Powerful 2.0L TFSI Engine 177BHP, Tiptronic Auto Transmission, Cruise Control, Multi Function Steering, Paddle Shifter, Dual Climate Control Aircon.	Audi A6 2.0 TFSI Multitronic, 4 Cylinder 180 Bhp, Audi Drive Select, Audi Parking Aid, Comfort Key, Cruise Control.	Audi A6 2.0 TFSI Multitronic, 4 Cylinder 180 Bhp, Audi Drive Select, Audi Parking Aid, Comfort Key, Cruise Control.	6 Speed Multitronic 180 Bhp, Audi Park Multi Function Stee With Shift Paddles.
Accessories	Black Leather Upholstery, Woods Trimming, Sports Rims, HID Head Lamp, Electric Memory Seats, Parking Sensor, Airbags, Electric Boot, Keyless Entry.	Keyless Engine Start/Stop, Front And Rear LED Daytime Running Lights, Multi Media Interface, Leather Seats. Original 20" Audi Sport Rim.	Keyless Engine Start/Stop, Front And Rear LED Daytime Running Lights, Multi Media Interface, Leather Seats. Original 20" Audi Sport Rims.	Original Factory Sp Engine Start/Stop LED Daytime Runn Leather Seats With Interface.
Description	Most Popular Sporty White Audi A6 For Your Family. Well Maintained And Service. No Further Repairs Needed. Beautiful Paintwork In Clean And Neat Interior. Bank Or In House Loan Available. Deal With Us Henly Enterprises, Well Established Since 1972. Hurry! Call Us Now For Viewings And Test Drive.	Signature Audi A6! Sporty Grey And Elegance Drive To Go On The Road. Superb Handling And Spacious. 1 Owner, 100% Accident Free. Agent Unit. Well Maintained By Owner. Superb Condition. Buy With A Peace Of Mind. Trade In And High Loan Available Call Us Now To Arrange A Viewing.	Agent Maintained. Agent Unit. Superb Condition. Car Parked Under Shelter. Accident Free. Car On Consignment, Viewing Strictly By Appointment Only.	Excellent Condition Luxury Silver With Super Low Mileage. Call Now To Fix Any Stand A Chance To Away!
COE	\$67,889	\$92,400	\$67,010	\$61,700
OMV	\$43,493	\$46,333	\$39,144	\$43,888
Depreciation	\$16,010 /year	\$16,079 /year	\$17,595 /year	\$17,132 /year
No. of Owners	2	1	2	2
Type of Vehicle	Luxury	Luxury	Luxury	Luxury
Category	PARF Car	PARF Car, Premium Ad Car	PARF Car	PARF Car
Availability	Available	Available	Available	Available
SELLER INFORMATION				
Seller	Henly Enterprises Co	Euro Performance	Nordad	De Cars
Address	61 Ubi Avenue 2 #05-19	1 Magazine Road #01-08	1557 Keppel Road #02-18A	53 Ubi Avenue 1 #
Office Number	67469930	65330588 / 85009000	63544555 / 63379200	-
Contact Person	Johnny Lim / Shirley	Joey / Shawn / Jus / Joseth	Jeffrey / Chris / Stephen	Ivan / Kenneth
Contact Number				



Text size + -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 6320J

Vehicle Details

Vehicle No.: SKH9091E

Vehicle to be
Exported: No

Intended De-
registration Date: 11 Oct 2016

Vehicle Make: AUDI

Vehicle Model: A6 2.0 TFSI MU

Primary Colour: Black

Manufacturing Year: 2012

Engine No.: CDN287435

Chassis No.: WAUZZZ4G4DN023599

Maximum Power
Output: 132.0 kW (177 bhp)

Open Market Value: \$49,680.00

Original Registration
Date: 25 Sep 2012

First Registration
Date: 25 Sep 2012

Transfer Count: 0

Actual ARF Paid: \$49,680.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility
Expiry Date: 24 Sep 2022

PARF Rebate
Amount: \$37,260.00

Intended COE Rebate Details

COE Expiry Date: 24 Sep 2022

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$88,500.00

COE Rebate
Amount: \$52,682.00

**Total Rebate
Amount: \$89,942.00**

The information contained herein is correct as at 11 Oct 2016

OK

Land Transport  Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2016 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

View Received Message

This mail is associated with :

***SKH9091E (2902894432SG)**

OD

Oct 5 2016 3:00PM

[TAN TENG WEE]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 14/10/2016 12:19 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$21000.00) - SKH9091E - Claim Handler: Chan, Kian Meng

Approved:21000.00:MV \$110,500.00, paper rebate \$89,546.00. Repair limit not exceeding \$21,000.00. Kindly check with repairer if they are able to repair within the repair limit.

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/10/2016 11:29
Date Of Accident	05/10/2016 15:00
Exact Location Of Accident	ALONG SIN MING AVE.
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH9091E
Insured/Policyholder	
Name Of Registered Owner	TAN TENG WEE
NRIC No	S1246320J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96398534
Alternative Phone No	Office-96398534

Vehicle Particulars

Manufacturer	AUDI
Model	A6-2.0 TFSI MU (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE

Are you claiming under your own insurance policy for repair to your vehicle? Yes

If No, Please state action to be taken

Vehicle Category	Private Car
------------------	-------------

Insurance Company

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	210003135162-04000
Cover Note Number	

Driver

Name of Driver	TAN TENG WEE
NRIC No	S1246320J
Date Of Birth	28/01/1957
Occupation	Indoor
Date Of Driving Pass	12/08/1977
Driving Experience	39 Years And 1 Month
Gender	Male
Mobile Number	(Local) +65-96398534
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address
 Postcode
 Was driver an employee of the Insured's Company No
 If No, Relationship of the Driver with the Insured Owner
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident Collision- Head to Rear (Insured Hit TP)
 Weather Conditions Clear
 Road Surface Dry

Other Information

Was any foreign vehicle involved in this accident? No
 Was any body injured in the Accident? No
 Was any other material or property damaged? Yes
 Was there any video captured by Car Camera? No
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. No
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? No
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? No
 If Yes, against whom?

Circumstances of Accident

At about 3 pm. on the 5/10/2016 along Sin Ming Ave., lorry vehicle no. GZ 3111 Z was not sure/hesitating/ finding the entrance to Bishan Point Condominium. He stopped suddenly in his quest to turn into the condominium. I could not stopped in time and crashed into vehicle no GZ 3111 Z driven by work permit no. : 402069120 Mr. Jyakumar A/L K Supraramanian working for the company Pool Connect Pte Ltd.

Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GZ3111Z
 Vehicle Make/Model/Colour LORRY

Details Of Properties

Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness



Name
 Phone Number
 Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that :
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 Policyholder's Signature / Date & Time 10/06/16	 Driver's Signature (If driver is not the policyholder) / Date & Time	Witnessed by Reporting Centre Personnel
---	---	---

Sketch Plan

Sketch Plan

Sim Mngy Ave

A = SKH 9891

B = GZ3111

Car A

Car B

Condo


Bishan Joml Condo

Describe Circumstances of the Accident


At about 3 pm on the 5/10/16 along Ain Ming Ave just at about the entrance of Ai Tong School. Yerry vehicle no GZ 3112 was not sure / hesitating / finding the entrance to Buhian Point condominium. He stopped suddenly in his quest to turn into the condominium. I could not stop in time & crashed into vehicle no GZ 3112 driven by work permit no :- 402069120 Mr. Jyokumar A/L K Suparamaniam working for the company Pool Connect Pte Ltd.

Declaration

We declare that foregoing particulars are true & every respect


 Reporting Officer's Signature: Date
 06/10/16
 @ 1000h

Driver's Signature (if driver is not the police officer) Date
 & Time


 Witnessed by Reporting Centre
 Personnel

Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR		OWN DAMAGE EXCESS S\$800.00 (1)
CERTIFICATE NO. 2100315162-04000		WINDSCREEN EXCESS S\$100.00
		(for policies with effect from 1st November 2002)
		SUM INSURED Market Value
		INSURING WITH COE/PARF Yes
1) VEHICLE REGISTRATION NO.	SKH9091E	
2) NAME OF INSURED	TAN TENG WEE	
3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT	25 Sep 2016	
4) DATE OF EXPIRY OF INSURANCE	24 Sep 2017	
5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE * SUBJECT TO AGE CONDITION :All Age Condition		
a) The Insured:		
b) Any other person who is driving on the Insured's order or with his permission.		
This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.		
A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the		
Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said		
Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.		
 Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.		
6) LIMITATION AS TO USE *		
Use only for social, domestic and pleasure purposes and for the Insured's business.		
The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.		
APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS		
1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)		
APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)		
2. ComfortDeigro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)		
4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only		
6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)		
8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)		
10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)		
 LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre		
NAMED DRIVER	NA	
HIRE PURCHASE COMPANY / EMPLOYER'S LOAN DBS BANK LTD		
* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.		

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 6 Sep 2016

AIG Asia Pacific Insurance Pte. Ltd.

504125-200
PREMIUM LEASING - AP
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

SSCSYK.

IDENTITY CARD NO. S1246320J



TAN TENG WEE

GENE

SINGAPORE



49821558

No. S1246320J



Speed Group 1800 cc

26-06-1994

SINGAPORE 500044

NPIC No: S1246320J

Date: 18-07-2004

No: 4984868

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

12 Aug 197



Licence No: S1246320J

NP 428A

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0884/2016/CCS
Date : 10-Oct-16

Vehicle in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tan Teng Wee
Address : 87 Jalan Kampong Chantek
Singapore 588644
Telephone : (HP) 96398534
Type of Claim : Own Damage Claim
Policy No. : 2100315162-04000
Vehicle No : **SKH 9091 E**
Model Code : Audi A6 C7 2.0 TFSI MU
Model / Year : Sep-12
Engine No : CDN 287435
Chassis No : WAUZZZ4G4DN023599
Mileage : -
Date In : 6-Oct-16
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Oct-16
Place of Accident : Along Sin Ming Avenue

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKH 9091 E.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, foglamps, outside temperature sensor, headlight washer assy and parking aid system.	S/N \$ 480.00	/
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,200.00	/
3	To remove front fittings, dismantle front bumper, both front fenders and bonnet. Renew front lock carrier and align to position. Renew front bumper both front fenders, bonnet and both headlights. Re-organised front crash management components. Reinstall all parts and removed.	\$ 5,600.00	3000 .
4	To re-spray front bumper, LHS & RHS front fenders & bonnet.	\$ 3,000.00	2200 .
5	To carry out diagnostic check.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		\$ 10,472.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 9091 E

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 2,209.00	✓ ✓ 1763.20
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 220.00	✓ X
3	FRONT BUMPER FOAM - INNER <i>new cubed</i>	\$ 78.00	✓ ✓ 61.84
4	FRONT REINFORCEMENT BEAM <i>new Bent</i>	\$ 630.00	✓ ✓ 504
5	FRONT REINFORCEMENT BEAM BOLT SET <i>new</i>	\$ 46.00	?
6	FRONT REINFORCEMENT BEAM HOLDER - LH/RH <i>new 2</i>	\$ 394.00	?
7	FRONT BUMPER TOP COVER <i>Distorted</i>	\$ 96.00	✓ ✓ 76.80
8	FRONT BUMPER GUIDE - LH/RH <i>new all</i>	2 \$ 58.00	✓ ✓ 22.96
9	FRONT BUMPER BRACE - LH/RH <i>new</i>	2 \$ 48.00	✓ X
10	FRONT BUMPER SUPPORT - LH/RH <i>new all</i>	2 \$ 17.00	✓ ✓ 13.60
11	FRONT BUMPER GRILLE - RH <i>new</i>	\$ 122.00	✓ X
12	HEADLIGHT MOUNTING - LH/RH <i>new 2</i>	2 \$ 192.00	✓ 76.40 ✓ 76.40
13	RADIATOR GRILLE <i>smashed</i>	\$ 1,121.00	✓ ✓ 896.80
14	HEADLIGHT - LH/RH <i>cracked</i>	2 \$ 5,638.00	✓ ✓ 4510.40
15	DAY DRIVING LIGHT POWER MODULE <i>new</i>	\$ 492.00	✓ X
16	GAS DISCHARGE LAMP CONTROL UNIT <i>new</i>	\$ 822.00	✓ X
17	GAS DISCHARGE LAMP <i>new</i>	\$ 392.00	✓ X
18	GAS DISCHARGE LAMP RETAINING PLATE <i>new</i>	\$ 71.00	✓ X
19	BONNET <i>Distorted</i>	\$ 4,482.00	✓ ✓ 3585.60
20	BONNET ATTACHMENT PARTS <i>new</i>	\$ 117.00	✓ X
SUB-TOTAL SPARE PARTS		\$ 17,245.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 9091 E

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/NETT		
21	BONNET HINGE - LH/RH <i>M m</i>	2 \$	262.00 ?	X
22	BONNET STOP BUFFER SET <i>m</i>	\$	87.00 /	✓ 69.44
23	BONNET CATCH HOOK - TOP <i>Deled</i>	\$	114.00 ?	✓ 90.80
24	BONNET LOCK BAR - LH/RH <i>Deled</i>	2 \$	81.00 ?	✓ 64.16
25	BONNET CATCH HOOK - BOTTOM <i>2 m</i>	\$	14.00 +	✓ 10.64
26	BONNET LOCK WITH MICRO-SWITCH	2 \$	336.00 +	✓ 268.80
27	BONNET LOCK CABLE <i>m m</i>	\$	59.00 x	X
28	FRONT FENDER - LH/RH <i>RH Deled, LH Buckled</i>	2 \$	2,264.00 -	905.60 ✓ 905.60
29	FRONT FENDER ATTACHMENT PARTS <i>M m</i>	2 \$	68.00 ?	X
30	FRONT FENDER STONE GUARD FILM - LH/RH <i>m</i>	2 \$	198.00 /	✓ 158.24
31	FRONT FENDER BRACE - LH/RH <i>ZH Bent</i>	2 \$	134.00 ?	53.20 ✓ 53.20
32	FRONT FENDER CLOSING ELEMENT - RH <i>M m</i>	\$	43.00 +	X
33	FRONT WHEEL HOUSING LINER - RH <i>m m</i>	\$	222.00 +	X
34	WHEEL HOUSING LINER ATTACHMENT PARTS <i>M m</i>	\$	62.00 x	X
35	FRONT WHEEL SPOILER - RH <i>m m</i>	\$	188.00 +	X
36	AIR FILTER <i>Not m</i>	\$	240.00 x	X
37	INTAKE AIR DUCT <i>Deled</i>	\$	59.00 /	✓ 46.96
38	AIR GUIDE FOR AIR FILTER <i>Deled</i>	\$	20.00 /	✓ 15.60
39	FRONT LOCK CARRIER <i>Curled</i>	\$	1,010.00 /	✓ 808
40	A/C CONDENSER <i>Deled</i>	\$	651.00 /	✓ 520.40
SUB-TOTAL SPARE PARTS		\$	6,112.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 9091 E

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	RADIATOR <i>Best</i>	\$ 638.00	? ✓ 510
42	RADIATOR RUBBER BUSH <i>new</i>	\$ 45.00	? ✓ 35.00
43	COOLANT <i>new</i>	\$ 118.00	✓ ✓ 93.76
44	TWIN FAN RING <i>new</i>	\$ 212.00	? X
45	RADIATOR FAN - 400MM <i>new</i>	\$ 718.00	? X
46	RADIATOR FAN - 350MM <i>new</i>	\$ 621.00	? X
47	FRONT LOCK CARRIER AIR GUIDE - LH/RH <i>new</i>	2 \$ 48.00	? ✓ 18.88
48	FRONT LOCK CARRIER COVER - TOP <i>new</i>	\$ 23.00	✓ ✓ 18.08
49	FRONT NO. PLATE <i>Best</i>	S/N \$ 25.00	✓ ✓ 25
50	SUNDRIES <i>new</i>	\$ 600.00	? ✓ 192
TOTAL SPARE PARTS		\$ 26,405.00	
TOTAL LABOUR CHARGES		\$ 10,472.00	
GRAND TOTAL		\$ 36,877.00	

All charges Remarks (OK) = Approved, Remarks (X) = Not approved

Legend : Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Admin by
Surveyed Date : 10/10/16.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 10 Days.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager



Allan Wu
Claims Consultant

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0884/2016/CCS
Date : 10-Oct-16

Vehicle in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120



Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tan Teng Wee
Address : 87 Jalan Kampong Chantek
Singapore 588644
Telephone : (HP) 96398534
Type of Claim : Own Damage Claim
Policy No. : 2100315162-04000
Vehicle No : **SKH 9091 E**
Model Code : Audi A6 C7 2.0 TFSI MU
Model / Year : Sep-12
Engine No : CDN 287435
Chassis No : WAUZZZ4G4DN023599
Mileage : -
Date In : 6-Oct-16
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Oct-16
Place of Accident : Along Sin Ming Avenue

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKH 9091 E.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, foglamps, outside temperature sensor, headlight washer assy and parking aid system.	S/N \$	480.00	\$ 480.00
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$	1,200.00	\$ 1,200.00
3	To remove front fittings, dismantle front bumper, both front fenders and bonnet. Renew front lock carrier and align to position. Renew front bumper both front fenders, bonnet and both headlights. Re-organised front crash management components. Reinstall all parts and removed.	\$	5,600.00	\$ 3,000.00
4	To re-spray front bumper, LHS & RHS front fenders & bonnet.	\$	3,000.00	\$ 2,200.00
5	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 10,472.00</u>	<u>\$ 7,072.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 9091 E

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,209.00	\$ 1,767.20
2	FRONT BUMPER FIXING PARTS	\$ 220.00	
3	FRONT BUMPER FOAM - INNER	\$ 78.00	\$ 61.84
4	FRONT REINFORCEMENT BEAM	\$ 630.00	\$ 504.00
5	FRONT REINFORCEMENT BEAM BOLT SET	\$ 46.00	
6	FRONT REINFORCEMENT BEAM HOLDER - LH/RH	2 \$ 394.00	
7	FRONT BUMPER TOP COVER	\$ 96.00	\$ 76.80
8	FRONT BUMPER GUIDE - LH/RH	2 \$ 58.00	\$ 22.96
9	FRONT BUMPER BRACE - LH/RH	2 \$ 48.00	
10	FRONT BUMPER SUPPORT - LH/RH	2 \$ 17.00	\$ 13.60
11	FRONT BUMPER GRILLE - RH	\$ 122.00	
12	HEADLIGHT MOUNTING - LH/RH	2 \$ 192.00	\$ 76.40
13	RADIATOR GRILLE	\$ 1,121.00	\$ 896.80
14	HEADLIGHT - LH/RH	2 \$ 5,638.00	\$ 4,510.40
15	DAY DRIVING LIGHT POWER MODULE	\$ 492.00	
16	GAS DISCHARGE LAMP CONTROL UNIT	\$ 822.00	
17	GAS DISCHARGE LAMP	\$ 392.00	
18	GAS DISCHARGE LAMP RETAINING PLATE	\$ 71.00	
19	BONNET	\$ 4,482.00	\$ 3,585.60
20	BONNET ATTACHMENT PARTS	\$ 117.00	
SUB-TOTAL SPARE PARTS		\$ 17,245.00	\$ 11,515.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 9091 E

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 11,515.60
21	BONNET HINGE - LH/RH	2 \$ 262.00	
22	BONNET STOP BUFFER SET	\$ 87.00	\$ 69.44
23	BONNET CATCH HOOK - TOP	\$ 114.00	\$ 90.80
24	BONNET LOCK BAR - LH/RH	2 \$ 81.00	\$ 64.16
25	BONNET CATCH HOOK - BOTTOM	\$ 14.00	\$ 10.64
26	BONNET LOCK WITH MICRO-SWITCH	2 \$ 336.00	\$ 268.80
27	BONNET LOCK CABLE	\$ 59.00	
28	FRONT FENDER - LH/RH	2 \$ 2,264.00	\$ 905.60
29	FRONT FENDER ATTACHMENT PARTS	2 \$ 68.00	
30	FRONT FENDER STONE GUARD FILM - LH/RH	2 \$ 198.00	\$ 158.24
31	FRONT FENDER BRACE - LH/RH	2 \$ 134.00	\$ 53.20
32	FRONT FENDER CLOSING ELEMENT - RH	\$ 43.00	
33	FRONT WHEEL HOUSING LINER - RH	\$ 222.00	
34	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 62.00	
35	FRONT WHEEL SPOILER - RH	\$ 188.00	
36	AIR FILTER	\$ 240.00	
37	INTAKE AIR DUCT	\$ 59.00	\$ 46.96
38	AIR GUIDE FOR AIR FILTER	\$ 20.00	\$ 15.60
39	FRONT LOCK CARRIER	\$ 1,010.00	\$ 808.00
40	A/C CONDENSER	\$ 651.00	\$ 520.40
	SUB-TOTAL SPARE PARTS	\$ 6,112.00	\$ 14,527.44

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 9091 E

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 14,527.44
41	RADIATOR	\$ 638.00	\$ 510.00
42	RADIATOR RUBBER BUSH	\$ 45.00	\$ 35.04
43	COOLANT	\$ 118.00	\$ 93.76
44	TWIN FAN RING	\$ 212.00	
45	RADIATOR FAN - 400MM	\$ 718.00	
46	RADIATOR FAN - 350MM	\$ 621.00	
47	FRONT LOCK CARRIER AIR GUIDE - LH/RH	2 \$ 48.00	\$ 18.88
48	FRONT LOCK CARRIER COVER - TOP	\$ 23.00	\$ 18.08
49	FRONT NO. PLATE	S/N \$ 25.00	\$ 25.00
50	SUNDRIES	\$ 600.00	\$ 192.00
TOTAL SPARE PARTS		:	\$ 26,405.00 \$ 15,420.20
TOTAL LABOUR CHARGES		:	\$ 10,472.00 \$ 7,072.00
GRAND TOTAL		:	\$ 36,877.00 \$ 22,492.20

All charges Remarks (OK) = Approved, Remarks (X) = Not approved

Legend : Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKH 9091 E

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0884/2016/MAS

8 Jan 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SKH 9091 E, Audi A6 C7 2.0 TFSI MU

With reference to the above-mentioned vehicle, no **SKH 9091 E**, claimant, **Mr. Tan Teng Wee**, please find the related document per attached.

1. A copy of the Original invoice no. 85011969 – S\$23,210.65
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SKH 9091 E

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408693
Telephone 6388 2323

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 16:33

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85011969 Date : 29/12/2017 Order : SKH9091E Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKH9091E (V 19145)	Regn Date: 25/09/2012	Mileage: 99477	WIP No.: 53290
Model: A6 C7 2.0 TFSI MU 4G207H (MY13)	Chassis: WAUZZZ4G4DN023599	Engine: CDN 287435	Dept: U
VSB No.:			
You have been assisted by :- UB-Carrine (22)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND PARKING AID SYSTEM.	480.00	1.00	480.00
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE.	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UN TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLIN SYSTEM.	1200.00	1.00	1,200.00
S	BODYWORK	M: TO REMOVE FRONT FITTINGS, DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER,	3000.00	1.00	3,000.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408599
Telephone 6388 2323

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 2 16:33

Invoice: 85011969 Date : 29/12/2017 Order : SKH9091E Term : 30	Account: A0006 (T 0) ATG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT ATG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120
---	--

Regn No.: SKH9091E (V 19145) Regn Date: 25/09/2012 Mileage: 99477 WIP No.: 53290

Model: A6 C7 2.0 TFSI MU 4G207H (MY13 Chassis: WAUZZZ464DN023599 Engine: CDN 287435 Dept: U

VS8 No.:

You have been assisted by :- UB-Carrine (22)

		Details	Qty	Unit Price	Amount
S	BODYWORK	RHS FRONT FENDERS, BONNET AND BOTH HEADLIGHTS. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. M:	2200.00	1.00	2,200.00
Q	OTHERS	TO RE-SPRAY FRONT BUMPER, BOTH FRONT FENDERS AND BONNET. M:	192.00	1.00	192.00
X	A4G0129624F	AIR DUCT(A) (C/S) Less 020%	1.00	58.70	46.96
X	AG A13A8JM1	COOLANT ADDITIVE(C/S) Less 020%	4.00	29.30	93.76
X	A4G0853651 T94	GRILLE Less 020%	1.00	1121.00	896.00
X	A4G0941044D	HEADLAMP Less 020%	1.00	2819.00	2,255.20
X	A4G0941043D	HEADLAMP(C/S) Less 020%	1.00	2819.00	2,255.20
X	A4G0821102	FENDER Less 020%	1.00	1132.00	905.60
X	A4G0807065B GRU	COVER Less 020%	1.00	2209.00	1,767.20
X	A4G0823029A	HOOD Less 020%	1.00	4482.00	3,585.60
X	A4G0807081	COVER Less 020%	1.00	96.00	76.80
X	ABK0121251L	RADIATOR(C/S) Less 020%	1.00	637.50	510.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone 6388 2323

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INS TAX INVOICE

Company Reg. No. 189902271W

GST Reg. No. 199902271W

Page 3 16:33

Invoice: 85011969	Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD	AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT	MOTOR CLAIM DEPT
AIG BUILDING	AIG BUILDING
78 SHENTON WAY	78 SHENTON WAY
#07-16	#07-16
SINGAPORE 079120 079120	SINGAPORE 079120
Date : 29/12/2017	
Order : SKH9091E	
Term : 30	

Regn No.: SKH9091E (V 19145)	Regn Date: 25/09/2012	Mileage: 99477	WIP No.: 53290
Model: A6 C7 2.0 TFSI MU 4G207H (MY13)	Chassis: WAUZZZ464DN023599	Engine: CDN 287435	Dept: U
VS8 No.:			
You have been assisted by :- UB-Carrine	(22)		

		Details	Qty	Unit Price	Amount
X	A4G0260403B	CONDENSER(C/S)	1.00	650.50	520.40
X	A4G0805594C	CARRIER	1.00	1010.00	808.00
X	A4G0807550J	FOAM INSER	1.00	77.30	61.84
X	A4G0807113A	BEAM	1.00	630.00	504.00
X	AD 007000A2	SILICSPRAY (DG)	1.00	28.40	22.72
X	A4H0121268	MOUNTING(C/S)	2.00	10.20	16.32
X	A4G0129618B	AIR DUCT(A)	1.00	19.50	15.60
X	A4G0823480	HOOK	1.00	113.50	90.80
X	A4G0121292E	COVER	1.00	22.60	18.08
X	A8K0121275C	MOUNTING(C/S)	2.00	4.40	7.04
X	A4H0121276	MOUNTING	2.00	7.30	11.68
X	A8E0805163	CLIP	4.00	2.30	7.36
X	A4G0823509C	LOCK	2.00	160.00	268.80
X	A8T0827249	BUMPER	2.00	23.40	37.44
X	A4G0821136A	SUPPORT(C/S)	1.00	66.50	53.20
X	A4G0890905	FOIL	1.00	98.90	79.12
X	A4E0260749B	WASHER	1.00	3.90	3.12
X	A4E0260749A	WASHER	1.00	3.00	2.40

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone 6388 2323

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 4 16:33

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85011969 Date : 29/12/2017 Order : SKH9091E Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKH9091E (V 19145)	Regn Date: 25/09/2012	Mileage: 99477	WIP No.: 53290
Model: A6 C7 2.0 TFSI MU 4G207H (MY13	Chassis: WAUZZZ4G4DN023599	Engine: CDN 287435	Dept: U
VS8 No.:			
You have been assisted by :- UB-Carrine (22)			

		Details		Qty	Unit Price	Amount
X	A4G0807891	LOC. PIN	Less 020%	2.00	4.00	6.40
X	A7H0820896	SEAL	Less 020%	1.00	2.20	1.76
X	A3D0823429A	BUMPER	Less 020%	2.00	20.00	32.00
X	A4G0820536B	BRACKET	Less 020%	1.00	18.30	14.64
X	A4G0807333	SUPPORT	Less 020%	2.00	8.50	13.60
X	A4G0823186	CLAMP	Less 020%	2.00	40.10	64.16
X	A4G0823485	HOOK	Less 020%	1.00	13.30	10.64
X	A4G0807284	GUIDE	Less 020%	1.00	28.70	22.96
X	A4G0805600	MOUNTING	Less 020%	1.00	95.50	76.40
X	A4H0998121	REPAIR KIT	Less 020%	1.00	52.70	42.16
X	A1T0919133B 9B9	WASHER	Less 020%	2.00	1.00	1.60
X	A1T0919133C 9B9	WASHER	Less 020%	4.00	1.00	3.20
X	A4G0010515	STICKER	Less 020%	1.00	15.90	12.72
X	A8K0010520A	PLATE	Less 020%	1.00	10.80	8.64
X	AD 438515A1	ADHERSIVE TAPE	Less 020%	1.00	49.30	39.44
X	A4G0890906	FOIL	Less 020%	1.00	98.90	79.12
X	A4G0121284AC	AIR DUCT	Less 020%	1.00	23.60	18.88
X	A4H001506A	BOLT(C/S)	Less 020%	2.00	1.30	2.08

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone 6388 2323

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 5 16:33

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85011969 Date : 29/12/2017 Order : SKH9091E Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKH9091E (V 19145) Regn Date: 25/09/2012 Mileage: 99477 WIP No.: 53290

Model: A6 C7 2.0 TFSI MU 4G207H (MY13 Chassis: WAUZZZ4G4DN023599 Engine: CDN 287435 Dept: U

VSU No.:

You have been assisted by :- UB-Carrine (22)

		Details	Qty	Unit Price	Amount
X	AWHT001308	NUT	7.00	1.10	6.16
X	AN 91093901	RIVET	4.00	0.60	1.92
X	AN 90765701	RIVET	4.00	1.10	3.52
X	AN 90817302	NUT	4.00	1.40	4.48
X	AN 90798808	NUT	4.00	1.00	3.20
X	AN 91022001	NUT	4.00	1.40	4.48

Parts 15,395.20
Labour 192.00
Sublet 6,905.00
Menus 0.00
Lubricant 0.00

Sub-Total 21,692.20

7% GST 1,518.45

Grand Total 23,210.65



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKH 9091 E

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0884/2016/SK
01 November 2016

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A6 C7 2.0 TFSI MU
Vehicle Chassis No. : WAUZZZ4G4DN023599
Vehicle Regn No. : **SKH 9091 E**
Vehicle Mileage : 86036KM
Vehicle Owner : Mr. Tan Teng Wee
Certificate No : 2100315162-04000
Policy Excess : **S\$ 856.00 (inclusive of 7% GST)**
Accident Date : 05 October 2016
Place : Along Sin Ming Avenue
Repair Cost : \$ 23,210.65
WIP No. : 53290
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733


Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


15:04
01/11/2016

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1246320J



Name

TAN TENG WEE

陳丁偉

Race

CHINESE


Date of Birth

28-01-1957 M

Country of Birth

SINGAPORE

ST



0621558

NRIC No. S1246320J



Blood Group Date of Issue

B+ 26-06-1994

87 JALAN KAMPONG CHANTEK
SINGAPORE 588644

NRIC No: S1246320J

Date: 19-07-2004 No: 4934868

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

12 Aug 1977

NP 428A





CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100315162-04000

OWN DAMAGE EXCESS S\$800.00 (1)
WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PARF Yes
SKH9091E

TAN TENG WEE

25 Sep 2016

24 Sep 2017

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

4) DATE OF EXPIRY OF INSURANCE

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION: All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the
Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said
Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or
has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf
from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing
the carriage of goods other than samples in connection with any trade or business or use for any purpose in
connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Pook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huan (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Maya Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER NA

HIRE PURCHASE COMPANY DBS BANK LTD
/ EMPLOYER'S LOAN

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and
Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-
Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 6 Sep 2016

AIG Asia Pacific Insurance Pte. Ltd.

504125-200
PREMIUM LEASING - AP
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

SSCSYK.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Oct 2016		11 Oct 2016 14:05 Edit Adj Rpt	S\$22,492.20 Edit Estimates	S\$22,492.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN TENG WEE, ID: S1246320J, Tel: +6596398534, Email: NOEMAIL								
Vehicle Reg. No.:	SKH9091E	Date of Loss:	05/10/2016 15:00 - :59						
Claim Type:	OD / 2902894432SG	Policy/Cover Note No.:	210003135162-04000 (Comprehensive)						
		Excess:	S\$800.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 20/10/2016]								
Driver/Custodian:	TAN TENG WEE (59 / Male), NRIC: S1246320J, Tel: +6596398534								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (20/10/2016): Alert - Adj Mandate Approved (S\$23000.00) - SKH9091E - Claim Handler: Chan, Kian... AIG_SG (14/10/2016): Upload MV & Paper value AIG_SG (14/10/2016): Alert - Adj Mandate Approved (S\$21000.00) - SKH9091E - Claim Handler: Chan, Kian... AIG_SG (14/10/2016): SKH9091E / OD / 05/10/2016 / Coverage & Excess update AIG_SG (12/10/2016): SKH9091E - Pending documents 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

































***SKH9091E (2902894432SG)**

OD

Oct 5 2016 3:00PM

[TAN TENG WEE]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser		▼	
Assessment Reports														1 per page		▼		<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print					
1	13/10/16 14:27		Adjuster Immediate Advice										 Load HTM							
Photos/Images														3 per page		▼		<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print					
1	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
2	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
3	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
4	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
5	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
6	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
7	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
8	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
9	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
10	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
11	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
12	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
13	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
14	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
15	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
16	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
17	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
18	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
19	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
20	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
21	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
22	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
23	13/10/16 14:25		General View										 Load JPG		<input checked="" type="checkbox"/>					
24	12/01/18 12:07		Reinspection Photo										 Load JPG		<input checked="" type="checkbox"/>					
25	12/01/18 12:07		Reinspection Photo										 Load JPG		<input checked="" type="checkbox"/>					
26	12/01/18 12:07		Reinspection Photo										 Load JPG		<input checked="" type="checkbox"/>					
27	12/01/18 12:07		Reinspection Photo										 Load JPG		<input checked="" type="checkbox"/>					
28	12/01/18 12:07		Reinspection Photo										 Load JPG		<input checked="" type="checkbox"/>					
29	12/01/18 12:07		Reinspection Photo										 Load JPG		<input checked="" type="checkbox"/>					
30	12/01/18 12:07		Reinspection Photo										 Load JPG		<input checked="" type="checkbox"/>					
31	12/01/18 12:07		Reinspection Photo										 Load JPG		<input checked="" type="checkbox"/>					
32	12/01/18 12:07		Reinspection Photo										Load JPG		<input checked="" type="checkbox"/>					
33	12/01/18 12:07		Reinspection Photo										Load JPG		<input checked="" type="checkbox"/>					

34	12/01/18 12:08	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
35	12/01/18 12:08	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
36	12/01/18 12:08	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
37	12/01/18 12:08	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
38	12/01/18 12:08	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
39	12/01/18 12:08	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation					
				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/10/16 14:24	workshop estimate	1	Load PDF	
2	13/10/16 14:24	Drivers Driving License	1	Load PDF	
3	13/10/16 14:24	Certificate of Insurance	1	Load PDF	
4	13/10/16 14:24	Singapore Accident Statement	1	Load PDF	
5	17/10/16 13:38	document mv	1	Load PDF	
6	20/10/16 08:33	Log card (if available)	1	Load PDF	
7	17/01/18 09:13	Discharge Voucher	1	Load PDF	
8	17/01/18 09:13	Workshop Invoice	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div> <div style="text-align: right;"> ^ v </div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG16019175/ATH3E2

Date: 17/01/2018

REFERENCE

Insured/Claimant: TAN TENG WEE Policy No: 210003135162-04000
Date of Loss: 05/10/2016 Nature of Claim: OD Claim No: 2902894432SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKH9091E
Make & Model: AUDI A6, 2.0 TFSI MU (A) Engine No: CDN287435
Reg. Date: 25/09/2012 (Man. Year: 2012) Chassis No: WAUZZZ4G4DN023599
Colour: Black Odometer: 86026 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$115,000.00
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,405.00	15,420.20	10,984.80	41.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,472.00	7,072.00	3,400.00	32.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	36,877.00	22,492.20	14,384.80	39.01
- Excess (\$\$)	800.00	800.00	0.00	0.00
(S\$)	36,077.00	21,692.20	14,384.80	39.87
+ GST 7.00/7.00% (\$\$)	2,525.39	1,518.45	1,006.94	39.87
Nett Amount (\$\$)	38,602.39	23,210.65	15,391.74	39.87

INSPECTION

Date of Assignment: 11/10/2016

Date Inspected: 10/10/2016 Inspected At:

Premium Automobiles Pte Ltd (HQ)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,209.00 FS	*1,767.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	220.00 FS	*- FS
3	1		*FRONT BUMPER FOAM - INNER	Cracked	78.00 FS	*61.84 FS
4	1		*FRONT REINFORCEMENT BEAM	Bent	630.00 FS	*504.00 FS
5	1		*SET FRONT REINFORCEMENT BEAM BOLT	Not Necessary	46.00 FS	*- FS
6	2		*FRONT REINFORCEMENT BEAM HOLDER - LH/RH	Not Necessary	394.00 FS	*- FS
7	1		*FRONT BUMPER TOP COVER	Deformed	96.00 FS	*76.80 FS
8	2		*FRONT BUMPER GUIDE - LH/RH	Necessary	58.00 FS	*22.96 FS
9	2		*FRONT BUMPER BRACE - LH/RH	Not Necessary	48.00 FS	*- FS
10	2		*FRONT BUMPER SUPPORT - LH/RH	Necessary	17.00 FS	*13.60 FS
11	1		*FRONT BUMPER GRILLE - RH	Not Necessary	122.00 FS	*- FS
12	1		*HEADLIGHT MOUNTING - LH/RH	O/S Damaged	192.00 FS	*76.40 FS
13	1		*RADIATOR GRILLE	Smashed	1,121.00 FS	*896.80 FS
14	2		*HEADLIGHT - LH/RH	Cracked	5,638.00 FS	*4,510.40 FS
15	1		*DAY DRIVING LIGHT POWER MODULE	Not Necessary	492.00 FS	*- FS
16	1		*GAS DISCHARGE LAMP CONTROL UNIT	Not Necessary	822.00 FS	*- FS
17	1		*GAS DISCHARGE LAMP	Not Necessary	392.00 FS	*- FS
18	1		*GAS DISCHARGE LAMP RETAINING PLATE	Not Necessary	71.00 FS	*- FS
19	1		*BONNET	Distorted	4,482.00 FS	*3,585.60 FS
20	1		*BONNET ATTACHMENT PARTS	Not Necessary	117.00 FS	*- FS
21	2		*BONNET HINGE - LH/RH	Not Necessary	262.00 FS	*- FS
22	1		*BONNET CATCH HOOK - TOP	Damaged	114.00 FS	*90.80 FS
23	2		*BONNET LOCK BAR - LH/RH	Damaged	81.00 FS	*64.16 FS
24	1		*BONNET CATCH HOOK - BOTTOM	Necessary	14.00 FS	*10.64 FS
25	2		*BONNET LOCK WITH MICRO-SWITCH	Necessary	336.00 FS	*268.80 FS
26	1		*BONNET LOCK CABLE	Not Necessary	59.00 FS	*- FS
27	1		*FRONT FENDER - LH/RH	O/S Repair / N/S Buckled	2,264.00 FS	*905.60 FS
28	2		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	68.00 FS	*- FS
29	2		*FRONT FENDER STONE GUARD FILM - LH/RH	Necessary	198.00 FS	*158.24 FS
30	1		*FRONT FENDER BRACE - LH/RH	N/S Bent	134.00 FS	*53.20 FS
31	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	43.00 FS	*- FS
32	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	222.00 FS	*- FS
33	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	62.00 FS	*- FS
34	1		*FRONT WHEEL SPOILER - RH	Not Necessary	188.00 FS	*- FS
35	1		*AIR FILTER	Not Necessary	240.00 FS	*- FS
36	1		*INTAKE AIR DUCT	Deformed	59.00 FS	*46.96 FS
37	1		*AIR GUIDE FOR AIR FILTER	Deformed	20.00 FS	*15.60 FS
38	1		*FRONT LOCK CARRIER	Cracked	1,010.00 FS	*808.00 FS
39	1		*A/C CONDENSER	Dented	651.00 FS	*520.40 FS
40	1		*RADIATOR	Bent	638.00 FS	*510.00 FS
41	1		*RADIATOR RUBBER BUSH	Necessary	45.00 FS	*35.04 FS
42	1		*COOLANT	Necessary	118.00 FS	*93.76 FS
43	1		*TWIN FAN RING	Not Necessary	212.00 FS	*- FS
44	1		*RADIATOR FAN - 400MM	Not Necessary	718.00 FS	*- FS
45	1		*RADIATOR FAN - 350MM	Not Necessary	621.00 FS	*- FS
46	2		*FRONT LOCK CARRIER AIR GUIDE - LH/RH	Damaged	48.00 FS	*18.88 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT LOCK CARRIER COVER - TOP	Deformed	23.00 FS	*18.08 FS
48	1		*FRONT NO. PLATE	Bent	25.00 FS	*25.00 FS
49	1		*SUNDRIES	Necessary	600.00 FS	*192.00 FS
50	1		*SET BONNET STOP BUFFER	Necessary	87.00 FS	*69.44 FS
Total Parts (S\$)					26,405.00	15,420.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOGLAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND PARKING AID SYSTEM	New	480.00	480.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,200.00	1,200.00
3	TO REMOVE FRONT FITTINGS, DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHTS. RE-ORGANISED FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS AND REMOVED	New	5,600.00	3,000.00
4	TO RE-SPRAY FRONT BUMPER, LHS & RHS FRONT FENDERS & BONNET	New	3,000.00	2,200.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			10,472.00	7,072.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >