



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE SINGAPORE PTE LTD		Ref : CC4/AXA16019193/yb3		
8 SHENTON WAY #27-01 SINGAPORE 068811		Date : 11-10-2016		
		Code : AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGW 4617R	Veh. Inspected	SKF 7078T	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/10/2016	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/10/2016	Inspection Date		
Survey held at	Z-ONE AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVE 6, BLK C, #01-52 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Supervisor: Taufik

REF:

AXA

1A193/1244

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 1 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKF 7078T Yr Regn: 2012, Jue

Type: ☒ Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 528T c.c. 1997

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 70439 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WB AXG 3206012 X82478

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/45R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 4/10/16P 1730

Survey held at Zone 7 Sou Lee ST

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

will pass estimate later.

1/51 \$7000.00 (Ref \$9,058.98 / 56.41%)

Date/Time, File Pass to?

☐ : Prel. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format : _____

Lump Sum / I.B.I. (\$) 2

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

☐ S + RS _____ \$

Photos _____

Others _____

TOTAL _____



Z-One Automotive Pte Ltd

1 Kall Bukit Ave 8, Bldg D #01-87, Autobay @ Kall Bukit Singapore 417883
Tel: 6534 2112 / 6534 2292 Fax: 6534 2122 Email: enquiry@z-one.com.sg
7 Soon Lee Street #01-27/47, ISpace, Singapore 627608
Tel: 6250 2115 Email: service@z-one.com.sg
Company Reg No. 201118055N GST Reg No. 201118055N

AUTOMOTIVE & PERFORMANCE

ESTIMATE

TAN CHOON HWEE
BLK 917 HOUGANG AVE 9 #05-20 Singapore
530917

Contact: 98003112

Code: C101600
Date In: 11/10/2016
Vehicle Num.: SKF7078T
Model: BMW 528i 2.0A
Chassis/Eng#: WBAXG32060DX82478/A4100215N20B20A

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
Front Door Checker RH	1	82.25	bt X 82.25
Front Door Hinges RH	2	54.40	bt X 108.80
Front Door Lock Striker RH	1	19.45	bt X 19.45
Front Door Mechanism Lock RH	1	663.25	bt 663.25
Front Door Outer Handle RH	1	580.00	cut 580.00
Front Door RH	1	1689.20	bt 1,689.20
Front Door Side Mirror RH	1	1728.05	cut 1,728.05 912.80
Front Door Weather Strip RH	1	161.50	wf 161.50
Front Door Window Glass Regulator Motor RH	1	297.80	bt 297.80
Front Fender RH	1	842.30	bt 842.30
Front Fender Signal Lamp RH	1	79.65	wf 79.65
Rear Door RH	1	1689.20	Ry 1,689.20
Rear Knuckle Arm RH	1	1217.80	X 1,217.80
Rear Knuckle Bearing RH	1	189.95	X 189.95
Rear Lower Arm RH	1	202.05	X 202.05
Rear Shock Absorber RH	1	484.70	X 484.70
Rear Sport Rim RH	1	991.40	cut 991.40

page 1

Tanfikh 97495344
7 days

Unsure

Resin after repair



Z-One Automotive Pte Ltd

1 Kald Bukit Ave 8, Bldg D #01-87, Autobay @ Kald Bukit Singapore 417883
Tel: 6534 2112 / 6534 2292 Fax: 6534 2122 Email: enquiry@z-one.com.sg
7 Soon Lee Street #01-27/47, ISpace, Singapore 627608
Tel: 6250 2115 Email: service@z-one.com.sg
Company Reg No. 201118055N GST Reg No. 201118055N

AUTOMOTIVE O PERFORMANCE

Rear Upper Arm RH	1	552.85	X 552.85
Side Skirt RH	1	429.25	de✓ 429.25

Subtotal before discount

12,009.45

Percentage discount 5%

600.47

Sub-total 1

11,408.98

Rear Tyre RH (SN)

1

680.00

680.00

Subtotal before discount

680.00

Percentage discount 0%

0.00

Sub-total 2

680.00

Parts-total

12,088.98

LABOUR

Description	Price
To diagnose, replace and/or repair to rectify front door electrical system for proper functioning	60 200.00
To diagnose, replace and/or repair to rectify rear door electrical system for proper functioning	60 100.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	X 250.00
To conduct computerise wheel alignment and adjustments	80 120.00
To transfer front door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	80 200.00
To transfer rear door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle	X 100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1200 1,600.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	900 1,400.00
Labour Total	3,970.00
Parts & Labour Total	16,058.98

page 2

6420.62
2380
8800.62
4577000
7days

2800.62
11577000
7days

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 79781

Vehicle Details

Vehicle No.: SKF7078T

Vehicle to be Exported: No

Intended De-registration Date: 10 Oct 2016

Vehicle Make: B.M.W.

Vehicle Model: 528i 2.0L AT D/AB 2WD 4DR GAS/D NAV

Primary Colour: White

Manufacturing Year: 2012

Engine No.: A4100215N20B20A

Chassis No.: WBAXG32060DX82478

Maximum Power Output: 180.0 kW (241 bhp)

Open Market Value: \$47,936.00

Original Registration Date: 27 Jun 2012

First Registration Date: 27 Jun 2012

Transfer Count: 1

Actual ARF Paid: \$47,936.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 26 Jun 2022

PARF Rebate Amount: \$35,952.00

Intended COE Rebate Details

COE Expiry Date: 26 Jun 2022

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$83,000.00

COE Rebate Amount: \$47,402.00

Total Rebate Amount: \$83,354.00

The information contained herein is correct as at 10 Oct 2016

OK

View Received Message

This mail is associated with :

***SKF7078T (C0403249)
[SGW4617R]**

TP
TAN CHOON HWEE
Oct 1 2016 9:00PM
[N-51 AUTOMOTIVE PTE LTD]
Z-One Automotive Pte Ltd - Kaki Bukit

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on **01/10/2018 16:07 PM**,
To AXA_SG; LKK_HQ
CC sur@lkkauto.com; assignments@lkkauto.com
Subject Please let us have your Adjuster Report / Re: File Review



AXA INSURANCE PTE LTD
6 Bras Basah Way, #24-01 AXA Tower
Singapore 189511
Customer Centre 951-01
Tel: (65) 6591-6666
Fax: (65) 6518-5000
www.axa.com.sg
GST Reg No: 19906133130
U.S. Reg No: 15000105120

Hi LKK,

Please let us have your Adjuster Report/survey photos. We have received TP legal LOD on this case.

Thank you,
Wancong

<-- Original Message -->

From: AXA_SG
To: LKK_HQ
CC: AXA_SG
Sent On: 28/05/2018 02:30 PM
Subject: File Review

Dear LKK

Please let us have an update of the matter.

We look forward to hear from you. Thank you.

Regards
Xinyou

DOCUMENTS SUMMARY

There are no documents.



Z-One Automotive Pte Ltd

1 Kaki Bukit Ave 6, Blk D #01-87, Autobay @ Kaki Bukit Singapore 417883
Tel: 6634 2112 / 6634 2292 Fax: 6634 2122 Email: enquiry@z-one.com.sg
7 Soon Lee Street #01-27/47, iSpace, Singapore 627608
Tel: 6250 2115 Email: service@z-one.com.sg
Company Reg No. 201118055N GST Reg No. 201118055N

Our Ref : SKF7078T

Your Ref : SGW4617R (CC4/AXA16019193/TLy)

10 March 2017

BY EMAIL & POST

WITHOUT PREJUDICE

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Attention: Mr. Chen Xinyou (Motor Claims Dept)

Dear Mr Chen,

CLAIMANT: TAN CHOON HWEE

ACCIDENT INVOLVING SKF7078T & SGW4617R ON 1 OCT 2016 AT 21.15HRS ALONG HOUGANG AVE 4/HOUGANG AVE 9.

We refer to the above matter.

As the quantum was agreed between your surveyor and our Mr Erik Chan, we are submitting our claims as follows:

1. Cost of Repair	\$7,490.00 (Including 7% GST)
2. LOU	\$1,260.00 (7days @S\$180/- p/day)
3. GIA Invoices	\$ 29.00
Total :	<u>\$8,779.00</u>
	=====

A copy each of the following supporting documents is enclosed:

- 1) Final Bill
- 2) GIA report
- 3) GIA Invoice
- 4) Certificate of Insurance
- 5) Vehicle Registration Card
- 6) Letter of Authority

Yours faithfully


Z-One Automotive Pte Ltd
Encls

LETTER OF AUTHORITY

RE: ACCIDENT INVOLVING VEHICLE NOS SKF70787

Hougang Ave 4/Hougang Ave 9 at 2115 hrs & SGW4617R ALONG
ON 1 Oct 2016

1. I/We, hereby appoint Z-ONE AUTOMOTIVE PTE LTD to be my agent and I/We authorize my said agent to give you all instructions pertaining to the conduct of my claim including instructions to commence legal proceedings in court in my name against the third party driver/or his employers, if applicable.
2. ** My said agent also has my authority to decide on my behalf whether to accept any offer of settlement from the third party and/or his insurers.
3. I understand and accept that until I revoke my said agent's authority in writing to you, I am bound by all instructions given by my said agent to you
4. ** Upon settlement of the third party claim and in case the settlement monies was sent to me/us by the third party's insurers, I/We undertake to pay you and my/our Solicitor the cost of repair settled and related expenses and disbursement incurred.
5. My vehicle is repaired on my own will without any inducement, threat or promise.

Signature

(Company's stamp if applicable)

Name: Tan Choon Hwee

NRIC No: S72779781

Address: Blk 917 Hougang Ave 9
05-20
Spore 530917



Z-One Automotive Pte Ltd

1 Kaki Bukit Ave 6, Blk D #01-87, Autobay @ Kaki Bukit Singapore 417883
Tel: 6634 2112 / 6634 2292 Fax: 6634 2122 Email: enquiry@z-one.com.sg
7 Soon Lee Street #01-27/47, iSpace, Singapore 627608
Tel: 6250 2115 Email: service@z-one.com.sg
Company Reg No. 201118055N GST Reg No. 201118055N

TAX INVOICE

TAN CHOON HWEE
BLK 917 HOUGANG AVE 9
#05-20
Singapore 530917

Contact : 98003112

Date : 10/03/2017
Date in : 11/10/2016
Vehicle Num. : SKF7078T
Make/Model : BMW 528i 2.0A-2012
Chassis/Eng# : WBAXG32060DX82478/A4100215N20B20A
Accident Date : 01/10/2016
Claim No : C101600
Reference :
Policy No. : 5073800106 (26/12/2016)

LUMPSUM REPAIR BILL
AS PER SURVEYOR REPORT
DATED 10/03/2017
BY LKK Auto Consultants Pte Ltd

Amount \$
7,000.00

E. & O.E.	Sub \$:	7,000.00
Add GST (7%) \$:		490.00
Total Amount \$:		7,490.00



Z-ONE AUTOMOTIVE PTE LTD



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-16-117270

Date of Request: 04/10/2016

Your Ref No:

EM.ZONE

CROSSBORDERS LLC
133 New Bridge Road #23-03/04/05
Chinatown Point
Singapore 059413

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 01/10/2016

Place of Accident: HOUGANG AVE 4 TWDS AVE 9

Client Vehicle No: SKF7078T

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



TAX INVOICE

Our Ref No: GR-16-117344
Date of Request: 04/10/2016

Your Ref No: EM ZONE

CROSSBORDERS LLC
133 New Bridge Road #23-03/04/05
Chinatown Point
Singapore 059413

Dear Sir/Madam,

Date of Accident: 01/10/2016
Vehicle No: SKF7078T
Place of Accident: HOUGANG AVE 4 / HOUGANG AVE 9
Involving Vehicle No: SGW4617R

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SGW4617R	HOUGANG AVE 4 / HOUGANG AVE 9	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Oct 2016		10 Oct 2016 16:43 Edit Adj Rpt	S\$7,000.00 Edit Estimates	S\$7,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	N-51 AUTOMOTIVE PTE LTD , Co. Reg. No.: 200616038C								
Main Claimant:	TAN CHOON HWEE , ID: 572779781								
Vehicle Reg. No.:	SKF7078T	Date of Loss:	01/10/2016 21:00 - :59 [51 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0403249	Policy/Cover Note No.:	GA084995 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGW4617R	Policy No. (Claimant):	5073800106						
		Excess:	S\$0.00						
Repairer:	Z-One Automotive Pte Ltd - Kaki Bukit (HQ) 1 Kaki Bukit Avenue 6,, Bldg D #01-87, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6634 2112								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Tan Wancong - 68804832]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 19/10/2016]								
Driver/Custodian (Insured):	FOO KWONG WAH (), NRIC: S1306508Z, Tel: +6581806608								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AXA_SG (01/10/2018): Please let us have your Adjuster Report / Re: File Review - AXA_SG (28/05/2018): File Review - AXA_SG (10/10/2016): New TP Assignment - C0403249/GA084995									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKF7078T (C0403249)
[SGW4617R]
TP
TAN CHOON HWEE
Oct 1 2016 9:00PM
[N-51 AUTOMOTIVE PTE LTD]
Z-One Automotive Pte Ltd - Kaki Bukit

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	08/12/17 13:54	General View														Load JPG	☒			
2	08/12/17 13:54	General View														Load JPG	☒			
3	08/12/17 13:54	General View														Load JPG	☒			
4	08/12/17 13:54	General View														Load JPG	☒			
5	08/12/17 13:54	General View														Load JPG	☒			
6	08/12/17 13:54	General View														Load JPG	☒			
7	08/12/17 13:54	General View														Load JPG	☒			
8	08/12/17 13:54	General View														Load JPG	☒			
9	08/12/17 13:54	General View														Load JPG	☒			
10	08/12/17 13:54	General View														Load JPG	☒			
11	08/12/17 13:54	General View														Load JPG	☒			
12	08/12/17 13:54	General View														Load JPG	☒			
13	08/12/17 13:54	General View														Load JPG	☒			
14	08/12/17 13:54	General View														Load JPG	☒			
15	08/12/17 13:54	General View														Load JPG	☒			
16	08/12/17 13:54	General View														Load JPG	☒			
17	08/12/17 13:54	General View														Load JPG	☒			
18	08/12/17 13:54	General View														Load JPG	☒			
19	08/12/17 13:54	General View														Load JPG	☒			
20	08/12/17 13:54	General View														Load JPG	☒			
21	08/12/17 13:54	General View														Load JPG	☒			
22	08/12/17 13:54	General View														Load JPG	☒			
23	08/12/17 13:54	General View														Load JPG	☒			
24	08/12/17 13:54	General View														Load JPG	☒			
25	08/12/17 13:54	General View														Load JPG	☒			
26	08/12/17 13:54	General View														Load JPG	☒			
27	08/12/17 13:54	General View														Load JPG	☒			
28	08/12/17 13:54	General View														Load JPG	☒			
29	08/12/17 13:54	General View														Load JPG	☒			
30	08/12/17 13:54	General View														Load JPG	☒			
31	08/12/17 13:54	General View														Load JPG	☒			
32	08/12/17 13:54	Odometer Reading														Load JPG	☒			
33	08/12/17 13:54	Chassis Number														Load JPG	☒			
34	08/12/17 13:55	Reinspection Photo														Load JPG	☒			
35	08/12/17 13:55	Reinspection Photo														Load JPG	☒			
36	08/12/17 13:55	Reinspection Photo														Load JPG	☒			
37	08/12/17 13:55	Reinspection Photo														Load JPG	☒			

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
39	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
40	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
41	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
42	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
43	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
44	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
45	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
46	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
47	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
48	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
49	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
50	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
51	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
52	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
53	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
54	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
55	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
56	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
57	08/12/17 13:55	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	10/10/16 16:40	EMAIL_ABS	 Load PDF	
2	10/10/16 16:40	CO-CLAIMANT_ABS	 Load PDF	
3	10/10/16 16:40	SKF7078T TP GIA REPORT_ABS	 Load PDF	
4	10/10/16 16:40	SGW4617R INSD GIA REPORT_ABS	 Load PDF	
5	10/10/16 16:40	TO LKK	 Load TIF	
6	08/06/18 13:09	TP LOD	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/12/18 12:05	TP Estimate-Marked	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA16019193/T1FB3Q2

Date: 17/12/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

GA084995

Claimant Vehicle No: SKF7078T

Insured Vehicle No:

SGW4617R

Date of Loss: 01/10/2016

Nature of Claim:

TP

Claim No: C0403249

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKF7078T

Make & Model: BMW 528i, 2.0 (A)

Reg. Date: 27/06/2012 (Man. Year: 2012)

Colour: White

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: A4100215N20B20A

Chassis No: WBAXG32060DX82478

Odometer: 70439 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18

Front Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Tyre Size: 245/45 R18

Rear Left Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,088.98	6,420.62	5,668.36	46.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,970.00	2,380.00	1,590.00	40.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,058.98	8,800.62	7,258.36	45.20
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	16,058.98	7,000.00	9,058.98	56.41
+ GST 7.00/7.00% (S\$)	1,124.13	490.00	634.13	56.41
Nett Amount (S\$)	17,183.11	7,490.00	9,693.11	56.41

INSPECTION

Date of Assignment: 10/10/2016

Date Inspected: 11/10/2016 Inspected At:

Z-One Automotive Pte Ltd - Kaki Bukit (HQ)

1 Kaki Bukit Avenue 6., Blk D #01-87,

Autobay @ Kaki Bukit

Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Poh Kin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Dec 2018)
Parts: 143	BMW 528i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKF7078T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR CHECKER RH (CONSISTENT)	Bent	82.25 FL	*82.25 FL
2	2		*FRONT DOOR HINGES RH (CONSISTENT)	Bent	108.80 FL	*108.80 FL
3	1		*FRONT DOOR LOCK STRIKER RH (CONSISTENT)	Not Necessary	19.45 FL	*- FL
4	1		*FRONT DOOR MECHANISM LOCK RH (CONSISTENT)	Bent	663.25 FL	*663.25 FL
5	1		*FRONT DOOR OUTER HANDLE RH (CONSISTENT)	Cut	580.00 FL	*580.00 FL
6	1		*FRONT DOOR RH (CONSISTENT)	Bent	1,689.20 FL	*1,689.20 FL
7	1		*FRONT DOOR SIDE MIRROR RH (CONSISTENT)	Cut	1,728.05 FL	*912.80 FL
8	1		*FRONT DOOR WEATHER STRIP RH (CONSISTENT)	Necessary	161.50 FL	*161.50 FL
9	1		*FRONT DOOR WINDOW GLASS REGULATOR MOTOR RH (CONSISTENT)	Bent	297.80 FL	*297.80 FL
10	1		*FRONT FENDER RH (CONSISTENT)	Bent	842.30 FL	*842.30 FL
11	1		*FRONT FENDER SIGNAL LAMP RH (CONSISTENT)	Not Necessary	79.65 FL	*- FL
12	1		*REAR DOOR RH (CONSISTENT)	Repair	1,689.20 FL	*- FL
13	1		*REAR KNUCKLE ARM RH (CONSISTENT)	Not Necessary	1,217.80 FL	*- FL
14	1		*REAR KNUCKLE BEARING RH (CONSISTENT)	Not Necessary	189.95 FL	*- FL
15	1		*REAR LOWER ARM RH (CONSISTENT)	Not Necessary	202.05 FL	*- FL
16	1		*REAR SHOCK ABSORBER RH (CONSISTENT)	Not Necessary	484.70 FL	*- FL
17	1		*REAR SPORT RIM RH (CONSISTENT)	Cut	991.40 FL	*991.40 FL
18	1		*REAR UPPER ARM RH (CONSISTENT)	Not Necessary	552.85 FL	*- FL
19	1		*SIDE SKIRT RH (CONSISTENT)	Deformed	429.25 FL	*429.25 FL
20	1		*REAR TYRE (RH) (CONSISTENT)	Not Necessary	680.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,689.45	6,758.55
- List Item Discount on L Items 5.00/5.00% (S\$)	600.47	337.93
Total Parts (S\$)	12,088.98	6,420.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DIAGNOSE ,REPLACE AND OR REPAIR TO RECTIFY FRONT DOOR ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	200.00	60.00
2	TO DIAGNOSE ,REPLACE AND /OR REPAIR TO RECTIFY REAR DOOR ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	100.00	60.00
3	TO REMOVE ,CHARGE FRONT SUSPENSION PARTS ,ABSORBER ,LOWER ARM ,KNUCKLE ARM WHEEL BEARING ,BEARING HUB ,DRIVE SHAFT ,ANTI-ROLL BAR ,TOP-ARM AND STEERING RACK AND PINION	New	250.00	0.00
4	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT AND ADJUSTMENTS	New	120.00	80.00
5	TO TRANSFER FRONT DOOR GLASS ,REGULATOR GEAR,MOTOR ,RAILING ,CHANNEL ,TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	200.00	80.00
6	TO TRANSFER REAR DOOR GLASS ,REGULATOR GEAR ,MOTOR ,RAILING ,CHANNEL ,TRIM BOARD,MECHANISM LOCK AND HANDLE	New	100.00	0.00
7	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,600.00	1,200.00
8	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,400.00	900.00
Gross Labour Cost (\$\$)			3,970.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >