

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9543A - CHINA**Candy***Not Ashok
U/Sing &*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD 9543A - Candy
KL1LA69RJB089142
CHEVROLET
EPICA 2.0
13.10.16
CHINA

		PART		LIST	
1	1	Front Bumper	\$	B ₁ 1,202.00	✓
2	1	Front Bumper Reinforcement	\$	B ₁ 295.25	✓
3	1	Front Bumper Lower Absorber	\$	CM 180.00	—
4	1	Front Bumper Lower Grille	\$	M ₁ 78.00	✓
5	1	Front Bumper Retainer RH	\$	S ₁ 102.00	X
6	1	Front Bumper Retainer LH	\$	S ₁ 102.00	X
7	1	Front Bumper Lower Stiffener	\$	R 134.37	X
8	1	Front Headlamp RH	\$	M ₁ 816.00	✓
9	1	Front Headlamp LH	\$	M ₁ B ₂ 816.00	✓
10	1	Front Bumper Fog Lamp Outer Cover LH	\$	S ₁ 32.40	X
11	1	Front Bumper Fog Lamp Outer Cover RH	\$	S ₁ 32.40	X
12	1	Front Support Panel Assy (Panel A-Frt)	\$	B ₁ 1,222.32	✓
13	1	Bonnet (Panel A-Hood)	\$	B ₁ 1,250.00	✓
14	1	Centre 'CHEVROLET' Logo Badge	\$	M 144.30	✓
15	1	Bonnet Moulding	\$	P ₁ 257.00	✓
16	1	Bonnet Insulator	\$	S ₁ 84.63	X
17	1	Bonnet hinge RH	\$	R 36.00	X
18	1	Bonnet hinge LH	\$	R 36.00	✓
19	1	Bonnet cable	\$	S ₁ 150.00	X
20	1	Bonnet lock	\$	B ₁ 200.00	✓
21	2	HORN LH	\$	320.00	?
22	1	Radiator Grille (Grille A-Rad)	\$	CM 367.00	✓
23	1	Radiator Assembly (Radiator A)	\$	1 _{two} B ₂ 618.00	✓
24	1	Radiator upper hose	\$	30.00	?
25	1	Radiator lower hose	\$	120.00	?
26	1	Aircon Condenser (Condenser A)	\$	B ₁ 600.00	✓
27	1	Aircon hose - condenser to compressor	\$	215.40	?
28	1	Aircon hose - compressor to evaporator	\$	316.20	?
29	1	Aircon hose - condenser to evaporator	\$	332.10	?
30	1	Aircon compressor - pump	\$	1,847.95	?
31	1	Aircon compressor bracket	\$	245.30	?
32	1	Front Centre Member	\$	S ₁ 265.63	X
33	1	Air Intercooler	\$	B ₁ P ₁ 652.00	✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9543A - CHINA

Candy

34	1	Fan Blade (Small)	\$	CM	536.00	✓
35	1	Fan Blade (Big)	\$		634.00	?
36	1	Front Fender LH	\$	Bu	837.60	✓
37	1	Front Fender RH	\$	Bu	837.60	✓
38	1	Fender Insulation RH	\$	Sm	39.00	X
39	1	Front Fender Liner RH	\$	Sm	47.00	X
40	1	Front Fender Liner LH	\$	Sm	47.00	X
41	1	Rear Bumper	\$	Bu	1,202.00	✓
42	1	Rear Bumper Beam	\$	Bu	239.94	✓
43	1	Rear Bumper Centre Absorber	\$	CM	260.00	✓
44	1	Rear Bumper Side Retainer RH	\$	CM	68.76	✓
45	1	Rear Bumper side support RH	\$	Sm	25.00	X
46	1	Rear Bumper Reflectors RH	\$	CM	119.74	✓
47	1	Rear Bumper stay RH	\$	Sm	35.00	X
48	1	Rear Bumper Tow Hook Cover	\$	Sm	93.00	X
49	1	Rear End Panel Inner	\$	Bu	336.84	✓
50	1	Rear End Panel Outer	\$	Bu	623.76	✓
51	1	Rear End Panel Inner Trim	\$	Dis	263.84	✓
52	1	Bootlid	\$	Bu	973.00	✓
53	1	Bootlid inner trim board	\$	Sm	400.00	X
54	1	Bootlid Weatherstrip	\$	Not in	344.28	50% in
55	1	Bootlid Lock - Top	\$	Dis	466.56	✓
56	1	Bootlid lock - bottom	\$	Bu	39.40	✓
57	1	Bootlid 'CHEVROLET' Badge	\$	Bu	120.62	✓
58	1	Bootlid Logo	\$	Bu	138.84	✓
59	1	Bootlid 'EPICA LT' Badge	\$	Bu	119.84	✓
60	1	Bootlid inner handle	\$	Sm	45.55	X
61	1	Bootlid Reflector Centre	\$	Sm	217.97	X
62	1	Bootlid Reflector RH	\$	CM	128.40	✓
63	1	Bootlid Reflector LH	\$	CM	128.40	✓
64	1	Bootlid Hinge RH	\$	K	120.00	X
65	1	Bootlid Hinge LH	\$	K	120.00	X
66	1	Rear Gas T/Gate Spring RH	\$	Sm	286.90	X
67	1	Rear Gas T/Gate Spring LH	\$	Sm	286.90	X
68	1	Rear number plate lamp RH	\$	Sm	25.00	X
69	1	Rear number plate lamp LH	\$	Sm	25.00	X
70	1	Rear Tail Lamp RH	\$	Bu	479.30	✓
71	1	Rear Tail Lamp Panel RH	\$	Bu	359.00	✓
72	1	Rear Tail Lamp LH	\$	Bu	479.30	✓
73	1	Rear Tail Lamp Panel LH	\$	Bu	359.00	✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9543A - CHINA

Candy

74	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	Bz 1,110.00	✓
75	1	Centre Exhaust Pipe	\$	403.00	?
76	1	Rear Fender RH	\$	Bz 1,145.00	✓
77	1	Rear Fender Inner Cowling RH	\$	Sm 298.00	X
78	1	Rear Fender Inner Trim RH	\$	De form 418.44	✓
79	1	Rear Fender Inner Wheel House Panel RH	\$	R 2,556.35	X
80	1	Rear Fender LH	\$	Bz 1,145.00	✓
81	1	Rear Fender Inner Cowling LH	\$	Sm 298.00	X
82	1	Rear Fender Inner Trim LH	\$	De form 418.44	✓
83	1	Rear Fender Inner Wheel House Panel LH	\$	R 2,556.35	X
84	1	Rear Door RH (Panel A-RR DR RH)	\$	R 1,133.00	X
85	1	Rear Door weatherstrip - Inner RH	\$	Sm 41.40	✓

TOTAL	\$	36,532.57
10%	\$	3,653.26
	\$	32,879.31

Special Nett

1	1Set	Front Bumper Fastener Clip	\$	Mc 24.00	✓
2	1Set	Front Licence Plate With Holder	\$	De 192.00	2.5 Sm
6	1Set	Bonnet Insulator Clip	\$	nn 40.00	X
7	1Set	Radiator Grille Clip	\$	nn 18.00	✓
8	1Set	Radiator Grille Top Cover Clip	\$	nn 10.00	✓
9	1Set	Front Fender Liner Clip LH	\$	nn 40.00	X
10	1Set	Front Fender Liner Clip RH	\$	nn 40.00	X
11	1Set	Engine Splash Cover Clip RH	\$	nn 12.00	X
12	1Set	Rear Bumper Parking Sensor	\$	De 300.00	✓
13	1Set	Rear Bumper Fastener Clip	\$	nn 30.00	✓
14	1Set	Rear Fender inner cowling clip RH	\$	nn 30.00	X
15	1	Rear Boot Sticker 'Trans-cab'	\$	nn 30.00	✓
16	1	Rear Boot Sticker '6555-3333'	\$	nn 30.00	✓
18	1	Rear Door Sticker '6555-3333' RH	\$	nn 30.00	X
18	1	Rear Door Sticker '6555-3333' LH	\$	nn 30.00	X
22	1	Spare Tyre RH	\$	Sm 180.00	X
23	1	Spare Wheel Rim RH	\$	Sm 126.74	X
24	2	Rear Windscreen Sealant	\$	nn 80.00	40 Sm
25	1	Rear Windscreen Inner Sponge Seal	\$	nn 100.00	30 Sm

TOTAL	\$	1,342.74
TOTAL PARTS	\$	34,222.05

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9543A - CHINA**Candy**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	16,800.00 <i>2800</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>40</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 ✓
Putty And Spray Painting Of The Affected Portion.	\$	16,200.00 <i>2200</i>
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00 <i>220</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>60</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 <i>250</i>
To transfer of Fender fittings, attachments and perform water seepage test.	\$	170.00 <i>100</i>
Towing Fees.	\$	120.00 <i>50</i>
To check steering geometry and computer wheel alignment	\$	220.00 <i>60</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>~</i> 170.00 <i>X</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 <i>120</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>~</i> 120.00 <i>X</i>
To check ABS brake efficiency, final checking and testing.	\$	<i>~</i> 380.00 <i>X</i>

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9543A - CHINA

Candy

To replace, refix and top up coolant for radiator	\$	170.00	<i>50</i>
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	<i>50</i>
	\$	35,960.00	
TOTAL	\$	70,182.05	

Repair Days

~~60 Days~~
21 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: