



GIA

SMRT Automotive Services Pte Ltd


60 Woodlands Industrial Park E4, Singapore 757705

Tel : 65 6362 3422 Fax : 65 6368 7420

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1103A
Ref. No : TAX/10/16/2126
Reg. Date : 05/06/2013
Vehicle Type : TAXI
Make : CHEVROLET EPICA 2.0 VCDI
Model : EPICA-2.0
Name of Driver : WEE SOON WAH
Type of Accident : SIDE SWIPE
Date / Time of Accident : 15/10/2016 06:10:00 PM
Accident Reported Date / Time : 17/10/2016 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024085409
Special Instruction to ARC, if any :
GBE897D - /Chinat / Repair after repair
Prepared Date : 17/10/2016 10:12:40 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB138302 Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	507.00	0.00
Total Spray Painting Charges :	756.00	0.00
Total Material Charges :	2,671.20	2,671.20
Other Charges :	348.44	0.00
TOTAL :	4,282.64	0.00
Lum Sum Total :	4,300.00	0.00
No. of Repair Days :	4.00	0.00 <i>4 days</i>
Prepared / Adjusted By :		<i>4S</i>
Prepared / Adjusted Date :	17/10/2016 05:10:34 PM	01/01/1900 12:00:00 AM

*M**Pre 18/10/16 e 1440*

Prepared Date : 17/10/2016 04:50:23 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 10/17/2016 5:11:29 PM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	507.00	0.00 <i>400</i>
Total Labour	507.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 <i>200</i>
TO RESPRAY FRONT FENDER LH	378.00	0.00 <i>200</i>
Total Spray Painting & Panel Beating	756.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 <i>2030</i>
TO APPLY RUST-PROOFING ON AFFECTED AREA	120.00	0.00 <i>40</i>
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	148.44	0.00 <i>148.44</i>
Total Other Costs	348.44	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
93744489	FRONT	BUMPER FRT ASSY	1	1,238.00	10.00	1,114.20	Replace	Replace <i>TORR</i>	No
96644857	FRONT	LAMP HEAD LH	1	841.00	10.00	756.90	Replace	Replace <i>check?</i>	No
96636324	FRONT	PANEL FRT FENDER LH	1	606.00	10.00	545.40	Replace	Replace <i>M</i>	No
96633939	FRONT	LINER FENDER FRT LH (PROTECTOR)	1	49.00	10.00	44.10	Replace	Replace <i>TORR</i>	No
96644865	FRONT	LAMP FOG FRT LH	1	260.00	10.00	234.00	Replace	Replace <i>not given</i>	No X
96437321	FRONT	BEZEL FOG LAMP LH (COVER)	1	32.00	10.00	28.80	Replace	Replace <i>not given</i>	No X
96634054	FRONT	BEAM FRT BUMPER IMPACT	1	465.00	10.00	418.50	Replace	Replace <i>not given</i>	No X
96634053	FRONT	ABSORBER ENGY FRT BUMPER	1	219.00	10.00	197.10	Replace	Replace <i>not given</i>	No X
TOTAL MATERIALS						2,671.20			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: