

SHD 377Y - III

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

Not Asherim
§

Candy

SHD 377Y - Candy
VF1ABL15AUC282280
RENAULT
LATITUDE
13.10.16
III

PART

LIST

QTY	DESCRIPTION	UNIT PRICE	TOTAL PRICE
1	BUMPER COVER FRT	\$	968.79
2	BUMPER SPOILER FRT	\$	139.81
3	BUMPER ABSORBER FRT	\$	303.60
4	BUMPER BRACKET FRT LH	\$	116.47
5	BUMPER RETAINER FRT LH	\$	18.37
6	BUMPER BRACKET FRT RH	\$	115.98
7	BUMPER REPAIRER FRT RH	\$	18.37
8	BUMPER UNDERTRAY FRT	\$	363.71
9	BUMPER GRILLE LOWER FRT	\$	205.23
10	BUMPER FOG LAMP GRILLE LH	\$	159.39
11	BUMPER FOG LAMP GRILLE RH	\$	159.39
12	BUMPER BEAM FRT	\$	703.14
13	RADIATOR GRILLE	\$	1,313.68
14	RADIATOR GRILLE BADGE 'RENAULT'	\$	173.36
15	RADIATOR GRILLE FRAME	\$	1,041.35
16	FRAME FULL SUPPORT PANEL	\$	473.77
17	FRAME FULL SUPPORT BRACKET	\$	69.07
18	FRONT BRACE PANEL	\$	136.32
19	SUBFRAME OUTER FRT	\$	2,040.34
20	SUBFRAME INNER FRT (crossmember)	\$	1,757.54
21	SUBFRAME SUPPORT INNER	\$	71.04
22	SUBFRAME BRACKET OUTER LH	\$	71.04
23	SUBFRAME BRACKET OUTER RH	\$	71.04
24	SUBFRAME BRACKET INNER LH	\$	138.44
25	SUBFRAME BRACKET INNER RH	\$	138.44
26	LOWER ARM RH	\$	527.51
27	BRAKE DISC FRT	\$	211.91
28	KUNCKLE ARM RH	\$	651.53
29	KUNCKLE HUB+BEARING RH	\$	382.84
30	KUNCKLE ARM SHIELD RH	\$	101.10
31	KUNCKLE ARM PLATE RH	\$	133.89
32	BRAKE DISC FRT	\$	211.91
33	ABSORBER FRT RH	\$	277.34
34	ABSORBER MOUNTING KIT RH	\$	338.97

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 377Y - III

35	1	ABSORBER DUST COVER	\$	175.94 ✓
36	1	STABILIZER BAR FRT	\$	465.12 ✓
37	1	STABILIZER LINK FRT	\$	90.17 ✓
38	1	BRAKE CALIPER FRT RH	\$	505.34 X
39	1	BRAKE CALIPER BRACKET FRT RH	\$	427.01 ✓
40	1	ABS SENSOR FRT RH	\$	196.73 ?
41	1	BRAKE HOSE FRT RH	\$	96.70 X
42	1	DRIVESHAFT RH	\$	1,344.19 ✓
43	1	LOWER ARM LH	\$	527.51 X
44	1	BRAKE DISC FRT	\$	211.91 X
45	1	KUNCKLE ARM LH	\$	651.53 X
46	1	KUNCKLE HUB+BEARING LH	\$	382.84 X
47	1	KUNCKLE ARM SHIELD LH	\$	101.10 X
48	1	KUNCKLE ARM PLATE LH	\$	133.89 X
49	1	BRAKE DISC FRT	\$	211.91 X
50	1	ABSORBER FRT LH	\$	277.34 X
51	1	ABSORBER MOUNTING KIT LH	\$	338.97 X
52	1	ABSORBER DUST COVER	\$	175.94 X
53	1	STABILIZER BAR FRT	\$	465.12 X
54	1	STABILIZER LINK FRT	\$	90.17 X
55	1	BRAKE CALIPER FRT LH	\$	505.34 X
56	1	BRAKE CALIPER BRACKET FRT LH	\$	427.01 X
57	1	ABS SENSOR FRT LH	\$	196.73 X
58	1	BRAKE HOSE FRT LH	\$	96.70 X
59	1	DRIVESHAFT LH	\$	1,344.19 X
60	1	SEATBELT BUCKLE RH	\$	730.61 ?
61	1	SEATBELT RH	\$	2,250.28 ✓
62	1	SEATBELT BUCKLE LH	\$	730.61 ?
63	1	SEATBELT LH	\$	2,250.28 ✓
64	1	PASSENGER AIRBAG	\$	2,624.93 ✓
65	1	PASSENGER AIRBAG COMPUTER	\$	969.09 ✓
66	1	PASSENGER AIRBAG SENSOR	\$	557.41 ✓
67	1	STEERING AIRBAG	\$	1,942.89 ✓
68	1	STEERING AIRBAG SENSOR	\$	222.54 ✓
69	1	STEERING AIRBAG COMPUTER	\$	969.09 X
70	1	ROTARY SWITCH	\$	963.93 ?
71	1	DASHBOARD	\$	3,769.65 ✓
72	1	GLOVE BOX	\$	799.83 ?
73	1	GLOVE BOX FLAP	\$	983.82 X
74	1	HEADLAMP LH	\$	911.10 X
75	1	HEADLAMP RH	\$	911.10 ✓
76	1	HEADLAMP HARNESS RH	\$	714.07 ?

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 377Y - III

77	1	HEADLAMP HARNESS LH	\$	Sm 714.07 X
78	1	HEADLAMP PANEL FRT RH	\$	R 134.59 ✓
79	1	HEADLAMP PANEL FRT LH	\$	R 134.59 X
80	1	BONNET	\$	R 1,493.56 ✓
81	1	BONNET INSULATOR	\$	Sm 312.10 X
82	1	BONNET STRUT LH	\$	Sm 166.29 X
83	1	BONNET STRUT RH	\$	Sm 166.29 X
84	1	BONNET HINGE LH	\$	Di 267.93 —
85	1	BONNET HINGE RH	\$	Di 267.93 —
86	2	BAL HOOD	\$	Sm 75.60 X
87	1	BONNET LOCK	\$	R 234.99 X
88	1	BONNET CABLE	\$	Sm 91.69 X
89	1	BONNET CABLE COVER	\$	R 123.87 X
90	1	BONNET SEAL OUTER	\$	Sm 71.04 X
91	1	FENDER PANEL FRT LH	\$	R 602.95 X
92	1	FENDER PANEL FRT RH	\$	R 602.95 ✓
93	1	FENDER WHEELARCH FRT LH (Linner)	\$	Sm 107.32 X
94	1	FENDER WHEELARCH FRT RH (Linner)	\$	R 214.49 ✓
95	1	FENDER INSULATOR RH	\$	100.64 ?
96	1	FENDER INSULATOR LH	\$	Sm 100.64 X
97	1	FENDER PANEL BRACKET FRT RH	\$	161.52 ?
98	1	FENDER PANEL BRACKET FRT LH	\$	R 161.52 X
99	1	WHEEL HOUSING PANEL FRT RH	\$	3,601.61 ?
100	1	WHEEL HOUSING PANEL FRT LH	\$	R 3,601.61 X
101	1	FENDERCHASSIS REINFORCEMENT FRT LH	\$	R 765.90 X
102	1	FENDERCHASSIS REINFORCEMENT FRT RH	\$	765.90 ?
103	1	RADIATOR	\$	Sm 924.77 X
104	1	RADIATOR FAN COWLING	\$	Sm 573.80 X
105	1	RADIATOR FAN MOTOR LH	\$	Sm 676.48 X
106	1	RADIATOR FAN MOTOR RH	\$	Sm 676.48 X
107	1	RADIATOR HOSE UPPER	\$	Sm 168.22 X
108	1	RADIATOR HOSE LOWER	\$	Sm 343.48 X
109	1	AIR CLEANER HOSE	\$	Sm 58.57 X
110	1	AIR CLEANER LOWER	\$	Sm 311.95 X
111	1	ENGINE UNDERTRAY	\$	C 434.60 ✓
112	1	A/C CONDENSER	\$	Sm 1,554.13 X
113	1	A/C CONDENSER GARNISH LH UPPER	\$	Sm 27.74 X
114	1	A/C CONDENSER GARNISH RH UPPER	\$	Sm 27.74 X
115	1	A/C CONDENSER GARNISH LH	\$	Sm 41.12 X
116	1	A/C CONDENSER GARNISH RH	\$	Sm 41.68 X
117	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	Sm 145.73 X
118	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Sm 460.64 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 377Y - III

119	1	A/C PIPE COMPRESSOR
120	1	A/C PIPE
121	1	TRANSMISSION COOLER
122	1	AIR INTERCOOLER HOSE (LONG)
123	1	AIR INTERCOOLER HOSE (Short)
124	1	STEERING PUMP ELECTRIC
125	1	STERING HOSE LOW PRESSURE LONG
126	1	STERING HOSE LOW PRESSURE
127		WINDSCREEN FRT
128	1	WIPER RESERVOIR
129	1	WIPER RESERVOIR NECK
130	1	WIPER RESERVOIR MOTOR
131	1	DOOR PANEL FRT LH
132	1	DOOR MIRROR LH
133	1	DOOR SEAL FRT LH
134	1	DOOR PANEL FRT RH
135	1	DOOR MIRROR RH
136	1	DOOR SEAL FRT RH
137	1	ROCKER PANEL OUTER RH

\$	Sm	233.77	X
\$	Sm	460.64	X
\$	Sm	852.66	X
\$	Sm	709.18	X
\$	Sm	262.34	X
\$	Sm	1,543.08	X
\$	Sm	442.50	X
\$	Sm	247.18	X
\$	CM	1,005.56	✓
\$	Bu	190.96	✓
\$	Sm	27.78	✓
\$	CM	100.95	✓
\$	A	2,188.20	X
\$	Sm	1,141.08	X
\$	Sm	50.92	X
\$	R	2,188.20	X
\$	Sm	1,141.08	X
\$	Sm	50.92	X
\$	Bu	759.61	✓

TOTAL	\$	79,690.98
10%	\$	7,969.10
	\$	71,721.88

Specical Nett

1	1SET	RADIATOR GRILLE FRAME CLIP
2	1SET	BUMPER CLIP FRT
3	1	TOW COVER FRT
4	1SET	RADIATOR GRILLE SCREW
5	1SET	BUMPER GRILLE LOWER CLIP
6	1SET	FRAME FULL SUPPORT PANEL CLIP
7	2	FRAME FULL SUPPORT PANEL NUT
8	2	FRAME FULL SUPPORT PANEL STUD
9	2	BONNET CABLE CLIP
10	1SET	WHEELARCH CLIP LH
11	1SET	WHEELARCH CLIP RH
12	2	Front windscreen sealant
13	2	Front windscreen moulding
14	2	"E.R.P" Sticker
15	1	DOOR STICKER "Trans-cab"
16	1	DOOR STICKER "Classic"
17	1	DOOR STICKER "6555-3333"
18	1SET	NUMBER PLATE WITH HOLDER

\$	Sm	52.00	✓
\$	Sm	66.00	✓
\$	Sm	14.50	✓
\$	Sm	16.00	✓
\$	Sm	69.00	X
\$	Sm	70.00	X
\$	Sm	20.00	X
\$	Sm	30.00	X
\$	Sm	6.40	✓
\$	NA Bu	30.50	X
\$	Sm	29.40	✓
\$	Sm	80.00	40sm
\$	Sm	100.00	✓
\$	Sm	65.00	26sm
\$	Sm	80.00	60sm
\$	Sm	30.00	15sm
\$	Sm	80.00	X
\$	Sm	140.00	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 377Y - III

19	1	DASHBOARD SCREW	\$	55.55	✓
20	1	CAP HUB RH FRT	\$	cm 35.00	✓
21	1	RIM RH FRT	\$	R 385.00	✓
22	1	TYRE RH FRT	\$	Per 330.00	30/52
23	1	CAP HUB LH FRT	\$	52 35.00	X
24	1	RIM LH FRT	\$	52 385.00	X
25	1	TYRE LH FRT	\$	52 330.00	X
26	1	CAP HUB LH RR	\$	52 35.00	X
27	1	RIM LH RR	\$	52 385.00	X
28	1	TYRE LH RR	\$	52 330.00	X

TOTAL	\$	3,284.35
TOTAL PARTS	\$	75,006.23

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 8,400.00 1200

Putty and spray painting of the affected portion.

\$ 9,000.00 1320

To rust-proofing of the affected areas.

\$ 170.00 1200

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 600

Towing Fees.

\$ 120.00 500

To transfer of tire, rim and on wheel balancing.

\$ 170.00 200

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.

\$ 380.00 2800

To remove and renew engine and gear box mounting.

\$ 380.00 } 2800

To lift-up engine with gear box and refit.

\$ 440.00 }

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHD 377Y - III

To dismantle and refit engine cross-member and engine mounting.	\$	380.00 ?
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00 ?
To remove and refit air bag system and reset.	\$	480.00 250
To check ABS brake efficiency, final checking and testing.	\$	380.00 ?
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 250
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 }
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 120
To Check Electrical Lighting Concerned.	\$	170.00 30
TOTAL	\$	22,440.00
Over All Total	\$	97,446.23

< parts by parts > Repair Days

30 DAYS

16 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental parts must be resurveyed and is subject to the approval from Insurance Company

Acknowledged by Insurance:

Signature:

Date: