

**金興(龔)汽車私人有限公司**

新民通道 (大牌 34 座) 門牌 114 號  
Blk 34 Sin Ming Drive, #01-114, Singapore 575708.  
Tel: 6452 7018 (5 Lines) Fax: 6458 3895  
Email: service@kkimhin.com.sg

No. : 28388

Vehicle Insured : SKX 3815 P  
Accident Date : 05-Nov-2016

Date : 21-Nov-2016

Our Ref : 160841 (LONPAC) / JUSTIN

PAGE : 1

MS KAM LAI LIN  
Singapore

*Not Authorised  
11/Nov/87  
Resurvey After Paint*

ESTIMATED COST OF REPAIR FOR HONDA FIT 1.3 A (2007) SGU4422X  
=====

|                                            |            |                       |
|--------------------------------------------|------------|-----------------------|
| 1 pc front bumper                          |            | <i>Bu</i> 170.00 c ✓  |
| 1 pc o/s front bumper side retainer        |            | <i>Di</i> 15.00 c ✓   |
| 10 pcs front bumper clip                   | @ S\$ 0.60 | <i>Ma</i> 6.00 c ✓    |
| 1 pc o/s front fender                      |            | <i>Bu</i> 170.00 c ✓  |
| 1 pc o/s front fender inner shield         |            | 45.00 c ?             |
| 10 pcs o/s front fender inner shield clips | @ S\$ 0.60 | 6.00 c ?              |
| 1 pc o/s front fender signal lamp          |            | 15.00 c ?             |
| 1 pc o/s headlamp                          |            | <i>Cut</i> 350.00 c ✓ |
| 1 pc o/s headlamp lower bracket            |            | <i>R</i> 24.00 c X    |
| 1 pc o/s front lower arm                   |            | <i>R</i> 115.00 c X   |
| 1 pc o/s front knuckle arm                 |            | <i>Sh</i> 175.00 c X  |
| 1 pc o/s front knuckle arm bearing         |            | <i>nn</i> 90.00 c X   |
| 1 pc o/s front shock absorber              |            | <i>Sn</i> 115.00 c X  |
| 1 pc o/s front shock absorber mounting     |            | <i>Sn</i> 28.00 c X   |
| 1 pc o/s front shock absorber stopper      |            | <i>Sn</i> 25.00 c X   |
| 1 pc o/s front shock absorber bearing      |            | <i>nn</i> 30.00 c X   |
| 1 pc o/s front shock absorber cover        |            | <i>R</i> 25.00 c X    |

1,404.00

Add 15% : 210.60

1,614.60

1 pc o/s front tyre  
1 pc o/s front sport rim

*Sn* 280.00 sn X  
*Bu* 450.00 sn 250

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...



金興(龔)汽車私人有限公司

新民通道(大牌34座)門牌114號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

Vehicle Insured : SKX 3815 P  
Our Ref : 160841

Page : 2  
No. : 28388

To remove, cut out damaged parts,  
panel beating, welding, align,  
refix and to renew affected parts.

400  
480.00

To dismantle and check front under-  
carriages. To replace affected  
portions.

~ 170.00 X

To conduct front wheel alignment  
test.

80.00 60

To putty and respray on affected  
portions.

650.00 400

To focus headlamps. To check front  
wiring and lighting operation.

30.00 20

To apply undersealing

40.00 30

Total : S\$ 3,794.60  
=====

Singapore Dollars Three Thousand Seven Hundred  
and Ninety Four and Cents Sixty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.