

15/5/2010

INS. CASE OWNER:

CCH / LPC160

21875, m1h3n2

LKK:

IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

LTS

SS 1,500.00

(4 days)

Reduction:

57 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

30

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

\$1,000.00

SS

829.25

(COMPUTING VERSION)

Loss of Rental (LOR):

\$400

SS

200.00

(4 days)

x \$100.00

Loss of Use (LOU):

SS

-

(\$

x

days)

Loss of Income (LOI):

SS

-

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search \$2.00

SS

200

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$450.00

Total: \$2,000.00

SS

1,031.25

Global Sum SS:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

1,031.25

Name 1:

S H A MOTOR PTE LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC16021875/M1hg3	
100 BEACH ROAD #19-00 SHAW TOWERS SINGAPORE 189702			Date : 16-11-2016	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGU 4422X	Veh. Inspected	SKX 3815P	
Policy No.	Z16VP05008502	Coverage (\$)	0.00	
Claim No.	16/16/16/VP05/019416	Excess (\$)	0.00	
Assign From		Assign Date	16/11/2016	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/11/2016	Inspection Date	15/11/2016	
Survey held at	S & H MOTOR PTE LTD BLK 11 SIN MING ROAD #01-83 SIN MING INDUSTRIAL ESTATE . SINGAPORE 575655			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Text size + -

Enquire Transfer Fee

Vehicle Details

Vehicle No. : SKX3815P
 Vehicle Type : R10 - Private Hire (Self-Drive) Motor Car
 Vehicle Attachment 1 : No Attachment
 Vehicle Scheme : Normal
 Vehicle Make : HONDA
 Vehicle Model : CIVIC 1.8L A
 Chassis No. : JHMFD16307S206688
 Propellant: Petrol
 Engine No. : R18A12017167
 Engine Capacity : 1799 cc
 Maximum Power Output: 103.0 kW (138 bhp)
 Maximum Laden Weight: 1640 kg
 Unladen Weight: 1219 kg
 Year Of Manufacture: 2006
 Original Registration Date: 23 Feb 2007
 Lifespan Expiry Date : -
 COE Category : B - Car (1601cc & above)
 Quota Premium : \$12,152.00
 COE Expiry Date : 22 Feb 2017
 Road Tax Expiry Date : 29 Dec 2016
 PARF Eligibility Expiry Date : 22 Feb 2017
 Inspection Due Date : 22 Feb 2018
 Intended Transfer Date : 14 Nov 2016

CO2 Emission: -

The current road tax expiry is 29 Dec 2016. You may renew the road tax from 30 Sep 2016 with all pre-requisite(s) fulfilled. If the road tax is renewed after 29 Dec 2016, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 30 Dec 2016 to 22 Feb 2017)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	11.00	-	11.00
Sub Total :			11.00
Nett Road Tax Amount (After Offsetting Over Payment) :	151.00	-	151.00

EVERVIT LEASING PTE LTD

File No :

SH/2016

Date :

14-November-2016



Estimated cost of repair for vehicle no : **SKX3815P** Model **HONDA CIVIC**
 Accident involving vehicle no: **SKX3815P** & **SGU4422X** on **05.11.2016**

Description	Quantity	Cost Price
Rear Bumper		\$ 280.00
LH rear alloy wheel		\$ 550.00 200 S/N.
LH rear knuckle arm		\$ 290.00
LH rear knuckle arm wheel bearing		\$ 225.00
LH rear bumper retinner bracket		\$ 28.00
LH tial lamp		\$ 155.00 200 S/N.
		\$ 1,528.00
	Add 15%	\$ 229.20
		\$ 1,757.20
Labour to remove rear bumper , wheel arch panel & panel beating, LH rear fender, LH rear wheel housing innel panel & LH rear running board panel		\$ 650.00 500
To spray painting LH rear door, rear fender, rear bumper and LH running board panel		\$ 950.00 500.
Remove & check rear suspension and renew knuckle		\$ 220.00 80.
To check rear wheel alignment		\$ 65.00
		\$ 3,642.20

T/Party: Lonpac Insurance

Not Authorised
 W/S Repair
 After painting
 L&K Auto (M) Ltd
 15/11/2016
 4 wlday

\$1550 k
 4 wlday
 15/11/2016

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Thursday, 15 December, 2016 5:06 PM
To: ONG LI LI
Cc: MT_Claim_SG; Jas Khine (LKKAUTO); Admin A; Vic (LKKAUTO)
Subject: RE: Our Ref: 16/16/16/VP05/019416 Accident involving SGU 4422X & SKX 3815P at Sin Ming Rd on 5/11/16 ***LKK REF: CC4/LPC16021875/M1hg3
Attachments: 15122016165010.pdf

Dear Li Li,

We refer to your below email and the contents were duly noted.

We noted that both vehicles involved were under LONPAC and were claiming against each other.

We will revert back for our mandate proposal in due course.

Thank you.

"Wishes you a Merry Christmas & Happy New Year 2017"

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Thursday, 15 December, 2016 4:55 PM
To: Agnes Lim (LKKAUTO) <AgnesLim@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Jas Khine (LKKAUTO) <jaskhine@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Our Ref: 16/16/16/VP05/019416 Accident involving SGU 4422X & SKX 3815P at Sin Ming Rd on 5/11/16 ***LKK REF: CC4/LPC16021875/M1hg3

Dear Agnes/Vic

Attached is the TP LOD for your handling.

Please remind TP workshop to send the LOD directly to your office in future.

Regards,
Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd
100 Beach Road, #19-00 Shaw Tower, Singapore 189702
Tel : (65) 6250 7388 Ext. 247 Fax: (65) 6296 2706

From: ONG LI LI
Sent: Monday, 21 November, 2016 11:51 AM
To: 'Agnes Lim (LKKAUTO)'
Cc: MT_Claim_SG; Vic (LKKAUTO); Jas Khine (LKKAUTO); Admin A
Subject: RE: Our Ref: 16/16/16/VP05/019416 Accident involving SGU 4422X & SKX 3815P at Sin Ming Rd on 5/11/16 ***LKK REF: CC4/LPC16021875/M1hg3

Hi Agnes/Vic

Attached is our insured's GIA report for your assessment and handling.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
100 Beach Road, #19-00 Shaw Tower, Singapore 189702
Tel : (65) 6250 7388 Ext. 247 Fax: (65) 6296 2706

From: Agnes Lim (LKKAUTO) [<mailto:AgnesLim@lkkauto.com>]
Sent: Thursday, 17 November, 2016 9:11 AM
To: GERALD POH WEE BIN
Cc: ERIC WOO JUN KIAT; MT_Claim_SG; Vic (LKKAUTO); Jas Khine (LKKAUTO); Admin A
Subject: RE: Our Ref: 16/16/16/VP05/019416 Accident involving SGU 4422X & SKX 3815P at Sin Ming Rd on 5/11/16 ***LKK REF: CC4/LPC16021875/M1hg3

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SKX 3815P at M/s S&h motor Pte Ltd - Sin Ming.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice

Our case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Agnes Lim | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: AgnesLim@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ERIC WOO JUN KIAT [<mailto:ericwoo@lonpac.com>]

Sent: Monday, 14 November, 2016 5:12 PM

To: assignments@lkkauto.com

Cc: MT_Claim_SG

Subject: Our Ref: 16/16/16/VP05/019416 Accident involving SGU 4422X & SKX 3815P at Sin Ming Rd on 5/11/16

Dear Catherine,

Kindly refer to our attachment.

Please proceed to appoint Kenneth Kong to conduct a survey of the vehicle SKX 3815P on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

100 Beach Road, #19-00 Shaw Tower, Singapore 189702

Tel: (65) 6250 7388 Ext.252 | Fax: (65) 6296 2706

Vic (LKKAuto)

From: Vic (LKKAuto)
Sent: Wednesday, 5 April, 2017 2:54 PM
To: ONG LI LI
Cc: MT_Claim_SG; Admin A; Vic (LKKAuto)
Subject: RE: Our Ref: 16/16/16/VP05/019416 Accident involving SGU 4422X & SKX 3815P at Sin Ming Rd on 5/11/16 ***LKK REF: CC4/LPC16021875/M1hg3
Attachments: 15122016165010.pdf; LKK INSPECTION REPORT.pdf; LKK ADJUSTMENT PHOTO.pdf; LKK INSPECTION PHOTOS.pdf; Rental Agreement.tif; LTA Search fee1.tif; LTA Search fee2.tif; LTA Search fee3.tif

Your Ref: 16/16/16/VP05/019416
Our Ref: CC4/LPC16021875/M1hg3

Dear Li Li,

ACCIDENT INVOLVING VEHICLES SGU 4422X AND SKX 3815P ON 05/11/2016 ALONG SIN MING ROAD

We refer to the above matter.

We refer to the assignment from your good office dated 14 November 2016 of Third-Party's request to do Direct Settlement with our Principal, Lonpac Insurance Bhd.

This is a conflicting version where both drivers have different version of the accident scenario. Our Insured reported that TP changed lane and collided to his vehicle. TP reported that Insured vehicle came out from minor road when collision happened. No evidence available from both parties. As such, liability unclear.

We propose to offer to TP repairer "**S & H MOTOR PTE LTD**" as below:

	TP CLAIMED	REVISED - TO OF
Cost of Repair (w/gst)	\$ 1,658.50	\$ 1,658.50
Loss of Rental (\$100 x 4 days)	\$ 400.00	\$ 400.00
<i>Subtotal</i>	<i>\$ 2,058.50</i>	<i>\$ 2,058.50</i>
<i>@50%</i>		\$ 1,029.25
LTA Search Fee	\$ 2.00	\$ 2.00
TOTAL	\$ 2,060.50	\$ 1,031.25

***Total days = 4 recommended days

The above is for your approval please.

Thank you.

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Wednesday, 12 April, 2017 10:48 AM
To: Enquiry
Cc: Admin A; Vic (LKKAUTO)
Subject: RE: Accident Involving SKX3815P & SGU4422X along Sin Ming Rd on 5.11.2016 Our ref : 16/16/16/VC20/019416 (SGU4422X)
Attachments: DV.pdf

WITHOUT PREJUDICE

Dear Ms Wong,

We refer further to our below email.

On a without prejudice basis and purely for an amicable settlement and without admission of liability to our Insured's part, our principal is in the view that this is a conflicting version and we have instruction to offer settlement as below:

Cost of Repair (w/gst)		\$ 1,658.50
Loss of Rental (\$100 x 4 days)		\$ 400.00
	<i>Subtotal</i>	\$ 2,058.50
	<i>@50%</i>	\$ 1,029.25
GIA Search Fee		\$ 2.00
TOTAL		\$ 1,031.25

If agreeable, kindly let the owner sign the attached DV then forward back to us together the original copy (hard copy) and Authorization Letter for our principal to process the payment.

The above amount is to be made payable to **S & H MOTOR PTE LTD.**

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108




Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

TP Insurer Enquiry

ENQUIRY DETAILS	
Accident Date	05/11/2016   
NRIC/FIN or Co. Reg. No.	
Vehicle No.	SGU4422X

Policy Details								
Req. By	Req. Date	Search	Enq. Accident Date	TP Insurer	Tel No.	Period of Insurance	Status	Action
Doris Ang [S & H Motor Pte Ltd]	05/11/2016 16:32	SGU4422X	05/11/2016	Lonpac Insurance Bhd	+65 62507388	12/01/2016- 11/01/2017		Receipt

Note:

- All submitted enquiry will be recorded and you can refer back from the History.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC16021875/M1hb3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 09-04-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGU 4422X	Veh. Inspected	SKX 3815P
Policy No.	Z16VP05008502	Coverage (\$)	0.00
Claim No.	16/16/16/VP05/019416	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	14/11/2016

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JHMFD16307S206688	Colour	RED
Odometer	293798	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	CONTINENTAL	8 mm
L/H Front Tyre	205/55 R16	CONTINENTAL	8 mm
R/H Rear Tyre	205/55 R16	CONTINENTAL	8 mm
L/H Rear Tyre	205/55 R16	CONTINENTAL	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/11/2016	Inspection Date	15/11/2016
Survey held at	S & H MOTOR PTE LTD BLK 11 SIN MING ROAD #01-83 SIN MING INDUSTRIAL ESTATE . SINGAPORE 575655		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 3815P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (WCP)	DEFORMED	280.00	280.00
1	LH REAR KNUCKLE ARM WHEEL BEARING (WCP)	DAMAGED	225.00	225.00
1	LH REAR KNUCKLE ARM (WCP)	NOT NECESSARY	290.00	-
1	LH REAR BUMPER RETAINER BRACKET (WCP)	DAMAGED	28.00	28.00
1	LH TAIL LAMP (WCP)	SERVICEABLE	155.00	-
	COST PLUS 15%		146.70	79.95
			1,124.70	612.95
1	LH REAR ALLOY PANEL (LOCAL REPAIR) (SN)	CUT	550.00	200.00
	COST PLUS 15%		82.50	-
			632.50	200.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE REAR BUMPER, WHEEL ARCH PANEL & PANEL BEATING, LH REAR FENDER, LH REAR WHEEL HOUSING INNER PANEL & LH REAR RUNNING BOARD PANEL.		650.00	500.00
	TO SPRAY PAINTING LH REAR DOOR, REAR FENDER, REAR BUMPER AND LH RUNNING BOARD PANEL.		950.00	500.00
	REMOVE & CHECK REAR SUSPENSION AND RENEW KNUCKLE.		220.00	80.00
	TO CHECK REAR WHEEL ALIGNMENT.		65.00	65.00
			1,885.00	1,145.00
	GRAND TOTAL		3,642.20	1,957.95
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,550.00

Report Ref No. CC4/LPC16021875/M1hb3n2

MA CHIN FOOK

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.