

EVERVIT LEASING PTE LTD

File No : SH/201  
Date : 14-November-2016

Estimated cost of repair for vehicle no : **SKX3815P** Model **HONDA CIVIC**  
Accident involving vehicle no: **SKX3815P** & **SGU4422X** on **05.11.2016**

| Description                       | Quantity | Cost Price                              |
|-----------------------------------|----------|-----------------------------------------|
| Rear Bumper                       |          | \$ 280.00                               |
| LH rear alloy wheel               |          | <del>\$ local rep 550.00</del> 200 8/N. |
| LH rear knuckle arm               |          | \$ 290.00                               |
| LH rear knuckle arm wheel bearing |          | \$ 225.00                               |
| LH rear bumper retinner bracket   |          | \$ 28.00                                |
| LH tial lamp                      |          | \$ 155.00 <del>200</del>                |
|                                   |          | <hr/>                                   |
|                                   |          | \$ 1,528.00                             |
|                                   | Add 15%  | \$ 229.20                               |
|                                   |          | <hr/>                                   |
|                                   |          | \$ 1,757.20                             |

Labour to remove rear bumper , wheel arch panel & panel beating,  
LH rear fender, LH rear wheel housing innel panel & LH rear running  
board panel

\$ ~~650.00~~ 500

To spray painting LH rear door, rear fender, rear bumper and  
LH running board panel

\$ ~~950.00~~ 500

Remove & check rear suspension and renew knuckle

\$ ~~220.00~~ 80

To check rear wheel alignment

\$ 65.00

---

**\$ 3,642.20**

---

T/Party: Lonpac Insurance

W/ot Authorize  
4/5 Repair  
After painting  
LH rear fender  
15/11/2016  
4 w/d day 1

\$ 1550 k  
4 w/d day  
coaching