



Reference: QA165669(EXPIRED1)
 Date: 31/01/2017

Customer: SINGAPORE AIR FORCE
 Location: CRANK CAMP BLK 007 CHO A CHU KANG

Dear Sir,

ACCIDENT REPAIR

Job No: PO: 400/441520
 Vehicle: MID59105
 Model: MB 290GD GS (TRK, CARGO: MB290 GD, 1.5 TONS, HELI PORTABLE)
 P/NO: 82D1855468
 Contract Ref No: 0010100270

We hereby submit the quote for the repair of the above vehicle/component in accordance to the job description attached.

Jobs Carried Out by ST KINETICS

Accident Labour Cost	: \$	1,588.62	@ \$72.21 / MHR
Labour Cost	: \$	1,588.62	
Accident Spare Cost	: \$	4,803.13	
Total Spare Cost	: \$	4,803.13	
Assessment Cost	: \$	577.58	
Transportation Cost	: \$	248.88	
Freight Cost	: \$	0.00	
Grand Total Cost	: \$	7,218.41	

Delivery Period: 3 week(s) from the date of PO received.
 (Spares ETA - 2 weeks, Repair - 1 week)

Validity Period: 30 days from the date of quotation.

Spares purchase by ST Kinetics are subjected to mark-up for both local and overseas items based on CIF price. The grand total repair cost of labour and spares/materials used are subjected to Goods and Services Tax.

Yours faithfully,
 SINGAPORE TECHNOLOGIES KINETICS LTD

Tay Boon Kiat
 Manager
 ST Kinetics

TAY BOON KIAT
 Manager
 Fleet Services Division
 Kinetics Automotive Services

*Only applicable for Not Approved	
☐	BER/NOT APPROVED
NAME: _____	
Signature: _____	
Date: _____	
Remarks: _____	

Singapore Technology Kinetics Ltd
 249, Jalan Boon Lay, Singapore 610023
 T: (65) 8850 3677 F: (65) 6216 5371
 www.stengg.com
 Email: info@stengg.com

- ① Quoted received 040217
 - ② Let to get approval 020217
 - ③ Email sent to DC92 for 1st level approval 030217
 - ④ DC93 received 030217
- Advancing Smart Engineering



JOB SCOPE / INSPECTION REPORT

PARTICULARS OF VEHICLE

TYPE OF REPAIR : ACCIDENT REPAIR
 CONTRACT REF NO. : 8010100270
 VEHICLE NO. : MID59105
 VEHICLE MODEL : MB 280GD GS (TRK CARGO: MB290 GD, 1.5 TONS, HELI PORTABLE)

QUOTATION REF. NO. : QA163660 (EXPIRED 1)
 ST KINETICS JOB NO. :
 ZONAL : 9AMB92FMB
 UNIT : CLEMENTI CAMP

CHASSIS / HULL NO. : WDB46132327093887
 ENGINE / COMPONENT :
 MR/MO NO. : 8201855468
 SPEEDO READING : 15879.00
 CUSTOMER NO. :
 PREPARED BY : GHANI
 DATE OF RFQ : 06/12/2016
 QTAT START DATE : 07/12/2016
 SWD READING : 0227
 ENGINE HRS : 0

The scope of work and total man hours are agreed by customer.

Total Labour Manhours : 22
 Delivery Period : 3 week(s)
 ESR (PER MAN DAY) : 0
 Sub Contractor Cost : \$0.00
 LOE Cost : \$0.00
 Signature / Date :
 Subsidiary Cost : \$0.00
 Rank & Name :
 Transportation / Towing Service : \$248.98

S/N	Task ID	Job Description	Work Done	Quoted MHRS	Remarks	WKSP USE	QC USE
	10	Accident Trade Job					
1	20	Front bumper damaged	RPL	3.00			
	Item Number	Description	Qty	UM	Price	Markup	Selling Price
	461 520 2370	BUMPER FRONT	1	EA	\$2,100.00	17.5%	\$2,467.50
1.1	21	RH and cap ripped off and damaged	RPL				
	Item Number	Description	Qty	UM	Price	Markup	Selling Price
	000603 006003	SCREW	2	EA	\$1.00	20%	\$1.20
	461 526 1398	RH SIDE PLASTIC CAP	1	EA	\$375.60	20%	\$450.72
1.2	30	RH side convoy lamp ripped off and damaged	RPL				
	Item Number	Description	Qty	UM	Price	Markup	Selling Price
	000 544 1014	CONVOY LAMP	1	EA	\$360.00	20%	\$432.00
1.3	50	RH side lamp, ripped off and damaged	REP				

Note : Items that cannot be checked by QA will be written as NA
 LEGEND: REP - REPAIR, RPL - REPLACE, INFO - INFORMATION ONLY
 T/A - TIME ADJUSTED

Singapore Technology Kinetics Ltd
 249 Jalan Boon Lay, Singapore 619623
 T: (65) 6660 9877 F: (65) 6318 5371
 www.stengg.com
 Page No: 79770021214

Advancing Smart Engineering



JOB SCOPE / INSPECTION REPORT

PARTICULARS OF VEHICLE

TYPE OF REPAIR : ACCIDENT REPAIR

CONTRACT REF NO : 8010100270

VEHICLE NO. : MID59105

VEHICLE MODEL : MB 290GD GS (TRK CARGO) MB290 GD, 1.5 TONS, HELI PORTABLE

QUOTATION REF. NO. :

ST KINETICS JOB NO. :

ZONAL :

UNIT :

QA165989(EXPIRED1)

QAMB/92FMD

CLEMENTI CAMP

S/N	Task ID	Job Description	Work Done	Quoted MHRS	Remarks	WRSP USE	QC USE	
	Item Number	Description	Qty	UM	Price	Mark-up	Selling Price	Total Price
	001 820 2756	SIDE LAMP	1	EA	\$141.80	20%	\$170.16	\$170.16
2	120	RH front wheel mudguard damaged	RPL	5.00				
	Item Number	Description	Qty	UM	Price	Mark-up	Selling Price	Total Price
	002 884 9145	EXPENSION NUT	6	EA	\$1.40	20%	\$1.68	\$10.08
	460 880 2208	MUDGUARD RH FRONT	1	EA	\$918.10	17.5%	\$1,076.77	\$1,076.77
	460 884 0145	PLASTIC INSERT	13	EA	\$0.63	20%	\$0.64	\$8.32
2.1	130	RH headlamp guard bracket adrifted (refit), holding clip and finisher ripped off	RPL & REP					
	Item Number	Description	Qty	UM	Price	Mark-up	Selling Price	Total Price
	000 811 1340	GUARD HOLDER	1	EA	\$7.28	20%	\$8.74	\$8.74
	000 885 2820	CLIP, HEADLAMP GUARD	2	EA	\$2.30	20%	\$2.76	\$5.52
	460 881 0214	HOLDING CLIP, HEADLAMP FINISHER	2	EA	\$4.30	20%	\$5.16	\$10.32
	481 880 0240	HEADLAMP FINISHER RH	1	EA	\$81.42	20%	\$97.70	\$97.70
	461 880 0714	HOLDING CLIP, HEADLAMP FINISHER	1	EA	\$8.30	20%	\$11.16	\$11.16
2.2	140	RH front signal lamp ripped off and damaged	RPL					
	Item Number	Description	Qty	UM	Price	Mark-up	Selling Price	Total Price
	000 820 7221	FR SIGNAL LAMP ASSY	1	EA	\$62.00	20%	\$74.40	\$74.40
2.3	150	RH front signal lamp guard bracket adrifted (refit) and holding clips damaged	RPL & REP					
	Item Number	Description	Qty	UM	Price	Mark-up	Selling Price	Total Price
	000 893 2820	CLIP, SIGNAL LAMP GUARD	2	EA	\$2.30	20%	\$2.76	\$5.52
	461 811 0046	RUBBER CATCH	1	EA	\$5.84	20%	\$6.92	\$6.92
3	160	RH front wheelhouse panel bent and dented	REP	4.00				
4	170	Bonnet dented and shifted	REP	4.00				
5	180	Spray paint on all above accident repaired areas	RPL & REP	6.00				
	Item Number	Description	Qty	UM	Price	Mark-up	Selling Price	Total Price
		PAINT	2	L	\$94.00	20%	\$112.80	\$33.60
	190							

Note : Items that cannot be checked by QA will be written as NA

LEGEND: REP - REPAIR, RPL - REPLACE, INFO - INFORMATION ONLY

T/A - TIME ADJUSTED

Singapore Technology Kinetics Ltd


249 Jalan Boon Lay, Singapore 619528

T: (65) 6660 3977 F: (65) 6346 5371

www.stengs.com

Regd. No - 197108233Q

Advancing Smart Engineering



JOB SCOPE / INSPECTION REPORT

PARTICULARS OF VEHICLE		QUOTATION REF. NO.	: QA185669(EXPIRED1)
TYPE OF REPAIR	: ACCIDENT REPAIR	ST KINETICS JOB NO.	:
CONTRACT REF NO	: 8010100270	ZONAL	: 9AMB/42FMD
VEHICLE NO.	: MID59105	UNIT	: CLEMENTI CAMP
VEHICLE MODEL	: MB 290GD GS (TRK.CARGO:MB290 GD,1.5 TONS,HELIPORTABLE)		

S/N	Task ID	Job Description	Work Done	Quoted MHRS	Remarks	WKSP USE	QC USE
1	200	ASSESSMENT COST			\$577.68		
	210						
	220	TOWING SERVICES					
1	230	Collect vehicle from Clementi camp, return to same location	REP	1	\$248.86		
	240	POC - Abdul Hussain 94509362					
	250						
	251	REMARKS (INFO)					
	260	ERP JU present					
	270	Engine able to start					
	280	Fire extinguisher present					
	290	LH door window regulator not present					
	300						

Note : Items that cannot be checked by QA will be written as NA
 LEGEND: REP - REPAIR, RPL - REPLACE, INFO - INFORMATION ONLY
 T/A - TIME ADJUSTED

Singapore Technology Kinetics Ltd
 249 Jalan Besar Lay, Singapore 619522
 T: (65) 6880 3877 F: (65) 6376 6374
 www.stengg.com
 (Regd No: 3071022532)

Advancing Smart Engineering