

ASS. REC. BY:

REF:

CS/CT16022438/H#be2

Special Instruction:

Surveyor:

HIRM

ASSIGNMENT (Office)

From (Person):

Joel Goh

of

CT1

Date/Time:

21-11-2016 933am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCN 1616H

Insured:

at Workshop m/s

Car City Auto

Tel:

6781 0300

of

Blk 900b Tampines St 93 # 01-198

Policy No:

DMP/CSN 3007911003

Claim No:

SNM16D05432101/6

Sum Insured:

Excess:

Waived

Make of Veh:

(Client's Record)

D.O.A.

17-11-2016

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

21-11-2016 9:48am

Person Contacted:

Mr Ho

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SCN 1616H - X
24/11/18 @	4.27pm vault to Eddie via Merimen, (as instruction by Eddie)
08/3/18 @	9:17am Susan Teo informed C/A at \$75677.64 via Merimen.
16/03/18 @	3.08pm Confirmed with Mr Ho final fig \$75677.64, 14 days.
	- Car City already done for repair works before received authorisation
	(Red \$7730.65, 8%)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI16022138/H1qb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 21-11-2016



Code : CTI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SCN 1616H
Policy No.	DMPCSN3007911503	Coverage (\$)	0.00
Claim No.	SNM16D05432C01/6	Excess (\$)	0.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	21/11/2016

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	17/11/2016	Inspection Date	21/11/2016
Survey held at	CAR CITY AUTO CENTRE PTE LTD BLK 9006 TAMPINES ST 93 #01-198 SINGAPORE 528840		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Nov 2016 Sendback Est	19 Nov 2016 11:37 S\$25,792.01	21 Nov 2016 09:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	CHAN HIAN JOON, NRIC: S1600579G, Tel: +6598183137, Email: ROY@YEELEE.COM.SG								
Vehicle Reg. No.:	SCN1616H		Date of Loss:	17/11/2016 10:00 - :59					
Claim Type:	OD / SNM16D05432C01/6		Policy/Cover Note No.:	DMPCSN3007911503 (Comprehensive)					
			Excess:	S\$0.00					
Repairer:	Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93, 528840 Tampines - Tel: 6781 0300								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/11/2016]								
Driver/Custodian:	CHAN HIAN JOON (52 / Male), NRIC: S1600579G, Tel: +6598183137								
Adj Asg. Remarks:	EXCESS WAIVED. OD SURVEY AND REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: CAR CITY AUTO CENTRE PTE LTD <ccacpl@singnet.com.sg>
Sent: Friday, 16 March 2018 3:08 PM
To: Shiau Chan (LKKAuto)
Subject: Re: RE: SCN1616H V4 AUDATEX REPORT

Dear Miss Shiau Chan,

Not much choice just got to accept as this case have already gone their 2 Christmas don't want wait for another Christmas 2018.

Regards,

Ho Too Boon
CAR CITY AUTO CENTE PTE LTD
TEL: 67810300 FAX: 67820300
EMAIL: ccacpl@singnet.com.sg

>-----Original Message-----

>From : siewsc@lkkauto.com
>Date : 08/03/2018 - 10:05 GMT+8
>To : ccacpl@singnet.com.sg, sur@lkkauto.com Subject : RE: SCN1616H V4
>AUDATEX REPORT
>
>Dear Mr Ho,
>
>Offer final fig \$25,677.64 before GST and 14 repair days.
>Kindly confirm.
>
>Best Regards,
>Shiau Chan (Ms) | Case Handler
>LKK Auto Consultants Pte Ltd
>Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51,
>Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)
>

>-----Original Message-----

>From: CAR CITY AUTO CENTRE PTE LTD [mailto:ccacpl@singnet.com.sg]
>Sent: Tuesday, 12 December 2017 5:50 PM
>To: SUR <sur@lkkauto.com>
>Subject: SCN1616H V4 AUDATEX REPORT
>
>FROM HO
>

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	19 Nov 2016 11:30	Clim Veh Model Changed	(204512) MERCEDES-BENZ E250 1.8 CGI (A).	[R] Ho Too Boon
2	19 Nov 2016 11:30	Clim Created	Reg No: SCN1616H. Policy No: DMPCSN3007911503. Acct Date: 2016/11/17. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Car City Auto Centre Pte Ltd (HQ). Created from SAS:MCCA16145371	[R] Ho Too Boon
3	19 Nov 2016 11:37	Clim Submitted	25792.01.	[R] Ho Too Boon
4	21 Nov 2016 09:33	Clim Registration Modified	Excess: -> 0.00.	[I] Joel Goh
5	21 Nov 2016 09:33	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):EXCESS WAIVED. OD SURVEY AND REVERT	[I] Joel Goh
6	21 Nov 2016 09:33	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2016/11/30	[I] Joel Goh
7	21 Nov 2016 09:33	Adj Mandate Set	Approved:10000.00.	[I] Joel Goh
8	21 Nov 2016 09:43	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
9	21 Nov 2016 15:21	Adj Adjuster Assigned	[None] -> HENRY NG KOK HUA	[A] CATHERINE CHONG KAI LING
10	18 Mar 2017 16:31	Clim Supp Created (S:572324)		[R] Ho Too Boon
11	18 Mar 2017 16:36	Clim Submitted (S:572324)	2116.28.	[R] Ho Too Boon
12	18 Mar 2017 16:36	Adj Co Assigned (S:572324)	LKK Auto Consultants Pte Ltd (HQ):	[I] Merimen Administrator
13	20 Mar 2017 09:25	Supp Combined (S:572324)		[A] SHIAU CHAN
14	31 Mar 2017 16:37	Adj Rpt Initiated		[A] SHIAU CHAN
15	29 Jan 2018 16:26	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2016/11/30	[A] SHIAU CHAN
16	29 Jan 2018 16:27	Adj Mandate Request	Cur.Req:25677.64:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. THE VEHICLE REPAIR ON PART BY PART BASIS DUE TO NO SECOND HAND PARTS AVAILABLE.	[A] SHIAU CHAN
17	08 Mar 2018 09:17	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2016/11/30	[I] Susan Teo
18	08 Mar 2018 09:17	Adj Mandate Set	Approved:25677.64.	[I] Susan Teo

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1309923	19/11/2016 11:30	Motor	Car City Auto Centre Pte Ltd (HQ)	Car City Auto Centre Pte Ltd (HQ)	SCN1616H		xx.xx
1423798	31/03/2017 16:37	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SCN1616H		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joel Goh

Date: 29 Jan 2018

Preliminary Advice

Vehicle No	: SCN1616H	Accident Date	: 17/11/2016
Make	: MERCEDES-BENZ E250	Policy No.	: DMPCSN3007911503
Assignment Date	: 21/11/2016	Excess	: S\$0.00
Date of Inspection	: 21/11/2016	Est. Duration of Repair	: 14.00
Inspection At	: CAR CITY AUTO CENTRE PTE LTD (HQ) BLK 9006 #01-198, TAMPINES STREET 93 SINGAPORE 528840		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,908.29	(ESTIMATE \$25,792.01 + SUPPLEMENTARY \$2,116.28)
Revised Amount	:S\$	25,677.64	(INCLUSIVE OF CHECK ITEMS & SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	25,677.64	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	69,000.00
COE / PARF Rebate	:S\$	37,281.00
Salvage Value	:S\$	
Margin for Repair	:S\$	31,719.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON PART BY PART BASIS DUE TO NO SECOND HAND PARTS AVAILABLE.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 15 September 2017 2:00 PM
To: Chong Boon Sen
Cc: SUR
Subject: FW: Preliminary Advice of vehicle SCN 1616H
Attachments: SCN1616 PA(2).pdf; SCN1616 Audatex.pdf

Dear Boon Sen,

Re-send.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 15 August, 2017 3:51 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Preliminary Advice of vehicle SCN 1616H

Dear Boon Sen,

Refer to our tele-conversation.

Please find the attached of preliminary advice.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Celine Fong (LKKAUTO)
Sent: Thursday, 10 August, 2017 3:43 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: SUR <sur@lkkauto.com>
Subject: FW: Preliminary Advice of vehicle SCN 1616H

Dear Boon Sen,

Please refer to the email below.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Celine Fong (LKKAuto)

Sent: Thursday, 20 July, 2017 6:48 PM

To: 'joel.goh@sg.cntaiping.com' <joel.goh@sg.cntaiping.com>

Subject: RE: Preliminary Advice of vehicle SCN 1616H

Dear Joel,

Refer to my email dated 07.04.2017.

May I know what is the status for this case?

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Celine Fong (LKKAuto)

Sent: Friday, 7 April, 2017 5:48 PM

To: 'joel.goh@sg.cntaiping.com' <joel.goh@sg.cntaiping.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: Preliminary Advice of vehicle SCN 1616H

Dear Joel,

Following up on the email below, by our ex-colleague's case.

It appears that we did not received authorisation, please check have your side reverted.

Best Regards,

Celine Fong / Admin Head of Survey Dept.

LKK Auto Consultants Pte Ltd

phone: 6841-1262 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Siti (LKKAuto)
Sent: Tuesday, 22 November, 2016 4:01 PM
To: joel.goh@sg.cntaiping.com
Cc: SUR <sur@lkkauto.com>
Subject: Preliminary Advice of vehicle SCN 1616H

Dear Joel,

Enclosed preliminary revised of vehicle SCN 1616H
Date of survey: 21/11/2016

Best Regards,

Siti | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SNM16D05432C01/6

Date: 22 November 2016

Our Ref: CS/CTI16022138/H1qb

The Motor Claims Department
China Taiping Insurance (S) Pte Ltd

Attn: Joel

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SCN 1616H .

We thank you for the instruction on 21/11/2016 .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/11/2016 at the premises of M/s CAR CITY and have the following to report:-

Workshop Estimate Amount	: S\$ <u>25,792.01</u>
Revised Estimate Amount	: S\$ <u>19,454.48</u>
"Check" Items Amount	: S\$ <u>4,128.59</u>
Market Value	: S\$ <u>69,000.00</u>
LTA Reimbursement Value	: S\$ <u>37,281.00</u>
Nett Value	: S\$ <u>31,719.00</u>

Description of Damage:
The vehicle sustained damages at the n/s portion.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

Repairer asking for part by part basis as no second hand parts available.

Estimated normal period for repairs: 14 working days.

We have NOT authorise repair.

Yours faithfully

HENRY NG
Automobile Assessor



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SNM16D05432C01/6

Date: 22 November 2016

Our Ref: CS/CTH16022138/H1qb

The Motor Claims Department
China Taiping Insurance (S) Pte Ltd

Attn: Joel

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SCN 1616H .


We thank you for the instruction on 21/11/2016 .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/11/2016 at the premises of M/s CAR CITY and have the following to report:-

Workshop Estimate Amount	: S\$ <u>25,792.01</u>
Revised Estimate Amount	: S\$ <u>19,345.81</u>
"Check" Items Amount	: S\$ <u>4,074.25</u>
Market Value	: S\$ <u>69,000.00</u>
LTA Reimbursement Value	: S\$ <u>37,281.00</u>
Nett Value	: S\$ <u>31,719.00</u>

Description of Damage:

The vehicle sustained damages at the n/s portion.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

Repairer asking for part by part basis as no second hand parts available.

Estimated normal period for repairs: 14 working days.

We have NOT authorise repair.

Yours faithfully

HENRY NG
Automobile Assessor

27750.69

Marcus Chua (LKKAUTO)

From: CAR CITY AUTO CENTRE PTE LTD <ccacpl@singnet.com.sg>
Sent: Saturday, 5 August, 2017 11:34 AM
To: quoqiang@lkkauto.com; Admin A; Mei Kwan (LKKAUTO); Admin-B; Henry Ng (LKKAUTO); Marcus Chua (LKKAUTO)
Cc: Bryan Ang (LKKAUTO)
Subject: TOUCHING BASE ON FOLLOWING OUTSTANDING OD CASES (CHINA)

Dear Sir/ Mdm,

Can PLEASE help to check on the following cases:

1. SCN1616H email on 18/03/2017 to finalise...TAKING DAMN.....DAMN...TOO LONG TO FINALISE!!!!
2. SKX1014Y email on 09/06/2017 to finalise
3. SLH8008S email on 09/06/2017 to finalise
4. SJM4941X email on 06/07/2017 to finalise.

Gqhz

Gvbe2

Ufh3

H1q6

Please help to finalise so payment will come in.

Regards

Ho Too Boon
CAR CITY AUTO CENTRE PTE LTD
TEL: 67810300 FAX: 67820300
EMAIL: ccacpl@singnet.com.sg

booneen.chong@sg

Celine Fong (LKKAuto)

Subject: RE: Preliminary Advice of vehicle SCN 1616H

Dear Joel,

Following up on the email below, ^{by your} my ex-colleague's case.

It appears that we did not received authorisation, please check have your side reverted.

Best Regards,

Celine Fong / Admin Head of Survey Dept.

LKK Auto Consultants Pte Ltd

phone: 6841-1262 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Siti Binte Mansoor (LKKAuto)

Sent: Tuesday, 22 November, 2016 4:01 PM

To: joel.goh@sg.cntaiping.com

Cc: SUR <sur@lkkauto.com>

Subject: Preliminary Advice of vehicle SCN 1616H

Dear Joel,

Enclosed preliminary revised of vehicle SCN 1616H

Date of survey: 21/11/2016

Best Regards,

Siti Binte Mansoor | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SCN1616H (SNM16D05432C01/6)

OD

Nov 17 2016 10:00AM

[CHAN HIAN JOON]

Car City Auto Centre Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 14/03/2017 11:42 AM.
To CARCITY_HQ; LKK_HQ
CC jason.tea@sg.cntatiping.com; CNTP_ALFRED; CNTP_CHEE
Subject

Dear all

We refer to the above matter.

Please let us have an update on the Own Damage claim urgently.

Regards

Alfred

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/11/2016 17:00
Date Of Accident	17/11/2016 10:45
Exact Location Of Accident	TRAFFIC JUNC XILIN AVE/LAGUNA GOLF GDN/CHANGI SOUT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCN1616H
Insured/Policyholder	
Name Of Registered Owner	CHAN HIAN JOON
NRIC No	S1600579G
Email Address	ROY@YEELEE.COM.SG
Mobile Phone No	(LOCAL) +65-98183137
Alternative Phone No	Others-98183137
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	E250-1.8 CGI (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
If No, Please state action to be taken	
Vehicle Category	Private Car
Insurance Company	
Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMPCSN3007911503
Cover Note Number	
Driver	
Name of Driver	CHAN HIAN JOON
NRIC No	S1600579G
Date Of Birth	17/12/1963
Occupation	Indoor
Date Of Driving Pass	24/04/1981
Driving Experience	35 Years And 6 Months
Gender	Male
Mobile Number	(Local) +65-98183137
Fax Number	
Contact Number	Others-98183137
Email Address	ROY@YEELEE.COM.SG

Address 16 JALAN KECHOT
 Postcode 419196
 Was driver an employee of the Insured's Company No
 If No, Relationship of the Driver with the Insured Owner
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident Collision- Traffic Light Junction
 Weather Conditions Clear
 Road Surface Dry

Other Information

Was any foreign vehicle involved in this accident? No
 Was any body injured in the Accident? Yes
 Was any other material or property damaged? Yes
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. No
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? Yes
 If Yes, Please state which Police Station
 Police Station Name Tampines East Neighbourhood Police Post
 Police Station Address ROAD: Blk 263 Tampines Street 21 #01-128 , POSTCODE: 520263 , COUNTRY: Singapore
 Police Station Contact TEL NO: 1800-7839999 - FAX NO: 67832500
 Was notice of intended Prosecution given? No
 If Yes, against whom?

Circumstances of Accident

SEE ATTACHED POLICE REPORT T/20161117/2108 DATED 17/11/2016 1428HRS

Attachment(s)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB8974G
 Vehicle Make/Model/Colour PREMIER TAXI KIA SILVER COLOUR
 Details Of Properties
 Name of Driver ABDUL HALID BIN JUMA'AT
 NRIC/Passport Number S1281121G
 Contact Number 96739035
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 2

Details of Witness

Name
 Phone Number
 Email Address

DETAILS OF INJURED PERSON 1

Name	ABDUL HALID BIN JUMA'AT
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHB8974G
Were seat belts worn?	
Was injured conveyed to hospital by ambulance?	Yes
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


1.40pm
17/11/2016

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



① SCN 1616H


② SHB 8974G

Describe Circumstances of the Accident

As per police report no. T/2016/117/2108
dated 17/11/2016 at 14:28

Declaration

We declare the foregoing particulars are true in every respect.

X 
1:40pm 17/11/2016

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel



SINGAPORE POLICE FORCE



T/20161117/2108

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

1 of 3

Report No. T/20161117/2108

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/11/2016 14:28			Vide Report No.: G/20161117/0077		Station Diary No.: 67
Name of Informant: CHAN HIAN JOON			Address: 16 JALAN KECHOT SINGAPORE 419196		
ID Type / ID No.: NRIC NO / S1600579G			Contact No.: Home/Office: Mobile: 98183137		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 52	Date of Birth: 17/12/1963	Type of Informant: Driver		
Race: Chinese			Language:	Institution / School Name:	
Occupation: Company director			Driving Licence Information: Class: 2B,3 Date of Expiry:		

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 17/11/2016 10:45	Type of Location: X-Junction
Location: Along Road 1 XILIN AVENUE LAGUNA GOLF GREEN				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

SCN	Car	MERCEDES BENZ	E 250CGI	Black	Seriously Damaged	0
SHB8974G	Car					0

SCN1616H	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMPCSN3007911503	18/11/2015	17/11/2016
----------	---	------------------	------------	------------



**SINGAPORE
POLICE FORCE**



T/20161117/2108

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

2 of 3

Report No. T/20161117/2108

CONTINUATION OF REPORT

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	CHAN HIAN JOON	ID No.	S1600579G
Related Vehicle	SCN1616H (Car)	Contact No.	98183137
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	ABDUL HALID BIN JUMA'AT	ID No.	S1281121G
Related Vehicle	SHB8974G (Car)	Contact No.	96739035
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 17/11/2016 at about 1045 hrs, I was travelling along Cross (X) junction of Xilin Ave and Laguna Golf green. The traffic light signalled green arrow, indicating I have the right of way to move. While I was making a right turn, taxi SHB8974G front portion collided with my left passenger portion. The impact was very big that it left the passenger door portion seriously damaged.

The taxi driver was also conveyed by the ambulance and traffic police came to the scene and advised me to lodge a traffic accident report. There is no CCTV installed in my car. My car was being towed.



**SINGAPORE
POLICE FORCE**



T/20161117/2108

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

3 of 3

Report No. T/20161117/2108

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Staff Sgt WONG JIANYONG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

17/11/2016 14:28

Officer In Charge Of Case:

TP / GIT /

Staff Sgt LIM JUN HUI, ADRIAN

Contact No.: 65476350

Classification Of Case:

SN 099

Authentication Stamp

NP168



Signature: _____

Singapore Police Force



TRAFFIC INVESTIGATION BRANCH
TRAFFIC POLICE DEPARTMENT
10 UBI AVE 3
SINGAPORE 408865
Fax: 65476259

NP168

REPT/IP/PV NO.: 6/20161117/0077

CASE CARD

Traffic Accident along XILIN AVE x LAGUNA GOLF GREEN
involving vehicles: SCN16164 SHB89746

on 17/11/16 at about _____ am/pm

With reference to the above, you are advised to lodge an accident report at the nearest Police Stations/Neighbourhood Police Centres/Posts within 24 hours if you have not done so.

You are required to be present at Traffic Police on date: _____, at about _____ am/pm to see the Investigation Officer to assist in the investigation to the traffic accident.

2. Please bring along your:-

- a) Identity card/Passport/Work Permit
- b) Driving Licence/Vocational Licence/LTA Licence
- c) Vehicle Insurance/Medical Certificate
- d) Any other relevant documents/Witnesses (if any)

3. If you are unable to keep to the appointment, kindly contact the investigation officer:

Name: PA217

Contact: 6547 6200

**DRIVE MOTORING**

Your Fast Track To Complete Motoring

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 0579G

17/11/2016
Bal: 3783**Vehicle Details**

Vehicle No.: SCN1616H

Vehicle to be
Exported: YesIntended De-
registration Date: 30 Nov 2016

Vehicle Make: MERCEDES BENZ

Vehicle Model: E 250CGI

Primary Colour: Black

Manufacturing Year: 2009

Engine No.: 27186030003935

Chassis No.: WDD2120472A080252

Maximum Power
Output: 150.0 kW (201 bhp)

Open Market Value: \$52,997.00

Original Registration
Date: 18 Nov 2009First Registration
Date: 18 Nov 2009

Transfer Count: 1

Actual ARF Paid: \$52,997.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility
Expiry Date: 17 Nov 2019PARF Rebate
Amount: \$31,798.00**Intended COE Rebate Details**

COE Expiry Date: 17 Nov 2019

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$18,501.00

COE Rebate
Amount: \$5,483.00**Total Rebate
Amount: \$37,281.00**

26,498

The information contained herein is correct as at 17 Nov 2016

OK

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CAR CITY/1

Date Calculated: 19/11/2016 03:02

Full Report - V1

Registration: SCN1616H

Printed: 19/11/2016 11:04

PAINT WORK

Guide Number	Description	Time Basis 10 WU = 1 HR.	Price = \$46.00/HR	WU	Cost Price (\$)
	- TWO COAT METALLIC				
98-1731 01	FRONT BUMPER COVER PAINTING STAGE I-M			11.0	
98-2415 01	L/F WING PAINTING STAGE I-M			6.0	
98-4015 01	LEFT FRONT DOOR PAINTING STAGE I-M			11.0	
98-1881 01	L/DOOR MIRROR HSG PAINTING STAGE I-M			1.0	
98-4115 02	L/R DOOR PAINTING STAGE I-M			11.0	
98-5535 01	LEFT DOOR FRAME PAINTING STAGE I-E			28.0	
98-5350 01	L/F SILL PAINTING STAGE I-E			5.0	
98-1861 01	L/SILL PANELLING PAINTING STAGE I-M			5.0	
98-5555 01	LEFT B-PILLAR PAINTING STAGE I-E			36.0	
98-8980 ZAX	L/F WHEEL PAINT			4.0	
98-1735 01	REAR BUMPER COVER PAINTING STAGE III			13.0	
98-7047 01	L/R WING PAINTING STAGE III			23.0	
	WITHOUT FRT SURFACE BELOW DOOR				
98-2806 01	BONNET PAINTING STAGE II			23.0	
L 1155	L/UPP W-HOUSE S-MEMBPAINTING STAGE I-J			3.0	
98-1340 01	PREPARATION WORK FOR TWO COAT PAINTING			15.0	
	OF FITTED BODY PARTS				
98-1356 01	ADD/WORK FOR PLASTIC PARTS			3.0	
98-1620 ZAX	PRIME PLASTIC/METAL PARTS			3.0	
98-1630 ZAX	APPLY SMOOTHG FILLER ON PLAST/MET PARTS			3.0	
98-1625 ZAX	REPAIR/APPLY FILLER ON PLAST/METAL PARTS			2.0	
98-1620 ZAX	APPLY PRIMER REAR BUMPER (ADD/WORK)			1.0	
98-1630 ZAX	APPLY FILLER REAR BUMPER (ADD/WORK)			1.0	
98-1625 ZAX	APPLY FILLER PASTE REAR BUMPER (ADD)			3.0	
LABOUR COST - PAINT					
TIME(PAINT)				0.0	
Total Work Units (10WU/HR)				211.0	
Total Paintwork Labour				21.1HRS	\$970.60
MATERIAL COST - PAINT					
Total Excluding Pearlescent Uplift					Cost Price
Pearlescent Uplift @ 0.0%					\$421.16
Total Paint Material Cost					\$0.00
					\$421.16

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/06/2015	Bet.	Price (\$)
283	1	FRONT BUMPER COVER	212 880 1340 9999	deform	0%	—	850.00*
285	1	L/F SPACER	212 889 1195	nec	0%	—	10.00*
741	1	L/F WING	212 880 1118	Buc	0%	—	560.00*
783	1	L/F WING MOULDING	212 690 3362	nec	0%	—	28.00*
785	1	L/F WING BADGE	204 817 7220	nec	0%	—	45.00*
839	1	L/F W-HOUSE CVR FRT	212 690 4330	deform	0%	—	120.00*
841	1	L/F W-HOUSE CVR REAR	212 690 3030	deform	0%	—	125.00*
1179	1	L/REINFORCEMENT	212 620 0185		0%	?	35.00* Δ
1187	1	L/F UPP REINF	212 620 0191		0%	?	170.00* Δ
1411	1	WINDSCREEN REP KIT	221 670 8101		0%	?	0.00
1413	4	FRT SCREEN SUPPORTS	210 671 0397		0%	?	0.00
1479	1	L/F DOOR MODULE	212 720 1579	Activated	0%	—	420.00*
1481	1	LEFT FRONT DOOR	212 720 5300	Buc	0%	—	1,300.00*
1487	1	L/F UPPER DOOR HINGE	204 720 1537	Bent	0%	—	95.00*

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CAR CITY/1

Date Calculated: 19/11/2016 03:02

Full Report - V:

Registration: SCN16161

Printed: 19/11/2016 11:04

1495	1	L/F LOWER DOOR HINGE	204 720 1737	bent	0%	—	120.00*
1509	1	L/F DOOR SEAL	204 727 1187	rec	0%	—	180.00*
1513	1	L/F LOWER DOOR MLDG	212 690 4762	rec	0%	—	50.00*
1519	1	L/F DOOR WINDOW	212 725 0710	smashed	0%	—	150.00*
1551	1	L/F WINDOW MOTOR	212 906 6802	jam	0%	—	390.00*
1597	1	L/F WINDOW CHANNEL	212 725 0325	28 bent	0%	—	95.00*
1619	1	L/F CHANNEL SEAL	212 725 0965	rec	0%	—	30.00*
1625	1	L/F OUT WINDOW SEAL	212 725 0565	rec	0%	—	75.00*
1671	1	L/F W-FRAME INN TRIM	212 725 0171	9051 cra	0%	—	55.00*
1681	1	L/F DOOR MOULDING	212 690 2562	deform	0%	—	65.00*
1711	1	L/F DOOR TRIM	212 720 2370	cra	0%	—	600.00*
			9G50				
1749	1	L/OUT DR MIRROR CVR	212 811 0198	svc	0%		23.00*
1775	1	L/F DOOR LAMP	002 820 1901	svc	0%		26.00*
1777	1	L/F DOOR FRAME SEAL	212 697 0051	svc	0%		150.00*
			9G44				
1781	1	L/R DOOR	212 730 0105	dented	0%		1,250.00*
1809	1	L/R DOOR SEAL	204 727 1187	cra	0%		160.00*
1813	1	L/R LOWER DOOR MLDG	212 690 3782	cra	0%		35.00*
1831	1	L/R QUARTER GLASS	212 730 3900	rec	0%		0.00
1845	1	RR D/WDW BONDING KIT	221 670 8101	rec	0%	sl. 75u	0.00
1961	1	L/R OUT WINDOW GSKT	212 735 0965	rec	0%		85.00*
1981	1	L/R DOOR MOULDING	212 690 2962		0%		65.00*
2063	1	L/R DOOR FRAME PROT	212 697 0151		0%		150.00*
			9G44				
2085	1	LEFT DOOR FRAME	212 630 6101	dented	0%		1,500.00*
2107	1	2K ADHESIVE L/SIDE	009 989 3671	12 rec	0%		0.00
2127	1	L/SILL PANEL	212 637 1535		0%		0.00
2167	1	L/INNER SILL	212 630 3900		0%		0.00
2207	1	L/SILL PANELLING	212 698 0154	9999 dented	0%		400.00*
2309	1	L/INNER DOOR FRAME	212 630 4100		0%		0.00
2386	1	SERVICE LID	212 690 1750	cra	0%		135.00*
			9G26				
2417	1	L/ROOF FRAME MLDG	212 690 0780		0%	2	260.00*Δ
2593	1	L/R BUMPER GUIDE	212 880 1330		0%	2	30.00*Δ
2615	1	L/R MOULDING	212 885 2121	rec	0%		90.00*
3151	1	REAR SCREEN	212 670 0200	rec	0%		360.00*
3160	1	REAR SCREEN BOND KIT	221 670 8101	rec	0%	sl. 75u	0.00
3161	3	REAR SCREEN SUPPORTS	164 742 0097	rec	0%		0.00
4589	1	L/F BACKREST COVER	212 910 5547	9E43 svc	0%	X	1,100.00*Δ
4607	1	L/F SIDE AIRBAG	212 860 3402	9051 activated	0%		340.00*
4627	1	L/WINDOWBAG	212 860 4302	rec	0%		590.00*
4941	1	L/UPP FRONT TRIM	212 690 5925	form	0%		70.00*
			9G26				
4947	1	L/B-PILLAR TRIM	212 690 1926	cra	0%		120.00*
			9G26				
4949	1	L/LWR B-PILLAR TRIM	212 690 3925	9051 cra	0%		50.00*
4957	1	HEADLINING	212 690 5950	svc	0%		960.00*
			9G26				
7047	1	L/F TENSION ROD	212 330 2711		0%	2	320.00*
7055	1	L/TENSION ROD RUBBER	212 333 0014		0%	2	75.00*
7065	1	L/F BALL JOINT	212 330 0135		0%	2	105.00*
7071	1	L/F LWR CONTROL ARM	212 330 3900		0%	2	320.00*
7081	1	L/F STEERING KNUCKLE	212 332 0700		0%	2	750.00*

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CAR CITY/1

Date Calculated: 19/11/2016 03:02

Full Report - V:

Registration: SCN1616H

Printed: 19/11/2016 11:04

7087	1	L/F SHOCK ABSORBER	212 323 5300	Bent	0%	520.00*
7131	1	L/F WHEEL HUB	212 330 0025		0%	430.00*
7133	1	L/F PROTECT PLATE	212 420 1144		0%	85.00*
7201	1	L/F WHEEL	212 401	dented	0%	650.00*
			0002649765			
7251	1	L/F SPEED SENSOR	212 540 0117		0%	260.00*
7261	1	FRONT STABILISER	212 323 0965		0%	290.00*
7263	1	L/F STABILISER ARM	212 320 1189		0%	75.00*
7309	1	L/TIE ROD	212 330 2103		0%	145.00*
7311	1	L/OUTER TIE ROD BALL	212 330 2303		0%	130.00*
7521	1	L/B-PILLAR SENSOR	212 820 4926		0%	85.00*
8777	1	L/BRACKET	204 524 1340		0%	30.00*
9686	1	AIRBAG/TENS C-UNIT	212 901 4204	rec	0%	630.00*
f: OEM Parts			Sub Total			\$18,457.00
g: Original			Mark Up From Cost		(5 %)	\$922.85
h: Secondhand			Sundry Parts		(Fixed)	\$100.00
p: Parallel			Total Parts			\$19,479.85
x: Exchange						

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEES	0%	\$42.00 /
SEALANT		\$30.00 /
SPECIALIST		
SPECIALIST		
Total Extras		\$72.00

Final Calculation

Total Parts		\$19,479.85
Labour		
Total Panel/Mechanical		
Total Paintwork	\$4,627.60	
Total Visual Alignment work	\$970.60	
Corr Prot Internal 16 WU	\$147.20	
	\$73.60	
Total Labour		\$5,819.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Cost of Specialist	\$72.00	
Total of Additional Costs		\$72.00
Total Paint/Material Costs		\$421.16
Grand Total Excludes GST		\$25,792.01
GST @ 7 %		\$1,805.44
Grand Total Includes GST		\$27,597.45

Assessment Notes

**CHINA TAIPING
INSURANCE (S) PTE LTD
3 ANSON ROAD
#15-02 SPRINGLEAF
TOWER**

079909

**Claim Reference: CCA00176
Assessment Number: CCA00176
Version: CAR CITY/1
Date Calculated: 09/03/2017 07:34**

**Full Report - V1
Registration: SCN1616H
Printed: 09/03/2017 15:34**

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Mr K.K Lau	Date of Incident:	17/11/2016
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	Liberty Insurance Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	CCA00176	Estimated Repair Time:	
Policy Number:	DMPCSN3007911503	Quote Due Date:	
Other Reference:	OD/17017	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	E Class
Sub Model:	E 250 CGI
Model Sheet Number:	3AE 01
Registration:	SCN1616H
Registration Month:	October
Registration Year:	2009
VIN Number:	WDD2120472A080252
Manufacture Year:	2009
Odometer:	157160
Colour:	Black
Engine Number:	27186030003935
Fuel Level:	%

Model Specs

FROM A076363/L001354	TECH CHANGES 09/09
MODEL 2010	PARKTRONIC
LOAD COMPARTMENT BOX	AUDIO 20 CD CHANGER
MULTIMEDIA INTERFACE	LEATHER TRIM
SUN PROTECTION	TRIM ELEGANCE
MEMORY PACKAGE	PEDESTRIAN PROTECT
DIPPING MIRROR	S-WDW ROLLER BLIND
TRIM WALNUT BURL	REM RELEASE FUEL CAP
KEYLESS GO	DOUBLE CUP HOLDER
ENGINE PROTECTION	RR SCREEN SUN BLIND
AIR INJECTION	AUTO GEARBOX 5 SPEED
DIRECT STEERING	DIRECT CONTROL SUSP
TYRES 205/60 HR 16	WHEELS 7J X 16 ALLOY
SPACE SAVER S-WHEEL	FUEL TANK 80 LTR
HD COOLING	TWO COAT METALLIC
CLEAR COAT HARD	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Fair	Severity of Impact:	Heavy Panel
Steering:	Satisfactory	Vehicle Status on Inspection:	Unroadworthy
Brakes Pedal Travel:	Satisfactory	Date of Inspection:	17/11/2016
Place of Inspection:	Repairer		
Pre-Accident Damage:			
Tyres Condition:	Fair		
Tyres - Tread Depth (MM):			

Left Tyre



Right Tyre

CHINA TAIPING INSURANCE (S) PTE LTD**Claim Reference: CCA00176****Full Report - V1****Assessment Number: CCA00176****Registration: SCN1616H****Version: CAR CITY/1****Printed: 09/03/2017 15:34****Date Calculated: 09/03/2017 07:34**

	Axles	Depth	Depth
LHF	0	7.0	7.0
LHR	1	7.0	7.0

Damage Areas:

	RHF	RHR
Direction of Impact:		

**Addresses****Cost Summary**

Total Labour	\$5,644.20
Total Paint/Material	\$421.16
Total Parts	\$19,351.41
Total of Additional Costs	\$72.00
Excess:	TBA
Grand Total Exc GST:	\$25,488.77
7 % GST:	\$1,784.21
Grand Total Inc GST:	\$27,272.98

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$0.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY	3.0	13.80
54-1010 ZAX	CHECK ELECTRIC-/ELECTRONIC SYSTEMS (AFTER SHORT TEST OR ACCORDING TO ERROR CODE)	3.0	13.80
54-7989 03	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	9.20
91-1821 ZAX	SAFETY PRECAUTIONS BEFORE WELDING DISCONNECT AIRBAG/SEATBELT TENSIONER SYS	8.0	36.80
91-0660 01	CHECK SAFETY SYSTEM	3.0	13.80
61-1116 02	R + R L/UNDERFLOOR COVER	3.0	13.80
NO NUMBER	ALIGN BODY BY HANDHELD MEASURING SYSTEM	2.0	9.20
NO NUMBER	ANCHOR VEHICLE ON STRAIGHTENING SYSTEM	9.0	41.40
60-1065 01	REFIT MODUL CROSSMEMBER FROM CASSIS JIG	10.0	46.00
88-1102 02	R + R COMPLETE FRONT BUMPER INCLUDES: R + R RADIATOR COWL	11.0	50.60

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CAR CITY/1

Date Calculated: 09/03/2017 07:34

Full Report - V1

Registration: SCN1616H

Printed: 09/03/2017 15:34

88-1105 02	DIS + ASS FRONT BUMPER (BUMPER REMOVED)	9.0	41.40
	AFTER CHECK: RENEW PARTS IF NECESSARY		
88-1380 02	ADD TO DIS/ASS FRONT BUMPER CPL (LUXURY VERSION VEHICLE)	3.0	13.80
88-1358 02	ADDITION TO DIS + ASS FRONT BUMPER (BUMPER REMOVED) (VEHICLE WITH ULTRASONIC PARKING AID)	2.0	9.20
60-2289 01	R + R R/HEADLAMP UNIT (BUMPER REMOVED)	3.0	13.80
88-3818 02	RENEW LEFT WING (BUMPER REMOVED) INCLUDES: L/F WHEELHOUSE COVER CPL REMOVE AND REFIT.	7.0	32.20
88-2503 02	R + R BONNET	6.0	27.60
60-1609 01	REMOVE/REFIT LH FRONT SEAT AND LOOSE CARPETS AND PLACE IN STORAGE	9.0	41.40
60-1624 01	R + R COMPLETE REAR SEAT AND CARPETS AND PLACE IN STORAGE	7.0	32.20
67-1500 02	R + R WINDSCREEN	32.0	147.20
72-1450 02	RENEW L/F DOOR AND CONVERT PARTS INCLUDES: DOOR TRIM REMOVE AND REFIT AND ALL ATTACHED PARTS ASSEMBLE	37.0	170.20
72-1682 02	ADDITIONAL RENEW LEFT FRONT DOOR VEHICLE WITH LOWER MOULDING	1.0	4.60
72-2692 02)	RENEW L/F UPPER DOOR HINGE	7.0	32.20
72-6665 02)	RENEW L/F DOOR TRIM (REMOVED)	11.0	50.60
72-1590 02	RENEW L/R DOOR AND CONVERT PARTS INCLUDES: DOOR TRIM REMOVE AND REFIT AND ALL ATTACHED PARTS ASSEMBLE	37.0	170.20
72-1760 02	ADDITIONAL RENEW LEFT REAR DOOR VEHICLE WITH LOWER MOULDING	1.0	4.60
88-5205 02	R + R LEFT SILL TRIM	6.0	27.60
60-1657 ZAX	R + R L/INTERIOR TRIM (FOR RENEWING OUTER SIDEMEMBER SHELL) (DOORS, SEATS AND MATS REMOVED)	9.0	41.40
63-1362 ZAX	RENEW L/A-PILLAR, SIDEMEMBER AND B-PILLAR	227.0	1,044.20
63-1322 01	RENEW L/OUTER A-PILLAR	83.0	381.80
63-1430 01	RENEW L/B-PILLAR	113.0	519.80
63-1120 ZAX	RENEW OUTER SIDEMEMBER LH DOOR SILL, FORWARD OF CENTRE-PILLAR	21.0	96.60
68-1621 ZAX	R + R HEADLINING	20.0	92.00
68-1748 02	ADDITION TO R + R HEADLINING (VEHICLE WITH INTERIOR PROTECTION)	5.0	23.00
91-2102 02	R + R L/HEAD SIDE AIRBAG UNIT (STRIPPED)	3.0	13.80
67-5045 02	RENEW REAR PANEL WINDOW	21.0	96.60
88-9626 ZAX	R + R REAR BUMPER MOULDING	3.0	13.80
60-2430 02	R + R BOTH OUTER TAILLAMPS	3.0	13.80
97-2500 ZAX	CAVITY PROTECTION (ADD/WORK)	2.0	9.20
97-2500 ZAX	L/F UPPER SIDEMEMBER CAVITY PROTECTION	2.0	9.20
97-2500 ZAX	CAVITY PROTECTION LEFT FRONT DOOR	2.0	9.20
97-2500 ZAX	CAVITY PROTECTION LEFT REAR DOOR	2.0	9.20
97-2500 ZAX	L/SILL CAVITY PROTECTION	2.0	9.20

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: CCA00176

Full Report - V1

Assessment Number: CCA00176

Registration: SCN1616H

Version: CAR CITY/1

Printed: 09/03/2017 15:34

Date Calculated: 09/03/2017 07:34

97-2500 ZAX	APPLY CAVITY SEALING AT LEFT A-PILLAR	2.0	9.20
97-2500 ZAX	L/B-PILLAR CAVITY PROTECTION	2.0	9.20
97-2500 ZAX	L/R WING CAVITY PROTECTION	2.0	9.20
68-4605 01	R + R INSTRUMENT PANEL	28.0	128.80
91-5852 01	R + R L/F SEAT BACKREST TRIM	3.0	13.80
91-2070 01)	R + R L/F SEAT SIDEBAG UNIT	3.0	13.80
	INCLUDES: R + R SEAT BACKREST TRIM		
91-1905 01)	R + R AIRBAG CONT UNIT AND PRETENS SYS	4.0	18.40
33-1275 02	R + R BOTH FRONT AXLE HALFS	30.0	138.00
32-2050 02)	R + R FRONT STABILIZER	4.0	18.40
33-3510 03)	R + R L/F STEERING KNUCKLE	20.0	92.00
33-1421 03)	R + R LEFT FRONT TORSION BAR	9.0	41.40
32-1955 03)	R + R L/F STRUT	5.0	23.00
32-1908 02)	DISS/ASS L/F SUSPENSION STRUT REMOVED	3.0	13.80
32-1920 02)	DIS + ASS FRONT SPRING STRUT/S (REMOVED)	3.0	13.80
46-7004 01)	R + R LEFT TIE ROD	5.0	23.00
40-2410 01	R + R LEFT FRONT TYRE	3.0	13.80
40-2055 01	L/FRONT WHEEL BALANCE	2.0	9.20
42-1350 01	BLEED BRAKE SYSTEM	10.0	46.00
83-0640 01	CHECK AIR COND	3.0	13.80
40-6500 01	ALIGN VEHICLE	7.0	32.20
	INCLUDES: ALIGN FRONT AND REAR TOE AND CAMBER,		
	CHECK FRONT AND REAR VEHICLE LEVEL		
40-6710 01	ADD/WORK FOR VEHICLE WITH BOARDING-/EXITING SUPPORT	1.0	4.60
40-4064 01	ADJUST FRONT WHEEL TOE (DURING ALIGNMENT)	2.0	9.20
40-6716 01	ADDITIONAL TO OPTICAL ALIGNMENT	6.0	27.60
	ADJUST L/FRONT AXLE HALF CAMBER/CASTER		
40-6717 01	ADDITIONAL TO OPTICAL ALIGNMENT	6.0	27.60
	ADJUST R/FRONT AXLE HALF CAMBER/CASTER		
40-6992 ZAX	ADD/WORK FOR CALIBRATE VEHICLE AXLE LEVEL WITH STAR DIAGNOSIS (BOTH AXLES)	5.0	23.00
40-8052 ZAX	CHECK FRONT/REAR WHEEL TRACK ALIGNMENT DURING TRACK AND ALIGNMENT CHECK	5.0	23.00
1477	ADDITIONAL WORK PULLING L/SIDE	15.0*	69.00
1995	REMOVE AND REFIT INSULATION MATS	5.0*	23.00
9699	TYRE SERVICE	5.0*	23.00
9722	FAULT FINDING	5.0*	23.00
9854	READ OUT ERROR MEMORY	20.0*	92.00
9980	CARRY OUT CALIBRATION DRIVE	15.0*	69.00
1155	REPAIR L/UPP W-HOUSE S-MEMB	10.0*	46.00
2583	REPAIR REAR BUMPER COVER	8.0*	36.80
3481	REPAIR L/R WING	10.0*	46.00
0561	CHECK LEFT HEADLAMP ASSY		
1436	CHECK WASHER CONTAINER		
1445	CHECK WASHER JET HOSE		
1565	CHECK L/F DOOR OUT HANDLE		
1567	CHECK L/F OUT HANDLE PLATE		
1573	CHECK LEFT MEMBER TRIM		
1579	CHECK L/F DOOR LOCK COVER		
1601	CHECK L/F COVER		
1629	CHECK L/SEAT ADJ SWITCH		

CHINA TAIPING INSURANCE (S) PTE LTD**Claim Reference: CCA00176****Full Report - V1****Assessment Number: CCA00176****Registration: SCN1616H****Version: CAR CITY/1****Printed: 09/03/2017 15:34****Date Calculated: 09/03/2017 07:34**

1645	CHECK L/F UPPER SPEAKER
1655	CHECK L/F W-FRAME RR MLDG
1701	CHECK L/F LWR DOOR DAMPING
1707	CHECK L/F LWR DOOR SPEAKER
1723	CHECK L/F DOOR INSULATION
1737	CHECK LEFT DOOR MIRROR
1747	CHECK L/DOOR MIRROR COVER
1865	CHECK L/R DOOR OUT HANDLE
1871	CHECK L/R DOOR HANDLE TRIM
1947	CHECK L/R DR FRM FRT MLDG
2411	CHECK L/SEAT MOUNT PLATE
4551	CHECK L/OUTER SEAT COVER
4593	CHECK L/BACKREST SHELL
4595	CHECK L/F BACKREST TRIM
4611	CHECK L/F PRESSURE SENSOR
7011	CHECK FRONT AXLE SUPPORT
7097	CHECK L/LWR DAMPER RING
7099	CHECK L/UPPER DAMPER RING
7103	CHECK L/F S-ABSORB BOOT
7141	CHECK L/F BRAKE DISC
7227	CHECK L/F TYRE
7300	CHECK STEERING GEAR

LABOUR COST

Total Work Units	1,016.0	
Panel / Mechanical Labour	96.8HRS	\$4,452.80
Visual Alignment Labour	3.2HRS	\$147.20
Corrosion Protection		
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	1.6HRS	73.60
Sub Total	101.6HRS	\$4,673.60
Paint Labour	21.1HRS	\$970.60
Total Labour	122.7HRS	\$5,644.20

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
- TWO COAT METALLIC			
98-1731 01	FRONT BUMPER COVER PAINTING STAGE I-M	11.0	
98-2415 01	L/F WING PAINTING STAGE I-M	6.0	
98-4015 01	LEFT FRONT DOOR PAINTING STAGE I-M	11.0	
98-1881 01	L/DOOR MIRROR HSG PAINTING STAGE I-M	1.0	
98-4115 02	L/R DOOR PAINTING STAGE I-M	11.0	
98-5535 01	LEFT DOOR FRAME PAINTING STAGE I-E	28.0	
98-5350 01	L/F SILL PAINTING STAGE I-E	5.0	
98-1861 01	L/SILL PANELLING PAINTING STAGE I-M	5.0	
98-5555 01	LEFT B-PILLAR PAINTING STAGE I-E	36.0	
98-8980 ZAX	L/F WHEEL PAINT	4.0	
98-1735 01	REAR BUMPER COVER PAINTING STAGE III	13.0	
98-7047 01	L/R WING PAINTING STAGE III	23.0	
	WITHOUT FRT SURFACE BELOW DOOR		
98-2806 01	BONNET PAINTING STAGE II	23.0	
L 1155	L/UPP W-HOUSE S-MEMBPAINTING STAGE I-J	3.0	
98-1340 01	PREPARATION WORK FOR TWO COAT PAINTING	15.0	

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: CCA00176

Full Report - V1

Assessment Number: CCA00176

Registration: SCN1616H

Version: CAR CITY/1

Printed: 09/03/2017 15:34

Date Calculated: 09/03/2017 07:34

OF FITTED BODY PARTS			
98-1356 01	ADD/WORK FOR PLASTIC PARTS	3.0	
98-1620 ZAX	PRIME PLASTIC/METAL PARTS	3.0	
98-1630 ZAX	APPLY SMOOTHG FILLER ON PLAST/MET PARTS	3.0	
98-1625 ZAX	REPAIR/APPLY FILLER ON PLAST/METAL PARTS	2.0	
98-1620 ZAX	APPLY PRIMER REAR BUMPER (ADD/WORK)	1.0	
98-1630 ZAX	APPLY FILLER REAR BUMPER (ADD/WORK)	1.0	
98-1625 ZAX	APPLY FILLER PASTE REAR BUMPER (ADD)	3.0	
LABOUR COST - PAINT			
TIME(PAINT)		0.0	
Total Work Units (10WU/HR)		211.0	
Total Paintwork Labour		21.1HRS	\$970.60
MATERIAL COST - PAINT			Cost Price
Total Excluding Pearlescent Uplift			\$421.16
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$421.16

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
2107	1	2K ADHESIVE L/SIDE	009 989 3671 12		107.18 <i>rec</i>
9686	1	AIRBAG/TENS C-UNIT	212 901 4204		630.00* <i>rec</i>
283	1	FRONT BUMPER COVER	212 880 1340 9999		850.00* <i>rec</i>
7261	1	FRONT STABILISER	212 323 0965		290.00* <i>BT</i>
1413	4	FRT SCREEN SUPPORTS	210 671 0397		5.40U <i>xnm</i>
4957	1	HEADLINING	212 690 5950		960.00* <i>DE</i>
			9G26		
7521	1	L/B-PILLAR SENSOR	212 820 4926		85.00* <i>ACT</i>
4947	1	L/B-PILLAR TRIM	212 690 1926		120.00* <i>CRA</i>
			9G26		
8777	1	L/B-RACKET	204 524 1340		30.00* <i>xnm</i>
7065	1	L/F BALL JOINT	212 330 0135		105.00* <i>DIS</i>
1619	1	L/F CHANNEL SEAL	212 725 0965		30.00* <i>rec</i>
1479	1	L/F DOOR MODULE	212 720 1579		420.00* <i>ACT</i>
1681	1	L/F DOOR MOULDING	212 690 2562		65.00* <i>DE</i>
1509	1	L/F DOOR SEAL	204 727 1187		180.00* <i>rec</i>
1711	1	L/F DOOR TRIM	212 720 2370		600.00* <i>CRA</i>
			9G50		
1519	1	L/F DOOR WINDOW	212 725 0710		150.00* <i>SM</i>
1495	1	L/F LOWER DOOR HINGE	204 720 1737		120.00* <i>BT</i>
1513	1	L/F LOWER DOOR MLDG	212 690 4762		50.00* <i>rec</i>
7071	1	L/F LWR CONTROL ARM	212 330 3900		320.00* <i>DIS</i>
1625	1	L/F OUT WINDOW SEAL	212 725 0565		75.00* <i>rec</i>
7087	1	L/F SHOCK ABSORBER	212 323 5300		520.00* <i>BT</i>
4607	1	L/F SIDE AIRBAG	212 860 3402 9051		340.00* <i>ACT</i>
285	1	L/F SPACER	212 889 1195		10.00* <i>rec</i>
7263	1	L/F STABILISER ARM	212 320 1189		75.00* <i>BT</i>
7081	1	L/F STEERING KNUCKLE	212 332 0700		790.00* <i>DIS</i>
7047	1	L/F TENSION ROD	212 330 2711		320.00* <i>DIS</i>
1487	1	L/F UPPER DOOR HINGE	204 720 1537		95.00* <i>BT</i>
1671	1	L/F W-FRAME INN TRIM	212 725 0171 9051		55.00* <i>CRA</i>
7201	1	L/F WHEEL	212 401		650.00* <i>BD</i>
			0002649765		
7131	1	L/F WHEEL HUB	212 330 0025		430.00* <i>DIS</i>

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CAR CITY/1

Date Calculated: 09/03/2017 07:34

Full Report - V1

Registration: SCN1616H

Printed: 09/03/2017 15:34

839	1	L/F W-HOUSE CVR FRT	212 690 4330	0%	120.00*DE
841	1	L/F W-HOUSE CVR REAR	212 690 3030	0%	125.00*DE
1597	1	L/F WINDOW CHANNEL	212 725 0325 28	0%	95.00*BT
1551	1	L/F WINDOW MOTOR	212 906 6802	0%	390.00*Jm
741	1	L/F WING	212 880 1118	0%	560.00*BUC
785	1	L/F WING BADGE	204 817 7220	0%	45.00*REC
783	1	L/F WING MOULDING	212 690 3362	0%	28.00*REC
2309	1	L/INNER DOOR FRAME	212 630 4100	0%	1,065.89U x nA
2167	1	L/INNER SILL	212 630 3900	0%	418.11U x SVK
4949	1	L/LWR B-PILLAR TRIM	212 690 3925 9051	0%	50.00*CRA
7311	1	L/OUTER TIE ROD BALL	212 330 2303	0%	130.00*REC
1781	1	L/R DOOR	212 730 0105	0%	1,250.00*DD
1981	1	L/R DOOR MOULDING	212 690 2962	0%	65.00*REC
1809	1	L/R DOOR SEAL	204 727 1187	0%	160.00*CRA
1813	1	L/R LOWER DOOR MLDG	212 690 3782	0%	35.00*CRA
2615	1	L/R MOULDING	212 885 2121	0%	90.00*REC
1961	1	L/R OUT WINDOW GSKT	212 735 0965	0%	85.00*REC
1831	1	L/R QUARTER GLASS	212 730 3900	0%	REC 39.13U
2127	1	L/SILL PANEL	212 637 1535	0%	357.00U x SVK
2207	1	L/SILL PANELLING	212 698 0154 9999	0%	400.00*DD
7055	1	L/TENSION ROD RUBBER	212 333 0014	0%	75.00*DS
7309	1	L/TIE ROD	212 330 2103	0%	145.00*BT
4941	1	L/UPP FRONT TRIM	212 690 5925	0%	70.00*tn
9G26					
4627	1	L/WINDOWBAG	212 860 4302	0%	590.00*REC
2085	1	LEFT DOOR FRAME	212 630 6101	0%	1,500.00*DD
1481	1	LEFT FRONT DOOR	212 720 5300	0%	1,300.00*BUC
3151	1	REAR SCREEN	212 670 0200	0%	360.00*REC
3160	1	REAR SCREEN BOND KIT	221 670 8101	0%	57.50U REC
3161	3	REAR SCREEN SUPPORTS	164 742 0097	0%	1.47U REC
1845	1	RR D/WDW BONDING KIT	221 670 8101	0%	57.50U REC
2386	1	SERVICE LID	212 690 1750	0%	135.00*CRA
9G26					
1411	1	WINDSCREEN REP KIT	221 670 8101	0%	57.50U REC
f: OEM Parts				Sub Total	\$18,334.68
g: Original				Mark Up From Cost (5 %)	\$916.73
h: Secondhand				Sundry Parts (Fixed)	\$100.00
p: Parallel				Total Parts	\$19,351.41
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEES	0%	\$42.00
SEALANT		\$30.00
Total Extras		\$72.00

Final Calculation

Total Parts \$19,351.41

Labour

Total Panel/Mechanical	\$4,452.80
Total Paintwork	\$970.60
Total Visual Alignment work	\$147.20
Corr Prot Internal 16 WU	\$73.60

CHINA TAIPING INSURANCE (S) PTE LTD**Claim Reference: CCA00176****Full Report - V1****Assessment Number: CCA00176****Registration: SCN1616H****Version: CAR CITY/1****Printed: 09/03/2017 15:34****Date Calculated: 09/03/2017 07:34**

Total Labour	\$5,644.20
Additional Costs	
Corr Prot Materials External	\$0.00
Cost of Specialist	\$72.00
Total of Additional Costs	\$72.00
Total Paint/Material Costs	\$421.16
Grand Total Excludes GST	\$25,488.77
GST @ 7 %	\$1,784.21
Grand Total Includes GST	\$27,272.98

Assessment Notes

**CAR CITY AUTO CENTRE
PTE LTD
BLK 9006 TAMPINES
STREE 93**

#01-198

SINGAPORE 528840

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CAR CITY/1

Date Calculated: 19/11/2016 03:02

Full Report - V1

Registration: SCN1616H

Printed: 19/11/2016 11:04

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	HO TOO BOON	Date of Incident:	17/11/2016
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	Liberty Insurance Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	CCA00176	Estimated Repair Time:	
Policy Number:	DMPCSN3007911503	Quote Due Date:	
Other Reference:	OD/17017	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	E Class
Sub Model:	E 250 CGI
Model Sheet Number:	3AE 01
Registration:	SCN1616H
Registration Month:	October
Registration Year:	2009
VIN Number:	WDD2120472A080252
Manufacture Year:	2009
Odometer:	157160
Colour:	Black
Engine Number:	27186030003935
Fuel Level:	%

Model Specs

FROM A076363/L001354	TECH CHANGES 09/09
MODEL 2010	PARKTRONIC
LOAD COMPARTMENT BOX	AUDIO 20 CD CHANGER
MULTIMEDIA INTERFACE	LEATHER TRIM
SUN PROTECTION	TRIM ELEGANCE
MEMORY PACKAGE	PEDESTRIAN PROTECT
DIPPING MIRROR	S-WDW ROLLER BLIND
TRIM WALNUT BURL	REM RELEASE FUEL CAP
KEYLESS GO	DOUBLE CUP HOLDER
ENGINE PROTECTION	RR SCREEN SUN BLIND
AIR INJECTION	AUTO GEARBOX 5 SPEED
DIRECT STEERING	DIRECT CONTROL SUSP
TYRES 205/60 HR 16	WHEELS 7J X 16 ALLOY
SPACE SAVER S-WHEEL	FUEL TANK 80 LTR
HD COOLING	TWO COAT METALLIC
CLEAR COAT HARD	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Fair	Severity of Impact:	Heavy Panel
Steering:	Satisfactory	Vehicle Status on	Unroadworthy
		Inspection:	
Brakes Pedal Travel:	Satisfactory	Date of Inspection:	17/11/2016
Place of Inspection:	Repairer		
Pre-Accident Damage:			
Tyres Condition:	Fair		
Tyres - Tread Depth (MM):			

Left Tyre

Right Tyre

*LKK Henry
97884060
21/11/16 1205hrs.
PIP B4 paint photo
Excess waived
14 day PIP*

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CAR CITY/1

Date Calculated: 19/11/2016 03:02

Full Report - V1



Registration: SCN1616H

Printed: 19/11/2016 11:04

Damage Areas:

	Axles	Depth	Depth	
LHF	0	7.0	7.0	RHF
LHR	1	7.0	7.0	RHR

Direction of Impact:



Addresses

Cost Summary

Total Labour	\$5,819.00
Total Paint/Material	\$421.16
Total Parts	\$19,479.85
Total of Additional Costs	\$72.00
Excess:	TBA
Grand Total Exc GST:	\$25,792.01
7 % GST:	\$1,805.44
Grand Total Inc GST:	\$27,597.45

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$0.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY	3.0	13.80
54-1010 ZAX	CHECK ELECTRIC-/ELECTRONIC SYSTEMS (AFTER SHORT TEST OR ACCORDING TO ERROR CODE)	3.0	13.80
54-7989 03	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	9.20
91-1821 ZAX	SAFETY PRECAUTIONS BEFORE WELDING DISCONNECT AIRBAG/SEATBELT TENSIONER SYS	8.0	36.80
91-0660 01	CHECK SAFETY SYSTEM	3.0	13.80
61-1116 02	R + R L/UNDERFLOOR COVER	3.0	13.80
NO NUMBER	ALIGN BODY BY HANDHELD MEASURING SYSTEM	2.0	9.20
NO NUMBER	ANCHOR VEHICLE ON STRAIGHTENING SYSTEM	9.0	41.40
60-1065 01	REFIT MODUL CROSSMEMBER FROM CASSIS JIG	10.0	46.00
88-1102 02	R + R COMPLETE FRONT BUMPER INCLUDES: R + R RADIATOR COWL	11.0	50.60

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CAR CITY/1

Date Calculated: 19/11/2016 03:02

Full Report - V1

Registration: SCN1616H

Printed: 19/11/2016 11:04

88-1105 02	DIS + ASS FRONT BUMPER (BUMPER REMOVED)	9.0	41.40
88-1380 02	AFTER CHECK: RENEW PARTS IF NECESSARY ADD TO DIS/ASS FRONT BUMPER CPL (LUXURY VERSION VEHICLE)	3.0	13.80
88-1358 02	ADDITION TO DIS + ASS FRONT BUMPER (BUMPER REMOVED)	2.0	9.20
60-2289 01	(VEHICLE WITH ULTRASONIC PARKING AID) R + R R/HEADLAMP UNIT (BUMPER REMOVED)	3.0	13.80
88-3818 02	RENEW LEFT WING (BUMPER REMOVED)	7.0	32.20
88-2503 02	INCLUDES: L/F WHEELHOUSE COVER CPL REMOVE AND REFIT.		
60-1301 01	R + R BONNET	6.0	27.60
	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT	6.0	27.60
	(FOR RENEWAL OF THE REINFORCEMENT) DOES NOT INCLUDE: R + R BUMPER AND LAMP UNITS		
60-1609 01	REMOVE/REFIT LH FRONT SEAT AND LOOSE CARPETS AND PLACE IN STORAGE	9.0	41.40
60-1624 01	R + R COMPLETE REAR SEAT AND CARPETS AND PLACE IN STORAGE	7.0	32.20
62-1301 01	R + R OR RENEW L/F TRUSSING BETWEEN WHEELHOUSES	6.0	27.60
	INCLUDES: R + R CENTRE TRUSSING, RENEW IF NECESSARY		
62-1430 01	R + R LEFT FRONT BUMPER BRACKET	1.0	4.60
67-1500 02	R + R WINDSCREEN	32.0	147.20
72-1450 02	RENEW L/F DOOR AND CONVERT PARTS INCLUDES: DOOR TRIM REMOVE AND REFIT AND ALL ATTACHED PARTS ASSEMBLE	37.0	170.20
72-1682 02	ADDITIONAL RENEW LEFT FRONT DOOR VEHICLE WITH LOWER MOULDING	1.0	4.60
72-2692 02)	RENEW L/F UPPER DOOR HINGE	7.0	32.20
72-6665 02)	RENEW L/F DOOR TRIM (REMOVED)	11.0	50.60
72-1590 02	RENEW L/R DOOR AND CONVERT PARTS INCLUDES: DOOR TRIM REMOVE AND REFIT AND ALL ATTACHED PARTS ASSEMBLE	37.0	170.20
72-1760 02	ADDITIONAL RENEW LEFT REAR DOOR VEHICLE WITH LOWER MOULDING	1.0	4.60
88-5205 02	R + R LEFT SILL TRIM	6.0	27.60
60-1657 ZAX	R + R L/INTERIOR TRIM (FOR RENEWING OUTER SIDEMEMBER SHELL) (DOORS, SEATS AND MATS REMOVED)	9.0	41.40
63-1362 ZAX	RENEW L/A-PILLAR, SIDEMEMBER AND B-PILLAR	227.0	1,044.20
63-1322 01	RENEW L/OUTER A-PILLAR	83.0	381.80
63-1430 01	RENEW L/B-PILLAR	113.0	519.80
63-1120 ZAX	RENEW OUTER SIDEMEMBER LH DOOR SILL, FORWARD OF CENTRE-PILLAR	21.0	96.60
88-9705 02	R + R LEFT ROOF MOULDING	2.0	9.20
68-1621 ZAX	R + R HEADLINING	20.0	92.00

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CAR CITY/1

Date Calculated: 19/11/2016 03:02

Full Report - V:

Registration: SCN1616H

Printed: 19/11/2016 11:04

68-1748 02	ADDITION TO R + R HEADLINING (VEHICLE WITH INTERIOR PROTECTION)	5.0	23.00
91-2102 02	R + R L/HEAD SIDE AIRBAG UNIT (STRIPPED)	3.0	13.80
67-5045 02	RENEW REAR PANEL WINDOW	21.0	96.60
88-8802 02	R + R REAR BUMPER INCLUDES: R + R REAR CENTREPIECE PANELLING	8.0	36.80
88-9626 ZAX	R + R REAR BUMPER MOULDING	3.0	13.80
60-2430 02	R + R BOTH OUTER TAILLAMPS	3.0	13.80
97-2500 ZAX	CAVITY PROTECTION (ADD/WORK)	2.0	9.20
97-2500 ZAX	L/F UPPER SIDEMEMBER CAVITY PROTECTION	2.0	9.20
97-2500 ZAX	CAVITY PROTECTION LEFT FRONT DOOR	2.0	9.20
97-2500 ZAX	CAVITY PROTECTION LEFT REAR DOOR	2.0	9.20
97-2500 ZAX	L/SILL CAVITY PROTECTION	2.0	9.20
97-2500 ZAX	APPLY CAVITY SEALING AT LEFT A-PILLAR	2.0	9.20
97-2500 ZAX	L/B-PILLAR CAVITY PROTECTION	2.0	9.20
97-2500 ZAX	L/R WING CAVITY PROTECTION	2.0	9.20
68-4605 01	R + R INSTRUMENT PANEL	28.0	128.80
91-8759 01	R + R L/F SEAT BACKREST PAD AND COVER INCLUDES: R + R HEADREST, SEAT BACKREST TRIM AND SEAT BACKREST COVERING	14.0	64.40
91-8755 01	RENEW L/F SEAT BACKREST COVER (COVER AND PAD REMOVED)	3.0	13.80
91-9186 01	ADDITION TO RENEW L/F SEAT BACKREST COVER (VEHICLE WITH COMFORT COVER)	1.0	4.60
91-2070 01)	R + R L/F SEAT SIDEBAG UNIT INCLUDES: R + R SEAT BACKREST TRIM	3.0	13.80
91-1905 01)	R + R AIRBAG CONT UNIT AND PRETENS SYS	4.0	18.40
33-1275 02	R + R BOTH FRONT AXLE HALFS	30.0	138.00
32-2050 02)	R + R FRONT STABILIZER	4.0	18.40
33-3510 03)	R + R L/F STEERING KNUCKLE	20.0	92.00
33-1421 03)	R + R LEFT FRONT TORSION BAR	9.0	41.40
32-1955 03)	R + R L/F STRUT	5.0	23.00
32-1908 02)	DISS/ASS L/F SUSPENSION STRUT REMOVED	3.0	13.80
32-1920 02)	DIS + ASS FRONT SPRING STRUT/S (REMOVED)	3.0	13.80
46-7004 01)	R + R LEFT TIE ROD	5.0	23.00
40-2410 01	R + R LEFT FRONT TYRE	3.0	13.80
40-2055 01	L/FRONT WHEEL BALANCE	2.0	9.20
42-1350 01	BLEED BRAKE SYSTEM	10.0	46.00
83-0640 01	CHECK AIR COND	3.0	13.80
40-6500 01	ALIGN VEHICLE INCLUDES: ALIGN FRONT AND REAR TOE AND CAMBER, CHECK FRONT AND REAR VEHICLE LEVEL	7.0	32.20
40-6710 01	ADD/WORK FOR VEHICLE WITH BOARDING-/ EXITING SUPPORT	1.0	4.60
40-4064 01	ADJUST FRONT WHEEL TOE (DURING ALIGNMENT)	2.0	9.20
40-6716 01	ADDITIONAL TO OPTICAL ALIGNMENT ADJUST L/FRONT AXLE HALF CAMBER/CASTER	6.0	27.60
40-6717 01	ADDITIONAL TO OPTICAL ALIGNMENT ADJUST R/FRONT AXLE HALF CAMBER/CASTER	6.0	27.60
40-6992 ZAX	ADD/WORK FOR CALIBRATE VEHICLE AXLE LEVEL WITH STAR DIAGNOSIS (BOTH AXLES)	5.0	23.00

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CAR CITY/1

Date Calculated: 19/11/2016 03:02

Full Report - V1

Registration: SCN1616H

Printed: 19/11/2016 11:04

40-8052 ZAX	CHECK FRONT/REAR WHEEL TRACK ALIGNMENT	5.0	23.00
	DURING TRACK AND ALIGNMENT CHECK		
1477	ADDITIONAL WORK PULLING L/SIDE	15.0*	69.00
1995	REMOVE AND REFIT INSULATION MATS	5.0*	23.00
9699	TYRE SERVICE	5.0*	23.00
9722	FAULT FINDING	5.0*	23.00
9854	READ OUT ERROR MEMORY	20.0*	92.00
9980	CARRY OUT CALIBRATION DRIVE	15.0*	69.00
1155	REPAIR L/UPP W-HOUSE S-MEMB	10.0*	46.00
2583	REPAIR REAR BUMPER COVER	8.0*	36.80
3481	REPAIR L/R WING	10.0*	46.00
0561	CHECK LEFT HEADLAMP ASSY		
1436	CHECK WASHER CONTAINER		
1445	CHECK WASHER JET HOSE		
1565	CHECK L/F DOOR OUT HANDLE		
1567	CHECK L/F OUT HANDLE PLATE		
1573	CHECK LEFT MEMBER TRIM		
1579	CHECK L/F DOOR LOCK COVER		
1601	CHECK L/F COVER		
1629	CHECK L/SEAT ADJ SWITCH		
1645	CHECK L/F UPPER SPEAKER		
1655	CHECK L/F W-FRAME RR MLDG		
1701	CHECK L/F LWR DOOR DAMPING		
1707	CHECK L/F LWR DOOR SPEAKER		
1723	CHECK L/F DOOR INSULATION		
1737	CHECK LEFT DOOR MIRROR		
1747	CHECK L/DOOR MIRROR COVER		
1865	CHECK L/R DOOR OUT HANDLE		
1871	CHECK L/R DOOR HANDLE TRIM		
1947	CHECK L/R DR FRM FRT MLDG		
2411	CHECK L/SEAT MOUNT PLATE		
4551	CHECK L/OUTER SEAT COVER		
4593	CHECK L/BACKREST SHELL		
4595	CHECK L/F BACKREST TRIM		
4611	CHECK L/F PRESSURE SENSOR		
7011	CHECK FRONT AXLE SUPPORT		
7097	CHECK L/LWR DAMPER RING		
7099	CHECK L/UPPER DAMPER RING		
7103	CHECK L/F S-ABSORB BOOT		
7141	CHECK L/F BRAKE DISC		
7227	CHECK L/F TYRE		
7300	CHECK STEERING GEAR		

LABOUR COST

Total Work Units	1,054.0	
Panel / Mechanical Labour	100.6HRS	\$4,627.60
Visual Alignment Labour	3.2HRS	\$147.20
Corrosion Protection		
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	1.6HRS	73.60
Sub Total	105.4HRS	\$4,848.40
Paint Labour	21.1HRS	\$970.60
Total Labour	126.5HRS	\$5,819.00

//

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CAR CITY/1

Date Calculated: 19/11/2016 03:02

Full Report - V

Registration: SCN16161

Printed: 19/11/2016 11:00

PAINT WORK

Guide Number	Description	Time Basis 10 WU = 1 HR.	Price = \$46.00/HR	WU	Cost Price (\$)
	- TWO COAT METALLIC				
98-1731 01	FRONT BUMPER COVER PAINTING STAGE I-M			11.0	
98-2415 01	L/F WING PAINTING STAGE I-M			6.0	
98-4015 01	LEFT FRONT DOOR PAINTING STAGE I-M			11.0	
98-1881 01	L/DOOR MIRROR HSG PAINTING STAGE I-M			1.0	
98-4115 02	L/R DOOR PAINTING STAGE I-M			11.0	
98-5535 01	LEFT DOOR FRAME PAINTING STAGE I-E			28.0	
98-5350 01	L/F SILL PAINTING STAGE I-E			5.0	
98-1861 01	L/SILL PANELLING PAINTING STAGE I-M			5.0	
98-5555 01	LEFT B-PILLAR PAINTING STAGE I-E			36.0	
98-8980 ZAX	L/F WHEEL PAINT			4.0	
98-1735 01	REAR BUMPER COVER PAINTING STAGE III			13.0	
98-7047 01	L/R WING PAINTING STAGE III			23.0	
	WITHOUT FRT SURFACE BELOW DOOR				
98-2806 01	BONNET PAINTING STAGE II			23.0	
L 1155	L/UPP W-HOUSE S-MEMBPAINTING STAGE I-J			3.0	
98-1340 01	PREPARATION WORK FOR TWO COAT PAINTING OF FITTED BODY PARTS			15.0	
98-1356 01	ADD/WORK FOR PLASTIC PARTS			3.0	
98-1620 ZAX	PRIME PLASTIC/METAL PARTS			3.0	
98-1630 ZAX	APPLY SMOOTHG FILLER ON PLAST/MET PARTS			3.0	
98-1625 ZAX	REPAIR/APPLY FILLER ON PLAST/METAL PARTS			2.0	
98-1620 ZAX	APPLY PRIMER REAR BUMPER (ADD/WORK)			1.0	
98-1630 ZAX	APPLY FILLER REAR BUMPER (ADD/WORK)			1.0	
98-1625 ZAX	APPLY FILLER PASTE REAR BUMPER (ADD)			3.0	
LABOUR COST - PAINT					
TIME(PAINT)				0.0	
Total Work Units (10WU/HR)				211.0	
Total Paintwork Labour				21.1HRS	
MATERIAL COST - PAINT					\$970.60
Total Excluding Pearlescent Uplift					Cost Price
Pearlescent Uplift @ 0.0%					\$421.16
Total Paint Material Cost					\$0.00
					\$421.16

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
283	1	FRONT BUMPER COVER	212 880 1340 9999	deform	0% —	850.00*
285	1	L/F SPACER	212 889 1195	nec	0% —	10.00*
741	1	L/F WING	212 880 1118	Buc	0% —	560.00*
783	1	L/F WING MOULDING	212 690 3362	nec	0% —	28.00*
785	1	L/F WING BADGE	204 817 7220	nec	0% —	45.00*
839	1	L/F W-HOUSE CVR FRT	212 690 4330	deform	0% —	120.00*
841	1	L/F W-HOUSE CVR REAR	212 690 3030	deform	0% —	125.00*
1179	1	L/REINFORCEMENT	212 620 0185	} s/c	X 0% ?	35.00*
1187	1	L/F UPP REINF	212 620 0191		X 0% ?	170.00*
1411	1	WINDSCREEN REP KIT	221 670 8101	Activated	X 0% ?	0.00
1413	4	FRT SCREEN SUPPORTS	210 671 0397		X 0% ?	0.00
1479	1	L/F DOOR MODULE	212 720 1579	Buc	0% —	420.00*
1481	1	LEFT FRONT DOOR	212 720 5300	Bent	0% —	1,300.00*
1487	1	L/F UPPER DOOR HINGE	204 720 1537		0%	95.00*

Price Valid: 01/06/2015

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CAR CITY/1

Date Calculated: 19/11/2016 03:02

Full Report - V

Registration: SCN16161

Printed: 19/11/2016 11:0

1495	1	L/F LOWER DOOR HINGE	204 720 1737	bent	0%	—	120.00*
1509	1	L/F DOOR SEAL	204 727 1187	rec	0%	—	180.00*
1513	1	L/F LOWER DOOR MLDG	212 690 4762	rec	0%	—	50.00*
1519	1	L/F DOOR WINDOW	212 725 0710	smashed	0%	—	150.00*
1551	1	L/F WINDOW MOTOR	212 906 6802	jam	0%	—	390.00*
1597	1	L/F WINDOW CHANNEL	212 725 0325	28 bent	0%	—	95.00*
1619	1	L/F CHANNEL SEAL	212 725 0965	rec	0%	—	30.00*
1625	1	L/F OUT WINDOW SEAL	212 725 0565	rec	0%	—	75.00*
1671	1	L/F W-FRAME INN TRIM	212 725 0171	9051 cra	0%	—	55.00*
1681	1	L/F DOOR MOULDING	212 690 2562	deform	0%	—	65.00*
1711	1	L/F DOOR TRIM	212 720 2370	cra	0%	—	600.00*
			9G50				
1749	1	L/OUT DR MIRROR CVR	212 811 0198	svc	0%		23.00*
1775	1	L/F DOOR LAMP	002 820 1901	svc	0%		26.00*
1777	1	L/F DOOR FRAME SEAL	212 697 0051	svc	0%		150.00*
			9G44				
1781	1	L/R DOOR	212 730 0105	dented	0%		1,250.00*
1809	1	L/R DOOR SEAL	204 727 1187	cra	0%		160.00*
1813	1	L/R LOWER DOOR MLDG	212 690 3782	cra	0%		35.00*
1831	1	L/R QUARTER GLASS	212 730 3900	rec	0%	34.13u	0.00—
1845	1	RR D/WDW BONDING KIT	221 670 8101	rec	0%	59.50u	0.00—
1961	1	L/R OUT WINDOW GSKT	212 735 0965	rec	0%		85.00*
1981	1	L/R DOOR MOULDING	212 690 2962	rec	0%		65.00*
2063	1	L/R DOOR FRAME PROT	212 697 0151	svc	0%		X 150.00*?
			9G44				
2085	1	LEFT DOOR FRAME	212 630 6101	dented	0%		1,500.00*
2107	1	2K ADHESIVE L/SIDE	009 989 3671	12 rec	0%	167.16	0.00—
2127	1	L/SILL PANEL	212 637 1535	svc	0%		X 2 0.00 <
2167	1	L/INNER SILL	212 630 3900	svc	0%		X 2 0.00
2207	1	L/SILL PANELLING	212 698 0154	9999 dented	0%		—400.00*
2309	1	L/INNER DOOR FRAME	212 630 4100	an	0%		X 2 0.00 Δ
2386	1	SERVICE LID	212 690 1750	cra	0%		—135.00*
			9G26				
2417	1	L/ROOF FRAME MLDG	212 690 0780	an	0%	X 2	260.00*
2593	1	L/R BUMPER GUIDE	212 880 1330	an	0%	X 2	30.00*
2615	1	L/R MOULDING	212 885 2121	rec	0%		—90.00*
3151	1	REAR SCREEN	212 670 0200	rec	0%		—360.00*
3160	1	REAR SCREEN BOND KIT	221 670 8101	rec	0%	59.50u	—0.00 Δ
3161	3	REAR SCREEN SUPPORTS	164 742 0097	rec	0%	147u	—0.00
4589	1	L/F BACKREST COVER	212 910 5547	9E43 svc	0%		X 1,100.00*
4607	1	L/F SIDE AIRBAG	212 860 3402	9051 activated	0%		—340.00*
4627	1	L/WINDOWBAG	212 860 4302	rec	0%		—590.00*
4941	1	L/UPP FRONT TRIM	212 690 5925	tom	0%		—70.00*
			9G26				
4947	1	L/B-PILLAR TRIM	212 690 1926	cra	0%		—120.00*
			9G26				
4949	1	L/LWR B-PILLAR TRIM	212 690 3925	9051 cra	0%		—50.00*
4957	1	HEADLINING	212 690 5950	deform	0%		X 960.00*
			9G26				
7047	1	L/F TENSION ROD	212 330 2711	} distorted	0%	2	320.00*
7055	1	L/TENSION ROD RUBBER	212 333 0014		0%	2	75.00*
7065	1	L/F BALL JOINT	212 330 0135		0%	2	105.00*
7071	1	L/F LWR CONTROL ARM	212 330 3900		0%	2	320.00*
7081	1	L/F STEERING KNUCKLE	212 332 0700		0%	2	790.00*

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CAR CITY/1

Date Calculated: 19/11/2016 03:02

Full Report - V

Registration: SCN16161

Printed: 19/11/2016 11:0

7087	1	L/F SHOCK ABSORBER	212 323 5300	<i>bent</i>	0%	
7131	1	L/F WHEEL HUB	212 330 0025	<i>distorted</i>	0%	— 520.00*
7133	1	L/F PROTECT PLATE	212 420 1144	<i>NA</i>	0%	— 2 430.00*
7201	1	L/F WHEEL	212 401	<i>dented</i>	0%	X 2 85.00*
			0002649765		0%	— 650.00*
7251	1	L/F SPEED SENSOR	212 540 0117	<i>SLC</i>	0%	X 2 260.00*
7261	1	FRONT STABILISER	212 323 0965	<i>bent</i>	0%	— 2 290.00*
7263	1	L/F STABILISER ARM	212 320 1189	<i>bent</i>	0%	— 2 75.00*
7309	1	L/TIE ROD	212 330 2103	<i>bent</i>	0%	— 2 145.00*
7311	1	L/OUTER TIE ROD BALL	212 330 2303	<i>rec</i>	0%	— 2 130.00*
7521	1	L/B-PILLAR SENSOR	212 820 4926	<i>activated</i>	0%	— 2 85.00*
8777	1	L/B-RACKET	204 524 1340	<i>NA</i>	0%	X 2 30.00*
9686	1	AIRBAG/TENS C-UNIT	212 901 4204	<i>rec</i>	0%	— 630.00*
f: OEM Parts			Sub Total			\$18,457.00
g: Original			Mark Up From Cost (5 %)			\$922.85
h: Secondhand			Sundry Parts (Fixed)			\$100.00
p: Parallel			Total Parts			\$19,479.85
x: Exchange						

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER *+supp 19061.18*

Extras

Description	Betterment	Price
AUDATEX FEES	0% <i>rec</i>	\$42.00
SEALANT	<i>rec</i>	\$30.00
SPECIALIST		
SPECIALIST		
Total Extras		\$72.00

Final Calculation

Total Parts		
Labour		\$19,479.85
Total Panel/Mechanical	\$4,627.60	
Total Paintwork	\$970.60	
Total Visual Alignment work	\$147.20	
Corr Prot Internal 16 WU	\$73.60	
Total Labour		\$5,819.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Cost of Specialist	\$72.00	
Total of Additional Costs		\$72.00
Total Paint/Material Costs		\$421.16
Grand Total Excludes GST		\$25,792.01
GST @ 7 %		\$1,805.44
Grand Total Includes GST		\$27,597.45

Assessment Notes



CAR CITY AUTO CENTRE PTE LTD

Car City Always

Blk 9006 Tampines st93 #01-198 S'pore 528840

TEL: 6781 0300 FAX: 6782 0300

E-mail : ccacpl@singnet.com.sg

DATE : 5-Dec-16

TO:
ATTN: MOTOR CLAIMS DEPT

JOB TYPE :

VEH NO : SCN1616H

ESTIMATE REPORT

OWNER'S PARTICULAR

NAME:
ADDRESS:

MODEL : MERCEDES BENZ

CHASSIS NO : WDD2120472A080252

ENGINE NO:

ACCIDENT DATE :

CONTACT NO H/P:

TEL:

OWNERS INSURER :

POLICY NO:

QUOTATION SUMMARY (SUPPLEMENT)

REQUESTOR CONTACT :

CLAIM DETAIL: PARTS

S/NO	DESCRIPTION	QTY	UNIT COST PRICE	TOTAL COST PRICE
1	CONTROL UNIT <i>shunt</i>	1	\$85.00	\$85.00 ✓
2	32917 FRT S/A MTY <i>distorted</i>	1	\$125.00	\$125.00 ✓
3	2047200935 LOCK LH 212 889 <i>crn</i>	1	\$350.00	\$350.00 ✓
4	BRACKET <i>crn</i>	1	\$10.00	\$10.00 ✓
5	COVERING <i>crn</i>	1	\$13.00	\$13.00 ✓
6	COVERING <i>crn</i>	1	\$20.00	\$20.00 ✓
7	COVERING <i>crn</i>	1	\$20.00	\$20.00 ✓
8	DOOR HANDLE <i>crn</i>	1	\$240.00	\$240.00 ✓
9	COVERING <i>crn</i>	1	\$40.00	\$40.00 ✓
10	RAIL <i>dented</i>	1	\$88.00	\$88.00 ✓
11	RIVET <i>rec</i>	30	\$3.00	\$90.00 ✓
12	2127350125 W/D RUNN LH <i>dented</i>	1	\$110.00	\$110.00 ✓
13	2128605385 REAR SAFETY BELT <i>jam</i>	1	\$310.00	\$310.00 ✓
14	SAFETY BELT <i>jam</i>	1	\$310.00	\$310.00 ✓
15	FRT FENDER END COVER <i>turn</i>	1	\$18.00	\$18.00 ✓
16	PROTECTIVE HOSE <i>crn</i>	1	\$12.00	\$12.00 ✓
17	GUIDE RAIL <i>bent</i>	1	\$17.50	\$17.50 ✓
18	2127601434 BEARING BRACKET <i>distorted</i>	1	\$98.00	\$98.00 ✓
19	CABLE HARNESS ROOF AIR BAG <i>tom</i>	1	\$59.00	\$59.00 ✓

PARTS PRICE : \$2,015.50

ADD 5% : \$100.78

TOTAL PARTS PRICE : \$2,116.28

Resurvey
5/12/15
1700hrs
LKK Henry

CAR CITY AUTO CENTRE
PTE LTD
BLK 9006 TAMPINES
STREE 93

#01-198
SINGAPORE 528840

43

Claim Reference: CCA00176
Assessment Number: CCA00176
Version: CAR CITY/3
Date Calculated: 17/03/2017 04:44

Full Report - V1
Registration: SCN1616H
Printed: 17/03/2017 12:45

Summary Information

Claim			
Location:	Singapore (SG)	Currency:	SGD
Printed by:	HO TOO BOON	Date of Incident:	17/11/2016
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	Liberty Insurance Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	CCA00176	Estimated Repair Time:	
Policy Number:	DMPCSN3007911503	Quote Due Date:	
Other Reference:	OD/17017	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle		Model Specs	
Manufacturer:	MERCEDES	FROM A076363/L001354	TECH CHANGES 09/09
Model:	E Class	MODEL 2010	PARKTRONIC
Sub Model:	E 250 CGI	LOAD COMPARTMENT BOX	AUDIO 20 CD CHANGER
Model Sheet Number:	3AE 01	MULTIMEDIA INTERFACE	LEATHER TRIM
Registration:	SCN1616H	SUN PROTECTION	TRIM ELEGANCE
Registration Month:	October	MEMORY PACKAGE	PEDESTRIAN PROTECT
Registration Year:	2009	DIPPING MIRROR	S-WDW ROLLER BLIND
VIN Number:	WDD2120472A080252	TRIM WALNUT BURL	REM RELEASE FUEL CAP
Manufacture Year:	2009	KEYLESS GO	DOUBLE CUP HOLDER
Odometer:	157160	ENGINE PROTECTION	RR SCREEN SUN BLIND
Colour:	Black	AIR INJECTION	AUTO GEARBOX 5 SPEED
Engine Number:	27186030003935	DIRECT STEERING	DIRECT CONTROL SUSP
Fuel Level:	%	TYRES 205/60 HR 16	WHEELS 7J X 16 ALLOY
		SPACE SAVER S-WHEEL	FUEL TANK 80 LTR
		HD COOLING	TWO COAT METALLIC
		CLEAR COAT HARD	

Vehicle Condition

Vehicle Status			
Pre-Accident Condition:	Fair	Severity of Impact:	Heavy Panel
Steering:	Satisfactory	Vehicle Status on	Unroadworthy
		Inspection:	
Brakes Pedal Travel:	Satisfactory	Date of Inspection:	17/11/2016
Place of Inspection:	Repairer		
Pre-Accident Damage:			
Tyres Condition:	Fair		
Tyres - Tread Depth (MM):			

Left Tyre

Right Tyre

CAR CITY AUTO CENTRE PTE LTD



Claim Reference: CCA00176
 Assessment Number: CCA00176
 Version: CAR CITY/3
 Date Calculated: 17/03/2017 04:44

Full Report - V1
 Registration: SCN1616H
 Printed: 17/03/2017 12:45

	Axles	Depth	Depth
LHF	0	7.0	7.0
LHR	1	7.0	7.0

Damage Areas:

RHF
 RHR
 Direction of Impact:



Addresses

Cost Summary

Total Labour	\$6,118.00
Total Paint/Material	\$423.78
Total Parts	\$21,226.19
Total of Additional Costs	\$72.00
Excess:	TBA
Grand Total Exc GST:	\$27,839.97
7 % GST:	\$1,948.80
Grand Total Inc GST:	\$29,788.77

Repair Information

LABOUR		Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR Price/Dent = \$0.00/HR	
Repair / Guide Number	Repair Details	WU	Cost Price (\$)
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY	3.0	13.80
54-1010 ZAX	CHECK ELECTRIC-/ELECTRONIC SYSTEMS (AFTER SHORT TEST OR ACCORDING TO ERROR CODE)	3.0	13.80
54-7989 03	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	9.20
91-1821 ZAX	SAFETY PRECAUTIONS BEFORE WELDING DISCONNECT AIRBAG/SEATBELT TENSIONER SYS	8.0	36.80
91-0660 01	CHECK SAFETY SYSTEM	3.0	13.80
61-1116 02	R + R L/UNDERFLOOR COVER	3.0	13.80
NO NUMBER	ALIGN BODY BY HANDHELD MEASURING SYSTEM	2.0	9.20
NO NUMBER	ANCHOR VEHICLE ON STRAIGHTENING SYSTEM	9.0	41.40
60-1065 01	REFIT MODUL CROSSMEMBER FROM CASSIS JIG	10.0	46.00
88-1102 02	R + R COMPLETE FRONT BUMPER INCLUDES: R + R RADIATOR COWL	11.0	50.60

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00176
Assessment Number: CCA00176
Version: CAR CITY/3
Date Calculated: 17/03/2017 04:44

Full Report - V1
Registration: SCN1616H
Printed: 17/03/2017 12:45

88-1105 02	DIS + ASS FRONT BUMPER (BUMPER REMOVED)	9.0	41.40
	AFTER CHECK: RENEW PARTS IF NECESSARY		
88-1380 02	ADD TO DIS/ASS FRONT BUMPER CPL (LUXURY VERSION VEHICLE)	3.0	13.80
88-1358 02	ADDITION TO DIS + ASS FRONT BUMPER (BUMPER REMOVED)	2.0	9.20
	(VEHICLE WITH ULTRASONIC PARKING AID)		
60-2289 01	R + R R/HEADLAMP UNIT (BUMPER REMOVED)	3.0	13.80
88-3818 02	RENEW LEFT WING (BUMPER REMOVED)	7.0	32.20
	INCLUDES: L/F WHEELHOUSE COVER CPL REMOVE AND REFIT.		
88-2503 02	R + R BONNET	6.0	27.60
60-1609 01	REMOVE/REFIT LH FRONT SEAT AND LOOSE CARPETS AND PLACE IN STORAGE	9.0	41.40
60-1624 01	R + R COMPLETE REAR SEAT AND CARPETS AND PLACE IN STORAGE	7.0	32.20
67-1500 02	R + R WINDSCREEN	32.0	147.20
72-1450 02	RENEW L/F DOOR AND CONVERT PARTS INCLUDES: DOOR TRIM REMOVE AND REFIT AND ALL ATTACHED PARTS ASSEMBLE	37.0	170.20
72-1682 02	ADDITIONAL RENEW LEFT FRONT DOOR VEHICLE WITH LOWER MOULDING	1.0	4.60
72-2692 02)	RENEW L/F UPPER DOOR HINGE	7.0	32.20
72-6665 02)	RENEW L/F DOOR TRIM (REMOVED)	11.0	50.60
72-1590 02	RENEW L/R DOOR AND CONVERT PARTS INCLUDES: DOOR TRIM REMOVE AND REFIT AND ALL ATTACHED PARTS ASSEMBLE	37.0	170.20
72-1760 02	ADDITIONAL RENEW LEFT REAR DOOR VEHICLE WITH LOWER MOULDING	1.0	4.60
88-5205 02	R + R LEFT SILL TRIM	6.0	27.60
60-1657 ZAX	R + R L/INTERIOR TRIM (FOR RENEWING OUTER SIDEMEMBER SHELL) (DOORS, SEATS AND MATS REMOVED)	9.0	41.40
63-1362 ZAX	RENEW L/A-PILLAR, SIDEMEMBER AND B-PILLAR	227.0	1,044.20
63-1322 01	RENEW L/OUTER A-PILLAR	83.0	381.80
63-1430 01	RENEW L/B-PILLAR	113.0	519.80
63-1120 ZAX	RENEW OUTER SIDEMEMBER LH DOOR SILL, FORWARD OF CENTRE-PILLAR	21.0	96.60
91-2141 01)	R + R R/SIDEBAG SENSOR	3.0	13.80
68-1621 ZAX	R + R HEADLINING	20.0	92.00
68-1748 02	ADDITION TO R + R HEADLINING (VEHICLE WITH INTERIOR PROTECTION)	5.0	23.00
91-2102 02	R + R L/HEAD SIDE AIRBAG UNIT (STRIPPED)	3.0	13.80
67-5045 02	RENEW REAR PANEL WINDOW	21.0	96.60
88-9626 ZAX	R + R REAR BUMPER MOULDING	3.0	13.80
60-2430 02	R + R BOTH OUTER TAILLAMPS	3.0	13.80
97-2500 ZAX	CAVITY PROTECTION (ADD/WORK)	2.0	9.20
97-2500 ZAX	L/F UPPER SIDEMEMBER CAVITY PROTECTION	2.0	9.20
97-2500 ZAX	CAVITY PROTECTION LEFT FRONT DOOR	2.0	9.20
97-2500 ZAX	CAVITY PROTECTION LEFT REAR DOOR	2.0	9.20

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CAR CITY/3

Date Calculated: 17/03/2017 04:44

Full Report - V1

Registration: SCN1616H

Printed: 17/03/2017 12:45

97-2500 ZAX	L/SILL CAVITY PROTECTION	2.0	9.20
97-2500 ZAX	APPLY CAVITY SEALING AT LEFT A-PILLAR	2.0	9.20
97-2500 ZAX	L/B-PILLAR CAVITY PROTECTION	2.0	9.20
97-2500 ZAX	L/R WING CAVITY PROTECTION	2.0	9.20
68-4605 01	R + R INSTRUMENT PANEL	28.0	128.80
91-5852 01	R + R L/F SEAT BACKREST TRIM	3.0	13.80
91-2070 01)	R + R L/F SEAT SIDEBAG UNIT	3.0	13.80
	INCLUDES: R + R SEAT BACKREST TRIM		
91-1087 01)	R + R LEFT REAR SEAT BELT	2.0	9.20
91-1107 01)	R + R CENTRE REAR SEAT BELT	3.0	13.80
54-7940 ZAX	RENEW ROOF WIRING HARNESS	7.0	32.20
91-1905 01)	R + R AIRBAG CONT UNIT AND PRETENS SYS	4.0	18.40
33-1275 02	R + R BOTH FRONT AXLE HALFS	30.0	138.00
32-2050 02)	R + R FRONT STABILIZER	4.0	18.40
33-3510 03)	R + R L/F STEERING KNUCKLE	20.0	92.00
33-1421 03)	R + R LEFT FRONT TORSION BAR	9.0	41.40
32-1955 03)	R + R L/F STRUT	5.0	23.00
32-1908 02)	DISS/ASS L/F SUSPENSION STRUT REMOVED	3.0	13.80
32-1920 02)	DIS + ASS FRONT SPRING STRUT/S (REMOVED)	3.0	13.80
40-2410 01	R + R LEFT FRONT TYRE	3.0	13.80
40-2055 01	L/FRONT WHEEL BALANCE	2.0	9.20
42-1350 01	BLEED BRAKE SYSTEM	10.0	46.00
83-0640 01	CHECK AIR COND	3.0	13.80
40-6500 01	ALIGN VEHICLE	7.0	32.20
	INCLUDES: ALIGN FRONT AND REAR TOE AND CAMBER,		
	CHECK FRONT AND REAR VEHICLE LEVEL		
40-6710 01	ADD/WORK FOR VEHICLE WITH BOARDING-/EXITING SUPPORT	1.0	4.60
40-4064 01	ADJUST FRONT WHEEL TOE (DURING ALIGNMENT)	2.0	9.20
40-6716 01	ADDITIONAL TO OPTICAL ALIGNMENT	6.0	27.60
	ADJUST L/FRONT AXLE HALF CAMBER/CASTER		
40-6717 01	ADDITIONAL TO OPTICAL ALIGNMENT	6.0	27.60
	ADJUST R/FRONT AXLE HALF CAMBER/CASTER		
40-6992 ZAX	ADD/WORK FOR CALIBRATE VEHICLE AXLE LEVEL WITH STAR DIAGNOSIS (BOTH AXLES)	5.0	23.00
40-8052 ZAX	CHECK FRONT/REAR WHEEL TRACK ALIGNMENT DURING TRACK AND ALIGNMENT CHECK	5.0	23.00
1477	ADDITIONAL WORK PULLING L/SIDE	15.0*	69.00
1995	REMOVE AND REFIT INSULATION MATS	5.0*	23.00
9699	TYRE SERVICE	5.0*	23.00
9722	FAULT FINDING	5.0*	23.00
9854	READ OUT ERROR MEMORY	92.0*	423.20
9980	CARRY OUT CALIBRATION DRIVE	18.0*	82.80
1155	REPAIR L/UPP W-HOUSE S-MEMB	10.0*	46.00
1179	REPAIR L/REINFORCEMENT	5.0*	23.00
1187	REPAIR L/F UPP REINF	8.0*	36.80
2583	REPAIR REAR BUMPER COVER	8.0*	36.80
3481	REPAIR L/R WING	10.0*	46.00
0561	CHECK LEFT HEADLAMP ASSY		
1436	CHECK WASHER CONTAINER		
1445	CHECK WASHER JET HOSE		
1573	CHECK LEFT MEMBER TRIM		

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CAR CITY/3

Date Calculated: 17/03/2017 04:44

Full Report - V1

Registration: SCN1616H

Printed: 17/03/2017 12:45

1579	CHECK L/F DOOR LOCK COVER
1629	CHECK L/SEAT ADJ SWITCH
1645	CHECK L/F UPPER SPEAKER
1655	CHECK L/F W-FRAME RR MLDG
1701	CHECK L/F LWR DOOR DAMPING
1707	CHECK L/F LWR DOOR SPEAKER
1723	CHECK L/F DOOR INSULATION
1737	CHECK LEFT DOOR MIRROR
1747	CHECK L/DOOR MIRROR COVER
1865	CHECK L/R DOOR OUT HANDLE
1871	CHECK L/R DOOR HANDLE TRIM
1947	CHECK L/R DR FRM FRT MLDG
2411	CHECK L/SEAT MOUNT PLATE
4551	CHECK L/OUTER SEAT COVER
4593	CHECK L/BACKREST SHELL
4595	CHECK L/F BACKREST TRIM
4611	CHECK L/F PRESSURE SENSOR
7011	CHECK FRONT AXLE SUPPORT
7097	CHECK L/LWR DAMPER RING
7103	CHECK L/F S-ABSORB BOOT
7141	CHECK L/F BRAKE DISC
7227	CHECK L/F TYRE
7300	CHECK STEERING GEAR

LABOUR COST

Total Work Units	1,114.0	
Panel / Mechanical Labour	106.6HRS	\$4,903.60
Visual Alignment Labour	3.2HRS	\$147.20
Corrosion Protection		
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	1.6HRS	73.60
Sub Total	111.4HRS	\$5,124.40
Paint Labour	21.6HRS	\$993.60
Total Labour	133.0HRS	\$6,118.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
98-1731 01	FRONT BUMPER COVER PAINTING STAGE I-M	11.0	
98-2415 01	L/F WING PAINTING STAGE I-M	6.0	
98-4015 01	LEFT FRONT DOOR PAINTING STAGE I-M	11.0	
98-1710 ZAX	L/F DOOR OUT HANDLE PAINTING STAGE I-M	1.0	
98-1710 ZAX	L/F COVER PAINTING STAGE I-M	1.0	
98-1881 01	L/DOOR MIRROR HSG PAINTING STAGE I-M	1.0	
98-4115 02	L/R DOOR PAINTING STAGE I-M	11.0	
98-5535 01	LEFT DOOR FRAME PAINTING STAGE I-E	28.0	
98-5350 01	L/F SILL PAINTING STAGE I-E	5.0	
98-1861 01	L/SILL PANELLING PAINTING STAGE I-M	5.0	
98-5555 01	LEFT B-PILLAR PAINTING STAGE I-E	36.0	
98-8980 ZAX	L/F WHEEL PAINT	4.0	
98-1735 01	REAR BUMPER COVER PAINTING STAGE III	13.0	
98-7047 01	L/R WING PAINTING STAGE III	23.0	
	WITHOUT FRT SURFACE BELOW DOOR		

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00176

Full Report - V1

Assessment Number: CCA00176

Registration: SCN1616H

Version: CAR CITY/3

Printed: 17/03/2017 12:45

Date Calculated: 17/03/2017 04:44

98-2806 01	BONNET PAINTING STAGE II	23.0	
L 1155	L/UPP W-HOUSE S-MEMBPAINTING STAGE I-J	3.0	
L 1187	L/F UPP REINF PAINTING STAGE I-J	3.0	
98-1340 01	PREPARATION WORK FOR TWO COAT PAINTING OF FITTED BODY PARTS	15.0	
98-1356 01	ADD/WORK FOR PLASTIC PARTS	3.0	
98-1620 ZAX	PRIME PLASTIC/METAL PARTS	3.0	
98-1630 ZAX	APPLY SMOOTHG FILLER ON PLAST/MET PARTS	3.0	
98-1625 ZAX	REPAIR/APPLY FILLER ON PLAST/METAL PARTS	2.0	
98-1620 ZAX	APPLY PRIMER REAR BUMPER (ADD/WORK)	1.0	
98-1630 ZAX	APPLY FILLER REAR BUMPER (ADD/WORK)	1.0	
98-1625 ZAX	APPLY FILLER PASTE REAR BUMPER (ADD)	3.0	
LABOUR COST - PAINT			
TIME(PAINT)		0.0	
Total Work Units (10WU/HR)		216.0	
Total Paintwork Labour		21.6HRS	\$993.60
MATERIAL COST - PAINT			Cost Price
Total Excluding Pearlescent Uplift			\$423.78
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$423.78

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
283	1	FRONT BUMPER COVER	212 880 1340 9999		0%	850.00*
285	1	L/F SPACER	212 889 1195		0%	10.00*
741	1	L/F WING	212 880 1118		0%	860.00*
745	1	L/F WING COVER	212 889 0125		0%	18.00*
783	1	L/F WING MOULDING	212 690 3362		0%	28.00*
785	1	L/F WING BADGE	204 817 7220		0%	45.00*
839	1	L/F W-HOUSE CVR FRT	212 690 4330		0%	120.00*
841	1	L/F W-HOUSE CVR REAR	212 690 3030		0%	125.00*
1411	1	WINDSCREEN REP KIT	221 670 8101		0%	57.50*
1413	4	FRT SCREEN SUPPORTS	210 671 0397		0%	5.40*
1479	1	L/F DOOR MODULE	212 720 1579		0%	420.00*
1481	1	LEFT FRONT DOOR	212 720 5300		0%	1,300.00*
1487	1	L/F UPPER DOOR HINGE	204 720 1537		0%	95.00*
1495	1	L/F LOWER DOOR HINGE	204 720 1737		0%	120.00*
1509	1	L/F DOOR SEAL	204 727 1187		0%	180.00*
1519	1	L/F DOOR WINDOW	212 725 0710		0%	150.00*
1551	1	L/F WINDOW MOTOR	212 906 6802		0%	390.00*
1565	1	L/F DOOR OUT HANDLE	204 760 1370 9197		0%	240.00*
1575	1	L/BEARING COVER	212 723 0508		0%	98.00*
1577	1	L/F DOOR LOCK	204 720 2135		0%	350.00*
1597	1	L/F WINDOW CHANNEL	212 725 0325 28		0%	95.00*
1601	1	L/F COVER	204 760 0520 9197		0%	40.00*
1619	1	L/F CHANNEL SEAL	212 725 0965		0%	30.00*
1625	1	L/F OUT WINDOW SEAL	212 725 0565		0%	75.00*
1671	1	L/F W-FRAME INN TRIM	212 725 0171 9051		0%	55.00*
1681	1	L/F DOOR MOULDING	212 690 2562		0%	65.00*
1711	1	L/F DOOR TRIM	212 720 2370		0%	600.00*
			9G50			
1781	1	L/R DOOR	212 730 0105		0%	1,250.00*
1809	1	L/R DOOR SEAL	204 727 1187		0%	160.00*

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CAR CITY/3

Date Calculated: 17/03/2017 04:44

Full Report - V1

Registration: SCN1616H

Printed: 17/03/2017 12:45

1831	1	L/R QUARTER GLASS	212 730 3900	0%	39.130
1845	1	RR D/WDW BONDING KIT	221 670 8101	0%	57.500
1897	1	L/R WINDOW CHANNEL	212 735 0925	0%	110.00*
1913	1	L/R WINDOW GUIDE	212 730 0119	0%	17.50*
1961	1	L/R OUT WINDOW GSKT	212 735 0965	0%	85.00*
1981	1	L/R DOOR MOULDING	212 690 2962	0%	65.00*
2085	1	LEFT DOOR FRAME	212 630 6101	0%	1,500.00*
2107	1	2K ADHESIVE L/SIDE	009 989 3671 12	0%	107.18
2127	1	L/SILL PANEL	212 637 1535	0%	357.000
2167	1	L/INNER SILL	212 630 3900	0%	418.110
2191	1	L/F SILL COVER	212 686 0936	0%	88.00*
			7M39		
2207	1	L/SILL PANELLING	212 698 0154 9999	0%	400.00*
2309	1	L/INNER DOOR FRAME	212 630 4100	0%	1,065.890
2386	1	SERVICE LID	212 690 1750	0%	135.00*
			9G26		
2615	1	L/R MOULDING	212 885 2121	0%	90.00*
3151	1	REAR SCREEN	212 670 0200	0%	850.00*
3160	1	REAR SCREEN BOND KIT	221 670 8101	0%	57.500
3161	3	REAR SCREEN SUPPORTS	164 742 0097	0%	1.470
4607	1	L/F SIDE AIRBAG	212 860 3402 9051	0%	420.00 340.00*
4627	1	L/WINDOWBAG	212 860 4302	0%	590.00*
4840	1	REAR CTR SEAT BELT	212 860 1485	0%	310.00*
			9C94		
4841	1	L/R SEAT BELT	212 860 9585	0%	310.00*
			9C94		
4941	1	L/UPP FRONT TRIM	212 690 5925	0%	70.00*
			9G26		
4947	1	L/B-PILLAR TRIM	212 690 1926	0%	120.00*
			9G26		
4949	1	L/LWR B-PILLAR TRIM	212 690 3925 9051	0%	50.00*
4957	1	HEADLINING	212 690 5950	0%	950.00*
			9G26		
7047	1	L/F TENSION ROD	212 330 2711	0%	75.00*
7055	1	L/TENSION ROD RUBBER	212 333 0014	0%	65.00*
7065	1	L/F BALL JOINT	212 330 0135	0%	105.00*
7071	1	L/F LWR CONTROL ARM	212 330 3900	0%	320.00*
7081	1	L/F STEERING KNUCKLE	212 332 0700	0%	790.00*
7087	1	L/F SHOCK ABSORBER	212 323 5300	0%	520.00*
7099	1	L/UPPER DAMPER RING	212 322 0284	0%	125.00*
7131	1	L/F WHEEL HUB	212 330 0025	0%	430.00*
7201	1	L/F WHEEL	212 401	0%	650.00*
			0002649765		
7261	1	FRONT STABILISER	212 323 0965	0%	290.00*
7521	1	L/B-PILLAR SENSOR	212 820 4926	0%	85.00*
7522	1	R/B-PILLAR SENSOR	212 820 4926	0%	85.00*
9584	1	ROOF WIRING	212 540 4510	0%	59.00*
9686	1	AIRBAG/TENS C-UNIT	212 901 4204	0%	630.00*
1000	1	FRT DR LH OUT BRKT	Renew	0%	10.00*
1000	1	FT DR OUT COVER	Renew	0%	13.00*
1000	1	FRT DR OUT COVER	Renew	0%	20.00*
1000	1	FRT DR OUT COVER	Renew	0%	20.00*
1000	1	FRT DR WIRE PROTEC	Renew	0%	12.00*
1000	1	RIVET FOR DR MOTOR	Renew	0%	90.00*

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00176
 Assessment Number: CCA00176
 Version: CAR CITY/3
 Date Calculated: 17/03/2017 04:44

Full Report - V1
 Registration: SCN1616H
 Printed: 17/03/2017 12:45

f: OEM Parts	Sub Total		\$20,120.18
g: Original	Mark Up From Cost	(5 %)	\$1,006.01
h: Secondhand	Sundry Parts	(Fixed)	\$100.00
p: Parallel	Total Parts		\$21,226.19
x: Exchange			

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras	Description	Betterment	Price
	AUDATEX FEES	0%	\$42.00
	SEALANT	SPECIALIST	\$30.00
	Total Extras		\$72.00

Final Calculation

Total Parts		\$21,226.19
Labour		
	Total Panel/Mechanical	\$4,903.60
	Total Paintwork	\$993.60
	Total Visual Alignment work	\$147.20
	Corr Prot Internal 16 WU	\$73.60
Total Labour		\$6,118.00
Additional Costs		
	Corr Prot Materials External	\$0.00
	Cost of Specialist	\$72.00
Total of Additional Costs		\$72.00
Total Paint/Material Costs		\$423.78
Grand Total Excludes GST		\$27,839.97
	GST @ 7 %	\$1,948.80
Grand Total Includes GST		\$29,788.77

Assessment Notes

SEN 16/6 H

01/12/2016 12:31:04

SURPASS AUTO PARTS SUPPLIES PTE LTD

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175

Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com

Co & Gst Reg No: 199904808E

CAR CITY AUTO CENTRE PL

BLK 9006 TAMPINES ST 93

#01-198

SINGAPORE 528840

TAX INVOICE

Inv No. : 16110244

Date : 21/11/2016

Page : 1 of 5

S/N	Item No.	Description	Qty	U/ Price	Amount
1	A21288013409999	FRT BUMPER 220 283	1	850.00	850.00
2	A2128891195	INTERMEDIATE LAYER 285	1	10.00	10.00
3	A2128801118	FRONT FENDER 741	1	560.00	560.00
4	A2126903362	MOULDING FRT FENDER 783	1	28.00	28.00
5	A2048177220	GUIDE SIGN 785	1	45.00	45.00
6	A2126904330	OLD FRT FENDER LH 1 839	1	120.00	120.00
7	A2126903030	REAR FENDER II COV LH 841	1	125.00	125.00
8	A2127201579	2047200579/2479 BASIC CARRIER RAIL 1479	1	420.00	420.00
9	A2127205300	F/DOOR 1481	1	1,300.00	1,300.00
10	A2047201537	HINE 1487	1	95.00	95.00
11	A2047201737	HINE 1495	1	120.00	120.00
12	A2047271187	DOOR RUBBER 1509	1	180.00	180.00
13	A2127250710	GLASS PANE 1519	1	150.00	150.00
14	A2129066802	2048200142 FRT MOTOR 1551	1	390.00	390.00

SURPASS AUTO PARTS SUPPLIES PTE LTD

01/12/2016 12:31:04

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175

Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com

Co & Gst Reg No: 199904808E

CAR CITY AUTO CENTRE PL

BLK 9006 TAMPINES ST 93

#01-198

SINGAPORE 528840

TAX INVOICE

Inv No. : 16110244

Date : 21/11/2016

Page : 2 of 5

S/N	Item No.	Description	Qty	U/ Price	Amount
15	A2127250325	2127250125 W/D RUNN 1597	1	95.00	95.00
16	A2127250965	SEALING RAIL 1619	1	30.00	30.00
17	A2127250565	OUTSIDER M/D 955/954 1625	1	75.00	75.00
18	A21272501719051	PANELING 1671	1	55.00	55.00
19	A2126902562	MOULDING FRT DOOR 1681	1	65.00	65.00
20	A21272023709G50	PANELING 1711	1	600.00	600.00
21	A2127300105	DOOR 1781	1	1,250.00	1,250.00
22	A2047271187	DOOR RUBBER 1809	1	160.00	160.00
23	A2127350965	OUTER MOULDING W/SEAL 1961	1	85.00	85.00
24	A2126902962	MOULDING REAR DOOR 1981	1	65.00	65.00
25	A2126306101	A/B SIDE PANEL 2085	1	1,500.00	1,500.00
26	A21269801549999	SIDE PANELING LH 2207	1	400.00	400.00
27	A21269017507M36	HEADLINER 2386	1	135.00	135.00
28	A2128852121	2128850721 REAR BUMPER LH 2615	1	90.00	90.00

SURPASS AUTO PARTS SUPPLIES PTE LTD

01/12/2016 12:31:04

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175
Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com
Co & Gst Reg No: 199904808E

CAR CITY AUTO CENTRE PL
BLK 9006 TAMPINES ST 93
#01-198
SINGAPORE 528840

TAX INVOICE

Inv No. : 16110244
Date : 21/11/2016
Page : 3 of 5

S/N	Item No.	Description	Qty	U/ Price	Amount
29	A2126700200	2126701580 REAR W/S 3151	1	850.00	850.00
30	A21286034029051	SIDE AIRBAG 4667	1	420.00	420.00
31	A21269059257M36	PANELING 4941	1	70.00	70.00
32	A21269019269G26	B-PILLAR TRIM 4947	1	120.00	120.00
33	A21269039259051	PANELING 4949	1	50.00	50.00
34	A21269059507L34	HEADLINER 4957	1	960.00	960.00
35	A2123231300*	2123235300 F/SABSORBER 485 7067	1	520.00	520.00
36	A2124010002649765	DISK WHEEL 7201	1	650.00	650.00
37	A2123300025	HUP FRT 7131	1	430.00	430.00
38	A2123303900	2123302911 LOWER ARM LH 7071	1	320.00	320.00
39	A2123302711	TOP ARM 7047	1	75.00	75.00
40	A2123330014	BUSH TOP ARM 7055	1	65.00	65.00
41	A2123322301	2123320700 FRT KNUCKLE LH 7081	1	790.00	790.00
42	A2123300135	B'JOINT 7065	1	105.00	105.00

SURPASS AUTO PARTS SUPPLIES PTE LTD

01/12/2016 12:31:04

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175
Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com
Co & Gst Reg No: 199904808E

CAR CITY AUTO CENTRE PL
BLK 9006 TAMPINES ST 93
#01-198
SINGAPORE 528840

TAX INVOICE

Inv No. : 16110244
Date : 21/11/2016
Page : 4 of 5

S/N	Item No.	Description	Qty	U/ Price	Amount
43	A2129014204*	2129010700 CONTROL U AIR BAG 9686	1	630.00	630.00
44	A2128204926	TRIGGER UNIT 7521	1	85.00	85.00
45	A2128205026	CONTROL UNIT 7522	1	85.00	85.00
46	A2128604302* 7	AIR BAG 4627 4000	1	590.00	590.00
47	A2123230020S1	32917 FRT S/A MTY 7099	1	125.00	125.00
48	A2123231665	TUBULAR TORSION BAR 7261	1	290.00	290.00
49	A2047202135	2047200935 LOCK LH 212 889 / FRT LH 1577	1	350.00	350.00
50	A2127230114	BRACKET - FRT DR LH 1000	1	10.00	10.00
51	A2127230108	COVERING - H DR LH 1000	1	13.00	13.00
52	A2127230308	COVERING - 1000	1	20.00	20.00
53	A2127230508	COVERING - 1000	1	20.00	20.00
54	A2047601370 9999	DOOR HANDLE 1565	1	240.00	240.00
55	A2047600520 9999	COVERING - cap 1601	1	40.00	40.00
56	A21268609367M39	RAIL - 2191	1	88.00	88.00

SURPASS AUTO PARTS SUPPLIES PTE LTD

01/12/2016 12:31:04

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175

Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com

Co & Gst Reg No:199904808E

CAR CITY AUTO CENTRE PL

BLK 9006 TAMPINES ST 93

#01-198

SINGAPORE 528840

TAX INVOICE

Inv No. : 16110244

Date : 21/11/2016

Page : 5 of 5

S/N Item No.	Description	Qty	U/ Price	Amount
57 A0009915932	RIVET 1000	30	3.00	90.0
58 A2127350925	2127350125 W/D RUNN LH - RND 1897	1	110.00	110.0
59 A21286095859C94	2128605385 REAR SAFETY BELT - L 4841	1	310.00	310.0
60 A21286096859C94	SAFETY BELT A840 - R 4841	1	310.00	310.0
61 A2128890125	FRT FENDER END COVERING - S 1745	1	18.00	18.0
62 A2048210197	PROTECTIVE HOSE FLDR - 1000	1	12.00	12.0
63 A2047221449	GUIDE RAIL - COVER FL RT 1913	1	17.50	17.5
64 A2047602534	2127601434 BEARING BRACKET - Handle 1575	1	98.00	98.0
65 A0025402305	CABLE HARNESS ROOF AIR BEG 9584	1	59.00	59.0


Customer's Signature

Sub Total	18,033.
GST 7%	1,262.
Total	19,295.

Customer Name	CAR CITY AUTO CENTRE PTE LTD	Invoice No.	00505318
Contact No	6781 0300	Invoice Date	15/12/2016
Vehicle No	SCN1616H	Mileage	157164
Vehicle Make	MERCEDES BENZ	Page	1
Vehicle Model	MB E250	Print by	COUNTER (ACC REC)
Chassis No	WDD2120472A080252	Terms	50 DAYS

No.	Description of Goods / Services	Qty	Unit Price	Amount
1.	LABOUR AND DIAGNOSIS CHARGES Remark: -CARRY OUT DIAGNOSIS TEST -CHECK SRS ELECTRIC CIRCUIT -REPAIR DRIVER SEAT BELT TENSIONER CIRCUIT -CARRY OUT PROGRAMMING AND CODING FOR SRS CONTROL MODULE -READ AND ERASE FAULT MEMORY	1 SERVICE	420.00	420.00
2.	COMPUTERIZED WHEEL ALIGNMENT	1 SERVICE	80.00	80.00

OD/12/12 - 2016 5/5/16

*Remarks

FIVE HUNDRED THIRTY FIVE ONLY

The above repairs have been carried out according to the owner's request.
The owner acknowledge the amount of repairs which has been agreed upon
Any dispute to the invoice must be lodged within 7 days from the date of invoice
We will not responsible for any damage not related to the above repairs

[Signature]



Authorised signature

Nett	500.00
Discount	0.00
7% GST	35.00
Total Due	535.00

Received by

Opening Hours: Monday - Saturday : 9:00am - 6.30pm
Sunday & Public Holidays : Closed

*** OPEN 6 DAYS A WEEK ***

24 hours breakdown towing service, please call: 9720 3785
For your next service appointment, please call: 6786 2811

Thank You For Your Patronage

**CHINA TAIPING
INSURANCE (S) PTE LTD
3 ANSON ROAD
#15-02 SPRINGLEAF
TOWER
079909**

Claim Reference: CCA00176
Assessment Number: CCA00176
Version: CHINATAI/16
Date Calculated: 29/01/2018 08:16

Full Report - V1
Registration: SCN1616H
Printed: 29/01/2018 16:16

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Mr K.K Lau	Date of Incident:	17/11/2016
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	CCA00176	Estimated Repair Time:	
Policy Number:	DMPCSN3007911503	Quote Due Date:	
Other Reference:	OD/17017	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	E Class
Sub Model:	E 250 CGI
Model Sheet Number:	3AE 01
Registration:	SCN1616H
Registration Month:	October
Registration Year:	2009
VIN Number:	WDD2120472A080252
Manufacture Year:	2009
Odometer:	157160
Colour:	Black
Engine Number:	27186030003935
Fuel Level:	%

Model Specs

FROM A076363/L001354	TECH CHANGES 09/09
MODEL 2010	PARKTRONIC
LOAD COMPARTMENT BOX	AUDIO 20 CD CHANGER
MULTIMEDIA INTERFACE	LEATHER TRIM
SUN PROTECTION	TRIM ELEGANCE
MEMORY PACKAGE	PEDESTRIAN PROTECT
DIPPING MIRROR	S-WDW ROLLER BLIND
TRIM WALNUT BURL	REM RELEASE FUEL CAP
KEYLESS GO	DOUBLE CUP HOLDER
ENGINE PROTECTION	RR SCREEN SUN BLIND
AIR INJECTION	AUTO GEARBOX 5 SPEED
DIRECT STEERING	DIRECT CONTROL SUSP
TYRES 205/60 HR 16	WHEELS 7J X 16 ALLOY
SPACE SAVER S-WHEEL	FUEL TANK 80 LTR
HD COOLING	TWO COAT METALLIC
CLEAR COAT HARD	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Fair	Severity of Impact:	Heavy Panel
Steering:	Satisfactory	Vehicle Status on Inspection:	Unroadworthy
Brakes Pedal Travel:	Satisfactory	Date of Inspection:	17/11/2016
Place of Inspection:	Repairer		
Pre-Accident Damage:			
Tyres Condition:	Fair		
Tyres - Tread Depth (MM):			

Left Tyre

Right Tyre

CHINA TAIPING INSURANCE (S) PTE LTD


Claim Reference: CCA00176
Assessment Number: CCA00176
Version: CHINATAI/16
Date Calculated: 29/01/2018 08:16

Full Report - V1
Registration: SCN1616H
Printed: 29/01/2018 16:16

Damage Areas:

	Axles	Depth	Depth
LHF 0		7.0	7.0
LHR 1		7.0	7.0

RHF
RHR
Direction of Impact:



Addresses

Cost Summary

Total Labour	\$6,145.60
Total Paint/Material	\$424.86
Total Parts	\$19,035.18
Total of Additional Costs	\$72.00
Excess:	TBA
Grand Total Exc GST:	\$25,677.64
7 % GST:	\$1,797.43
Grand Total Inc GST:	\$27,475.07

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
 Price/Dent = \$0.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY	3.0	13.80
54-1010 ZAX	CHECK ELECTRIC-/ELECTRONIC SYSTEMS (AFTER SHORT TEST OR ACCORDING TO ERROR CODE)	3.0	13.80
54-7989 03	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	9.20
91-1821 ZAX	SAFETY PRECAUTIONS BEFORE WELDING DISCONNECT AIRBAG/SEATBELT TENSIONER SYS	8.0	36.80
91-0660 01	CHECK SAFETY SYSTEM	3.0	13.80
61-1116 02	R + R L/UNDERFLOOR COVER	3.0	13.80
NO NUMBER	ALIGN BODY BY HANDHELD MEASURING SYSTEM	2.0	9.20
NO NUMBER	ANCHOR VEHICLE ON STRAIGHTENING SYSTEM	9.0	41.40
60-1065 01	REFIT MODUL CROSSMEMBER FROM CASSIS JIG	10.0	46.00
88-1102 02	R + R COMPLETE FRONT BUMPER INCLUDES: R + R RADIATOR COWL	11.0	50.60
88-1105 02	DIS + ASS FRONT BUMPER (BUMPER REMOVED)	9.0	41.40

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CHINATAI/16

Date Calculated: 29/01/2018 08:16

Full Report - V1

Registration: SCN1616H

Printed: 29/01/2018 16:16

88-1380 02	AFTER CHECK: RENEW PARTS IF NECESSARY ADD TO DIS/ASS FRONT BUMPER CPL (LUXURY VERSION VEHICLE)	3.0	13.80
88-1358 02	ADDITION TO DIS + ASS FRONT BUMPER (BUMPER REMOVED) (VEHICLE WITH ULTRASONIC PARKING AID)	2.0	9.20
60-2289 01	R + R R/HEADLAMP UNIT (BUMPER REMOVED)	3.0	13.80
88-3818 02	RENEW LEFT WING (BUMPER REMOVED) INCLUDES: L/F WHEELHOUSE COVER CPL REMOVE AND REFIT.	7.0	32.20
88-2503 02	R + R BONNET	6.0	27.60
60-1609 01	REMOVE/REFIT LH FRONT SEAT AND LOOSE CARPETS AND PLACE IN STORAGE	9.0	41.40
60-1624 01	R + R COMPLETE REAR SEAT AND CARPETS AND PLACE IN STORAGE	7.0	32.20
67-1500 02	R + R WINDSCREEN	32.0	147.20
72-1450 02	RENEW L/F DOOR AND CONVERT PARTS INCLUDES: DOOR TRIM REMOVE AND REFIT AND ALL ATTACHED PARTS ASSEMBLE	37.0	170.20
72-1682 02	ADDITIONAL RENEW LEFT FRONT DOOR VEHICLE WITH LOWER MOULDING	1.0	4.60
72-2692 02)	RENEW L/F UPPER DOOR HINGE	7.0	32.20
72-6665 02)	RENEW L/F DOOR TRIM (REMOVED)	11.0	50.60
72-1590 02	RENEW L/R DOOR AND CONVERT PARTS INCLUDES: DOOR TRIM REMOVE AND REFIT AND ALL ATTACHED PARTS ASSEMBLE	37.0	170.20
72-1760 02	ADDITIONAL RENEW LEFT REAR DOOR VEHICLE WITH LOWER MOULDING	1.0	4.60
88-5205 02	R + R LEFT SILL TRIM	6.0	27.60
60-1657 ZAX	R + R L/INTERIOR TRIM (FOR RENEWING OUTER SIDEMEMBER SHELL) (DOORS, SEATS AND MATS REMOVED)	9.0	41.40
63-1362 ZAX	RENEW L/A-PILLAR, SIDEMEMBER AND B-PILLAR	227.0	1,044.20
63-1322 01	RENEW L/OUTER A-PILLAR	83.0	381.80
63-1430 01	RENEW L/B-PILLAR	113.0	519.80
63-1120 ZAX	RENEW OUTER SIDEMEMBER LH DOOR SILL, FORWARD OF CENTRE-PILLAR	21.0	96.60
91-2141 01)	R + R R/SIDEBAG SENSOR	3.0	13.80
68-1621 ZAX	R + R HEADLINING	20.0	92.00
68-1748 02	ADDITION TO R + R HEADLINING (VEHICLE WITH INTERIOR PROTECTION)	5.0	23.00
91-2102 02	R + R L/HEAD SIDE AIRBAG UNIT (STRIPPED)	3.0	13.80
67-5045 02	RENEW REAR PANEL WINDOW	21.0	96.60
88-9626 ZAX	R + R REAR BUMPER MOULDING	3.0	13.80
60-2430 02	R + R BOTH OUTER TAILLAMPS	3.0	13.80
97-2500 ZAX	CAVITY PROTECTION (ADD/WORK)	2.0	9.20
97-2500 ZAX	L/F UPPER SIDEMEMBER CAVITY PROTECTION	2.0	9.20
97-2500 ZAX	CAVITY PROTECTION LEFT FRONT DOOR	2.0	9.20
97-2500 ZAX	CAVITY PROTECTION LEFT REAR DOOR	2.0	9.20

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CHINATAI/16

Date Calculated: 29/01/2018 08:16

Full Report - V1

Registration: SCN1616H

Printed: 29/01/2018 16:16

97-2500 ZAX	L/SILL CAVITY PROTECTION	2.0	9.20
97-2500 ZAX	APPLY CAVITY SEALING AT LEFT A-PILLAR	2.0	9.20
97-2500 ZAX	L/B-PILLAR CAVITY PROTECTION	2.0	9.20
97-2500 ZAX	L/R WING CAVITY PROTECTION	2.0	9.20
68-4605 01	R + R INSTRUMENT PANEL	28.0	128.80
91-5852 01	R + R L/F SEAT BACKREST TRIM	3.0	13.80
91-2070 01)	R + R L/F SEAT SIDEBAG UNIT	3.0	13.80
	INCLUDES: R + R SEAT BACKREST TRIM		
91-1087 01)	R + R LEFT REAR SEAT BELT	2.0	9.20
91-1107 01)	R + R CENTRE REAR SEAT BELT	3.0	13.80
54-7940 ZAX	RENEW ROOF WIRING HARNESS	7.0	32.20
91-1905 01)	R + R AIRBAG CONT UNIT AND PRETENS SYS	4.0	18.40
33-1275 02	R + R BOTH FRONT AXLE HALFS	30.0	138.00
32-2050 02)	R + R FRONT STABILIZER	4.0	18.40
33-3510 03)	R + R L/F STEERING KNUCKLE	20.0	92.00
33-1421 03)	R + R LEFT FRONT TORSION BAR	9.0	41.40
32-1955 03)	R + R L/F STRUT	5.0	23.00
32-1908 02)	DISS/ASS L/F SUSPENSION STRUT REMOVED	3.0	13.80
32-1920 02)	DIS + ASS FRONT SPRING STRUT/S (REMOVED)	3.0	13.80
40-2410 01	R + R LEFT FRONT TYRE	3.0	13.80
40-2055 01	L/FRONT WHEEL BALANCE	2.0	9.20
42-1350 01	BLEED BRAKE SYSTEM	10.0	46.00
83-0640 01	CHECK AIR COND	3.0	13.80
40-6500 01	ALIGN VEHICLE	7.0	32.20
	INCLUDES: ALIGN FRONT AND REAR TOE AND CAMBER,		
	CHECK FRONT AND REAR VEHICLE LEVEL		
40-6710 01	ADD/WORK FOR VEHICLE WITH BOARDING-/EXITING SUPPORT	1.0	4.60
40-4064 01	ADJUST FRONT WHEEL TOE (DURING ALIGNMENT)	2.0	9.20
40-6716 01	ADDITIONAL TO OPTICAL ALIGNMENT ADJUST L/FRONT AXLE HALF CAMBER/CASTER	6.0	27.60
40-6717 01	ADDITIONAL TO OPTICAL ALIGNMENT ADJUST R/FRONT AXLE HALF CAMBER/CASTER	6.0	27.60
40-6992 ZAX	ADD/WORK FOR CALIBRATE VEHICLE AXLE LEVEL WITH STAR DIAGNOSIS (BOTH AXLES)	5.0	23.00
40-8052 ZAX	CHECK FRONT/REAR WHEEL TRACK ALIGNMENT DURING TRACK AND ALIGNMENT CHECK	5.0	23.00
1477	ADDITIONAL WORK PULLING L/SIDE	15.0*	69.00
1995	REMOVE AND REFIT INSULATION MATS	5.0*	23.00
9699	TYRE SERVICE	5.0*	23.00
9722	FAULT FINDING	5.0*	23.00
9854	READ OUT ERROR MEMORY	92.0*	423.20
9980	CARRY OUT CALIBRATION DRIVE	18.0*	82.80
1155	REPAIR L/UPP W-HOUSE S-MEMB	10.0*	46.00
1179	REPAIR L/REINFORCEMENT	5.0*	23.00
1187	REPAIR L/F UPP REINF	8.0*	36.80
2583	REPAIR REAR BUMPER COVER	8.0*	36.80
3481	REPAIR L/R WING	10.0*	46.00
0561	CHECK LEFT HEADLAMP ASSY		
1436	CHECK WASHER CONTAINER		

CHINA TAIPING INSURANCE (S) PTE LTD**Claim Reference: CCA00176****Full Report - V1****Assessment Number: CCA00176****Registration: SCN1616H****Version: CHINATAI/16****Printed: 29/01/2018 16:16****Date Calculated: 29/01/2018 08:16**

1445	CHECK WASHER JET HOSE
1573	CHECK LEFT MEMBER TRIM
1579	CHECK L/F DOOR LOCK COVER
1629	CHECK L/SEAT ADJ SWITCH
1645	CHECK L/F UPPER SPEAKER
1655	CHECK L/F W-FRAME RR MLDG
1701	CHECK L/F LWR DOOR DAMPING
1707	CHECK L/F LWR DOOR SPEAKER
1723	CHECK L/F DOOR INSULATION
1737	CHECK LEFT DOOR MIRROR
1747	CHECK L/DOOR MIRROR COVER
1865	CHECK L/R DOOR OUT HANDLE
1871	CHECK L/R DOOR HANDLE TRIM
1947	CHECK L/R DR FRM FRT MLDG
2411	CHECK L/SEAT MOUNT PLATE
4551	CHECK L/OUTER SEAT COVER
4593	CHECK L/BACKREST SHELL
4595	CHECK L/F BACKREST TRIM
4611	CHECK L/F PRESSURE SENSOR
7011	CHECK FRONT AXLE SUPPORT
7097	CHECK L/LWR DAMPER RING
7103	CHECK L/F S-ABSORB BOOT
7141	CHECK L/F BRAKE DISC
7227	CHECK L/F TYRE
7300	CHECK STEERING GEAR

LABOUR COST

Total Work Units	1,114.0	
Panel / Mechanical Labour	106.6HRS	\$4,903.60
Visual Alignment Labour	3.2HRS	\$147.20
Corrosion Protection		
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	1.6HRS	73.60
Sub Total	111.4HRS	\$5,124.40
Paint Labour	22.2HRS	\$1,021.20
Total Labour	133.6HRS	\$6,145.60

PAINT WORK**Time Basis 10 WU = 1 HR. Price = \$46.00/HR**

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
98-1731 01	FRONT BUMPER COVER PAINTING STAGE I-M	11.0	
98-2415 01	L/F WING PAINTING STAGE I-M	6.0	
98-4015 01	LEFT FRONT DOOR PAINTING STAGE I-M	11.0	
98-1710 ZAX	L/F DOOR OUT HANDLE PAINTING STAGE I-M	1.0	
98-1710 ZAX	L/F COVER PAINTING STAGE I-M	1.0	
98-1881 01	L/DOOR MIRROR HSG PAINTING STAGE I-M	1.0	
98-4115 02	L/R DOOR PAINTING STAGE I-M	11.0	
98-5535 01	LEFT DOOR FRAME PAINTING STAGE I-E	28.0	
98-5350 01	L/F SILL PAINTING STAGE I-E	5.0	
98-1861 01	L/SILL PANELLING PAINTING STAGE I-M	5.0	
98-5555 01	LEFT B-PILLAR PAINTING STAGE I-E	36.0	
98-8980 ZAX	L/F WHEEL PAINT	4.0	

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CHINATAI/16

Date Calculated: 29/01/2018 08:16

Full Report - V1

Registration: SCN1616H

Printed: 29/01/2018 16:16

98-1735 01	REAR BUMPER COVER PAINTING STAGE III	13.0	
98-7047 01	L/R WING PAINTING STAGE III	23.0	
	WITHOUT FRT SURFACE BELOW DOOR		
98-2806 01	BONNET PAINTING STAGE II	23.0	
L 1155	L/UPP W-HOUSE S-MEMBPAINTING STAGE I-J	3.0	
L 1179	L/REINFORCEMENT PAINTING STAGE I-J	6.0	
L 1187	L/F UPP REINF PAINTING STAGE I-J	3.0	
98-1340 01	PREPARATION WORK FOR TWO COAT PAINTING OF FITTED BODY PARTS	15.0	
98-1356 01	ADD/WORK FOR PLASTIC PARTS	3.0	
98-1620 ZAX	PRIME PLASTIC/METAL PARTS	3.0	
98-1630 ZAX	APPLY SMOOTHG FILLER ON PLAST/MET PARTS	3.0	
98-1625 ZAX	REPAIR/APPLY FILLER ON PLAST/METAL PARTS	2.0	
98-1620 ZAX	APPLY PRIMER REAR BUMPER (ADD/WORK)	1.0	
98-1630 ZAX	APPLY FILLER REAR BUMPER (ADD/WORK)	1.0	
98-1625 ZAX	APPLY FILLER PASTE REAR BUMPER (ADD)	3.0	
LABOUR COST - PAINT			
	TIME(PAINT)	0.0	
	Total Work Units (10WU/HR)	222.0	
	Total Paintwork Labour	22.2HRS	\$1,021.20
MATERIAL COST - PAINT			
	Total Excluding Pearlescent Uplift		Cost Price
	Pearlescent Uplift @ 0.0%		\$424.86
	Total Paint Material Cost		\$0.00
			\$424.86

PARTS

						Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)	
283	1	FRONT BUMPER COVER	212 880 1340 9999		0%	850.00*	
285	1	L/F SPACER	212 889 1195		0%	10.00*	
741	1	L/F WING	212 880 1118		0%	560.00*	
745	1	L/F WING COVER	212 889 0125		0%	18.00*	
783	1	L/F WING MOULDING	212 690 3362		0%	28.00*	
785	1	L/F WING BADGE	204 817 7220		0%	45.00*	
839	1	L/F W-HOUSE CVR FRT	212 690 4330		0%	120.00*	
841	1	L/F W-HOUSE CVR REAR	212 690 3030		0%	125.00*	
1411	1	WINDSCREEN REP KIT	000 670 0100		0%	0.00G	
1413	4	FRT SCREEN SUPPORTS	210 671 0397		0%	0.00F	
1479	1	L/F DOOR MODULE	212 720 1579		0%	420.00*	
1481	1	LEFT FRONT DOOR	212 720 5300		0%	1,300.00*	
1487	1	L/F UPPER DOOR HINGE	204 720 1537		0%	95.00*	
1495	1	L/F LOWER DOOR HINGE	204 720 1737		0%	120.00*	
1509	1	L/F DOOR SEAL	204 727 1187		0%	180.00*	
1519	1	L/F DOOR WINDOW	212 725 0710		0%	150.00*	
1551	1	L/F WINDOW MOTOR	212 906 6802		0%	390.00*	
1565	1	L/F DOOR OUT HANDLE	204 760 1370 9197		0%	240.00*	
1575	1	L/BEARING COVER	212 723 0508		0%	98.00*	
1577	1	L/F DOOR LOCK	204 720 2135		0%	350.00*	
1597	1	L/F WINDOW CHANNEL	212 725 0325 28		0%	95.00*	
1601	1	L/F COVER	204 760 0520 9197		0%	40.00*	
1619	1	L/F CHANNEL SEAL	212 725 0965		0%	30.00*	
1625	1	L/F OUT WINDOW SEAL	212 725 0565		0%	75.00*	
1671	1	L/F W-FRAME INN TRIM	212 725 0171 9051		0%	55.00*	

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: CCA00176

Assessment Number: CCA00176

Version: CHINATAI/16

Date Calculated: 29/01/2018 08:16

Full Report - V1

Registration: SCN1616H

Printed: 29/01/2018 16:16

1681	1	L/F DOOR MOULDING	212 690 2562	0%	65.00*
1711	1	L/F DOOR TRIM	212 720 2370	0%	600.00*
			9G50		
1781	1	L/R DOOR	212 730 0105	0%	1,250.00*
1809	1	L/R DOOR SEAL	204 727 1187	0%	160.00*
1831	1	L/R QUARTER GLASS	212 730 3900	0%	0.00F
1845	1	RR D/WDW BONDING KIT	000 670 0100	0%	0.00F
1897	1	L/R WINDOW CHANNEL	212 735 0925	0%	110.00*
1913	1	L/R WINDOW GUIDE	212 730 0119	0%	17.50*
1961	1	L/R OUT WINDOW GSKT	212 735 0965	0%	85.00*
1981	1	L/R DOOR MOULDING	212 690 2962	0%	65.00*
2085	1	LEFT DOOR FRAME	212 630 6101	0%	1,500.00*
2107	1	2K ADHESIVE L/SIDE	009 989 3671 12	0%	0.00F
2127	1	L/SILL PANEL	212 637 1535	0%	0.00F
2167	1	L/INNER SILL	212 630 3900	0%	0.00F
2191	1	L/F SILL COVER	212 686 0936	0%	88.00*
			7M39		
2207	1	L/SILL PANELLING	212 698 0154 9999	0%	400.00*
2309	1	L/INNER DOOR FRAME	212 630 4100	0%	0.00F
2386	1	SERVICE LID	212 690 1750	0%	135.00*
			9G26		
2615	1	L/R MOULDING	212 885 2121	0%	90.00*
3151	1	REAR SCREEN	212 670 0200	0%	850.00*
3160	1	REAR SCREEN BOND KIT	000 670 0100	0%	0.00F
3161	3	REAR SCREEN SUPPORTS	164 742 0097	0%	0.00F
4607	1	L/F SIDE AIRBAG	212 860 3402 9051	0%	420.00*
4627	1	L/WINDOWBAG	212 860 4302	0%	590.00*
4840	1	REAR CTR SEAT BELT	212 860 1485	0%	310.00*
			9C94		
4841	1	L/R SEAT BELT	212 860 9585	0%	310.00*
			9C94		
4941	1	L/UPP FRONT TRIM	212 690 5925	0%	70.00*
			9G26		
4947	1	L/B-PILLAR TRIM	212 690 1926	0%	120.00*
			9G26		
4949	1	L/LWR B-PILLAR TRIM	212 690 3925 9051	0%	50.00*
4957	1	HEADLINING	212 690 5950	0%	960.00*
			9G26		
7047	1	L/F TENSION ROD	212 330 2711	0%	75.00*
7055	1	L/TENSION ROD RUBBER	212 333 0014	0%	65.00*
7065	1	L/F BALL JOINT	212 330 0135	0%	105.00*
7071	1	L/F LWR CONTROL ARM	212 330 3900	0%	320.00*
7081	1	L/F STEERING KNUCKLE	212 332 0700	0%	790.00*
7087	1	L/F SHOCK ABSORBER	212 323 5300	0%	520.00*
7099	1	L/UPPER DAMPER RING	212 322 0284	0%	125.00*
7131	1	L/F WHEEL HUB	212 330 0025	0%	430.00*
7201	1	L/F WHEEL	212 401	0%	650.00*
			0002649765		
7261	1	FRONT STABILISER	212 323 0965	0%	290.00*
7521	1	L/B-PILLAR SENSOR	212 820 4926	0%	85.00*
7522	1	R/B-PILLAR SENSOR	212 820 4926	0%	85.00*
9584	1	ROOF WIRING	212 540 4510	0%	59.00*

CHINA TAIPING INSURANCE (S) PTE LTD**Claim Reference: CCA00176****Full Report - V1****Assessment Number: CCA00176****Registration: SCN1616H****Version: CHINATAI/16****Printed: 29/01/2018 16:16****Date Calculated: 29/01/2018 08:16**

9686	1	AIRBAG/TENS C-UNIT	212 901 4204	0%	630.00*
1000	1	FRT DR LH OUT BRKT	Renew	0%	10.00*
1000	1	FT DR OUT COVER	Renew	0%	13.00*
1000	1	FRT DR OUT COVER	Renew	0%	20.00*
1000	1	FRT DR OUT COVER	Renew	0%	20.00*
1000	1	FRT DR WIRE PROTEC	Renew	0%	12.00*
1000	1	RIVET FOR DR MOTOR	Renew	0%	90.00*
f: OEM Parts				Saving	\$2,152.01
g: Original				Sub Total	\$18,033.50
h: Secondhand				Mark Up From Cost (5 %)	\$901.68
p: Parallel				Sundry Parts (Fixed)	\$100.00
x: Exchange				Total Parts	\$19,035.18

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEES	0%	\$42.00
SEALANT		\$30.00
Total Extras		\$72.00

Final Calculation

Total Parts	\$19,035.18
Labour	
Total Panel/Mechanical	\$4,903.60
Total Paintwork	\$1,021.20
Total Visual Alignment work	\$147.20
Corr Prot Internal 16 WU	\$73.60
Total Labour	\$6,145.60
Additional Costs	
Corr Prot Materials External	\$0.00
Cost of Specialist	\$72.00
Total of Additional Costs	\$72.00
Total Paint/Material Costs	\$424.86
Grand Total Excludes GST	\$25,677.64
GST @ 7 %	\$1,797.43
Grand Total Includes GST	\$27,475.07

Assessment Notes

Car City Auto Centre Pte Ltd (Co.Reg.No:200719980C)

Blk 9006 #01-198, Tampines Street 93
Singapore 528840

Tel: 6781 0300 Fax: 6782 0300 Email: ccacpl@singnet.com.sg;carcity@singnet.com.sg

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/17017
Policy No:	DMPCSN3007911503	Date of Loss:	17/11/2016
Vehicle Reg. No.:	SCN1616H	Driveable?	
Driver Age/Info:	52 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	CHAN HIAN JOON	Contact No:	+6598183137
Driver:	CHAN HIAN JOON		
Make/Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Vehicle Reg. Date:	18/11/2009
Vehicle Colour:	BLACK		
Engine No:	27186030003935	Chassis No:	WDD2120472A080252
Odometer:	157160 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Description of Accident/Loss	SEE ATTACHED POLICE REPORT T/20161117/2108 DATED 17/11/2016 1428HRS		
Present Location:	CAR CITY AUTO CENTRE PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	19,379.85
Miscellaneous Items	172.00
Labour	6,240.16
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	25,792.01
+ GST 7.00% (\$\$)	1,805.44
Nett Amount (\$\$)	27,597.45

This claim is handled by: **HO TOO BOON**

Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Nov 2016)

Parts: 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Car City Auto Centre Pte Ltd/SCN1616H/19/11/2016 11:37

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*2K ADHESIVE L/SIDE	0.00	0.00	*-F X N
2	1	NA	*AIRBAG/TENS C-UNIT	0.00	0.00	*630.00 F / N
3	1	NA	*FRONT BUMPER COVER	0.00	0.00	*850.00 F / DE
4	1	NA	*FRONT STABILISER	0.00	0.00	*290.00 F / B
5	1	NA	*FRT SCREEN SUPPORTS	0.00	0.00	*-F X N
6	1	NA	*HEADLINING	0.00	0.00	*960.00 F / DE
7	1	NA	*L/B-PILLAR SENSOR	0.00	0.00	*85.00 F / AC
8	1	NA	*L/B-PILLAR TRIM	0.00	0.00	*120.00 F / CR
9	1	NA	*L/BRACKET	0.00	0.00	*30.00 F X N
10	1	NA	*L/F BACKREST COVER	0.00	0.00	*1,100.00 F X N
11	1	NA	*L/F BALL JOINT	0.00	0.00	*105.00 F / M
12	1	NA	*L/F CHANNEL SEAL	0.00	0.00	*30.00 F / N
13	1	NA	*L/F DOOR FRAME SEAL	0.00	0.00	*150.00 F X N
14	1	NA	*L/F DOOR LAMP	0.00	0.00	*26.00 F X N
15	1	NA	*L/F DOOR MODULE	0.00	0.00	*420.00 F / AC
16	1	NA	*L/F DOOR MOULDING	0.00	0.00	*65.00 F / DE
17	1	NA	*L/F DOOR SEAL	0.00	0.00	*180.00 F / N
18	1	NA	*L/F DOOR TRIM	0.00	0.00	*600.00 F / CR
19	1	NA	*L/F DOOR WINDOW	0.00	0.00	*150.00 F / SN
20	1	NA	*L/F LOWER DOOR HINGE	0.00	0.00	*120.00 F / B
21	1	NA	*L/F LOWER DOOR MLDG	0.00	0.00	*50.00 F X N
22	1	NA	*L/F LWR CONTROL ARM	0.00	0.00	*320.00 F / P.
23	1	NA	*L/F OUT WINDOW SEAL	0.00	0.00	*75.00 F / N
24	1	NA	*L/F PROTECT PLATE	0.00	0.00	*85.00 F X N
25	1	NA	*L/F SHOCK ABSORBER	0.00	0.00	*520.00 F / B
26	1	NA	*L/F SIDE AIRBAG	0.00	0.00	*340.00 F / AC
27	1	NA	*L/F SPACER	0.00	0.00	*10.00 F / N
28	1	NA	*L/F SPEED SENSOR	0.00	0.00	*260.00 F X N
29	1	NA	*L/F STABILISER ARM	0.00	0.00	*75.00 F X N
30	1	NA	*L/F STEERING KNUCKLE	0.00	0.00	*790.00 F / P.
31	1	NA	*L/F TENSION ROD	0.00	0.00	*320.00 F / M
32	1	NA	*L/F UPP REINF	0.00	0.00	*170.00 F X N
33	1	NA	*L/F UPPER DOOR HINGE	0.00	0.00	*95.00 F / B
34	1	NA	*L/F W-FRAME INN TRIM	0.00	0.00	*55.00 F / CR
35	1	NA	*L/F WHEEL	0.00	0.00	*650.00 F / DE
36	1	NA	*L/F WHEEL HUB	0.00	0.00	*430.00 F / P.
37	1	NA	*L/F W-HOUSE CVR FRT	0.00	0.00	*120.00 F / P.
38	1	NA	*L/F W-HOUSE CVR REAR	0.00	0.00	*125.00 F / DE
39	1	NA	*L/F WINDOW CHANNEL	0.00	0.00	*95.00 F / B
40	1	NA	*L/F WINDOW MOTOR	0.00	0.00	*390.00 F / N
41	1	NA	*L/F WING	0.00	0.00	*560.00 F / B
42	1	NA	*L/F WING BADGE	0.00	0.00	*45.00 F / N
43	1	NA	*L/F WING MOULDING	0.00	0.00	*28.00 F / N
44	1	NA	*L/INNER DOOR FRAME	0.00	0.00	*-F X N
45	1	NA	*L/INNER SILL	0.00	0.00	*-F X N
46	1	NA	*L/LWR B-PILLAR TRIM	0.00	0.00	*50.00 F / CR
47	1	NA	*L/OUT DR MIRROR CVR	0.00	0.00	*23.00 F X N

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
48	1	NA	*L/OUTER TIE ROD BALL	0.00	0.00	*130.00 F <i>X/N</i>
49	1	NA	*L/R BUMPER GUIDE	0.00	0.00	*30.00 F <i>X/N</i>
50	1	NA	*L/R DOOR	0.00	0.00	*1,250.00 F <i>DR</i>
51	1	NA	*L/R DOOR FRAME PROT	0.00	0.00	*150.00 F <i>X/N</i>
52	1	NA	*L/R DOOR MOULDING	0.00	0.00	*65.00 F <i>acc</i>
53	1	NA	*L/R DOOR SEAL	0.00	0.00	*160.00 F <i>CR</i>
54	1	NA	*L/R LOWER DOOR MLDG	0.00	0.00	*35.00 F <i>X/N</i>
55	1	NA	*L/R MOULDING	0.00	0.00	*90.00 F <i>N</i>
56	1	NA	*L/R OUT WINDOW GSKT	0.00	0.00	*85.00 F <i>re</i>
57	1	NA	*L/R QUARTER GLASS	0.00	0.00	*-F <i>X</i>
58	1	NA	*L/REINFORCEMENT	0.00	0.00	*35.00 F <i>X/N</i>
59	1	NA	*L/ROOF FRAME MLDG	0.00	0.00	*260.00 F <i>DR</i>
60	1	NA	*L/SILL PANEL	0.00	0.00	*-F <i>X</i>
61	1	NA	*L/SILL PANELLING	0.00	0.00	*400.00 F <i>DR</i>
62	1	NA	*L/TENSION ROD RUBBER	0.00	0.00	*75.00 F <i>DR</i>
63	1	NA	*L/TIE ROD	0.00	0.00	*145.00 F <i>X/N</i>
64	1	NA	*L/UPP FRONT TRIM	0.00	0.00	*70.00 F <i>N</i>
65	1	NA	*L/WINDOWBAG	0.00	0.00	*590.00 F <i>N</i>
66	1	NA	*LEFT DOOR FRAME	0.00	0.00	*1,500.00 F <i>DR</i>
67	1	NA	*LEFT FRONT DOOR	0.00	0.00	*1,300.00 F <i>DR</i>
68	1	NA	*REAR SCREEN	0.00	0.00	*360.00 F <i>re</i>
69	1	NA	*REAR SCREEN BOND KIT	0.00	0.00	*-F <i>X</i>
70	1	NA	*REAR SCREEN SUPPORTS	0.00	0.00	*-F <i>X/N</i>
71	1	NA	*RR D/WDW BONDING KIT	0.00	0.00	*-F <i>X</i>
72	1	NA	*SERVICE LID	0.00	0.00	*135.00 F <i>CR</i>
73	1	NA	*WINDSCREEN REP KIT	0.00	0.00	*-F <i>X</i>

F=Franchise part.

Sub Total (\$\$)	18,457.00
+ Margin on L,N Items 5.00% (\$\$)	922.85
Total Parts (\$\$)	19,379.85

Car City Auto Centre Pte Ltd/SCN1616H/19/11/2016 11:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	AUDATEX FEE	42.00 ✓
2	2	SEALANT	30.00 ✓
3	1	SUNDRY PARTS	100.00 ✓
Sub Total (S\$)			172.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Total Paint Labour	New	970.60
2	Total Paint Materials	New	421.16
3	Total Panel/Mechanical Labour	New	4,848.40
Gross Labour Cost (S\$)			6,240.16

Car City Auto Centre Pte Ltd/SCN1616H/19/11/2016 11:37. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Car City Auto Centre Pte Ltd (Co.Reg.No:200719980C)

Blk 9006 #01-198, Tampines Street 93

Singapore 528840

Tel: 6781 0300 Fax: 6782 0300 Email: ccacpl@singnet.com.sg;carcity@singnet.com.sg

(SUPPLEMENTARY)

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/17017
Policy No:	DMPCSN3007911503	Date of Loss:	17/11/2016
Vehicle Reg. No.:	SCN1616H	Driveable?	
Driver Age/Info:	52 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	CHAN HIAN JOON	Contact No:	+6598183137
Driver:	CHAN HIAN JOON		

Make/Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Vehicle Reg. Date:	18/11/2009
Vehicle Colour:	BLACK		
Engine No:	27186030003935	Chassis No:	WDD2120472A080252
Odometer:	157160 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) 14

Description of Accident/Loss: SEE ATTACHED POLICE REPORT T/20161117/2108 DATED 17/11/2016 1428HRS
Present Location: CAR CITY AUTO CENTRE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	2,116.28
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,116.28
+ GST 7.00% (S\$)	148.14
Nett Amount (S\$)	2,264.42
+ Previous Estimates (S\$)	27,597.45
Claim Total (S\$)	29,861.87

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 18 Mar 2017)**Parts:** 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Car City Auto Centre Pte Ltd/SCN1616H/18/03/2017 16:36**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*CONTROL UNIT	0.00	0.00	*85.00 F ✓
2	1		*FRONT S/A MTY	0.00	0.00	*125.00 F ✓ MS
3	1		*LOCK LH	0.00	0.00	*350.00 F ✓ CR
4	1		*BRACKET	0.00	0.00	*10.00 F ✓ CR
5	1		*COVERING	0.00	0.00	*13.00 F ✓ CR
6	1		*COVERING	0.00	0.00	*20.00 F ✓ CR
7	1		*COVERING	0.00	0.00	*20.00 F ✓ CR
8	1		*DOOR HANDLE	0.00	0.00	*240.00 F ✓ CR
9	1		*COVERING	0.00	0.00	*40.00 F ✓ CR
10	1		*RAIL	0.00	0.00	*88.00 F ✓ CR
11	20		*RIVET	0.00	0.00	*60.00 F ✓ CR
12	10		*RIVET	0.00	0.00	*30.00 F ✓ CR
13	1		*W/D RUNN LH	0.00	0.00	*110.00 F ✓ CR
14	1		*REAR SAFETY BELT	0.00	0.00	*310.00 F ✓ Jn
15	1		*SAFETY BELT	0.00	0.00	*310.00 F ✓ Jn
16	1		*FRT FENDER END COVER	0.00	0.00	*18.00 F ✓ CR
17	1		*PROTECTIVE HOSE	0.00	0.00	*12.00 F ✓ CR
18	1		*GUIDE RAIL	0.00	0.00	*17.50 F ✓ CR
19	1	98	*BEARING BRACKET	0.00	0.00	*98.00 F ✓ CR
20	1		*CABLE HARNESS ROOF AIR BAG	0.00	0.00	*59.00 F ✓ T1

F=Franchise part.

Sub Total (S\$)	2,015.50
+ Margin on L,N Items 5.00% (S\$)	100.78
Total Parts (S\$)	2,116.28

Car City Auto Centre Pte Ltd/SCN1616H/18/03/2017 16:36. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Car City Auto Centre Pte Ltd/SCN1616H/18/03/2017 16:36. Not valid without Reference section.

Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Nov 2016	19 Nov 2016	21 Nov 2016	S\$25,677.64	S\$25,677.64		Pending for Survey Report
	Sendback Est	11:37 S\$25,792.01	09:33 Edit Adj Rpt	Edit Estimates	View Rpt		Cancel Case
Supp #1	18 Mar 2017 16:31	18 Mar 2017 16:36 S\$2,116.28	18 Mar 2017 16:36			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	CHAN HIAN JOON, ID: S1600579G, Tel: +6598183137, Email: ROY@YEELEE.COM.SG		
Vehicle Reg. No.:	SCN1616H	Date of Loss:	17/11/2016 10:00 - :59
Claim Type:	OD / SNM16D05432C01/6	Policy/Cover Note No.:	DMPCSN3007911503 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93, 528840 Tampines - Tel: 6781 0300		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by HENRY NG KOK HUA] ... [Final Rpt due 30/11/2016]		
Driver/Custodian:	CHAN HIAN JOON (52 / Male), NRIC: S1600579G, Tel: +6598183137		
Adj Asg. Remarks:	EXCESS WAIVED. OD SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- CHINA_TAIPING (08/03/2018): Alert - Adj Mandate Approved (S\$25677.64) - SCN1616H - Claim Handler: Joel Goh
- CHINA_TAIPING (12/12/2017): SCN1616H Inspection Photos
- CHINA_TAIPING (14/03/2017): < No subject >

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SCN1616H (SNM16D05432C01/6)

OD

Nov 17 2016 10:00AM

[CHAN HIAN JOON]

Car City Auto Centre Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)		Thumbnail	Print
1	19/11/16 11:37	Repairer Estimates	1	Load HTM	
2	18/03/17 16:36	Repairer Estimates Suppl. #1	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/01/18 16:26	Adjuster Immediate Advice	1	Load HTM	
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/12/17 15:34	INSPECTION PHOTO	1	Load PDF	
2	29/01/18 16:21	RE-SURVEY PHOTO	1	Load PDF	
3	06/02/18 11:53	REVISED AUDATEX 2	1	Load PDF	
4	22/03/18 09:24	SUPPLEMENTARY	1	Load PDF	

Linked Accident Report Documents

		View View in Browser	
Assessment Reports		1 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail Print
1	17/11/16 17:15	Accident Statement	1 Load HTM
Photos/Images		3 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail Print
1	17/11/16 17:08	SCENE PHOTO	1 Load JPG ☒
2	17/11/16 17:08	3RD PARTY CAR	1 Load JPG ☒
3	17/11/16 17:08	3RD PARTY CAR	1 Load JPG ☒
4	17/11/16 17:08	INSURED CAR	1 Load JPG ☒
5	17/11/16 17:08	INSURED CAR	1 Load JPG ☒
6	17/11/16 17:08	SCENE PHOTO	1 Load JPG ☒
7	17/11/16 17:08	SCENE PHOTO	1 Load JPG ☒
8	17/11/16 17:08	INSURED CAR	1 Load JPG ☒
9	17/11/16 17:10	INSURED CAR	1 Load JPG ☒
10	17/11/16 17:10	INSURED CAR	1 Load JPG ☒
11	17/11/16 17:10	INSURED CAR	1 Load JPG ☒
12	17/11/16 17:10	INSURED CAR	1 Load JPG ☒
13	17/11/16 17:10	INSURED CAR	1 Load JPG ☒
14	17/11/16 17:10	INSURED CAR	1 Load JPG ☒
15	17/11/16 17:10	INSURED CAR	1 Load JPG ☒
16	17/11/16 17:10	INSURED CAR	1 Load JPG ☒
17	17/11/16 17:11	INSURED CAR	1 Load JPG ☒
18	17/11/16 17:11	INSURED CAR	1 Load JPG ☒

19	17/11/16 17:11	INSURED CAR	1	Load JPG	☒
20	17/11/16 17:11	INSURED CAR	1	Load JPG	☒
21	17/11/16 17:11	INSURED CAR	1	Load JPG	☒
22	17/11/16 17:11	INSURED CAR	1	Load JPG	☒
Documentation					
			1 per page		☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)		Thumbnail	Print
1	17/11/16 17:06	Sketch Plan	1	Load TIF	
2	17/11/16 17:06	Sketch Plan #2	1	Load TIF	
3	17/11/16 17:07	POLICE REPORT PAGE 1	1	Load TIF	
4	17/11/16 17:07	POLICE REPORT PAGE 2	1	Load TIF	
5	17/11/16 17:07	POLICE REPORT PAGE 3	1	Load TIF	
6	17/11/16 17:07	POLICE CASE CARD	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^
v

Show Remarks To: ☐ Repairer ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI16022138/GQBE2

Date: 22/03/2018

REFERENCE

Insured/Claimant: CHAN HIAN JOON Policy No: DMPCSN3007911503
Date of Loss: 17/11/2016 Nature of Claim: OD Claim No: SNM16D05432C01/6

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCN1616H**
Make & Model: MERCEDES-BENZ E250, 1.8 CGI (A) Engine No: 27186030003935
Reg. Date: 18/11/2009 (Man. Year: 2009) Chassis No: WDD2120472A080252
Colour: Black Odometer: 157160 km
Engine Capacity: 1796 cc
Market Value/New Car Price: S\$69,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/45Z R17 Rear Tyre Size: 245/45Z R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,496.13	18,935.18	2,560.95	11.91
Miscellaneous Items	172.00	172.00	0.00	0.00
Labour	6,240.16	6,570.46	-330.30	-5.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	27,908.29	25,677.64	2,230.65	7.99
+ GST 7.00/7.00% (S\$)	1,953.58	1,797.43	156.15	7.99
Nett Amount (S\$)	29,861.87	27,475.07	2,386.80	7.99

INSPECTION

Date of Assignment: 21/11/2016 Present Location: Car City Auto Centre Pte Ltd (HQ)
Date Inspected: 21/11/2016 Inspected At: Blk 9006 #01-198, Tampines Street 93
Singapore 528840
Estimated Period of Repair: 14.0 days

Adjuster: HENRY NG KOK HUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Mar 2018)
Parts: 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SCN1616H)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*2K ADHESIVE L/SIDE (NPA)(WCP)	Not Necessary	0.00 F	*- F
2	1	NA	*AIRBAG/TENS C-UNIT (WCP)	Necessary	630.00 F	*630.00 F
3	1	NA	*FRONT BUMPER COVER (WCP)	Deformed	850.00 F	*850.00 F
4	1	NA	*FRONT STABILISER (WCP)	Bent	290.00 F	*290.00 F
5	1	NA	*FRT SCREEN SUPPORTS (NPA)(WCP)	Not Necessary	0.00 F	*- F
6	1	NA	*HEADLINING (WCP)	Deformed	960.00 F	*960.00 F
7	1	NA	*L/B-PILLAR SENSOR (WCP)	Activated	85.00 F	*85.00 F
8	1	NA	*L/B-PILLAR TRIM (WCP)	Cracked	120.00 F	*120.00 F
9	1	NA	*L/BRACKET (WCP)	Not Necessary	30.00 F	*- F
10	1	NA	*L/F BACKREST COVER (WCP)	Not Necessary	1,100.00 F	*- F
11	1	NA	*L/F BALL JOINT (WCP)	Distorted	105.00 F	*105.00 F
12	1	NA	*L/F CHANNEL SEAL (WCP)	Necessary	30.00 F	*30.00 F
13	1	NA	*L/F DOOR FRAME SEAL (WCP)	Not Necessary	150.00 F	*- F
14	1	NA	*L/F DOOR LAMP (WCP)	Not Necessary	26.00 F	*- F
15	1	NA	*L/F DOOR MODULE (WCP)	Activated	420.00 F	*420.00 F
16	1	NA	*L/F DOOR MOULDING (WCP)	Deformed	65.00 F	*65.00 F
17	1	NA	*L/F DOOR SEAL (WCP)	Necessary	180.00 F	*180.00 F
18	1	NA	*L/F DOOR TRIM (WCP)	Cracked	600.00 F	*600.00 F
19	1	NA	*L/F DOOR WINDOW (WCP)	Snapped	150.00 F	*150.00 F
20	1	NA	*L/F LOWER DOOR HINGE (WCP)	Bent	120.00 F	*120.00 F
21	1	NA	*L/F LOWER DOOR MLDG (WCP)	Not Necessary	50.00 F	*- F
22	1	NA	*L/F LWR CONTROL ARM (WCP)	Distorted	320.00 F	*320.00 F
23	1	NA	*L/F OUT WINDOW SEAL (WCP)	Necessary	75.00 F	*75.00 F
24	1	NA		Not Necessary	85.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*L/F PROTECT PLATE (WCP)			
25	1	NA	*L/F SHOCK ABSORBER (WCP)	Bent	520.00 F	*520.00 F
26	1	NA	*L/F SIDE AIRBAG (WCP)	Activated	340.00 F	*420.00 F
27	1	NA	*L/F SPACER (WCP)	Necessary	10.00 F	*10.00 F
28	1	NA	*L/F SPEED SENSOR (WCP)	Not Necessary	260.00 F	*- F
29	1	NA	*L/F STABILISER ARM (WCP)	Not Necessary	75.00 F	*- F
30	1	NA	*L/F STEERING KNUCKLE (WCP)	Distorted	790.00 F	*790.00 F
31	1	NA	*L/F TENSION ROD (WCP)	Distorted	320.00 F	*75.00 F
32	1	NA	*L/F UPP REINF (WCP)	Not Necessary	170.00 F	*- F
33	1	NA	*L/F UPPER DOOR HINGE (WCP)	Bent	95.00 F	*95.00 F
34	1	NA	*L/F W-FRAME INN TRIM (WCP)	Cracked	55.00 F	*55.00 F
35	1	NA	*L/F WHEEL (WCP)	Dented	650.00 F	*650.00 F
36	1	NA	*L/F WHEEL HUB (WCP)	Distorted	430.00 F	*430.00 F
37	1	NA	*L/F W-HOUSE CVR FRT (WCP)	Deformed	120.00 F	*120.00 F
38	1	NA	*L/F W-HOUSE CVR REAR (WCP)	Deformed	125.00 F	*125.00 F
39	1	NA	*L/F WINDOW CHANNEL (WCP)	Bent	95.00 F	*95.00 F
40	1	NA	*L/F WINDOW MOTOR (WCP)	Jammed	390.00 F	*390.00 F
41	1	NA	*L/F WING (WCP)	Buckled	560.00 F	*560.00 F
42	1	NA	*L/F WING BADGE (WCP)	Necessary	45.00 F	*45.00 F
43	1	NA	*L/F WING MOULDING (WCP)	Necessary	28.00 F	*28.00 F
44	1	NA	*L/INNER DOOR FRAME (NPA)(WCP)	Not Necessary	0.00 F	*- F
45	1	NA	*L/INNER SILL (NPA)(WCP)	Serviceable	0.00 F	*- F
46	1	NA	*L/LWR B-PILLAR TRIM (WCP)	Cracked	50.00 F	*50.00 F
47	1	NA	*L/OUT DR MIRROR CVR (WCP)	Not Necessary	23.00 F	*- F
48	1	NA	*L/OUTER TIE ROD BALL (WCP)	Not Necessary	130.00 F	*- F
49	1	NA	*L/R BUMPER GUIDE (WCP)	Not Necessary	30.00 F	*- F
50	1	NA	*L/R DOOR (WCP)	Dented	1,250.00 F	*1,250.00 F
51	1	NA	*L/R DOOR FRAME PROT (WCP)	Not Necessary	150.00 F	*- F
52	1	NA	*L/R DOOR MOULDING (WCP)	Necessary	65.00 F	*65.00 F
53	1	NA	*L/R DOOR SEAL (WCP)	Cracked	160.00 F	*160.00 F
54	1	NA	*L/R LOWER DOOR MLDG (WCP)	Not Necessary	35.00 F	*- F
55	1	NA	*L/R MOULDING (WCP)	Necessary	90.00 F	*90.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1	NA	*L/R OUT WINDOW GSKT (WCP)	Necessary	85.00 F	*85.00 F
57	1	NA	*L/R QUARTER GLASS (NPA)(WCP)	Not Necessary	0.00 F	*- F
58	1	NA	*L/REINFORCEMENT (WCP)	Not Necessary	35.00 F	*- F
59	1	NA	*L/ROOF FRAME MLDG (WCP)	Not Necessary	260.00 F	*- F
60	1	NA	*L/SILL PANEL (NPA)(WCP)	Serviceable	0.00 F	*- F
61	1	NA	*L/SILL PANELLING (WCP)	Dented	400.00 F	*400.00 F
62	1	NA	*L/TENSION ROD RUBBER (WCP)	Distorted	75.00 F	*65.00 F
63	1	NA	*L/TIE ROD (WCP)	Not Necessary	145.00 F	*- F
64	1	NA	*L/UPP FRONT TRIM (WCP)	Torn	70.00 F	*70.00 F
65	1	NA	*L/WINDOWBAG (WCP)	Necessary	590.00 F	*590.00 F
66	1	NA	*LEFT DOOR FRAME (WCP)	Dented	1,500.00 F	*1,500.00 F
67	1	NA	*LEFT FRONT DOOR (WCP)	Buckled	1,300.00 F	*1,300.00 F
68	1	NA	*REAR SCREEN (WCP)	Necessary	360.00 F	*850.00 F
69	1	NA	*REAR SCREEN BOND KIT (NPA) (WCP)	Not Necessary	0.00 F	*- F
70	1	NA	*REAR SCREEN SUPPORTS (NPA) (WCP)	Not Necessary	0.00 F	*- F
71	1	NA	*RR D/WDW BONDING KIT (NPA) (WCP)	Not Necessary	0.00 F	*- F
72	1	NA	*SERVICE LID (WCP)	Cracked	135.00 F	*135.00 F
73	1	NA	*WINDSCREEN REP KIT (NPA)(WCP)	Not Necessary	0.00 F	*- F
Supplementary #1						
74	1		*CONTROL UNIT (WCP)	Shorted	85.00 F	*85.00 F
75	1		*FRONT S/A MTY (WCP)	Distorted	125.00 F	*125.00 F
76	1		*LOCK LH (WCP)	Cracked	350.00 F	*350.00 F
77	1		*BRACKET (WCP)	Cracked	10.00 F	*10.00 F
78	1		*COVERING (WCP)	Cracked	13.00 F	*13.00 F
79	1		*COVERING (WCP)	Cracked	20.00 F	*20.00 F
80	1		*COVERING (WCP)	Cracked	20.00 F	*20.00 F
81	1		*DOOR HANDLE (WCP)	Cracked	240.00 F	*240.00 F
82	1		*COVERING (WCP)	Cracked	40.00 F	*40.00 F
83	1		*RAIL (WCP)	Dented	88.00 F	*88.00 F
84	20		*RIVET (WCP)	Necessary	60.00 F	*60.00 F
85	10		*RIVET (WCP)	Necessary	30.00 F	*30.00 F
86	1		*W/D RUNN LH (WCP)	Dented	110.00 F	*110.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
87	1		*REAR SAFETY BELT (WCP)	Jammed	310.00 F	*310.00 F
88	1		*SAFETY BELT (WCP)	Jammed	310.00 F	*310.00 F
89	1		*FRT FENDER END COVER (WCP)	Torn	18.00 F	*18.00 F
90	1		*PROTECTIVE HOSE (WCP)	Cracked	12.00 F	*12.00 F
91	1		*GUIDE RAIL (WCP)	Bent	17.50 F	*17.50 F
92	1	98	*BEARING BRACKET (WCP)	Distorted	98.00 F	*98.00 F
93	1		*CABLE HARNESS ROOF AIR BAG (WCP)	Torn	59.00 F	*59.00 F

F=Franchise part.

Sub Total (S\$)	20,472.50	18,033.50
+ Margin on L,N Items 5.00/5.00% (S\$)	1,023.63	901.68
Total Parts (S\$)	21,496.13	18,935.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	AUDATEX FEE	42.00	42.00
2	2	SEALANT (NECESSARY)	30.00	30.00
3	1	SUNDRY PARTS (NECESSARY)	100.00	100.00
Sub Total (S\$)			172.00	172.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	970.60	1,021.20
2	Total Paint Materials	New	421.16	424.86
3	Total Panel/Mechanical Labour	New	4,848.40	5,124.40
Gross Labour Cost (S\$)			6,240.16	6,570.46

Report was unsubmitted during this print-out.

< END OF ESTIMATES >