



新 福 德 車 廠

NEW HOCK TECK MOTOR WORKSHOP

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

RCB No.: 52989088K GST Reg No.: M90368118A

LEE VICTOR


Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 31st Dec 2016

Estimated repair cost for vehicle no: SLF6788Y BMW 318I 2.0 A '10



S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>new</i>		\$1,166.55 +
2	1	Front Bonnet Emblem Logo <i>not nec</i>		\$66.15 +
3	2	Front Head Lamp <i>both</i>	\$1,055.25	\$2,110.50 ✓
4	2	Front Head Lamp Lower Bracket <i>both</i>	\$68.50	\$137.00 ✓
5	2	Front Grille <i>both</i>	\$134.60	\$269.20 ✓
6	8	Front Grille Clip <i>both</i>	\$6.50	\$52.00 ✓
7	1	Front Bumper <i>both</i>		\$ 998.00 ✓
8	8	Front Bumper Clip <i>re</i>	\$6.50	\$52.00 -
9	2	Front Bumper Side Retainer <i>re</i>	\$28.90	\$57.80 ✓
10	2	Front Bumper Fog Lamp <i>re</i>	\$245.70	\$491.40 +
11	2	Front Bumper Fog Lamp Cover <i>re</i>	\$68.95	\$137.90 +
12	1	Front Bumper Lower Grille <i>both</i>		\$66.55 ✓
13	1	Front Bumper Reinforcement <i>re</i>		\$523.75 +
15	1	Front Bumper Number Plate <i>Best</i>		\$50.00 ✓
17	1	Front Support Panel <i>re not nec</i>		\$531.15 +

3741.05

3553.99

Subtotal :- \$6,567.15

Labour charges

To remove & refit air-con condenser, radiator, fan motor & top up gas

\$280.00 +

To check wiring

550

\$100.00 30

Tuff kote

\$150.00 +

Panel beating

\$800.00 250

Spray painting

4/s Addison

04/01/17.

\$800.00 250

Subtotal :- \$2,130.00

Total:- \$8,697.15

total: 4103.99

4/s: 3.3K

3.3K

04/01/17