



新 福 德 車 廠

NEW HOCK TECK MOTOR WORKSHOP

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

RCB No.: 52989088K GST Reg No.: M90368118A

TAX INVOICE

AXA Insurance Singapore Pte Ltd

8 Shenton Way,

#B1-01,

Singapore 068811

Client: LEE VICTOR

Invoice No : NPI702-0057

Date : 04-Feb-17

Date of Accident : 31-Dec-16

Vehicle No. : SLF6788Y

Model Type : BMW 318I

Descriptions		Amount
Lump Sum Repair Cost		3,300.00
Sub Total		: 3,300.00
GST 7%		: 231.00
Total		: 3,531.00

SIN DOLLARS: THREE THOUSAND FIVE HUNDRED AND THIRTY ONE ONLY

