

CS REC BY:

REF: CS/GA21700 GA21/Gcd362 Special Instruction:

From (Person):

Stella Cohn

of

GA2

Date/Time:

9/12/17 7:22am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SF 7485P

Insured:

at Workshop m/s

Indeco

Tel:

91820027

of

10 Delta Lane 8

Policy No:

Claim No:

CLMOMV000000313

Sum Insured:

Excess:

IBF \$2000

Make of Veh:

D.O.A. 22/12/2016

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9/12/17 9:52am

Person Contacted:

Sam

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SF 7485P - CS2/GA216024545/Gcd362
	Def. 22/12/2016

ASSIGNMENT

From: _____ Date: 9/1/2017

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SUF 7485Pat Workshop m/s Indeco

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: TBA

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$110K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SUF 7485P Yr Regn: 08 Sep 2016Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798Colour: white A/C: Insured / Std / NI / NASp. Reading: 37036 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STD/KB3FU-403532560Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195 / 65R15R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front


Rear

R/Bal. 7/8 mmR/Bal. 8 mmL/Bal. 7/8 mmL/Bal. 8 mm

D.O.A. _____

D.O.I. 09-01-16 17Survey held at W/S4pmDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orFrt o/s & Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

10/1/17 email preli REV to stella.

11/1/17 stella email approved CA, EX: 2000

11/1/17 @ 5.00pm email to Sam, CA, EX: 2000

3/10 Submit preli report. (Revised Sig 236, 357.70; Check Home: \$12,409.30)

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 18Resurvey No. of Trip: 3

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee: 1150

Transportation:

) S + RS. \$

) Photos

) Others

TOTAL

Report Format: ODLump Sum / I.B.I: (\$ Preli)1150



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI17000421/Ggh3	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 09-01-2017	
		Code : GAI	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SLF 7485P
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000000373	Excess (\$)	0.00
Assign From	STELLA GOH	Assign Date	09/01/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	22/12/2016	Inspection Date	09/01/2017
Survey held at	10 DEFU LANE 8		
Repairer	INDECO ENGINEERS PTE LTD		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

Ai Phing (LKKAUTO)

From: Ai Phing (LKKAUTO)
Sent: Wednesday, 11 January, 2017 5:00 PM
To: yongsingmotors@gmail.com
Cc: SUR
Subject: SLF 7485P GAI-OD (DOA 22-12-2016)

Dear All,

Instructed by our client, please proceed to repair the insured vehicle **SLF 7485P (Excess \$2,000)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

Any supplementary are subjected to further approval from our client.

"Wishing you a Happiness and Prosperity New Year"

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

Ai Phing (LKKAUTO)

From: Goh, Stella <Stella.Goh@sg.gaig.com>
Sent: Wednesday, 11 January, 2017 4:21 PM
To: Ai Phing (LKKAUTO)
Cc: SUR
Subject: RE: OD Claim for SLF7485P

Our Claim ref: CLMOMVC000000373

Dear Ai Phing,

Please authorize repair.

Excess is \$ 2,000.

Thank you.

Stella Goh, Senior Executive | P. 65 6804 6059 | F. 65 6235 3354 | stella.goh@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



Moody's
A1 (Good)
Affirmed June 15, 2015

Standard & Poor's
A+ (Strong)
Affirmed March 2, 2015

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Ai Phing (LKKAUTO) [<mailto:aiphing@lkkauto.com>]
Sent: Tuesday, January 10, 2017 3:22 PM
To: Goh, Stella <Stella.Goh@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD Claim for SLF7485P

Dear Stella,

Enclosed herewith preliminary advise of vehicle SLF 7485P.
We have not authorise repair.

Ashley Chong (LKK Auto)

From: Goh, Stella <Stella.Goh@sg.gaig.com>
Sent: Monday, 9 January, 2017 7:22 AM
To: Yong Sing
Cc: Admin A; assignments
Subject: RE: OD Claim for SLF7485P
Attachments: SLF 7485 P Indeco Repair Estimate - Copy.xlsx; SLF 7485 P.PDF

Our Claim ref: CLMOMVC000000373

Dear Sam,

We refer to your email dated 06.01.17.

We would appoint LKK to conduct the PRS.

By copy to Catherine, please assist.

Thank you.

Stella Goh, Senior Executive | P. 65 6804 6059 | F. 65 6235 3354 | stella.goh@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



Moody's
A1 (Good)
Affirmed June 15, 2015

Standard & Poor's
A+ (Strong)
Affirmed March 2, 2016

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Yong Sing [<mailto:yongsingmotors@gmail.com>]
Sent: Friday, January 06, 2017 10:41 AM
To: Goh, Stella <Stella.Goh@sg.gaig.com>
Subject: OD Claim for SLF7485P

Hi Stella

Our Ref: **SLF7485P**

Date/Time of Accident: 22/12/2016 07:15

**RE: OD CLAIM ON YOUR INSURED'S VEHICLE SLF7485P ON THE 22/12/2016 07:15
ALONG CTE BEFORE MOULMEIN ROAD**

On behalf of Indeco Engineers Pte Ltd, attached is our client's SAS report and our

estimated repair cost (based on our visual inspection) on your insured vehicle .

Kindly arrange your surveyor to survey **SLF7485P** at our workshop @ 10 Defu Lane 8, Singapore 539315. Your surveyor may contact me at 9182 0027 or Lam at 8694 6881 for clarification.

We will greatly appreciate if you can confirm your agreement for direct settlement with our workshop for the COR and number of days to repair under the recommendations of your surveyor.

With Regards,

Sam Sim (Mr)

Sales Executive

Mobile: 9182 0027 Fax: 8284 2788

T/O Defu Lane 8, Singapore 539315



The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CLMOMVC000000373

Date: 10-01-2017

Our Ref: CS/GAI17000421/Ggh3

The Motor Claims Department
Great American Insurance Company

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SLF 7485P


We thank you for the instruction on 09-01-2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 09-01-2017 at the premises of M/s INDECO ENGINEERS and have the following to report:-

Workshop Estimate Amount	: S\$ <u>34,487.70</u>
Revised Estimate Amount	: S\$ <u>26,357.70</u>
"Check" Items Amount	: S\$ <u>3,215.00</u>
Market Value	: S\$ <u>110,000.00</u>
LTA Reimbursement Value	: S\$ <u>59,988.00</u>
Nett Value	: S\$ <u>50,012.00</u>

Description of Damage:

The vehicle sustained damages at the front o/s and rear o/s portion.



Comments/ Present Status:

Damages Consistent.
Repair Cost Economical.
We have not authorize repair.

Yours faithfully

Xing Guo Qiang
Automotive Assessor

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 7200G

Vehicle Details

Vehicle No.: SLF7485P

Vehicle to be Exported: No

Intended De-registration
Date: 10 Jan 2017

Vehicle Make: TOYOTA

Vehicle Model: PRIUS HYBRID 1.8 CVT

Primary Colour: White

Manufacturing Year: 2016

Engine No.: 2ZRR935204

Chassis No.: JTDKB3FU403532560

Maximum Power
Output: 90.0 kW (120 bhp)

Open Market Value: \$31,008.00

Original Registration
Date: 08 Sep 2016

First Registration Date: 08 Sep 2016

Transfer Count: 0

Actual ARF Paid: \$5,412.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 07 Sep 2026

PARF Rebate Amount: \$4,059.00

Intended COE Rebate Details

COE Expiry Date: 07 Sep 2026

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$58,201.00

COE Rebate Amount: \$55,929.00

Total Rebate Amount: \$59,988.00

The information contained herein is correct as at 10 Jan 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/12/2016 13:55
Date Of Accident	22/12/2016 07:15
Exact Location Of Accident	CTE BEFORE MOULMEIN ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF7485P
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	enquiries.sg@grabcar.com
Mobile Phone No	(LOCAL) +65-90977736
Alternative Phone No	Office-65703925

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRING JOB
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
If No, Please state action to be taken	
Vehicle Category	Private Car

Insurance Company

Name of Insurance Company	Great American Insurance Company
Type Of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	
Cover Note Number	MTGRAB20160032

Driver

Name of Driver	WOON SHUNG FONG
NRIC No	S1488944B
Date Of Birth	11/12/1961
Occupation	Outdoor
Date Of Driving Pass	28/05/1982
Driving Experience	34 Years And 6 Months
Gender	Male
Mobile Number	(Local) +65-93922822
Fax Number	
Contact Number	
Email Address	bw1shung@gmail.com

Address	242 JALAN KAYU SINGAPORE 799466
Postcode	799466
Was driver an employee of the Insured's Company	Yes
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	Unknown - Insured suddenly felt an impact on rear of vehicle
Weather Conditions	Clear
Road Surface	Dry

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	Yes
Was any other material or property damaged?	Yes
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	No
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	Yes
If Yes, Please state which Police Station	
Police Station Name	Paya Lebar Npp
Police Station Address	ROAD: 114 HOUGANG AVE 1 #01-1270 . POSTCODE: 530114 . COUNTRY: Singapore
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT NO. T/20161222/2105.

Attachment(s)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJP42B
Vehicle Make/Model/Colour	MAZDA
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?


Was injured conveyed to hospital by ambulance?

Address

Postcode

Any data reported may be referred to the Police for investigation.

10. The report will be forwarded by the directors of the QIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for availability and that copies of this report will be for free made available upon application by interested parties.



A - SEP 7485P

B-55P-42R

Sketch Plan #2

PHS 72a Police Report No. 7/20161222/2105



Police Report Pg 1



**SINGAPORE
POLICE FORCE**



T/20161222/2105

Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999

1 of 4

Report No: T/20161222/2105

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/12/2016 16:44	Vide Report No.	Station Diary No 15
--	-----------------	------------------------

Informant's Particulars

Name of Informant: WOON SHUNG FONG		Address APT BLK 942 HOUGANG STREET 92 #12-109 SINGAPORE 530942	
ID Type / ID No. NRIC NO / S14889448		Contact No. Home/Office: Mobile: 93922822	
Nationality SINGAPORE CITIZEN		Email	
Sex Male	Age 55	Date of Birth 11/12/1961	Type of Informant Driver
Race Chinese		Language English	Institution / School Name
Occupation DRIVER		Driving Licence Information Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 22/12/2016 07:15	Type of Location Straight Road
Location: CENTRAL EXPRESSWAY Towards AMK				
Weather: Clear		Road Surface Dry	Road Speed Limit	
Traffic Flow:		Traffic Control:	Traffic Volume Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJP42B	Car				Seriously Damaged	0
SLF7485P	Car				Seriously Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report Pg 2



**SINGAPORE
POLICE FORCE**



T/20161222/2105

Police Station Of Origin
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999

2 of 4

Report No: T/20161222/2105

CONTINUATION OF REPORT

Driver			
Name	Tan Jie Ying	ID No	S9040749Z
Related Vehicle	SJP42B (Car)	Contact No	81805010
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	WOON SHUNG FONG	ID No	S1488944B
Related Vehicle	SLF7485P (Car)	Contact No	93922822
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	Mohammad Iskandar	ID No	S8114833C
Related Vehicle	SLF7485P (Car)	Contact No	82533234
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 22/12/2016 at about 0715hrs, I was driving my vehicle bearing registration plate number SLF7485P with a passenger along lane 3 of Central Express Way towards Ang Mo Kio, suddenly, I felt an impact on my rear, causing me to lose control of my vehicle. My vehicle swerved to the left and collided on the concrete wall on lane 6 and made a 360degree turn.

Both my passenger and I was in a state of shock and could not feel any pain on our body. However, there are no visible injuries. As a result in the collision, my vehicle's rear bumper and front right & left portion was seriously dented. There is also multiple scratches on the overall body of my vehicle. The other party and I agreed on private settlement and signed a mutual settlement form. After which, both our vehicles were towed by EMAS to a nearest open carpark and subsequently, sent to the other party's designated workshop. After the initial check on my vehicle, a relative of the other party called me and informed that



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-127D
SINGAPORE 530114
Tel No. 1800-2899999



T/20161222/2105

3 of 4

Report No. T/20161222/2105

CONTINUATION OF REPORT

the cost of repair is too high. Hence, we decided to make our insurance claims.

On the same day at about 1000hrs, I started to feel a strain on my left knee and a bruise on my right knee. My passenger also reported of headache, back and leg pain. Thus, he decided to lodge a police report. There is in-built camera in my vehicle. However, while my vehicle was in the workshop, I was informed that my SD card was missing.



**SINGAPORE
POLICE FORCE**



T/20161222/2105

4 of 4

Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999

Report No. T/20161222/2105

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report

F/

Cpl CHONG TECK WEI, JEFFREY

Signature Of Informant

Signature Of Interpreter

Not applicable

Date/Time

22/12/2016 16:44

Officer in Charge Of Case:

TP / G/T /

Staff Sgt YUS MASTARI / KHAZALI

Contact No : 65476214

Classification Of Case:

Authentication Stamp

SP1168

Veron Chen (LKKAUTO)

From: Yong Sing <yongsingmotors@gmail.com>
Sent: Wednesday, 7 June, 2017 5:05 PM
To: Guo Qiang (LKKAUTO); SUR
Cc: Veron Chen (LKKAUTO); Denise Tay (LKKAUTO); Shiao Chan (LKKAUTO)
Subject: FINALISED FOR SLF7485P
Attachments: SLF 7485 P FINAL BILL.pdf; SLF 7485 P Surveyor Marking07062017.pdf; 7485.jpg; 7485_0001.jpg; 7485_0002.jpg; 7485_0003.jpg

Dear Guo Qiang,

Re: Finalised for SLF7485P

Our COR for the above mentioned vehicle is \$45,499.25 excluding GST.

PART BY PART repair job and 18 repair days were given.


Please refer to the attachment.

We hope to hear from your confirmation soon. Thank you.

With Regards,

Sam Sim (Mr)

Sales Executive
Mobile: 9182 0027 Fax: 6264 2796
111 Dohi Lane 8, Singapore 539315



Indeco

REPAIR ESTIMATE

M/S GREAT AMERICAN INSURANCE COMPANY
3 Temasek Avenue #15-01 Centennial Tower
Singapore 039190

Attn: Stella Goh

Tel: 6504 6089

Fax: 6235 3384

Email: stella.goh@gaiig.com

Date : 29/12/2016

Policy No. :

Vehicle No. : SLF7485P

Make/Model : TOYOTA PRIUS

Date of Accident : 22/12/2016 07:15

Vehicle Survey By :

Date / Time :

Summary of Charges

	Our Quotation	Adjustment by Surveyor
Total Labour Charges	\$5,440.00	\$2,600.00
Total Spray Painting Charges	\$3,200.00	\$2,300.00
Other Charges	\$720.00	\$330.00
Total Parts Charges	\$36,156.30	\$40,269.25
	\$44,816.30	\$45,499.25

Lump Sum Repair (if any)

No. of Repair Days [25 Days]

No. of Repair Days [18 Days]

Surveyor Remarks:

Our Remarks:

Labour Charges

Item	Job Scope	Quotation	Adjustment by Surveyor
1	TO REMOVE REAR BUMPER ASSY, REAR BOOT LID, REAR RH FENDER TOP PLASTIC COVER TO FACILITATE WELDING AND CUTTING. TO CUT OUT REAR END PANELS & REAR RH FENDER, REINSTALL REAR END PANEL & REAR RH FENDER. TO REALIGN REAR END VEHICLE STRUCTURE. TO REPAIR REAR RH INNER FENDER.	\$2,800.00	\$1,400.00
2	TO REMOVE FRONT BUMPER, LH FENDER, RH FENDER, BONNET, RADIATOR, SUPPORT PANEL. TO STRAIGHTENED AND REALIGN VEHICLE STRUCTURE. TO REINSTALL ALL DAMAGED ITEMS.	\$2,000.00	\$1,000.00
3	TO REMOVE, REFIT AND REPLACE UNDERCARRIAGE ITEMS.	\$640.00	\$200.00
Total Labour Charges		\$5,440.00	\$2,600.00

Spray Painting Charges

Item	Job Scope	Quotation	Adjustment by Surveyor
1	TO SPRAY PAINT FRONT BONNET	\$300.00	\$250.00
2	TO SPRAY PAINT FRONT BUMPER	\$300.00	\$250.00
3	TO SPRAY PAINT FRONT LH FENDER	\$300.00	\$250.00
4	TO SPRAY PAINT FRONT RH FENDER	\$300.00	\$250.00
5	TO SPRAY PAINT FRONT RH DOOR	\$300.00	\$250.00
6	TO SPRAY PAINT FRONT SUPPORT PANEL	\$150.00	\$150.00
7	TO SPRAY PAINT FRONT REINFORCEMENT	\$150.00	X
8	TO SPRAY PAINT REAR END PANEL	\$200.00	\$150.00
9	REAR END PANEL RH 1	\$150.00	X
10	REAR END PANEL RH 2	\$150.00	X
11	TO SPRAY PAINT REAR BUMPER	\$300.00	\$250.00
12	TO SPRAY PAINT REAR BOOT LID PLASTIC COVER	\$300.00	\$250.00
13	TO SPRAY PAINT REAR END FENDER	\$300.00	\$250.00
Total Spray Painting Charges		\$3,200.00	\$2,300.00

Other Charges

Item	Job Scope	Quotation	Adjustment by Surveyor
1	TO TOW VEHICLE	\$80.00	\$80.00
2	TO CHECK AND TOP UP AIRCON GAS.	\$150.00	\$80.00
3	TO CONDUCT RADIATOR PRESSURE CHECK.	\$150.00	\$40.00
4	TO APPLY ANTI RUST COATING	\$100.00	\$80.00
5	TO REMOVE AND REFIT WIRE HARDNESS.	\$120.00	X
6	TO CONDUCT SYSTEM WIRING CHECK.	\$40.00	\$30.00
7	TO CONDUCT WHEEL ALIGNMENT TEST	\$80.00	\$80.00
Total Other Charges		\$720.00	\$330.00

Parts Charges

Adjusted by
Surveyor

Item	Part Code	Parts Description	Qty	Cost Price	Mark up (%)	Final Price	To Replace (/) To Repair (R)	To Replace (/) To Repair (R) Not Given (X)
1	52119A	FRONT BUMPER	1	\$442.00	1.15	\$508.30	/	REPLACE (/)
2	52116A	FRONT BUMPER RETAINER LH	1	\$45.50	1.15	\$52.33	/	REPLACE (/)
3	53385E	FRONT BUMPER SEAL RUBBER	1	\$18.50	1.15	\$22.43	/	REPLACE (/)
4	53289A	FRONT BUMPER TOP GARNISH COVER	1	\$150.00	1.15	\$172.50	/	REPLACE (/)
5	75310	FRONT TOYOTA EMBLEM	1	\$87.60	1.15	\$77.74	/	REPLACE (/)
6	53101	FRONT TOP GRILLE	1	\$286.00	1.15	\$328.90	/	REPLACE (/)
7	53112E	FRONT BOTTOM GRILLE	1	\$150.00	1.15	\$172.50	/	REPLACE (/)
8	52128B	FRONT BUMPER LH COVER	1	\$29.90	1.15	\$34.39	/	REPLACE (/)
9		FRONT BUMPER RH COVER	1	\$29.90	1.15	\$34.39	/	REPLACE (/)
10	85330	FRONT LH HEADLAMP	1	\$2,080.00	1.15	\$2,392.00	/	REPLACE (/)
11	85301	FRONT RH HEADLAMP	1	\$2,080.00	1.15	\$2,392.00	/	REPLACE (/)
12		FRONT RH FOGLAMP	1	\$474.50	1.15	\$545.68	/	REPLACE (/)
13	53301	FRONT BONNET	1	\$790.00	1.15	\$897.00	/	REPLACE (/)
14		FRONT BONNET LH HINGE	1	\$45.50	1.15	\$52.33	/	REPLACE (/)
15		FRONT BONNET RH HINGE	1	\$45.50	1.15	\$52.33	/	REPLACE (/)
16	53341B	FRONT BONNET INSULATION	1				/	X
17		FRONT BONNET INSULATION CLIP	1	\$20.00	1.15	\$29.90	/	REPLACE (/)
18	52618	FRONT REINFORCEMENT ABSORBER	1	\$65.00	1.15	\$74.75	/	REPLACE (/)
19	52611	FRONT REINFORCEMENT SPONGE	1	\$655.00	1.15	\$753.25	/	REPLACE (/)
20	52021	FRONT REINFORCEMENT	1	\$520.00	1.15	\$598.00	/	REPLACE (/)
21	52112F	ARM ASSY FRONT BUMPER RH	1				/	X
22		FRONT FENDER LH	1	\$806.00	1.15	\$926.90	/	REPLACE (/)
23		FRONT FENDER RH	1	\$806.00	1.15	\$926.90	/	REPLACE (/)
24	60117	FRONT FENDER RH PLASTIC COVER	1	\$78.00	1.15	\$89.70	/	REPLACE (/)
25		FRONT LH FENDER BRACKET	1	\$13.00	1.15	\$14.95	/	REPLACE (/)
26		FRONT RH FENDER BRACKET	1	\$13.00	1.15	\$14.95	/	REPLACE (/)
27		FRONT FENDER LH WORDING	1	\$45.50	1.15	\$52.33	/	REPLACE (/)
28		FRONT FENDER RH WORDING	1	\$45.50	1.15	\$52.33	/	REPLACE (/)
29		WASHER TANK	1	\$183.60	1.15	\$188.37	/	REPLACE (/)
30		WASHER TANK FUNNEL	1	\$162.50	1.15	\$186.88	/	REPLACE (/)
31		FRONT RH DOOR	1				/	X
32	51406A	FRONT UNDERCOVER	1	\$195.00	1.15	\$224.25	/	REPLACE (/)
33		FRONT SUPPORT PANEL	1	\$871.00	1.15	\$1,001.65	/	REPLACE (/)
34	16400	FRONT RADIATOR	1	\$1,430.00	1.15	\$1,644.50	/	REPLACE (/)
35		FRONT RADIATOR DEFLECTOR RH	1	\$52.00	1.15	\$59.80	/	REPLACE (/)
36	16594	FRONT RADIATOR TOP COVER	1	\$58.50	1.15	\$67.28	/	REPLACE (/)
37	16711	FRONT RADIATOR FAN SHROUD	1				/	X
38	88480	FRONT CONDENSER	1	\$1,430.00	1.15	\$1,644.50	/	REPLACE (/)
39		FRONT WINDSCREEN	1	\$1,521.00	1.15	\$1,748.15	/	REPLACE (/)
40	75533G	FRONT WINDSCREEN TOP MOULDING	1	\$45.50	1.15	\$52.33	/	REPLACE (/)

65

41		REAR BUMPER	1	\$298.00	1.15	\$343.85	/	REPLACE (1)
42		REAR BUMPER REINFORCEMENT	1	\$234.00	1.15	\$269.10	/	REPLACE (1)
43		REAR BUMPER RETAINER RH	1	\$78.00	1.15	\$89.70	/	REPLACE (1)
44		REAR BUMPER LOWER MOULDING MIDDLE	1	\$364.00	1.15	\$418.60	/	REPLACE (1)
45	53565	REAR BUMPER LOWER MOULDING RH	1	\$110.50	1.15	\$127.08	/	REPLACE (1)
46		REAR BUMPER RH VENTILATION COVER	1	\$58.50	1.15	\$67.28	/	REPLACE (1)
47		REAR UPPER LAMP RH	1	\$325.00	1.15	\$373.75	/	REPLACE (1)
48		REAR LOWER LAMP RH	1	\$298.00	1.15	\$343.85	/	REPLACE (1)
49	58307	REAR END PANEL	1	\$416.00	1.15	\$478.40	/	REPLACE (1)
50	816210	REAR END PANEL RH 1	1				/	X
51	817370	REAR END PANEL RH 2	1				/	X
52		REAR FENDER RH	1	\$747.50	1.15	\$859.63	/	REPLACE (1)
53	76801	REAR BOOT LID PLASTIC COVER	1	\$910.00	1.15	\$1,046.50	/	REPLACE (1)
54		REAR BOOT LID PLASTIC COVER PRIUS WORDING	1	\$39.00	1.15	\$44.85	/	REPLACE (1)
55		REAR BOOT LID PLASTIC COVER HYBRID WORDING	1	\$39.00	1.15	\$44.85	/	REPLACE (1)
56	48730F	ARM ASSY REAR SUSPENSION- LOWER ARM RH	1	\$572.00	1.15	\$657.80	/	REPLACE (1)
57	48770A	ARM ASSY UPPER CONTROL REAR - UPPER ARM	1	\$234.00	1.15	\$269.10	/	REPLACE (1)
58	48530	ABSORBER RH	2	\$208.00	1.15	\$239.20	/	REPLACE (1)
59	48790	ARM ASSY TRAILING REAR RH	1	\$286.00	1.15	\$328.90	/	REPLACE (1)
60	48710A	ARM ASSY REAR SUSPENSION RH	1	\$168.00	1.15	\$194.35	/	REPLACE (1)
61	488300	REAR STABILIZER LINK RH	1	\$104.00	1.15	\$119.80	/	REPLACE (1)
62	48812	REAR STABILIZER BAR RH	1	\$234.00	1.15	\$269.10	/	REPLACE (1)
63	48818	STABILIZER BUSH	2	\$260.00	1.15	\$299.00	/	REPLACE (1)
64	17430	REAR EXHAUST	1	\$1,066.00	1.15	\$1,225.90	/	REPLACE (1)
65		RIM	1	\$650.00	1.15	\$747.50	/	REPLACE (1)

		SUPPLEMENTARY ITEMS						
1	88703	CONDENSER HOSE DISCHARGE	1	\$280.00	1.15	\$322.00	/	REPLACE (1)
2	51206	REAR CROSSMEMBER	1	\$1,625.00	1.15	\$1,868.75	/	REPLACE (1)
3	16100	WATER PUMP / CRA	1	\$781.30	1.15	\$898.50	/	REPLACE (1)
4		AIRCON COMPRESSOR PIPE / CRA	1	\$390.00	1.15	\$448.50	/	REPLACE (1)
5	75571P	REAR W/B MOULDING / NEC	1	\$26.00	1.15	\$29.90	/	REPLACE (1)
6	64995	BOX RH / CRA	1	\$390.00	1.15	\$448.50	/	REPLACE (1)
7	48510	LOWER BALL JOINT RH / BT	1	\$58.50	1.15	\$67.28	/	REPLACE (1)
8	45046	TIE ROD / BT	1	\$58.50	1.15	\$67.28	/	REPLACE (1)
9	45510	TIE ROD END / BT	1	\$1,820.00	1.15	\$2,093.00	/	REPLACE (1)
10	43501C	KNUCKLE BEARING / NEC	1	\$488.30	1.15	\$561.55	/	REPLACE (1)
11		FRONT RH HEADLAMP COMPUTER / OR	1	\$224.00	1.15	\$257.60	/	REPLACE (1)
12	53213A	FRONT RH SUPPORT ARM (UPPER) / BT	1	\$40.00	1.15	\$46.00	/	REPLACE (1)
13	53705F	FRONT RH SUPPORT ARM (LOWER) / BT	1	\$40.00	1.15	\$46.00	/	REPLACE (1)
14	52112E	ARM ASSY LH / DT	1	\$80.00	1.15	\$92.00	/	REPLACE (1)
15	52112F	ARM ASSY RH / BT	1	\$80.00	1.15	\$92.00	/	REPLACE (1)
16	164A2	RADIATOR WASHER TANK / CRA	1	\$105.00	1.15	\$120.75	/	REPLACE (1)
17	68710E	FRONT CONDENSER LOWER PIPE / DT	1	\$390.00	1.15	\$448.50	/	REPLACE (1)
18	51441	FRONT UNDERCOVER NO 1 / BT	1	\$416.00	1.15	\$478.40	/	REPLACE (1)
19	52169C	REAR RH TOW COVER / mis	1	\$12.00	1.15	\$13.80	/	REPLACE (1)
20		REAR LH LOWER LAMP / Bro	1	\$296.00	1.15	\$340.40	/	REPLACE (1)
21	82183	REAR BUMPER WIRE / Cut	1	\$119.00	1.15	\$136.85	/	REPLACE (1)
22	64370	REAR RH LUGGAGE SIDE TRIM / DC	1	\$288.00	1.15	\$331.20	/	REPLACE (1)
23	65837	REAR RH LINEAR / Cut	1	\$117.00	1.15	\$134.55	/	REPLACE (1)
24	52591	REAR RH BUMPER SEAL / Cut	1	\$71.50	1.15	\$82.23	/	REPLACE (1)
25		REAR LH LINEAR / Cut	1	\$117.00	1.15	\$134.55	/	REPLACE (1)
26	52592	REAR LH BUMPER SEAL / Cut	1	\$71.50	1.15	\$82.23	/	REPLACE (1)
27	12305	INSULATOR, ENGINE MOUNTING / BT	1	\$323.00	1.15	\$371.45	/	REPLACE (1)
28	12315A	BRACKET, ENGINE MOUNTING RH / BT	1	\$1,445.00	1.15	\$1,661.75	/	REPLACE (1)
29		REAR BOOT LID / BT	1	\$525.00	1.15	\$598.75	/	REPLACE (1)
		LABOUR						
1		TO REMOVE REAR CROSS MEMBER, FRONT KNUCKLE, LOWER ARM, BEARING, TIE ROD AND TIE ROD END TO REFIX		\$640.00	1.00	\$640.00		
2		TO CONDUCT WHEEL ALIGNMENT TEST		\$80.00	1.00	\$80.00		
3		TO REALIGN FRONT CHASSIS		\$200.00	1.00	\$200.00		
4		TO REMOVE AND REPLACE ENGINE MOUNTING		\$150.00	1.00	\$150.00		
Total Parts Charges				\$35,166.30		\$40,269.25		

REQUEST FOR SUPPLEMENT PARTS

Workshop	Indeco Engineers Pte Ltd		
Vehicle No.	SLF 7485 P	Date of Request	
Vehicle Model.		Number of Days to Extend (if any)	

S/N	Part Number	Part Description	Quantity	Unit Price	Photo Reference
1		Front RH headlamp complete	1	224	see ✓
2	53213A	Front RH Support Arm (upper)	1	40	PA ✓
3	53705F	Front RH Support Arm (lower)	1	40	PA ✓
4	53113E	Arm Assy LH	1	80	PA ✓
5	52112F	Arm Assy RH	1	80	PA ✓
6	164A2	Reelster Washer Tank	1	105	CRA - /
7	88710E	Front Condenser lower pipe	1	390	PA ✓ /
8	51441	Front undercover No 1	1	416	PA ✓
9		Front RH Liner	1 /	168	X NN X
10	52169C	Rear Bumper RH fastener	1	12	MIS ✓ /
11		Rear LH lower lamp	1	299	PA ✓

Additional Job Scope	Quotation	
To receive front chassis	\$ 500	X
To receive and replace engine mounting	\$ 400	X

X } NN.

REQUEST FOR SUPPLEMENT PARTS

Workshop	Indeco Engineers Pte Ltd		
Vehicle No.	SLE 7685P	Date of Request	
Vehicle Model.		Number of Days to Extend (if any)	

S/N	Part Number	Part Description	Quantity	Unit Price	Photo Reference
1	16100	Water Pump	1	781.30	✓ HP Sebastian 28/3/2017
2		Aircon Compressor Gyle	1		CEK ✓ HP Sebastian 28/3/2017
3	75571P	Rear w/s moulding	1	26	CEK ✓ HP REC ✓
4	64995	Box RH	1	390	✓ CPA ✓
5	48510	Front RH Shock Absorber	1	221	X X
6	43211	Knuckle RH	1	273	X, } NN X
7	48068	Lower Arm RH	1	260	X } X
8	43330K	Lower ball joint RH	1	58.50	✓ ✓
9	45046	TIE ROD	1	58.50	✓ } BT ✓
10	45510	Tie Rod End	1	1820	✓ 58.50 ✓
		Knuckle Bearing	1		✓ REC

Additional Job Scope	Quotation
	Gm G.4
	07/4/17

REQUEST FOR SUPPLEMENT PARTS

Workshop	Indeco Engineers Pte Ltd		
Vehicle No.	SIF 7485P	Date of Request	
Vehicle Model		Number of Days to Extend (if any)	

S/N	Part Number	Part Description	Quantity	Unit Price	Photo Reference
1	82183	Rear bumper Wire	1	119	at / /
2	64370	Rear RH Luggage Side trim	1	288	at / /
3	65637	Rear RH Mirror	1	117	cut /
4	52591	Rear RH RH Passenger Seat	1	71.50	cut /
5		Rear LH Mirror	1	117	cut /
6	52592	Rear LH Passenger Seat	1	71.50	cut /
7	12305	Insulator - Engine Mounting RH	1	323	at /
8	12315A	Bracket, Engine Mounting LH	1	144.5	at / /
		Rear Boot Lid	1		at /

Additional Job Scope	Quotation



SL Automotive Pte Ltd

184, Woodlands Industrial Park E5, #01-02, Singapore 757514

Tel: 6365 4742 Fax: 6368 4750



TOYOTA



MAZDA

GENUINE PARTS

TAX INVOICE

Bill To:	Invoice No.:	SAL17-5264
Indeco Engineers Pte Ltd	Date:	1/3/2017 13:08
Vehicle & Equipment Division	Salesman:	DANIEL
Deliver To: 10 Defu Lane 8, S539315		
Purchaser:		
Vehicle No.: SLF 7485P		

No.	Part No.	Location Description	Qty	Unit Price	Disc	Amount Due
1	✓16400	RADIATOR ASSY	1	\$ 1,430.00		1,430.00
2	✓48530	SHOCK ABSORBER (REAR)	1	\$ 208.00		208.00
3	✓52021	REINFORCEMENT	1	\$ 520.00		520.00
4	✓52023	REAR BUMPER REINFORCEMENT	1	\$ 234.00		234.00
5	✓52116	SUPPORT FR BUMPER	1	\$ 45.50		45.50
6	✓52119	COVER FR BUMPER	1	\$ 442.00		442.00
7	✓52127	COVER FR BUMPER H	1	\$ 29.90		29.90
8	✓52128	COVER FR BUMPER H	1	\$ 29.90		29.90
9	✓52159	REAR BUMPER	1	\$ 299.00		299.00
10	✓52453	REAR BUMPER CENTRE	1	\$ 364.00		364.00
11	✓52565	REAR BUMPER RH GUARE	1	\$ 110.50		110.50
12	✓52575	REAR BUMPER RETAINER	1	\$ 78.00		78.00
13	✓52611	ABSORBER FR BUMPER	1	\$ 65.00		65.00
14	✓52618	ABSORBER FR BUMPER	1	\$ 65.00		65.00
15	✓53028	SUPPORT SUB-ASSY	1	\$ 872.00		872.00
16	✓53101	GRILLE SUB-ASSY	1	\$ 286.00		286.00
17	✓53112	GRILLE RADIATOR	1	\$ 150.00		150.00
18	✓53289	COVER RADIATOR	1	\$ 150.00		150.00

Goods sold are not refundable

Overdue account should bear interest at current bank lending rate.

NET 5,378.80
ADD GST 7% 376.516
TOTAL SGD 5,755.32



[Signature]

Goods Received in good condition and order (Customer's Signature)

[Signature]



Salesman Signature



SL Automotive Pte Ltd

184, Woodlands Industrial Park ES, #01-02, Singapore 757514

Tel: 6365 4742 Fax: 6368 4750



mazda

TOYOTA

GENUINE PARTS

TAX INVOICE

Bill To:	Invoice No.:
Indeco Engineers Pte Ltd	SAL17-5264
Vehicle & Equipment Division	Date: 1/3/2017 13:08
	Salesman: DANIEL
Deliver To: 10 Defu Lane 8, S539315	
Purchaser:	
Vehicle No.: SLF 7485P	

No.	Part No.	Location	Description	Qty	Unit Price	Disc	Amount Due
19	53301		HOOD SUB-ASSY	1	\$ 780.00	\$	780.00
20	53395		SEAL HOOD TO FR EN	1	\$ 19.50	\$	19.50
21	83410		HINGE ASSY HOOD RH	1	\$ 45.50	\$	45.50
22	83420		HINGE ASSY HOOD LH	1	\$ 45.50	\$	45.50
23	53802		FENDER SUB-ASSY FR	1	\$ 806.00	\$	806.00
24	58307		PANEL SUB-ASSY BODY	1	\$ 416.00	\$	416.00
25	60117		COVER SUB-ASSY FR	1	\$ 78.00	\$	78.00
26	61601		PANEL SUB-ASSY RH	1	\$ 806.00	\$	806.00
27	62940		DUCT ASSY QUARTER	1	\$ 58.50	\$	58.50
28	75310		EMBLEM ASSY	1	\$ 67.60	\$	67.60
29	75374		EMBLEM SIDE PANEL RH	1	\$ 45.50	\$	45.50
30	75374		EMBLEM SIDE PANEL LH	1	\$ 45.50	\$	45.50
31	75441		PLATE LUGGAGE COM	1	\$ 39.00	\$	39.00
32	75442		PLATE LUGGAGE COM	1	\$ 39.00	\$	39.00
33	76801		GARNISH SUB-ASSY	1	\$ 520.00	\$	520.00
34	81145		UNIT HEADLAMP RH	1	\$ 2,080.00	\$	2,080.00
35	81185		UNIT HEADLAMP LH	1	\$ 2,080.00	\$	2,080.00
36	81551		REAR COMBINATION	1	\$ 325.00	\$	325.00

Goods sold are not refundable

Overdue account should bear interest at current bank lending rate.

NET	:	8,296.60
ADD GST 7%	:	580.762
TOTAL SGD	:	8,877.36

Goods Received in good condition and order (Customer's Signature)

Salesman Signature



SL Automotive Pte Ltd

144 Woodlands Industrial Park E5, #01-02, Singapore 757514

Tel: 6365 4742 Fax: 6368 4750



TOYOTA



MAZDA

GENUINE PARTS

TAX INVOICE

Bill To:	Invoice No.:	SAL17-5264
Indeco Engineers Pte Ltd	Date:	1/3/2017 13:08
Vehicle & Equipment Division	Salesman:	DANIEL
Deliver To: 10 Defu Lane 8, S539315		
Purchaser:		
Vehicle No.: SLF 7485P		

No.	Part No.	Location	Description	Qty	Unit Price	Disc	Amount Due
55	53828		PROTECTOR FR FENDER	1	\$ 58.50		\$ 58.50
56	61210		LAMP ASSY FOG RH	1	\$ 474.50		\$ 474.50
57	65319		PIPE WASHER A	1	\$ 163.80		\$ 163.80
58	12305		INSULATOR SUB ASSY	1	\$ 323.00		\$ 323.00
59	164A2		RADIATOR WASHER TANK	1	\$ 105.00		\$ 105.00
60	52102		EXTENSION SUB-ASSY	1	\$ 78.00		\$ 78.00
61	52103		EXTENSION SUB-ASSY	1	\$ 78.00		\$ 78.00
62	52169		REAR BUMPER COVER	1	\$ 12.00		\$ 12.00
63	52591		REAR BUMPER SEAL RH	1	\$ 52.33		\$ 52.33
64	52592		REAR BUMPER SEAL LH	1	\$ 52.33		\$ 52.33
65	161A9		PUMP ASSY ELECTRIC	1	\$ 364.00		\$ 364.00
66	12315		ENGINE MOUNTING BRACKET	1	\$ 144.50		\$ 144.50
67	53875		FRONT LINEAR RH	1	\$ 97.50		\$ 97.50
68	67005		BACK DOOR	1	\$ 481.00		\$ 481.00
69	81016		HEADLAMP COMPUTER RH	1	\$ 260.00		\$ 260.00
70	61591		REAR LAMP LOWER LH	1	\$ 299.00		\$ 299.00
71	68710		TUBE & ACCESSORY	1	\$ 390.00		\$ 390.00

Goods sold are not refundable

Overdue account should bear interest at current bank lending rate.

NET	:	3,433.46
ADD GST 7%	:	240.34
TOTAL SGD	:	3,673.80

Goods Received in good condition and order (Customer's Signature)

Salesman Signature



SL Automotive Pte Ltd

184 Woodlands Industrial Park E5, #01-02, Singapore 757514

Tel: 6365 4742 Fax: 6368 4750



TOYOTA



MAZDA

GENUINE PARTS

TAX INVOICE

Bill To: Indeco Engineers Pte Ltd Vehicle & Equipment Division	Invoice No.: SAL17-5264 Date: 1/3/2017 13:08 Salesman: DANIEL
Deliver To: 10 Defu Lane 8, S539315 Purchaser: Vehicle No.: SLF 7485P	

No.	Part No.	Location	Description	Qty	Unit Price	Disc	Amount Due
72	51410		ENGINE UNDER COVER	1	\$ 364.00	\$	364.00
73	65637		REAR WHEEL LINEAR RH	1	\$ 91.00	\$	91.00
74	65638		REAR WHEEL LINEAR LH	1	\$ 91.00	\$	91.00
75	75571		REAR BONNET MOULDING	1	\$ 26.00	\$	26.00
76	82183		WIRE; LUGGAGE ROD	1	\$ 119.00	\$	119.00
77	43330		BALL JOINT	1	\$ 58.50	\$	58.50
78	43550		FRONT HUB & BEARING	1	\$ 325.00	\$	325.00
79	45046		END SET TIE ROD	1	\$ 58.50	\$	58.50
80			FENDER RR	1	\$ 747.50	\$	747.50
81	46618		STAB BUSH	1	\$ 260.00	\$	260.00
82	64370		RR TRIM	1	\$ 288.00	\$	288.00
83	56101		FR WINDSCREEN	1	\$ 1,521.00	\$	1,521.00
84	75533		MOULDING WINDSCREEN	1	\$ 45.50	\$	45.50
85			COMPRESSOR	1	\$ 390.00	\$	390.00
86	75571		MOULDING RR W/S	1	\$ 26.00	\$	26.00
87	64995		BOX RH	1	\$ 390.00	\$	390.00
88	45510		TIE ROD END	1	\$ 58.50	\$	58.50

Goods sold are not refundable

Overdue account should bear interest at current bank lending rate.

NET	:	4,859.50
ADD GST 7%	:	340.17
TOTAL SGD	:	5,199.67

Goods Received in good condition and order (Customer's Signature)

Salesman Signature

Parts Charges

Adjusted by
Surveyor

Item	Part Code	Parts Description	Qty	Cost Price	Mark up (%)	Final Price	To Replace (/) To Repair (R)	To Replace (/) To Repair (R) Not Given (X)
1	52119A	FRONT BUMPER / Di's	1	\$442.00			/	
2	52116A	FRONT BUMPER RETAINER LH - MC	1	\$45.50			/	
3	53395E	FRONT BUMPER SEAL RUBBER - Cut	1	\$19.50			/	
4	53289A	FRONT BUMPER TOP GARNISH COVER - Re	1	\$150.00			/	
5	75310	FRONT TOYOTA EMBLEM - MC	1	\$67.60			/	
6	53101	FRONT TOP GRILLE - MC Re	1	\$286.00			/	
7	53112E	FRONT BOTTOM GRILLE - Re	1	\$150.00			/	
8	52128B	FRONT BUMPER LH COVER - M/S	1	\$29.90			/	
9		FRONT BUMPER RH COVER - Re	1	\$29.90			/	
10	85330	FRONT LH HEADLAMP - Cut	1	\$2,080.00			/	
11	85301	FRONT RH HEADLAMP - Di's	1	\$2,080.00			/	
12		FRONT RH FOGLAMP - Di's	1	\$474.50			/	
13	53301	FRONT BONNET - BT	1	\$780.00			/	
14		FRONT BONNET LH HINGE - BT	1	\$45.50			/	
15		FRONT BONNET RH HINGE - BT	1	\$45.50			/	
16	53341B	FRONT BONNET INSULATION X NN	1	\$280.00			/	
17		FRONT BONNET INSULATION CLIP - MC	1	\$26.00			/	
18	52618	FRONT REINFORCEMENT ABSORBER - Re	1	\$65.00			/	
19	52611	FRONT REINFORCEMENT SPONGE - Re	1	\$655.00			/	
20	52021	FRONT REINFORCEMENT - BT	1	\$520.00			/	
21	52112F	ARM ASSY FRONT BUMPER RH ?	1	\$104.00			/	
22		FRONT FENDER LH - fane	1	\$806.00			/	
23		FRONT FENDER RH - fane	1	\$806.00			/	
24	60117	FRONT FENDER RH PLASTIC COVER - Re	1	\$78.00			/	
25		FRONT LH FENDER BRACKET - fane	1	\$13.00			/	
26		FRONT RH FENDER BRACKET - fane	1	\$13.00			/	
27		FRONT FENDER LH WORDING - fane	1	\$45.50			/	
28		FRONT FENDER RH WORDING - fane	1	\$45.50			/	
29		WASHER TANK - M/S	1	\$163.80			/	
30		WASHER TANK FUNNEL - Re	1	\$162.50			/	
31		FRONT RH DOOR X Repair	1	\$975.00			/	
32	51406A	FRONT UNDERCOVER - Re	1	\$195.00			/	
33		FRONT SUPPORT PANEL - AT	1	\$871.00			/	
34	16400	FRONT RADIATOR - BT	1	\$1,430.00			/	
35		FRONT RADIATOR DEFLECTOR RH - Re	1	\$52.00			/	
36	16594	FRONT RADIATOR TOP COVER - Re	1	\$58.50			/	
37	16711	FRONT RADIATOR FAN SHROUD ?	1	\$169.00			/	
38	68460	FRONT CONDENSER - BT	1	\$1,430.00			/	
39		FRONT WINDSCREEN - CHA	1	\$1,321.00			/	
40	75533G	FRONT WINDSCREEN TOP MOULDING - MC	1	\$45.50			/	

41		REAR BUMPER - B's	1	\$299.00				
42		REAR BUMPER REINFORCEMENT - BT	1	\$234.00				
43		REAR BUMPER RETAINER RH - cut	1	\$78.00				
44		REAR BUMPER LOWER MOULDING MIDDLE - Re	1	\$364.00				
45	52565	REAR BUMPER LOWER MOULDING RH - m's	1	\$110.50				
46		REAR BUMPER RH VENTILATION COVER - Re	1	\$58.50				
47		REAR UPPER LAMP RH -	1	\$325.00				
48		REAR LOWER LAMP RH - 10's	1	\$299.00				
49	58307	REAR END PANEL - Bnc	1	\$416.00				
50	51621D	REAR END PANEL RH 1 ?	1	\$91.00				
51	51737D	REAR END PANEL RH 2 ?	1	\$78.00				
52		REAR FENDER RH - Bnc	1	\$747.50				
53	76801	REAR BOOT LID PLASTIC COVER - bnc	1	\$910.00				
54		REAR BOOT LID PLASTIC COVER PRIUS WORDING -	1	\$39.00				
55		REAR BOOT LID PLASTIC COVER HYBRID WORDING -	1	\$39.00				
56	48730F	ARM ASSY REAR SUSPENSION- LOWER ARM RH - BT	1	\$572.00				
57	48770A	ARM ASSY UPPER CONTROL REAR - UPPER ARM ?	1	\$234.00				
58	48530	ABSORBER RH - BT	2	\$208.00				
59	48760	ARM ASSY TRAILING REAR RH ?	1	\$286.00				
60	48710A	ARM ASSY REAR SUSPENSION RH ?	1	\$159.00				
61	48830D	REAR STABILIZER LINK RH ?	1	\$104.00				
62	48612	REAR STABILIZER BAR RH ?	1	\$234.00				
63	48818	STABILIZER BUSH ?	2	\$260.00				
64	17430	REAR EXHAUST ?	1	\$1,066.00				
65		RIM - cut	1	\$850.00				
Total Parts Charges				\$25,127.70		\$0.00		

Labour Charges

Item	Job Scope	Quotation	Adjustment by Surveyor
1	TO REMOVE REAR BUMPER ASSY, REAR BOOT LID, REAR RH FENDER TOP PLASTIC COVER TO FACILITATE WELDING AND CUTTING, TO CUT OUT REAR END PANELS & REAR RH FENDER, REINSTALL REAR END PANEL & REAR RH FENDER, TO REALIGN REAR END VEHICLE STRUCTURE, TO REPAIR REAR RH INNER FENDER.	\$2,800.00	2000 1400
2	TO REMOVE FRONT BUMPER, LH FENDER, RH FENDER, BONNET, RADIATOR, SUPPORT PANEL, TO STRAIGHTENED AND REALIGN VEHICLE STRUCTURE, TO REINSTALL ALL DAMAGED ITEMS	\$2,000.00	1000
3	TO REMOVE, REFIT AND REPLACE UNDERCARRIAGE ITEMS.	\$640.00	200
			2600
Total Labour Charges		\$5,440.00	\$0.00

Spray Painting Charges

Item	Job Scope	Quotation	Adjustment by Surveyor
1	TO SPRAY PAINT FRONT BONNET	\$300.00	250
2	TO SPRAY PAINT FRONT BUMPER	\$300.00	250
3	TO SPRAY PAINT FRONT LH FENDER	\$300.00	250
4	TO SPRAY PAINT FRONT RH FENDER	\$300.00	250
5	TO SPRAY PAINT FRONT RH DOOR	\$300.00	250
6	TO SPRAY PAINT FRONT SUPPORT PANEL	\$150.00	/
7	TO SPRAY PAINT FRONT REINFORCEMENT	\$150.00	X
8	TO SPRAY PAINT REAR END PANEL	\$200.00	/
9	REAR END PANEL RH 1 ?	\$150.00	
10	REAR END PANEL RH 2 ?	\$150.00	
11	TO SPRAY PAINT REAR BUMPER	\$300.00	250
12	TO SPRAY PAINT REAR BOOT LID PLASTIC COVER	\$300.00	250
13	TO SPRAY PAINT REAR END FENDER	\$300.00	250
			2300
Total Spray Painting Charges		\$3,200.00	\$0.00

Other Charges

Item	Job Scope	Quotation	Adjustment by Surveyor
1	TO TOW VEHICLE	\$80.00	/
2	TO CHECK AND TOP UP AIRCON GAS	\$150.00	100 60
3	TO CONDUCT RADIATOR PRESSURE CHECK *	\$150.00	40
4	TO APPLY ANTI RUST COATING	\$100.00	60
5	TO REMOVE AND REFIT WIRE HARDNESS ?	\$120.00	60 ?
6	TO CONDUCT SYSTEM WIRING CHECK	\$40.00	30
7	TO CONDUCT WHEEL ALIGNMENT TEST	\$80.00	60
			330
Total Other Charges		\$720.00	\$0.00

Indeco

REPAIR ESTIMATE

M/S. GREAT AMERICAN INSURANCE COMPANY
3 Temasek Avenue #16-01 Centennial Tower
Singapore 039190

Attn: Stella Goh
Tel: 6804 6059
Fax: 6256 3364
Email: stella.goh@gag.gaig.com

Date: 29/12/2016
Policy No.:
Vehicle No.: SLF7485P
Make/Model: TOYOTA PRIUS
Date of Accident: 22/12/2016 07:15

Vehicle Survey By:
Date / Time:

Summary of Charges

	Our Quotation
Total Labour Charges	\$5,445.00
Total Spray Painting Charges	\$3,200.00
Other Charges	\$720.00
Total Parts Charges	\$25,127.70
	\$34,487.70

	Adjustment by Surveyor
	\$0.00
	\$0.00
	\$0.00
	\$0.00
	\$0.00

Lump Sum Repair (if any)

No. of Repair Days (25 Days)

No. of Repair Days (18 Days)

Surveyor Remarks:

Excess: TBA
Not Authorised
Guo Qi'ang - 8288 0282
09/01/2017

part by part
before paint photos


12/1/17

Our Remarks:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

03682.00

REQUEST FOR SUPPLEMENT PARTS

Workshop	Indeco Engineers Pte Ltd		
Vehicle No.	SLF 7485 P	Date of Request	
Vehicle Model.		Number of Days to Extend (if any)	

S/N	Part Number	Part Description	Quantity	Unit Price	Photo Reference
1		Front RH headlamp complete	1	224	?
2	53213A	Front RH Support Arm (upper upper)	1	40	?
3	53705F	Front RH Support Arm (lower)	1	40	?
4	52113E	Arm Assy LH	1	80	?
5	52112F	Arm Assy RH	1	80	?
6	16AA2	Recliner Washer Tank	1	105	?
7	8871CE	Front Condenser tube pipe	1	390	?
8	51441	Front Undercover No 1	1	416	?
9		Front RH Liner	1	168	?
10	52169C	Recl. Backrest Kit tenton	1	12	?
11		Recl. LH lower lamp	1	299	?

1859

Additional Job Scope	Quotation
To rectify front chassis	\$ 500
To remove and replace engine mounting	\$ 400

REQUEST FOR SUPPLEMENT PARTS

Workshop	Indeco Engineers Pte Ltd		
Vehicle No.	SLE 7185P	Date of Request	
Vehicle Model.		Number of Days to Extend (if any)	

S/N	Part Number	Part Description	Quantity	Unit Price	Photo Reference
1	16100	Water Pump	1	781.30	?
2		Aircon Compressor Pipe	1		?
3	75571P	Rear w/s moulding	1	26	?
4	64995	Box RH	1	390	?
5	48510	Front RH Shock Absorber	1	221	?
6	43211	Knuckle RH	1	273	?
7	48068	Lower Arm RH	1	260	?
8	43330K	Lower ball joint RH	1	58.50	?
9	45046	TIE ROD	1	58.50	?
10	45510	Tie Rod End	1	1820	?
		Knuckle bearing	1		?

2268-30

Additional Job Scope	Quotation	

REQUEST FOR SUPPLEMENT PARTS

Workshop	Indeco Engineers Pte Ltd		
Vehicle No.	S/F 7185P	Date of Request	
Vehicle Model.		Number of Days to Extend (if any)	

S/N	Part Number	Part Description	Quantity	Unit Price	Photo Reference
1	82183	Rear bumper wire	1	119	7
2	64370	Rear RH Luggage side trim	1	288	7
3	65637	Rear RH Mirror	1	117	7
4	52591	Rear RH RH Bumper Seal	1	71.50	7
5		Rear LH Mirror	1	117	7
6	52592	Rear LH Bumper Seal	1	71.50	7
7	12305	Insulator Engine Mounting RH	1	323	7
8	12315A	Bracket, Engine mounting LH	1	144.5	7
		Rear Boot Lid	1		

2652

Additional Job Scope	Quotation



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI17000421/Gcd3e2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 27-11-2019



Code : GAI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLF 7485P
Policy No.	MTGRAB20160032	Coverage (\$)	0.00
Claim No.	CLMOMVC000000373	Excess (\$)	2,000.00
Assign From	STELLA GOH	Assign Date	09/01/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDKB3FU403532560	Colour	WHITE
Odometer	37036	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S AND REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/12/2016	Inspection Date	09/01/2017
Survey held at	10 DEFU LANE 8		
Repairer	INDECO ENGINEERS PTE LTD		

5a. Remarks

A)THE MARKET VALUE IS S\$110,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	18 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 7485P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DISTORTED	442.00	442.00
1	FRONT BUMPER RETAINER LH	NECESSARY	45.50	45.50
1	FRONT BUMPER SEAL RUBBER	CUT	19.50	19.50
1	FRONT BUMPER TOP GARNISH COVER	DEFORMED	150.00	150.00
1	FRONT TOYOTA EMBLEM	NECESSARY	67.60	67.60
1	FRONT TOP GRILLE	DEFORMED	286.00	286.00
1	FRONT BOTTOM GRILLE	DEFORMED	150.00	150.00
1	FRONT BUMPER LH COVER	MISSING	29.90	29.90
1	FRONT BUMPER RH COVER	DEFORMED	29.90	29.90
1	FRONT LH HEADLAMP	CUT	2,080.00	2,080.00
1	FRONT RH HEADLAMP	DISTORTED	2,080.00	2,080.00
1	FRONT RH FOG LAMP	DISTORTED	474.50	474.50
1	FRONT BONNET	BENT	780.00	780.00
1	FRONT BONNET LH HINGE	BENT	45.50	45.50
1	FRONT BONNET RH HINGE	BENT	45.50	45.50
1	FRONT BONNET INSULATION	NOT NECESSARY	280.00	-
1	FRONT BONNET INSULATION CLIP	NECESSARY	26.00	26.00
1	FRONT REINFORCEMENT ABSORBER	DEFORMED	65.00	65.00
1	FRONT REINFORCEMENT SPONGE	DEFORMED	655.00	655.00
1	FRONT REINFORCEMENT	BENT	520.00	520.00
1	ARM ASSY FRONT BUMPER RH	* CHECK	104.00	-
1	FRONT FENDER LH	BUCKLED	806.00	806.00
1	FRONT FENDER RH	BUCKLED	806.00	806.00
1	FRONT FENDER RH PLASTIC COVER	DEFORMED	78.00	78.00
1	FRONT LH FENDER BRACKET	NECESSARY	13.00	13.00
1	FRONT RH FENDER BRACKET	NECESSARY	13.00	13.00
1	FRONT FENDER LH WORDING	NECESSARY	45.50	45.50
1	FRONT FENDER RH WORDING	NECESSARY	45.50	45.50
1	WASHER TANK	DISTORTED	163.80	163.80
1	WASHER TANK FUNNEL	DEFORMED	162.50	162.50

Report Ref No. CS/GAI17000421/Gcd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RH DOOR	TO REPAIR SEE LABOUR	975.00	-
1	FRONT UNDERCOVER	DEFORMED	195.00	195.00
1	FRONT SUPPORT PANEL	BENT	871.00	871.00
1	FRONT RADIATOR	BENT	1,430.00	1,430.00
1	FRONT RADIATOR DEFLECTOR RH	DEFORMED	52.00	52.00
1	FRONT RADIATOR TOP COVER	DEFORMED	58.50	58.50
1	FRONT RADIATOR FAN SHROUD	* CHECK	169.00	-
1	FRONT CONDENSER	BENT	1,430.00	1,430.00
1	FRONT WINDSCREEN	CRACKED	1,521.00	1,521.00
1	FRONT WINDSCREEN TOP MOULDING	NECESSARY	45.50	45.50
1	REAR BUMPER	DISTORTED	299.00	299.00
1	REAR BUMPER REINFORCEMENT	BENT	234.00	234.00
1	REAR BUMPER RETAINER RH	CUT	78.00	78.00
1	REAR BUMPER LOWER MOULDING MIDDLE	DEFORMED	364.00	364.00
1	REAR BUMPER LOWER MOULDING RH	MISSING	110.50	110.50
1	REAR BUMPER RH VENTILATION COVER	DEFORMED	58.50	58.50
1	REAR UPPER LAMP RH	DISTORTED	325.00	325.00
1	REAR LOWER LAMP RH	DISTORTED	299.00	299.00
1	REAR END PANEL	BUCKLED	416.00	416.00
1	REAR END PANEL RH 1	* CHECK	91.00	-
1	REAR END PANEL RH 2	* CHECK	78.00	-
1	REAR FENDER RH	BUCKLED	747.50	747.50
1	REAR BOOT LID PLASTIC COVER	BUCKLED	910.00	910.00
1	REAR BOOT LID PLASTIC COVER PRIUS WORDING	NECESSARY	39.00	39.00
1	REAR BOOT LID PLASTIC COVER HYBRID WORDING	NECESSARY	39.00	39.00
1	ARM ASSY REAR SUSPENSION - LOWER ARM RH	BENT	572.00	572.00
1	ARM ASSY UPPER CONTROL REAR - UPPER ARM	* CHECK	234.00	-
2	ABSORBER RH	BENT	208.00	208.00
1	ARM ASSY TRAILING REAR RH	* CHECK	286.00	-
1	ARM ASSY REAR SUSPENSION RH	* CHECK	169.00	-
1	REAR STABILIZER LINK RH	* CHECK	104.00	-
1	REAR STABILIZER BAR RH	* CHECK	234.00	-

Report Ref No. CS/GAI17000421/Gcd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	STABILIZER BUSH	* CHECK	260.00	-
1	REAR EXHAUST	* CHECK	1,066.00	-
1	RIM	CUT	650.00	650.00
1	REAR END PANEL RH 1	* CHECK	150.00	-
1	REAR END PANEL RH 2	* CHECK	150.00	-
1	FRONT RH HEADLAMP COMPUTER (ADDITIONAL)	* CHECK	224.00	-
1	FRONT RH SUPPORT ARM (UPPER) (ADDITIONAL)	* CHECK	40.00	-
1	FRONT RH SUPPORT ARM (LOWER) (ADDITIONAL)	* CHECK	40.00	-
1	ARM ASSY LH (ADDITIONAL)	* CHECK	80.00	-
1	ARM ASSY RH (ADDITIONAL)	* CHECK	80.00	-
1	RADIATOR WASHER TANK (ADDITIONAL)	* CHECK	105.00	-
1	FRONT CONDENSER LOWER PIPE (ADDITIONAL)	* CHECK	390.00	-
1	FRONT UNDERCOVER NO.1 (ADDITIONAL)	* CHECK	416.00	-
1	FRONT RH LINEAR (ADDITIONAL)	* CHECK	168.00	-
1	REAR BUMPER RH TOW COVER (ADDITIONAL)	* CHECK	12.00	-
1	REAR LH LOWER LAMP (ADDITIONAL)	* CHECK	299.00	-
1	WATER PUMP (ADDITIONAL)	* CHECK	781.30	-
1	AIRCON COMPRESSOR PIPE (NPA) (ADDITIONAL)	* CHECK	-	-
1	REAR W/S MOULDING (ADDITIONAL)	* CHECK	26.00	-
1	BOX RH (ADDITIONAL)	* CHECK	390.00	-
1	FRONT RH SHOCK ABSORBER (ADDITIONAL)	* CHECK	221.00	-
1	KNUCKLE RH (ADDITIONAL)	* CHECK	273.00	-
1	LOWER ARM RH (ADDITIONAL)	* CHECK	260.00	-
1	LOWER BALL JOINT RH (ADDITIONAL)	* CHECK	58.50	-
1	TIE ROD (ADDITIONAL)	* CHECK	58.50	-
1	TIE ROD END (ADDITIONAL)	* CHECK	1,820.00	-
1	KNUCKLE BEARING (NPA) (ADDITIONAL)	* CHECK	-	-
1	REAR BUMPER WIRE (ADDITIONAL)	* CHECK	119.00	-
1	REAR RH LUGGAGE SIDE TRIM (ADDITIONAL)	* CHECK	288.00	-
1	REAR RH LINEAR (ADDITIONAL)	* CHECK	117.00	-
1	REAR RH BUMPER SEAL (ADDITIONAL)	* CHECK	71.50	-
1	REAR LH LINEAR (ADDITIONAL)	* CHECK	117.00	-
1	REAR LH BUMPER SEAT (ADDITIONAL)	* CHECK	71.50	-

Report Ref No. CS/GAI17000421/Gcd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199807198R GST Reg. No. 19-9607198-R

Page No.: 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	INSULATOR ENGINE MOUNTING RH (ADDITIONAL)	* CHECK	323.00	-
1	BRACKET, ENGINE MOUNTING RH (ADDITIONAL)	* CHECK	1,445.00	-
1	REAR BOOT LID (NPA) (ADDITIONAL)	* CHECK	-	-
			33,722.00	21,077.70
	LABOUR			
	TO REMOVE REAR BUMPER ASSY, REAR BOOT LID, REAR RH FENDER TOP PLASTIC COVER TO FACILITATE WELDING AND CUTTING. TO CUT OUT REAR END PANELS & REAR RH FENDER. REINSTALL REAR END PANEL & REAR RH FENDER. TO REALIGN REAR END VEHICLE STRUCTURE. TO REPAIR REAR RH INNER FENDER. INCLUSIVE OF THE REPAIR OF FRONT RH DOOR.		2,800.00	1,400.00
	TO REMOVE FRONT BUMPER, LH FENDER, RH FENDER, BONNET, RADIATOR, SUPPORT PANEL. TO STRAIGHTENED AND REALIGN VEHICLE STRUCTURE. TO REINSTALL ALL DAMAGED ITEMS.		2,000.00	1,000.00
	TO REMOVE, REFIT AND REPLACE UNDERCARRIAGE ITEMS.		640.00	200.00
	TO SPRAY PAINT FRONT BONNET.		300.00	250.00
	TO SPRAY PAINT FRONT BUMPER.		300.00	250.00
	TO SPRAY PAINT FRONT LH FENDER.		300.00	250.00
	TO SPRAY PAINT FRONT RH FENDER.		300.00	250.00
	TO SPRAY PAINT FRONT RH DOOR.		300.00	250.00
	TO SPRAY PAINT FRONT SUPPORT PANEL.		150.00	150.00
	TO SPRAY PAINT FRONT REINFORCEMENT.	NOT NECESSARY	150.00	-
	TO SPRAY PAINT REAR END PANEL.		200.00	200.00
	TO SPRAY PAINT REAR BUMPER.		300.00	250.00
	TO SPRAY PAINT REAR BOOT LID PLASTIC COVER.		300.00	250.00
	TO SPRAY PAINT REAR END FENDER.		300.00	250.00
	TO TOW VEHICLE.		80.00	80.00
	TO CHECK AND TOP UP AIRCON GAS.		150.00	60.00
	TO CONDUCT RADIATOR PRESSURE CHECK.		150.00	40.00
	TO APPLY ANTI RUST COATING.		100.00	60.00
	TO REMOVE AND REFIT WIRE HARDNESS.	* CHECK	120.00	-
	TO CONDUCT SYSTEM WIRING CHECK.		40.00	30.00

Report Ref No. CS/GAI17000421/Gcd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT WHEEL ALIGNMENT TEST.		80.00	60.00
	TO REALIGN FRONT CHASSIS. (ADDITIONAL)	* CHECK	500.00	-
	TO REMOVE AND REPLACE ENGINE MOUNTING. (ADDITIONAL)	* CHECK	400.00	-
			9,960.00	5,280.00
GRAND TOTAL			43,682.00	26,357.70

RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$12,409.30 NETT)			26,357.70
LESS EXCESS			-2,000.00
NETT LIABILITY			24,357.70

Report Ref No. CS/GAI17000421/Gcd3e2

Repairer unable to locate the physical file.

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.