

REQUEST FOR SUPPLEMENT PARTS

Workshop	Indeco Engineers Pte Ltd		
Vehicle No.	SLF 7485 P	Date of Request	
Vehicle Model.		Number of Days to Extend (if any)	

S/N	Part Number	Part Description	Quantity	Unit Price	Photo Reference
1		Front RH headlamp? complete	1	224	1
2	53213A	Front RH Support arm (set upper)	1	40	1
3	53705F	Front RH Support arm (lower)	1	40	1
4	52113E	Arm Assy LH	1	80	1
5	52112F	Arm Assy RH	1	80	1
6	16AA2	Radiator Washer Tank	1	105	1
7	88710E	Front Condenser lower pipe	1	390	1
8	51441	Front Undercover No. 1	1	416	1
9		Front RH Liner	1	168	1
10	52169C	Rear Bumper RH lower	1	12	1
11		Rear LH lower lamp	1	299	1

1854

Additional Job Scope	Quotation
To receive front chassis	\$ 500
To remove and replace engine mounting	\$ 400

REQUEST FOR SUPPLEMENT PARTS

Workshop	Indeco Engineers Pte Ltd		
Vehicle No.	SLK 7485P	Date of Request	
Vehicle Model.		Number of Days to Extend (if any)	

S/N	Part Number	Part Description	Quantity	Unit Price	Photo Reference
1	16100	Water Pump	1	781.30	?
2		Airion Compressor Type	1		?
3	75571P	Rear w/s moulding	1	26	?
4	64995	Box RH	1	390	?
5	48510	Front RH Shock Absorber	1	221	?
6	43211	Knuckle RH	1	273	?
7	48068	Lower Arm RH	1	260	?
8	43330K	Lower ball joint RH	1	58.50	?
9	45046	TIE ROD	1	58.50	?
10	45510	Tie Rod End	1	1820	?
		Knuckle bearing	1		?

2888-30

Additional Job Scope	Quotation	

REQUEST FOR SUPPLEMENT PARTS

Workshop	Indeco Engineers Pte Ltd		
Vehicle No.	SIF 7185P	Date of Request	
Vehicle Model.		Number of Days to Extend (if any)	

S/N	Part Number	Part Description	Quantity	Unit Price	Photo Reference
1	82183	Rear bumper wire	1	119	?
2	64370	Rear RH Luggage side trim	1	288	?
3	65637	Rear RH Mirror	1	117	?
4	52591	Rear RH Bumper Seal	1	71.50	?
5		Rear LH Liner	1	117	?
6	52592	Rear LH Bumper Seal	1	71.50	?
7	12305	Insulator Engine Mounting RH	1	323	?
8	12315A	Bracket, Engine mounting RH	1	144.5	?
		Rear Boot Lid	1		

2552

Additional Job Scope	Quotation