

S. REC. BY:

REF: CS/7CL17002026/GHbn2 Special Instruction:

ASSIGNMENT (Office)

From (Person): CW3 Lurene Jaw of TCI Date/Time: 01/02/2017 7:03pm

Estimated Cost: Bill to:

OD / RES / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SJS 6751H Insured: SHA 9848L

at Workshop m/s Chew Goo N Tel: 6484 1626

of Blk 10 AMK Ind Park 2A # 01-13

Policy No: Claim No: D17001266MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 29012017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS' 06-02-2017 H.O.D. Endorsement:

Date/Time: 01/02/2017 7:13pm Person Contacted: Grace Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJS 6751H - CCB / AXA 120114363 / Wedfl DUA: 200712
	SHA 9848L - CCB / AXA 12012157 / Hicc3dl DUA: 190612
13/2/17	Sent preli to Lurene
	Lump Sum \$4200, 5days CRed. 2681.40 (38%)

A.S. REC. BY: XHLREF: FCI**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Chew goon Motor
of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its
repair at the time of inspection.**

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : **Yes** or **No**GIA / PR Seen: _____ Consistent? : **Yes** or **No**Est. Repairs: 5 days Res.: **Yes** or **No**Lum Sum: 20 % 3 Val.: **Yes** or **No****CA / REV / REP. / 24 HRS**Vehicle: **IN / OUT**

Date: _____ Person Contacted: _____

Veh No: SIS67511 Yr Regn: 27 Aug 2009Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**

Truck / Trailer or _____

Make: Honda Fit C.C. 1339Colour: Silver A/C: **Insured / Std / NI / NA**Sp. Reading: 64842 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: GE61172394Gen. Cond: **Good / Fair / Poor / Burnt**Steering: **Inorder / Jammed / Leaked / Burnt** or _____Brake: **Inorder / Jammed / Leaked / Burnt** or _____Modi: **Nil / S/Rim / STD / Rim** or _____Tyre Size: **F:** 195/60 R15**R:** 11**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /****TOYO / YOKO** or CST**Front**R/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

RearR/Bal. 6 mmL/Bal. 6 mmD.O.I. 07-02-17Survey held at W/S 3:40pmDes. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** or _____The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	'Gpc'

RECEIVED 27 APR 2010

27
28/4 Typist5
2

Add Fee:

☐

Site Insp. \$

☐

Interview \$

☐

Tech. Insp. \$

☐

Weekend \$

Report Format: TP

Lump Sum / L.B.I. (S)

4200

TOTAL

145
50
50+50
34
329




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17002026/Gtb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-02-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9848L	Veh. Inspected	SJS 6751H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17001266MFSH	Excess (\$)	0.00	
Assign From	CWS (LURENE JAW)	Assign Date	01/02/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/01/2017	Inspection Date	06/02/2017	
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	01-02-2017	Our Ref No.	D17001266MFSH
Accident Date	29-01-2017	Claim Type.	Third Party
Insured Vehicle	SHA9848L	Third Party Vehicle.	SJS6751H
Survey Location	BLK 10, ANG MO KIO INDUSTRIAL PARK 2A AVE 5 #01-15,16,17 & #03-05AMK AUTOPOINT		
Contact Person.	GRACE		
Contact No.	64841626/ 0	Fax No.	64840465
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHEW GOON MOTOR	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	LURENE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/215956)



PRI Documents



Close



PRI Header Details

Claim No	D17001266MFSH	Policy No	D-17086801MFSH	Claimant S.No & Name	1 & CH
Workshop Name	CHEW GOON MOTOR (Contact Person : GRACE)	Survey Location & Contact Details	BLK 10, ANG MO KIO INDUSTRIAL PARK 2A AV 05AMK AUTOPOINT Mobile: 0 , Phone: 64841626 , Fax: 6484046 EmailId: AD3@CHEWGOONMOTOR.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9848L	TP Vehicle No	SJS675
PRI Recieved Date	01-02-2017 07:38:35 PM	Surveyor Appointed Date	01-02-2017 07:04:31 PM	Surveyor Accept Date	01-02-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	01-02-2017	Upload Survey Report *:	
-----------------------------	---	----------------------	------------	-------------------------	---

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Monday, 13 February, 2017 8:58 AM
To: 'Claim Workflow System'; LURENEJAW@FIRST-INSURANCE.COM.SG
Cc: SUR; Admin-D (LKKAUTO); assignments
Subject: RE: SURVEY ASSESSMENT - D17001266MFSH/1
Attachments: SJS 6751H.pdf

Dear Lurene,

Enclosed preliminary revised of vehicle **SJS 6751H**.
Date of survey : 07/02/2017

Thank you.

Best Regards,

Janice Lee (Ms) | Admin

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 1 February, 2017 7:14 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17001266MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

"Wishing you a Happiness and Prosperity New Year"

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Wednesday, 1 February, 2017 7:03 PM
To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; LURENEJAW@FIRST-INSURANCE.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D17001266MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Denise Tay (LKKAUTO)

From: Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>
Sent: Friday, 27 April 2018 11:50 AM
To: Denise Tay (LKKAUTO); Guo Qiang (LKKAUTO); SUR
Cc: chewgoon@singnet.com.sg
Subject: RE: SJS6751H Date of accident: 29.01.2017

Dear Denise,

Confirm L/S \$4200.00 and 5 working days.

Thanks & Regards,
Grace

Chew Goon Motor
Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15, 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 24 April 2018 4:24 PM
To: Chew Goon Motor(ad3); Guo Qiang (LKKAUTO); SUR
Cc: chewgoon@singnet.com.sg
Subject: RE: SJS6751H Date of accident: 29.01.2017

Dear Grace,

Our breakdown as following:-

Parts \$3772
-20%

3017.60

SN: 331

Labour: 1950

TOTAL: \$5298.60

Lump Sum \$4200/-

Please check and confirm

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Denise Tay (LKKAUTO)

From: Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>
Sent: Friday, 20 April 2018 10:23 AM
To: Guo Qiang (LKKAUTO); SUR
Cc: chewgoon@singnet.com.sg
Subject: RE: SJS6751H Date of accident: 29.01.2017
Attachments: SJS6751H.pdf

Dear Mr Guo Qiang,

We wish to counter propose L/S \$4400.00.

Our breakdown as following:-

Parts :	3772.00
-20% :	754.40

	3017.60
SN :	555.00
Labour:	1950.00

Total:	5522.60

L/S 4418.08

Please advise.

Thanks & Regards,
Grace

Chew Goon Motor
Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15 , 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

From: Chew Goon Motor(ad3)
Sent: Thursday, 8 February 2018 11:07 AM
To: guoqiang@lkkauto.com; sur@lkkauto.com
Cc: chewgoon@singnet.com.sg
Subject: RE: SJS6751H Date of accident: 29.01.2017

Dear Mr Guo Qiang,

As spoken, kindly refer to the attached estimate for finalise.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17001266MFSH
Our Ref: CS/FC117002026/Gtb

Date: 13 February 2017

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJS 6751H.

We thank you for the instruction on 01/02/2017.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 07/02/2017 at the premises of CHEW GOON MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,881.40</u>
Revised Estimate Amount	: S\$ <u>5,308.20</u>
"Check" Items Amount	: S\$ <u>243.20</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully

XING GUO QIANG
Automotive Assessor

IDENTITY CARD NO. S8420246J



Name

AINISHIKIN BINTE SAIARI

Race

JAVANESE

Date of birth

06-07-1984

Sex

F

Country/Place of birth

SINGAPORE



S8420246J



NRIC No. S8420246J



Date of issue
06-02-2015

Address

APT BLK 329A ANCHORVALE STREET
#12-501
SINGAPORE 541329

5421562

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

10 Oct 2007

Class 3A. Motor cars without clutch pedals (Auto) <= 3000kg
with <= 7 passengers, exclusive of the driver; and
other motor vehicles without clutch pedals <= 2500kg



Licence No: S8420246J

NP 428A



THE SCHEDULE

Private Car Insurance Policy

This Policy sets out the terms of a contract between NTUC Income Insurance Co-operative Limited (NTUC INCOME) and you (the Policyholder named in the schedule to this Policy).

The statements, information and declaration provided by you at the time of proposal shall form the basis of this contract. We (NTUC INCOME) will provide the insurance set out in this Policy in respect of events occurring during the Period of Insurance shown in the Schedule and any further period for which we may accept a renewal premium.

The provision of this insurance is subject to:

1. any Endorsement specified as operative in the Schedule
2. the Conditions and General Exclusions of this Policy, and
3. the payment of the premium specified in the Schedule.

This Policy, the Schedule and the Certificate of Insurance are to be read together as one document.

GST Reg No. M4-0003030-8

Policy Number	: 5061368808-03		
The Policyholder	: EZZUDDIN BIN ABDUL MUTTALIP		
	BLK 236 #04-589		
	TAMPINES STREET 21		
	SINGAPORE 520236		
Period of Insurance	: 27 Aug 2016 To 26 Aug 2017		
Sum Insured	: Market Value of Insured Vehicle at Time of Loss		
Premium (inclusive GST)	: S\$635.69		
Interest Insured			
Cover Type	: drivo CLASSIC		
Primary Driver	: SAIARI BIN SAKWAN		
Named Driver (1)	: AINISHIKIN BINTE SAIARI		
Named Driver (2)	: N/A		
Make/Model	: HONDA/FIT	Capacity	: 1339cc
Registration Number	: SJ56751H	Registration Date	: 27 Aug 2009
Chassis Number	: GE61172394	Off-peak Car	: Yes
Repair at Owner's Preferred Workshop	: No	Insure with COE	: Yes
Excess (Section 1)	: S\$600	NCD Entitlement	: 20%
Excess (Section 2)	: N/A	NCD Protection	: No
Windscreen Excess	: S\$100	Loyalty Discount	: 5%
Additional Excess	: N/A		
Unnamed Driver Excess	: Please refer to Terms and Conditions		
Hire Purchase Company	: DBS BANK LTD		
Optional Cover			
Transport Allowance	: No		
Excess Waiver	: No		

Memo A : N/A

Endorsement Operative : N/A

Agency	: SAFE HARBOUR AGENCY PTE. LTD. (00000572237)
Date of issue	: 10 Aug 2016 17:20 hrs

DUTY OF DISCLOSURE

We would remind you that you must disclose to us, fully and faithfully, the facts you know or ought to know, otherwise you may not receive any benefit from your Policy.

Signed in Singapore by order of the Board of Directors



Chief Executive

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 0499G

Vehicle Details

Vehicle No.: SJS6751H

Vehicle to be Exported: No

Intended De-registration
Date: 01 Feb 2017

Vehicle Make: HONDA

Vehicle Model: FIT 1.3G A

Primary Colour: Silver

Manufacturing Year: 2009

Engine No.: L13A4188597

Chassis No.: GE61172394

Maximum Power Output: 73.0 kW (97 bhp)

Open Market Value: \$13,892.00

Original Registration
Date: 27 Aug 2009

First Registration Date: 27 Aug 2009

Transfer Count: 0

Actual ARF Paid: \$11,911.00

OPC Cash Rebate DetailsOPC Cash Rebate
Eligibility: NoOPC Cash Rebate
Eligibility Expiry Date: -OPC Cash Rebate
Amount: -**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 26 Aug 2019

PARF Rebate Amount: \$7,146.00

Intended COE Rebate Details

COE Expiry Date: 26 Aug 2019

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$0.00

COE Rebate Amount: \$0.00

Total Rebate Amount: \$7,146.00

The information contained herein is correct as at 01 Feb 2017

OK

Land Transport Authority

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: First Capital Insurance Limited

Policy No: Third Party

Date: 06.02.2017

Accident Date : 29.01.2017

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Honda Fit" Reg. No. SJS6751H Claiming Against Your Insured Veh. No. SHA9848L			
1pc	Tailgate / <i>huc</i>		846.00
1pc	Tailgate Glass Moulding (Top) / <i>huc</i>		75.00
1pc	Tailgate Glass Lower Moulding / <i>huc</i>		38.00
1pc	Tailgate Emblem / <i>huc</i>		27.50
1pc	Tailgate Badge "Fit" / <i>huc</i>		38.00
1pc	Tailgate Lock / <i>huc</i>		210.00
1pc	Tailgate Trim Board / <i>huc</i>		110.00
10pcs	Tailgate Trim Board Clips / <i>huc</i>	6.00	60.00
1pc	Tailgate Weatherstrip / <i>huc</i>		102.00
1pc	Tailgate Stopper LH / <i>huc</i>		8.00
1pc	Rear Bumper / <i>huc</i>		520.00
10pcs	Rear Bumper Clips / <i>huc</i>	3.80	38.00
2pcs	Rear Bumper Brackets / <i>huc</i>	18.00	36.00
1pc	Rear Bumper Tow Cover / <i>huc</i>		14.50
2pcs	Rear Bumper Corner Holders / <i>huc</i>	18.00	36.00
2pcs	Taillamps Assy / <i>huc</i>	225.00	450.00
2pcs	Taillamp Gaskets / <i>huc</i>	25.00	50.00
2pcs	Taillamp Lock Clips / <i>huc</i>	6.00	24.00
4pcs	End Panel / <i>huc</i>		304.00
1pc	End Panel Garnish / <i>huc</i>		65.00
2pcs	Rear Fender Trim Boards / <i>huc</i>	270.00	540.00
1pc	Spare Tyre Top Board / <i>huc</i>		216.00
	Less 20%		3,808.00
			761.60
			3,046.40
1pc	Tailgate Glass Sealant / <i>huc</i>		50.00 SN
1pc	Tailgate Glass Sealer / <i>huc</i>		30.00 SN
1pc	Tailgate Glass Fastener / <i>huc</i>		50.00 SN
1pc	Roadside Assist Signage / <i>huc</i>		45.00 SN
2pcs	Tailgate Reflector Stickers / <i>huc</i>	15.00	30.00 SN
1pc	Rear Number Plate / <i>huc</i>		45.00 SN
1pc	Rear Number Plate Seal Pin / <i>huc</i>		25.00 SN
1pc	Rear Bumper Reverse Sensor / <i>huc</i>		200.00 SN
	To Dismantle / Refit Tailgate Fittings / Ancillary Accessories		60 150.00
	To Dismantle / Refit Tailgate Glass		100 160.00
	To Supply End Panel Joint Sealant		40 50.00
		C/F	3,961.40

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: First Capital Insurance Limited

Policy No: Third Party

Accident Date : 29.01.2017

Date: 06.02.2017

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Honda Fit" Reg. No. SJS6751H Claiming Against Your Insured Veh. No. SHA9848L			
1pc	Tailgate / <i>huc</i>		846.00
1pc	Tailgate Glass Moulding (Top)		75.00
1pc	Tailgate Glass Lower Moulding		38.00
1pc	Tailgate Emblem		27.50
1pc	Tailgate Badge "Fit"		38.00
1pc	Tailgate Lock		210.00
1pc	Tailgate Trim Board		110.00
10pcs	Tailgate Trim Board Clips	6.00	60.00
1pc	Tailgate Weatherstrip		102.00
1pc	Tailgate Stopper LH		8.00
1pc	Rear Bumper		520.00
10pcs	Rear Bumper Clips	3.80	38.00
2pcs	Rear Bumper Brackets	18.00	36.00
1pc	Rear Bumper Tow Cover		14.50
2pcs	Rear Bumper Corner Holders	18.00	36.00
2pcs	Taillamps Assy	225.00	450.00
2pcs	Taillamp Gaskets	25.00	50.00
4pcs	Taillamp Lock Clips	6.00	24.00
1pc	End Panel		304.00
1pc	End Panel Garnish		65.00
2pcs	Rear Fender Trim Boards	270.00	540.00
1pc	Spare Tyre Top Board		216.00
	Less 20%		3,808.00
			761.60
			3,046.40
1pc	Tailgate Glass Sealant		50.00 SN
1pc	Tailgate Glass Sealer		30.00 SN
1pc	Tailgate Glass Fastener		50.00 SN
1pc	Roadside Assist Signage		45.00 SN
2pcs	Tailgate Reflector Stickers	15.00	30.00 SN
1pc	Rear Number Plate		45.00 SN
1pc	Rear Number Plate Seal Pin		25.00 SN
1pc	Rear Bumper Reverse Sensor		280.00 SN
	To Dismantle / Refit Tailgate Fittings / Ancillary Accessories		150.00
	To Dismantle / Refit Tailgate Glass		160.00
	To Supply End Panel Joint Sealant		50.00
		C/F	3,961.40

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: First Capital Insurance Limited

Accident Date : 29.01.2017

Policy No: Third Party

Date: 06.02.2017

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Honda Fit" Reg. No. SJS6751H Claiming Against Your Insured Veh. No. SHA9848L		
		B/F	3,961.40
	To Conduct Electrical Check, Replace Reverse Sensors, Module, Rewiring Etc		26 120.00
	To Dismantle / Transfer Rear Spare Tyre Panel Inner Trims Boards / Garnish and Rear Fenders Inner Trims Boards / Garnish to Facilitate Repair		60 120.00
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		60 100.00
	To Seek Approval from LTA for Removal of Redplate Pin and to Supply Off Peak Supplementary License Coupon to transport vehicle from Workshop to Vicom Inspection Centre for Reseal and Inspection.		1 120.00
	To Provide Transportation (Towing)		50 60.00
	Labour Charge - Panel Beating, Repairing Of Rear Chassis Member, Inner Panel, Spare Tyre Panel Etc. Cut, Weld End Panel and Parts Replacement		1,300.00 400 600
	To Respray Affected Areas		800 1,100.00
		Total :	<u>6,881.40</u>
			1950

5298.6
20%: 4200

54-6 Days.
Lump Sum Repair
After repair photos.

07/2/17

Gmo Qiang - 82880382

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17002026/Gtbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 30-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9848L	Veh. Inspected	SJS 6751H	
Policy No.	D-17086801MFSH	Coverage (\$)	0.00	
Claim No.	D17001266MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	01/02/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	GE61172394	Colour	SILVER	
Odometer	64842	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	CST	6 mm	
L/H Front Tyre	195/60 R15	CST	6 mm	
R/H Rear Tyre	195/60 R15	CST	6 mm	
L/H Rear Tyre	195/60 R15	CST	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/01/2017	Inspection Date	07/02/2017	
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 6751H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	BUCKLED	846.00	846.00
1	TAILGATE GLASS MOULDING (TOP)	NECESSARY	75.00	75.00
1	TAILGATE GLASS LOWER MOULDING	NECESSARY	38.00	38.00
1	TAILGATE EMBLEM	NECESSARY	27.50	27.50
1	TAILGATE BADGE "FIT"	NECESSARY	38.00	38.00
1	TAILGATE LOCK	CUT	210.00	210.00
1	TAILGATE TRIM BOARD	DEFORMED	110.00	110.00
10	TAILGATE TRIM BOARD CLIPS @\$6.00	NECESSARY	60.00	60.00
1	TAILGATE WEATHERSTRIP	TORN	102.00	102.00
1	TAILGATE STOPPER LH	MISSING	8.00	8.00
1	REAR BUMPER	DEFORMED	520.00	520.00
10	REAR BUMPER CLIPS @\$3.80	NECESSARY	38.00	38.00
2	REAR BUMPER BRACKETS @\$18.00	NOT NECESSARY	36.00	-
1	REAR BUMPER TOW COVER	MISSING	14.50	14.50
2	REAR BUMPER CORNER HOLDERS @\$18.00	NECESSARY	36.00	36.00
2	TAILLAMPS ASSY @\$225.00	CRACKED	450.00	450.00
2	TAILLAMP GASKETS @\$25.00	NECESSARY	50.00	50.00
4	TAILLAMP LOCK CLIPS @\$6.00	NECESSARY	24.00	24.00
1	END PANEL	DENTED	304.00	304.00
1	END PANEL GARNISH	DEFORMED	65.00	65.00
2	REAR FENDER TRIM BOARDS @\$270.00	CRACKED	540.00	540.00
1	SPARE TYRE TOP BOARD	TORN	216.00	216.00
	LESS 20% DISCOUNT		-761.60	-754.40
			3,046.40	3,017.60
SPECIAL NETT ITEMS				
1	TAILGATE GLASS SEALANT (SN)	NECESSARY	50.00	20.00
1	TAILGATE GLASS SEALER (SN)	NECESSARY	30.00	20.00
1	TAILGATE GLASS FASTENER (SN)	NECESSARY	50.00	20.00
1	ROADSIDE ASSIST SIGNAGE (SN)	CRACKED	45.00	30.00
2	TAILGATE REFLECTOR STICKERS @\$15.00 (SN)	NOT NECESSARY	30.00	-

Report Ref No. CS/FCI17002026/Gtbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE (SN)	NECESSARY	45.00	25.00
1	REAR NUMBER PLATE SEAL PIN (SN)	NECESSARY	25.00	16.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
			555.00	331.00
	LABOUR			
	TO DISMANTLE/REFIT TAILGATE FITTINGS/ANCILLARY ACCESSORIES.		150.00	60.00
	TO DISMANTLE/REFIT TAILGATE GLASS.		160.00	100.00
	TO SUPPLY END PANEL JOINT SEALANT.		50.00	40.00
	TO CONDUCT ELECTRICAL CHECK,REPLACE REVERSE SENSORS,MODULE,REWIRING ETC.		120.00	60.00
	TO DISMANTLE/TRANSFER REAR SPARE TYRE PANEL INNER TRIMS BOARDS/GARNISH AND REAR FENDERS INNER TRIMS BOARDS/GARNISH TO FACILITATE REPAIR.		120.00	60.00
	TO APPLY RUST PROOFING/RESEAL TUFF COATING TREATMENT TO RESPRAY/REPLACED/REPAIR PANEL.		100.00	60.00
	TO SEEK APPROVAL FROM LTA FOR REMOVAL OF REDPLATE PIN AND TO SUPPLY OFF PEAK SUPPLEMENTARY LICENSE COUPON TO TRANSPORT VEHICLE FROM WORKSHOP TO VICOM INSPECTION CENTRE FOR RESEAL AND INSPECTION.		120.00	120.00
	TO PROVIDE TRANSPORTATION (TOWING).		60.00	50.00
	LABOUR CHARGE-PANEL BEATING,REPAIRING OF REAR CHASSIS MEMBER,INNER PANEL,SPARE TYRE PANEL ETC.CUT,WELD END PANEL AND PARTS REPLACEMENT.		1,300.00	600.00
	TO RESPRAY AFFECTED AREA.		1,100.00	800.00
			3,280.00	1,950.00
GRAND TOTAL			6,881.40	5,298.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,200.00

Report Ref No. CS/FC17002026/Gtbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.