

22/03/2007

ASS. REC. BY:

REF:

CS/SM017002640

Ggh332

Special Instruction:

Arveyor:

Gwo Gwang

ASSIGNMENT (Office)

From (Person):

rene

of

SMO

Date/Time:

9/2/07 1.35pm

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 5593G

Insured:

SOG5808J

at Workshop m/s

Vermagen

Tel:

644 4919 / 69044596 Pila

of

8 Kati Bukit A24 # 06-21

Policy No:

Claim No:

CM1D1700484 / THE

Sum Insured:

Excess:

Make of Veh:

D.O.A.

14/1/2016

(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

9/2/2017 1.55pm

Person Contacted:

Lina

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKU 5593G - A

SOG5808 J - X

## ASSIGNMENT

From: \_\_\_\_\_ Date: 9/2/2017

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKU 55936

at Workshop m/s

of

vermogen  
8kaki Bukit Ave 4 # 06-21

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKU 55936 Yr Regn: 31 Jul 2015Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c. 1598Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 124783 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MRO53REH104. 535850Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mm

D.O.A. \_\_\_\_\_

Rear

R/Bal. 7 mmL/Bal. 7 mmD.O.I. 09-02-17Survey held at w/sDes. of Damages: Frt + Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
18/2/17	email preli to Irene.

12/2/18 L/S @ 3,150 (Red 110810 0.77%)

12/2/18 File pass to Typist

RECEIVED 12 FEB 2018

Date/Time, File Pass to?

1) Typist - 12/2/18

Date/Time, File Return to?

2) \_\_\_\_\_



: Preli. Report



: Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: \_\_\_\_\_



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee: 350

Transportation: \_\_\_\_\_

S + RS, SI

Photos

Others

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PTE LTD		Ref : CS/SMO17002640/Ggh3		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 09-02-2017		
		Code : SMO		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SGG 5808J	Veh. Inspected	SKU 5593G	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1700484/THE	Excess (\$)	0.00	
Assign From	IRENE	Assign Date	09/02/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	14/11/2016	Inspection Date	09/02/2017	
Survey held at	8 KAKI BUKIT AVE 4 #06-21 PREMIER			
Repairer	VERMOGEN ACE PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



## Guo Qiang (LKKAUTO)

---

**From:** Norrita (LKKAUTO)  
**Sent:** Monday, 12 February, 2018 8:55 AM  
**To:** Guo Qiang (LKKAUTO)  
**Subject:** FW: Vehicle SKU5593G\_Agreed Finalised COR  
**Attachments:** SKU 5593G\_FINALISE.pdf

Dear Guo Qiang

FYI

Best Regards,

Rita AB |

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Zolar Auto Services [<mailto:zolar.auto@gmail.com>]  
**Sent:** Friday, 9 February 2018 7:25 PM  
**To:** Guo Qiang (LKKAUTO) <[GuoQiang@lkkauto.com](mailto:GuoQiang@lkkauto.com)>  
**Cc:** Norrita (LKKAUTO) <[norrita@lkkauto.com](mailto:norrita@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Mei Yan VMG <[pila.vermogenace@gmail.com](mailto:pila.vermogenace@gmail.com)>; Minoko VMG <[minokovermogenace@gmail.com](mailto:minokovermogenace@gmail.com)>; ezelvermogenace@gmail.com; VMG <[vermogenace@gmail.com](mailto:vermogenace@gmail.com)>; Zolar Auto Services <[zolar.auto@gmail.com](mailto:zolar.auto@gmail.com)>; Luis VMG <[luis.vermogenace@gmail.com](mailto:luis.vermogenace@gmail.com)>  
**Subject:** Fwd: Vehicle SKU5593G\_Agreed Finalised COR

Dear Guo Qiang,

In view of the price adjustment on the List Item.

We agreed and accept your finalised L/S COR @ S\$3,150.00 (Before GST) with 5 days (Excl. PRS/RS/PH/Weekend losses)

Thank you.

Warmest regards,

Marc  
+65 9146 1186  
Zolar Auto Services

Begin forwarded message:

**From:** "Guo Qiang (LKKAUTO)" <[GuoQiang@lkkauto.com](mailto:GuoQiang@lkkauto.com)>  
**Date:** 9 February 2018 at 16:10:54 SGT  
**To:** "zolar.auto@gmail.com" <[zolar.auto@gmail.com](mailto:zolar.auto@gmail.com)>  
**Cc:** "pila.vermogenace@gmail.com" <[pila.vermogenace@gmail.com](mailto:pila.vermogenace@gmail.com)>, "Norrita (LKKAUTO)" <[norrita@lkkauto.com](mailto:norrita@lkkauto.com)>, SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** Vehicle SKU 5593G

**Norrita (LKKAUTO)**

---

**From:** Norrita (LKKAUTO)  
**Sent:** Friday, 2 February 2018 11:31 AM  
**To:** 'vermogenace@gmail.com'  
**Cc:** SUR; Guo Qiang (LKKAUTO)  
**Subject:** Re : Vehicle No : SKU 5593G

Dear Sir /Madam

Please confirm this amount \$ 3,150.00 , repair 5 days for Vehicle SKU 5593G.

Kindly revert at the earliest.

Looking forward to hear from you soon.

Best Regards,

**Rita AB |**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Ai Phing (LKKAUTO)

---

**From:** Ai Phing (LKKAUTO)  
**Sent:** Monday, 13 February, 2017 10:37 AM  
**To:** 'Henry, Irene James'  
**Cc:** SUR  
**Subject:** RE: Somp - Pre Repair Notification For SKU5593G / YOUR REF: SGG5808J  
**Attachments:** SKU 5593G.pdf

Dear Irene,

Enclosed herewith preliminary advise of vehicle SKU 5593G.

*"Wishing you a Happiness and Prosperity New Year"*

Best Regards,

**Ai Phing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Thursday, 9 February, 2017 1:57 PM  
**To:** 'Henry, Irene James' <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: Somp - Pre Repair Notification For SKU5593G / YOUR REF: SGG5808J

Dear Irene,

Thank you for the assignment.

*"WISHING YOU A HAPPINESS AND PROSPERITY NEW YEAR"*

Best Regards,

**Ashley Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Henry, Irene James [<mailto:irene.henry@sompo.com.sg>]  
**Sent:** Thursday, 9 February, 2017 1:35 PM  
**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com)  
**Cc:** Catherine Chong (LKK Auto)  
**Subject:** FW: Somp - Pre Repair Notification For SKU5593G / YOUR REF: SGG5808J

## Ashley Chong (LKK Auto)

---

**From:** Henry, Irene James <irene.henry@sompo.com.sg>  
**Sent:** Thursday, 9 February, 2017 1:35 PM  
**To:** assignments@lkkauto.com  
**Cc:** Catherine Chong (LKK Auto)  
**Subject:** FW: Somo - Pre Repair Notification For SKU5593G / YOUR REF: SGG5808J  
**Attachments:** SKU5593G 20161114 TP.PDF

Our Reference: CMTD1700484/THE

Hi,

Kindly assign your surveyor to conduct motor survey of the mentioned (SKU 5593G).

Please refer to the email correspondence as below.

Best Regards

**Irene Henry**

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** Lina Rosli [mailto:linavermogenace@gmail.com]

**Sent:** Thursday, February 09, 2017 12:58 PM

**To:** Henry, Irene James

**Cc:** Vermogen ACE (vermogenace@gmail.com); Minoko Chan; Choo, Thelma

**Subject:** Re: Somo - Pre Repair Notification For SKU5593G / YOUR REF: SGG5808J

WITHOUT PREJUDICE

Dear Arrange Survey Dept,

Kindly arrange LKK for TP survey on **09/2/2017 (THURSDAY)** following detail & attach here GIA report.



Survey before repair

Our Client's Vehicle: SKU5593G

Your Client's Vehicle: SGG5808J

Location:

NO. 8 KAKI BUKIT AVENUE 4 #06-21 PREMIER@KAKI BUKIT (GATE2) SINGAPORE 415875

Kindly arrange as soon as possible. Appreciate with thanks

---

Dear Officer In-charge,

Please let us know what is the liability?

Kindly check & revert, with thanks.

Best Regards,

Lina R.



Vermogen Ace Pte Ltd  
1 Bukit Batok Crescent  
#05-23 Wcega Plaza  
Singapore 658064  
Tel: 6694 4919  
Fax: 6694 4929

On Thu, Feb 9, 2017 at 11:49 AM, Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)> wrote:

Our Reference: CMTD1700484/THE

Your Reference: SKU 5593G

Date: 09<sup>th</sup> February 2017

Without Prejudice

M/S VERMOGEN ACE PTE LTD

Dear Sir

We refer to your Notice of Accident dated 08/02/2017.

Please be informed that Thelma Choo is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	

		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** Lina Rosli [<mailto:linavermogenace@gmail.com>]

**Sent:** Wednesday, February 08, 2017 11:16 PM

**To:** Motor Survey

**Cc:** Vermogen ACE ([vermogenace@gmail.com](mailto:vermogenace@gmail.com)); Minoko Chan

**Subject:** Sompo - Pre Repair Notification For SKU5593G / YOUR REF: SGG5808J

WITHOUT PREJUDICE

Dear Sir/Mdm,

We attached our notification notice of accident for your attention.

Our Client's Vehicle: SKU5593G

Your Client's Vehicle: SGG5808J


Location:

NO. 8 KAKI BUKIT AVENUE 4 #06-21 PREMIER@KAKI BUKIT (GATE2) SINGAPORE 415875

Looking forward to hear from you, for the surveyor name within the next 2 working days.

Best Regards,

Lina R.



Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Weega Plaza

Singapore 658064

Tel: 6694 4919

Fax: 6694 4929

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/01/2017 17:07
Date Of Accident	14/11/2016 18:20
Exact Location Of Accident	BKE BEFORE SLE
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU5593G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LION CITY RENTALS PTE LTD
Co Reg No	201504621K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-90074443
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car

### Insurance Company

Name of Insurance Company	ERGO Insurance Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMPF16S001858
Cover Note Number	

### Driver

Name of Driver	MUHAMMAD FAQIEH BIN UBAIDILLAH
NRIC No	S9437897D
Date Of Birth	15/10/1994
Occupation	Outdoor
Date Of Driving Pass	22/07/2013
Driving Experience	3 Years And 3 Months
Gender	Male
Mobile Number	(Local) +65-90074443
Fax Number	
Contact Number	
EMail Address	FAQIEH@HOTMAIL.SG

Address

Postcode

Was driver an employee of the Insured's Company No  
If No, Relationship of the Driver with the Insured Other - HIRER

Vehicle Registration Number of Driver's Own Vehicle -  
-  
-

Insurance Company of Driver's Own Vehicle -  
-  
-

#### General Information of the Accident

Type Of Accident Collision- Chain Collision  
Weather Conditions LIGHT RAINS  
Road Surface Dry

#### Other Information

Was any foreign vehicle involved in this accident? No  
Was any body injured in the Accident? No  
Was any other material or property damaged? Yes  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. No  
Number of Passengers (Including Driver) 2

#### Details of Police Action

Was the accident reported to the police? No  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? No  
If Yes, against whom?

#### Circumstances of Accident

PLEASE REFER TO ATTACHMENT

#### Attachment(s)

Are accident photos available for attachment? Yes  
Was there any video captured by Car Camera? No  
Was there any audio recorded? No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGG5808J  
Vehicle Make/Model/Colour  
Details Of Properties  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### Details of Witness

Name  
Phone Number  
Email Address

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJG8613Z  
Vehicle Make/Model/Colour

### Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

### Details of Witness

Name

Phone Number

Email Address



## Sketch Plan Pg.1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time


X

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

#### Sketch Plan



(A) SKU55936

(B) SG45808J

(C) SJ68613Z

## Sketch Plan Pg.2

### Describe Circumstances of the Accident

Driving along RFE to SLE when car SJG 8613Z jammed  
brake and I also jammed brake and bumped into the  
first car followed by a second car JG-G 6808J that  
bumped into the rear of my car.

### Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &  
Time

Driver's Signature (If driver is not the policy holder) / Date  
& Time

Witnessed by Reporting Centre  
Personnel



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1700484/THE

Date: 13-02-2017

Our Ref: CS/SMO17002640/Ggh3

The Motor Claims Department  
Sompo Insurance Pte Ltd

**Without Prejudice**

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. SKU 5593G.**

Please be informed that we had conducted the inspection of the above mentioned vehicle on 09-02-2017 at the premises of M/s VERMOGEN ACE and have the following to report:-

Workshop Estimate Amount	: S\$ 14,231.10
Revised Estimate Amount	: S\$ 4,048.65
"Check" Items Amount	: S\$ 2,105.40
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

**Description of Damage:**

The vehicle sustained damages at the front and rear portion.



**Comments/ Present Status:**

Damages Consistent.

Yours faithfully

Xing Guo Qiang  
Automotive Assessor



# SKU55 3G

Vermogen ACE Pte Ltd  
1 Bukit Batok Crescent #04-54/55 Wcega Plaza 658064  
Tel : 6515 5230 Fax : 6515 5207  
Email: vermogenace@gmail.com  
Reg No : 201606023C

PRS by : .....

R-S Date : .....

Date : 8-Feb-17

Registration no. : SKU5593G / Toyota Altis

DOA : Estimate No. : VMG045\_SKU5593R\_ALTIS

S/N	Qty	Item	Amount
-----	-----	------	--------

## LIST ITEMS

1	1	Bootlid <i>X repair</i>	1493.00 <i>X</i>
2	1	Bootlid logo <i>/</i>	59.90 <i>/</i>
3	1	Bootlid emblem Corolla <i>=</i>	66.80 <i>/</i>
4	1	Bootlid emblem ALTIS <i>=</i>	68.50 <i>/</i>
5	1	Bootlid outer chrome moulding <i>X</i>	214.50 <i>X</i>
6	1	Bootlid lock switch <i>X</i>	198.00 <i>X</i>
7	1	Bootlid weatherstrip <i>X</i>	211.60 <i>X</i>
8	2	Bootlid hinges @ \$187.00 <i>X</i>	374.00 <i>X</i>
9	1	Rear bumper <i>/</i>	1085.90 <i>591.62</i>
10	2	Rear bumper reflector @ \$157.80 <i>X</i>	315.60 <i>X</i>
11	1	Rear end panel <i>X</i>	662.10 <i>X</i>
12	1	Rear end panel top garnish <i>X</i>	240.90 <i>X</i>
13	1set	Rear end panel top garnish clips <i>X</i>	35.00 <i>X</i>
14	2	Taillamp @ \$594.60 <i>X</i>	1189.20 <i>X</i>
15	1	Bonnet <i>X</i>	1128.10 <i>X</i>
16	2	Bonnet hinges @ \$ 85.50 <i>X</i>	171.00 <i>X</i>
17	1	Bonnet rubber <i>X</i>	69.00 <i>X</i>
18	1	Bonnet insulator <i>X</i>	192.30 <i>X</i>
19	1set	Bonnet insulator clips <i>X</i>	50.00 <i>X</i>
20	1	Bonnet lock <i>X</i>	197.70 <i>X</i>
21	1	Front grille base <i>? CBA</i>	595.00 <i>40.30</i>
22	1	Front grille chrome garnish <i>? X NV</i>	213.00 <i>X</i>
23	1set	Front grille clips <i>? CBA</i>	30.00 <i>/</i>
24	1	Front grille logo <i>? CBA</i>	37.20 <i>/</i>
25	2	Headlamp @ \$ 1420.60 <i>&lt; CH ? CBA</i>	2841.20 <i>1754.6</i>
26	2	Headlamp lower bracket @ \$ 72.00 <i>? X NV</i>	144.00 <i>X</i>
27	2	Headlamp chrome garnish @ \$ 101.50 <i>/</i>	203.00 <i>/</i>
28	2	Headlamp panel @ \$ 194.00 <i>X</i>	388.00 <i>X</i>
29	1	Front support top panel <i>X</i>	223.00 <i>X</i>
30	1	Front bumper <i>/</i>	569.70 <i>557.00</i>

- 31 1set Front bumper clips  
 32 2 Front bumper side retainer @ \$ 116.90  
 33 1 Front bumper reinforcement

66.9  
 NN

50.00  
 233.8 233.80 133.8  
 287.40  
 13838.40

Less 25%

3459.60  
 10378.80

SPECIAL NETT ITEMS

- 1 1 Sundries  
 2 1 Bootlid reflector seal LH  
 3 1 Taillamp seal LH  
 4 1 Taillamp base panel sealant LH  
 5 1 Reverse sensor  
 6 1 Front number plate  
 7 1 A/C compressor fluid  
 8 1 Radiator coolant

NN

60.00  
 40.00  
 50.00  
 40.00  
 442.30  
 60.00  
 80.00  
 60.00  
 832.30

**Parts Total**

11211.10

LABOUR & MISC CHARGES

- 1 1 Panel beating and strenghten parts on accident area.  
 2 1 Check wiring system after disconnect and connect.  
 3 1 R&R bootlid component  
 4 1 R&R reverse sensor and check  
 5 1 R&R a/c condenser and temperature test.  
 6 1 R&R radiator and pressure test.  
 7 1 To apply undercoating for rust roofing.  
 8 1 Spray painting on accident area.

1200.00  
 80.00  
 120.00  
 120.00  
 200.00  
 100.00  
 200.00  
 1000.00  
 3020.00

**Labour Total**

**Total Parts and Labour Cost of Repair**

14231.10  
 209,394.3

5 Days  
 Lumpsum Repair  
 After repair photo  
 Eric Qian - 82880282  
 09/02/17  
 13/2/17

Total: 3150

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



# SKU5593G

Vermogen ACE Pte Ltd  
Bukit Batok Crescent #04-54/55 Wcega Plaza 658064  
Tel : 6515 5230 Fax : 6515 5207  
Email : vermogenace@gmail.com  
Reg No : 201606023C

PRS by : .....

PRS Date : .....

R-S Date : .....

Date : 8-Feb-17

Registration no. : SKU5593G / Toyota Altis

Estimate No. : VMG045\_SKU5593R\_ALTIS

S/N	Qty	Item	Amount
-----	-----	------	--------

## LIST ITEMS

1	1	Bootlid X repair	1493.00 X
2	1	Bootlid logo /	59.90 /
3	1	Bootlid emblem Corolla = { MC	66.80 /
4	1	Bootlid emblem ALTIS =	68.50 /
5	1	Bootlid outer chrome moulding X	214.50 X
6	1	Bootlid lock switch X	198.00 X
7	1	Bootlid weatherstrip X	211.60 X
8	2	Bootlid hinges @ \$187.00 X	374.00 X
9	1	Rear bumper / ll	1085.90 511.62
10	2	Rear bumper reflector @ \$157.80 X	315.60 X
11	1	Rear end panel X	662.10 X
12	1	Rear end panel top garnish X	240.90 X
13	1set	Rear end panel top garnish clips X	35.00 X
14	2	Taillamp @ \$594.60 X	1189.20 X
15	1	Bonnet X	1128.10 X
16	2	Bonnet hinges @ \$ 85.50 X	171.00 X
17	1	Bonnet rubber X	69.00 X
18	1	Bonnet insulator X	192.30 X
19	1set	Bonnet insulator clips X	50.00 X
20	1	Bonnet lock X	197.70 X
21	1	Front grille base ?	595.00 40.30
22	1	Front grille chrome garnish ? X	213.00 X
23	1set	Front grille clips ?	30.00 /
24	1	Front grille logo ?	37.20 /
25	2	Headlamp @ \$ 1420.60 < MC / CRA	2841.20 1754.6
26	2	Headlamp lower bracket @ \$ 72.00 ? X	144.00 X
27	2	Headlamp chrome garnish @ \$ 101.50 / MC	203.00 /
28	2	Headlamp panel @ \$ 194.00 X { NN	388.00 X
29	1	Front support top panel X	223.00 X
30	1	Front bumper / ll	569.70 557.00



# SKU5593G

Vermogen ACE Pte Ltd  
1 Bukit Batok Crescent #04-54/55 Wcega Plaza 658064  
Tel : 6515 5230 Fax : 6515 5207  
Email: vermogenace@gmail.com  
Reg No : 201606023C

PRS by : .....

PRS Date : .....

R-S Date : .....

Date : 8-Feb-17

Registration no. : SKU5593G / Toyota Altis

Estimate No. : VMG045\_SKU5593G\_ALTIS

DOA :

S/N	Qty	Item	Amount
-----	-----	------	--------

## LIST ITEMS

1	1	Bootlid <del>X</del> repair	1493.00
2	1	Bootlid logo /	59.90
3	1	Bootlid emblem Corolla /	66.80
4	1	Bootlid emblem ALTIS /	68.50
5	1	Bootlid outer chrome moulding X	214.50
6	1	Bootlid lock switch X	198.00
7	1	Bootlid weatherstrip X	211.60
8	2	Bootlid hinges @ \$187.00 X	374.00
9	1	Rear bumper /	1085.90
10	2	Rear bumper reflector @ \$157.80 X	315.60
11	1	Rear end panel X	662.10
12	1	Rear end panel top garnish X	240.90
13	1set	Rear end panel top garnish clips X	35.00
14	2	Taillamp @ \$594.60 X	1189.20
15	1	Bonnet X	1128.10
16	2	Bonnet hinges @ \$ 85.50 X	171.00
17	1	Bonnet rubber X	69.00
18	1	Bonnet insulator X	192.30
19	1set	Bonnet insulator clips X	50.00
20	1	Bonnet lock X	197.70
21	1	Front grille base P /	595.00
22	1	Front grille chrome garnish X	213.00
23	1set	Front grille clips P /	30.00
24	1	Front grille logo P /	37.20
25	2	Headlamp @ \$ 1420.60 CH /	2841.20
26	2	Headlamp lower bracket @ \$ 72.00 X	144.00
27	2	Headlamp chrome garnish @ \$ 101.50 /	203.00
28	2	Headlamp panel @ \$ 194.00 X	388.00
29	1	Front support top panel X	223.00
30	1	Front bumper / de	569.70



31	1set	Front bumper clips	50.00	
32	2	Front bumper side retainer @ \$ 116.90	233.80	
33	1	Front bumper reinforcement	<del>287.40</del>	
			13838.40	6054

Less 25%

3459.60	1513.50
10378.80	4540.50

### SPECIAL NETT ITEMS

1	1	Sundries	<del>60.00</del>	
2	1	Bootlid reflector seal LH	<del>40.00</del>	
3	1	Taillamp seal LH	<del>50.00</del>	
4	1	Taillamp base panel sealant LH	<del>40.00</del>	
5	1	Reverse sensor	<del>442.30</del>	
6	1	Front number plate	60.00	
7	1	A/C compressor fluid	<del>80.00</del>	
8	1	Radiator coolant	<del>60.00</del>	
			832.30	60

Parts Total

11211.10	4600.50
----------	---------

### LABOUR & MISC CHARGES

1	1	Panel beating and strenghten parts on accident area.	1200.00	500
2	1	Check wiring system after disconnect and connect.	80.00	30
3	1	R&R bootlid component	<del>120.00</del>	X
4	1	R&R reverse sensor and check	120.00	40
5	1	R&R a/c condenser and temperature test.	<del>200.00</del>	X
6	1	R&R radiator and pressure test.	100.00	X
7	1	To apply undercoating for rust roofing.	<del>200.00</del>	X
8	1	Spray painting on accident area.	1000.00	500
			3020.00	4000.50

Labour Total

1170

Total Parts and Labour Cost of Repair

14231.10	5770.50
----------	---------

5 Days

lumpsum Repair

After repair photo

Eno Qiang - 82880282

09/02/17

L- 4540.50

SN- 60

L- 1170

5770.50

20%

4616.40

L/S - \$4600 / 5 days



## **Denise Tay (LKKAuto)**

---

**From:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Sent:** Wednesday, 7 February 2018 2:31 PM  
**To:** SUR  
**Subject:** RE: Arrange survey for Vehicle No. SJB 6075R

Hi  
Claim No: CLMOMVM0000000009  
Please provide latest update on this survey, thank you.

Regards  
Rachel Tan  
Executive, Motor Claims, Great American Insurance Company  
Tel: 6804 7846

---

**From:** Ashley Chong (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Friday, October 21, 2016 3:25 PM  
**To:** Goh, Stella <Stella.Goh@sg.gaig.com>; 'assignments' <assignments@lkkauto.com>  
**Cc:** 'KKLau' <kklau@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>; 'SUR' <sur@lkkauto.com>  
**Subject:** RE: Arrange survey for Vehicle No. SJB 6075R

Dear Stella,

Thank you for the assignment.

Kindly provide us claim number for this case.

Best Regards,  
**Ashley Chong** | Admin  
**LKK Auto Consultants Pte Ltd**  
Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Goh, Stella [mailto:Stella.Goh@sg.gaig.com]  
**Sent:** Friday, 21 October, 2016 3:19 PM  
**To:** Chia Sin Muk  
**Cc:** KKLau; Admin A; assignments  
**Subject:** RE: Arrange survey for Vehicle No. SJB 6075R

WITHOUT PREJUDICE

Dear Karen,

We refer to your email on even date.

We will appoint LKK to conduct the PRS.

2019  
CCV



SKU5593G

Vermogen ACE Pte Ltd  
1 Bukit Batok Crescent #04-54/55 Wcega Plaza 658064  
Tel : 6515 5230 Fax : 6515 5207  
Email: vermogenace@gmail.com  
Reg No : 201606023C

PRS by : .....

PRS Date : .....

R-S Date : .....

Date : 8-Feb-17

Registration no. : SKU5593G / Toyota Altis

DOA :

Estimate No. : VMG045\_SKU5593G\_ALTIS

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	1	Bootlid X repair	1493.00
2	1	Bootlid logo /	59.90
3	1	Bootlid emblem Corolla /	66.80
4	1	Bootlid emblem ALTIS /	68.50
5	1	Bootlid outer chrome moulding X	214.50
6	1	Bootlid lock switch X	198.00
7	1	Bootlid weatherstrip X	211.60
8	2	Bootlid hinges @ \$187.00 X	374.00
9	1	Rear bumper /	1085.90
10	2	Rear bumper reflector @ \$157.80 X	315.60
11	1	Rear end panel X	662.10
12	1	Rear end panel top garnish X	240.90
13	1set	Rear end panel top garnish clips X	35.00
14	2	Taillamp @ \$594.60 X	1189.20
15	1	Bonnet X	1128.10
16	2	Bonnet hinges @ \$ 85.50 X	171.00
17	1	Bonnet rubber X	69.00
18	1	Bonnet insulator X	192.30
19	1set	Bonnet insulator clips X	50.00
20	1	Bonnet lock X	197.70
21	1	Front grille base P /	595.00
22	1	Front grille chrome garnish X	213.00
23	1set	Front grille clips P /	30.00
24	1	Front grille logo P /	37.20
25	2	Headlamp @ \$ 1420.60 CH /	2841.20
26	2	Headlamp lower bracket @ \$ 72.00 X	144.00
27	2	Headlamp chrome garnish @ \$ 101.50 /	203.00
28	2	Headlamp panel @ \$ 194.00 X	388.00
29	1	Front support top panel X	223.00
30	1	Front bumper / re	569.70

- 31 1set Front bumper clips ✓  
 32 2 Front bumper side retainer @ \$ 116.90 ✓  
 33 1 Front bumper reinforcement X

50.00  
 233.80  
~~287.40~~  
 13838.40 6054

Less 25%

3459.60 1513.50  
 10378.80 4540.50

SPECIAL NETT ITEMS

- 1 1 Sundries X  
 2 1 Bootlid reflector seal LH X  
 3 1 Taillamp seal LH X  
 4 1 Taillamp base panel sealant LH X  
 5 1 Reverse sensor X  
 6 1 Front number plate ✓  
 7 1 A/C compressor fluid X  
 8 1 Radiator coolant X

60.00  
~~40.00~~  
~~50.00~~  
~~40.00~~  
~~442.30~~  
~~60.00~~  
~~80.00~~  
~~60.00~~  
 832.30 60  
 11211.10 4600.50

Parts Total

LABOUR & MISC CHARGES

- 1 1 Panel beating and strenghten parts on accident area.  
 2 1 Check wiring system after disconnect and connect.  
 3 1 R&R bootlid component  
 4 1 R&R reverse sensor and check  
 5 1 R&R a/c condenser and temperature test.  
 6 1 R&R radiator and pressure test.  
 7 1 To apply undercoating for rust roofing.  
 8 1 Spray painting on accident area.

1200.00 500  
 80.00 30  
~~120.00~~ X  
 120.00 40  
~~200.00~~ X  
 100.00 X  
~~200.00~~ X  
 1000.00 500  
 1170 3020.00 600

Labour Total

Total Parts and Labour Cost of Repair

14231.10 5770.50

5 Days.

lumpsum repair

After repair photo

Eno Qiang - 82880282

09/02/17

L- 4540.50

SN- 60

L- 1170

5770.50

20%

4616.40

1/5 - \$4600 / 5 days.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17002640/Gnh3s2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 22-02-2018



Code : SMO

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGG 5808J	Veh. Inspected	SKU 5593G
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1700484/THE	Excess (\$)	0.00
Assign From	IRENE	Assign Date	09/02/2017

## 2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MR053REH104535850	Colour	SILVER
Odometer	124783	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	7 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	7 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	7 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	7 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	14/11/2016	Inspection Date	09/02/2017
Survey held at	8 KAKI BUKIT AVE 4 #06-21 PREMIER		
Repairer	VERMOGEN ACE PTE LTD		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 5593G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BOOTLID	TO REPAIR SEE LABOUR	1,493.00	-
1	BOOTLID LOGO	NECESSARY	59.90	59.90
1	BOOTLID EMBLEM COROLLA	NECESSARY	66.80	66.80
1	BOOTLID EMBLEM ALTIS	NECESSARY	68.50	68.50
1	BOOTLID OUTER CHROME MOULDING	NOT NECESSARY	214.50	-
1	BOOTLID LOCK SWITCH	NOT NECESSARY	198.00	-
1	BOOTLID WEATHERSTRIP	NOT NECESSARY	211.60	-
2	BOOTLID HINGES @ \$187.00	NOT NECESSARY	374.00	-
1	REAR BUMPER	DEFORMED	1,085.90	591.62
2	REAR BUMPER REFLECTOR @ \$157.80	NOT NECESSARY	315.60	-
1	REAR END PANEL	NOT NECESSARY	662.10	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	240.90	-
1	SET REAR END PANEL TOP GARNISH CLIPS	NOT NECESSARY	35.00	-
2	TAILLAMP @ \$594.60	NOT NECESSARY	1,189.20	-
1	BONNET	NOT NECESSARY	1,128.10	-
2	BONNET HINGES @ \$85.50	NOT NECESSARY	171.00	-
1	BONNET RUBBER	NOT NECESSARY	69.00	-
1	BONNET INSULATOR	NOT NECESSARY	192.30	-
1	SET BONNET INSULATOR CLIPS	NOT NECESSARY	50.00	-
1	BONNET LOCK	NOT NECESSARY	197.70	-
1	FRONT GRILLE BASE	CRACKED	595.00	410.30
1	FRONT GRILLE CHROME GARNISH	NOT NECESSARY	213.00	-
1	SET FRONT GRILLE CLIPS	NECESSARY	30.00	30.00
1	FRONT GRILLE LOGO	NECESSARY	37.20	37.20
2	HEADLAMP @ \$1420.60	CRACKED	2,841.20	1,754.60
2	HEADLAMP LOWER BRACKET @ \$72.00	NOT NECESSARY	144.00	-
2	HEADLAMP CHROME GARNISH @ \$101.50	NECESSARY	203.00	203.00
2	HEADLAMP PANEL @ \$194.00	NOT NECESSARY	388.00	-
1	FRONT SUPPORT TOP PANEL	NOT NECESSARY	223.00	-
1	FRONT BUMPER	DEFORMED	569.70	557.00
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
2	FRONT BUMPER SIDE RETAINER @ \$116.90	NECESSARY	233.80	133.80
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	287.40	-

Report Ref No. CS/SMO17002640/Gnh3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-3,459.60	-990.68
			10,378.80	2,972.04
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SUNDRIES (SN)	NOT NECESSARY	60.00	-
1	BOOTLID REFLECTOR SEAL LH (SN)	NOT NECESSARY	40.00	-
1	TAILLAMP SEAL LH (SN)	NOT NECESSARY	50.00	-
1	TAILLAMP BASE PANEL SEALANT LH (SN)	NOT NECESSARY	40.00	-
1	REVERSE SENSOR (SN)	NOT NECESSARY	442.30	-
1	FRONT NUMBER PLATE (SN)	BENT	60.00	40.00
1	A/C COMPRESSOR FLUID (SN)	NOT NECESSARY	80.00	-
1	RADIATOR COOLANT (SN)	NOT NECESSARY	60.00	-
			832.30	40.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING AND STRENGTHEN PARTS ON ACCIDENT AREA. INCLUSIVE OF THE REPAIR OF BOOTLID.		1,200.00	500.00
	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT.		80.00	30.00
	R&R BOOTLID COMPONENT.	NOT NECESSARY	120.00	-
	R&R REVERSE SENSOR AND CHECK.		120.00	40.00
	R&R A/C CONDENSER AND TEMPERATURE TEST.	NOT NECESSARY	200.00	-
	R&R RADIATOR AND PRESSURE TEST.	NOT NECESSARY	100.00	-
	TO APPLY UNDERCOATING FOR RUST PROOFING.	NOT NECESSARY	200.00	-
	SPRAY PAINTING ON ACCIDENT AREA.		1,000.00	400.00
			3,020.00	970.00
	<b>GRAND TOTAL</b>		<b>14,231.10</b>	<b>3,982.04</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,150.00</b>

Report Ref No. CS/SMO17002640/Gnh3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.