

ASS. REC. BY:

REF:

CS/CS17002736/eng^b17

Special Instruction:

Surveyor:

Quo Giang

ASSIGNMENT (Office)

From (Person):

Lionel Chua

of

ICS

Date/Time:

9/2/2017 5:53pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJL9784D

Insured:

GBC1762M

at Workshop m/s

SK Automobile

Tel:

921 0478

of

8 Kak, Bukit Ave 6 #08-46

Policy No:

Claim No:

DMCV1700014H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

8/2/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

(ap)

H.O.D. Endorsement:

Date/Time:

10/2/2017 9am

Person Contacted:

Song

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SJL9784D-x

GBC1762M-x

20/1/2017 2pm - Song said vehicle has been repaired. He will send finalize later.

ASSIGNMENT

From: Date 10/2/2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: S3A 9784D

at Workshop m/s SK Automobile
of 8 Kapi Bukit Ave 4 #08-46

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$22k.

DAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res: Yes or No

um Sum: 20 % 3 Val.: Yes or No

A / REV / REP. / 24 HRS Cup

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: S1A 9784D Yr Regn: 02 Jun 2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda city c.c 1497

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 175408 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRHEM 26509P020278

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/65R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A D.O.I. 10-02-17

Survey held at W/S 11:30 Am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/10 Finalized \$6150 with X'cap. (Red & 10717.04, 64%)

RECEIVED 10 OCT 2018

Date/Time, File Pass to?



Preli. Report

Date/Time, File Return to?



Final Report

Days Of Repair: 10

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Report Format:

Imp Sum / I.B.I. (\$

7P

6150

TOTAL

450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS/ICS17002736/Gqh3

7 TEMASEK BOULEVARD
#10-03 SUNTEC TOWER ONE
SINGAPORE 038987

Date : 10-02-2017



Code : ICS

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 1762M	Veh. Inspected	SJQ 9784D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	LIONEL CHUA	Assign Date	09/02/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	08/02/2017	Inspection Date	10/02/2017
Survey held at	8 KAKI BUKIT AVE 4 #08-46 PREMIER		
Repairer	SK AUTOMOBILE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Ashley Chong (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Thursday, 9 February, 2017 5:53 PM
To: admin@skauto.com.sg; assignments; Admin-D (LKKAuto)
Cc: ECICS Claims; Siva Venthan (ECICS, Operations / Claims); Phoebe Jay Xie (ECICS, Operations / Claims); SUR
Subject: RE: Arrange surveyor for SJQ9784D Your Ref:GBC1762M

Without Prejudice

Dear Huey Lee,

We shall be assigning your case to our surveyor from LKK was appointed to conduct a third party pre-repair inspection on your client motorcycle on a without prejudice basis.

Please furnish us a copy of repair quotation/estimate to show the detail of cost of repair breakdown for each item together with colour photographs of the damaged vehicle and the accident scene of all vehicles to evaluate transparency on the pre-repair survey of this claim.

Thank you.

Regards,
Lionel Chua
DID: +65 6303 0167
FAX: +65 6338 9267
ECICS LIMITED
Email: claims@ecics.com.sg

follow us on  facebook follow us on  twitter visit our website  ecics.com.sg

From: SK Admin [mailto:admin@skauto.com.sg]
Sent: Thursday, 9 February, 2017 5:36 PM
To: ECICS Claims
Cc: Siva Venthan (ECICS, Operations / Claims); Phoebe Jay Xie (ECICS, Operations / Claims)
Subject: Re: Arrange surveyor for SJQ9784D Your Ref:GBC1762M

Dear Lionel,

Thanks for the reply.
We choose surveyor: LKK Auto

--
Regards,
Huey Lee
SK Automobile Pte Ltd
Tel: 6789 5155 Fax: 6783 5155

On Thu, Feb 9, 2017 at 5:30 PM, ECICS Claims <claims@ecics.com.sg> wrote:

Without Prejudice

Dear Huey Lee,

We refer to the above accident.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in our list to conduct the joint pre-repair survey as a single joint expert.

Please let us know within 2 working days whether you are agreeable to the appointment of any these motor surveyors provided to you as a single joint expert. You may select one of the listed motor surveyors.

Our list of the survey firms for your nomination:

1. LKK
2. Formteam
3. Autoprobe
4. Raleigh
5. JP Knights

Please furnish us a copy of repair quotation/estimate to show the detail of cost of repair breakdown for each item together with colour photographs of the damaged vehicle and the accident scene of all vehicles to evaluate transparency on the pre- repair survey of this claim.

Thank you.

Regards,
Lionel Chua
DID: +65 6303 0167
FAX: +65 6338 9267
ECICS LIMITED

Email: claims@ecics.com.sg

Follow us on  facebook follow us on  twitter visit our website ecics.com.sg 

From: SK Admin [<mailto:admin@skauto.com.sg>]

Sent: Thursday, 9 February, 2017 3:42 PM

To: ECICS Claims; Siva Venthan (ECICS, Operations / Claims); Lionel Chua Kok Keong (ECICS, Operations / Claims); Phoebe Jay Xie (ECICS, Operations / Claims)

Subject: Arrange surveyor for SJQ9784D Your Ref:GBC1762M

Dear Sir/Mdm,


We the repairers of motor vehicle no. SJQ9784D
Kindly arrange surveyor to conduct a pre-repair inspection.

Location : 8 Kaki Bukit Ave 4#08-46
Premier @ Kaki Bukit
Singapore 415875


Contact No : 8121 0478 Xiong

We appreciate your early reply.
Thanks.

--
Regards,
Huey Lee
SK Automobile Pte Ltd
Tel: 6789 5155 Fax: 6783 5155



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Shiau Chan (LKKAUTO)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Thursday, 18 October 2018 10:23 AM
To: Shiau Chan (LKKAUTO)
Cc: ECICS Claims
Subject: RE: Arrange surveyor for SJQ9784D Your Ref:GBC1762M

Hi Shiau Chan

Our claim no DMCV1700014H.
Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Monday, 15 October, 2018 1:58 PM
To: ECICS Claims
Subject: RE: Arrange surveyor for SJQ9784D Your Ref:GBC1762M

Dear Sir/Madam,

Kindly assist to provide us the claim number of above mentioned.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ashley Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 10 February, 2017 9:05 AM
To: 'ECICS Claims' <claims@ecics.com.sg>; 'assignments' <assignments@lkkauto.com>
Cc: 'Siva Venthan (ECICS, Operations / Claims)' <Siva_Venthan@ecics.com.sg>; 'Phoebe Jay Xie (ECICS, Operations / Claims)' <PhoebeJay_Xie@ecics.com.sg>; 'SUR' <sur@lkkauto.com>
Subject: RE: Arrange surveyor for SJQ9784D Your Ref:GBC1762M

Dear Lionel,

Thank you for the assignment.

► City Used Vehicle List (6 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Honda City 1.5A LX	\$18,800	\$8,310 /yr	13-Nov-2009	1,497 cc	-	Ezy-1 Pte Ltd	Availal

One Of The Best Fuel Saving Car In The Market. Well Maintained By Previous Owner. New Facelift City. All Wear And Tear Just Replaced. Ne Paint. Drive With No Worries Till Vehicle Due For Scrap. Numbe...

Office No. - 68730300

Hao - 86885353 | Victor - 90043904

Honda City 1.5A LX	\$22,786	\$22,590 /yr	04-May-2009	1,497 cc	130,000 km	786 Blitz Automobile LLP	Availal
--------------------	----------	--------------	-------------	----------	------------	--------------------------	---------

\$5k Down Payment, Extended Warranty By Our Own Workshop, Test Drive To Feel The Engine And Gearbox.

Office No. - -

Dan - 93259171

Honda City 1.5A VTEC (New 5-yr COE)	\$29,800	\$5,960 /yr	17-Mar-2009	1,497 cc	135,805 km	Rexy Motor Trading Company	Availal
-------------------------------------	----------	-------------	-------------	----------	------------	----------------------------	---------

Beautiful Sleek Black Honda City! Well Known For It's Low Fuel Consumption And VTEC Power! Cheapest 5 Year Renewal COE In The Market Accident Free And Low Mileage Done As Its Off Peak Car Converted! ...

Office No. - 64680082

David - 94551891 | Desmond - 97323670 | Mr Yeo - 97482688

Honda City 1.5A LX (New 5-yr COE)	\$29,800	\$5,960 /yr	17-Jan-2009	1,497 cc	137,700 km	Dickson Automobile	Availal
-----------------------------------	----------	-------------	-------------	----------	------------	--------------------	---------

Renew 5 Years COE, View It And Believe! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professior After Sales Service Assured.

Office No. - 68447667

Eric Lee - 91827304 | Ting Ting - 83946026 | Ricky Eng - 91853390

Honda City 1.5A VTEC (New 5-yr COE)	\$29,800	\$5,960 /yr	21-Jan-2009	1,497 cc	-	A1 Motoring Pte Ltd	Availal
-------------------------------------	----------	-------------	-------------	----------	---	---------------------	---------

Office No. - 62646526

Mr Chua - 87999466 | Lee - 93678860 | Roy - 87999711 | Steve - 81820249

Honda City 1.5A VTEC (New 10-yr COE)	\$49,800	\$4,980 /yr	21-Jan-2009	1,497 cc	-	Ritz Auto	Availal
--------------------------------------	----------	-------------	-------------	----------	---	-----------	---------

New 10 Year COE! Depreciation \$4k Plus A Year! Cheaper Than Rental! \$400 A Month! No Repairs Needed! All Trade In Welcome, Major Bar And In House Loan Available! Night And Door Step Viewing Available...

Office No. - 62556118

Han - 97284422 | Krist - 97113211 | Owyong - 97227737

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or station wagons. You can also buy from a car auction, look up car loans, k mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and u car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news (the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2018 sgCarMart. All rights reserved.

Guo Qiang (LKKAuto)

From: Julie Johari <julie@skauto.com.sg>
Sent: Wednesday, 29 March, 2017 12:52 PM
To: Guo Qiang (LKKAuto)
Cc: Simon Koh; KY Leong; XIONG
Subject: PENDING FINALISED_SJQ 9784D_DOA 08.02.2017_HONDA CITY V-TEC
Attachments: REAR LH.jpg; REAR RH.jpg; REAR VIEW.jpg

Dear Sir / Madam, "WITHOUT PREJUDICE"

Vehicle No. : SJQ 9784D

Date of Inspection : 10.02.2017

D.O.A : 08.02.2017

Surveyor : GUO QIANG

PARTS : S\$ 7,622.64

S/NETT : S\$ 1,822.00

LABOUR : S\$ 2,730.00

TOTAL AFTER 20% : S\$ 9,739.71

Can we close at S\$ 3,730.00

Kindly assist us to finalize this case.

Attached after paint photos as per request.

We appreciate your early reply .

Thank you and hope to hear from you soon.

Please acknowledge the finalize!

Best Regards,

MALP17018230-01 / Alpine Motors Pte Ltd - HQ
ENTRY DATE & TIME: 09/02/2017 10:05

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 09/02/2017 10:05
Date Of Accident 08/02/2017 12:50
Exact Location Of Accident Junction of Kaki Bukit 3 & 4
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJQ9784D
Insured/Policyholder
Name Of Registered Owner HO MENG ANN
NRIC No S1130499J
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-96874560
Alternative Phone No Office-60000000
Vehicle Particulars
Manufacturer HONDA
Model CITY-1.5 i-VTEC (GM2) (A)
Exact Purpose for which vehicle was being used at time of accident Private Use
Are you claiming under your own insurance policy for repair to your vehicle? No
If No, Please state action to be taken Third Party
Vehicle Category Private Car
Insurance Company
Name of Insurance Company AXA Insurance Pte Ltd
Type Of Coverage Comprehensive
Fleet Policy No
Policy Number VPA/P0806405
Cover Note Number
Driver
Name of Driver HO MENG ANN
NRIC No S1130499J
Date Of Birth 21/01/1955
Occupation Indoor
Date Of Driving Pass 27/08/1975
Driving Experience 41 Years And 5 Months
Gender Male
Mobile Number (Local) +65-96874560
Fax Number
Contact Number Office-60000000
EMail Address NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company No

If No, Relationship of the Driver with the Insured Owner

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

Collision- Head to Rear (TP Hit Insured)

Weather Conditions

Clear

Road Surface

Dry

Other Information

Was any foreign vehicle involved in this accident? No

Was any body injured in the Accident? No

Was any other material or property damaged? Yes

I have been approached by unknown person(s) soliciting/offering accident claims assistance. No

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? No

If Yes, Please state which Police Station

Was notice of Intended Prosecution given? No

If Yes, against whom?

Circumstances of Accident

Report Please refer to Sketch Plan

Attachment(s)

Are accident photos available for attachment? Yes

Was there any video captured by Car Camera? No

Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC1762M

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent Under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


[Signature]
Policyholder's Signature / Date & Time

[Signature]
Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]
Witnessed by Reporting Centre Personnel

Sketch Plan

Katj Bukit
Ave 3



Katj Bukit Ave 4



Witness
Inspector

(A) SJO 9794D
(B) BBC 1762M


Sketch Plan #2


Describe Circumstances of the Accident


On 09.02.2017 at about 1250hrs, I was travelling along Kaki Road from 3 turning to Kaki Road from 4. I was at traffic junction & on stationary while waiting for the pedestrian to clear. All of a sudden I felt an impact from the rear. Then I realised a vehicle 65C 172111 had collided onto my rear. That's all.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Addendum Sheet

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MAP 17018230 Vehicle Registration No: 5JQ 9754 D
 Name(as shown in NRIC): HO MENG APH
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 NRIC/Passport No: 51130499J
 Address: _____
 Contact (Tel): 96874560 (H/P): 96874560
 (Email): _____
 Date of Accident: 8/2/2017 Time of Accident: 12.50
 Place of Accident: JUNCTION OF KAKI BUKIT AVE 3 AND 4
 Insurance Company: _____

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Amend: Junction of KAKI BUKIT AVE 3 AND 4 To
JUNCTION OF KAKI BUKIT AVE 3 AND 4

AS
 Signature of Vehicle Owner / Driver
 Date: _____

10 Anson Road #06-16 International Plaza Singapore 079903 Phone : + 65 6224 0010 Fax : +65 6224 0030
 Operating Hours : Monday to Friday 9am to 5pm

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

Lpk
GK

TO	: ECICS	DATE	: 8-Feb-17
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	LKK Auto G... Notify the Repairer of the following:	
ADDRESS	:	• To reserve • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary items must be resurveyed and is subject to final approval from Insurance Company	
TEL. NO.	:	VEHICLE NO : SJQ9784D MODEL : HONDA CITY VTEC CHASSIS NO :	
<u>ACCIDENT DETAILS</u>	DATE :	Acknowledged by Repairer	
	TIME :	Signature:	
		Date:	
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID / BUL	1	\$898.00	\$ 898.00
2	BOOTLID CHROME MOULDING / CRA	1	\$342.00	\$ 342.00
3	BOOTLID LOGO /	1	\$55.00	\$ 55.00
4	BOOTLID EMBLEM 'VTEC' /	1	\$54.00	\$ 54.00
5	BOOTLID EMBLEM 'CITY' /	1	\$54.00	\$ 54.00
6	BOOTLID TOP LOCK / BT	1	\$210.00	\$ 210.00
7	BOOTLID LOWER LOCK / BT	1	\$18.30	\$ 18.30
8	BOOTLID INSULATOR / TN	1	\$354.00	\$ 354.00
9	BOOTLID WEATHER STRIP / Twi	1	\$215.00	\$ 215.00
10	BOOTLID HINGE / BT	2	\$43.30	\$ 86.60
11	BOOTLID INNER STOPPER / mis	2	\$16.00	\$ 32.00
12	REAR BUMPER / RL	1	\$652.00	\$ 652.00
13	REAR BUMPER SIDE RETAINER / nbl	2	\$54.00	\$ 108.00
14	REAR BUMPER BRACKET X NN	2	\$45.00	\$ 90.00
15	TAILLAMP / CRA	2	\$486.00	\$ 972.00
16	TAILLAMP PANEL X Repair	2	\$354.00	\$ 708.00
17	REAR END PANEL / bue	1	\$548.00	\$ 548.00
18	REAR END PANEL TOP GARNISH / RL	1	\$285.00	\$ 285.00
19	REAR FENDER AIR VENT X NN	1	\$59.00	\$ 59.00

503.7
96.4
28.8
38.2
18.4
189
/
154.6
118.5
/
16
463.7
43.4
X
411.4
X
399.5
86.6
X

20	REAR FENDER INNER TRIM / TN	2	\$489.00	\$ 978.00
21	REAR WINDSCREEN GLASS / SCR	1	\$1,359.00	\$ 1,359.00
22	REAR WINDSCREEN MOULDING / MC	1	\$214.00	\$ 214.00
23	REAR FLOOR PANEL / Puc	1	\$857.40	\$ 857.40
24	REAR FLOOR PANEL TOP BOARD / CPA	1	\$214.00	\$ 214.00
25	REAR FLOOR TOWING HOOK PANEL X	1	\$210.00	\$ 210.00
26	REAR CHASSIS FRAME EXTENSION X	1	\$1,264.00	\$ 1,264.00
27	REAR CHASSIS TOP PANEL X	1	\$358.00	\$ 358.00
28	REAR SPARE TYRE BOLT X	1	\$25.00	\$ 25.00
29	REAR EXHAUST PIPE / BT	1	\$984.00	\$ 984.00
30	REAR EXHAUST PIPE INSULATOR X NN	1	\$189.00	\$ 189.00
31	REAR EXHAUST MOUNTING / BT	2	\$19.00	\$ 38.00

TOTAL PRICE \$ 12,431.30
 LESS 20% \$ 2,486.26
 SUB TOTAL PRICE \$ 9,945.04

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	TAIL LAMP CLIP / MC	4	\$ 8.00	\$ 32.00
2	REAR SPOILER / CPA	1	\$ 1,200.00	\$ 1,200.00
3	REAR WHEEL HOUSE PANEL SEALANT X NN	1	\$ 80.00	\$ 80.00
4	REAR FENDER INNER TRIM CLIPS / MC	12	\$ 5.00	\$ 60.00
5	REAR END PANEL TOP GARNISH CLIPS / MC	4	\$ 10.00	\$ 40.00
6	REAR END PANEL INSULATION SEAL X NN	1	\$ 120.00	\$ 120.00
7	REAR FLOOR PANEL INSULATION SEAL / MC	1	\$ 150.00	\$ 150.00
8	REAR EXHAUST CHROME PIPE X NN	1	\$ 180.00	\$ 180.00
9	REAR WINDSCREEN SEALANT / MC	1	\$ 80.00	\$ 80.00
10	REAR WINDSCREEN INNER SEAL / MC	1	\$ 60.00	\$ 60.00
11	REVERSE SENSOR / PM	1	\$ 200.00	\$ 200.00

TOTAL \$ 2,202.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$1,800.00	1200
2	TO SPRAY PAINT AFFECTED AREA	\$1,600.00	1100
3	TUFF COAT	\$250.00	80.
4	WIRING CHECK	\$60.00	30.

5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$180.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00	40	
7	REAR CHASSIS ALIGNMENT	\$250.00	X	NN
8	TRANFER BOOTLID MECHANISM	\$100.00	60	
9	REMOVE AND REFIX REAR WINDSCREEN	\$120.00	100	
10	CONDUCT WATER LEAKAGE TEST	\$100.00	X	NN
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$180.00	60.	

TOTAL

\$4,720.00

2730

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,147.04
TOTAL LABOUR COST : \$ 4,720.00
TOTAL REPAIR COST : \$ 16,867.04

APPROVED DETAILS

EXCESS :
NO. OF DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

10 Days.

lumpsum repair.

After repair photos.

Guo Qiang - 828 8028 2

10/2/17.

[Signature]
13/2/17.

7712.8
20%: 6150

11474.64
lump sum 89150



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD		Ref : CS/ICS17002736/Gqbn2		
10 EUNOS ROAD 8 SINGAPORE POST CENTRE #09-04A SINGAPORE 408600		Date : 24-10-2018		
		Code : ICS		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 1762M	Veh. Inspected	SJQ 9784D	
Policy No.		Coverage (\$)	0.00	
Claim No.	DMCV1700014H	Excess (\$)	0.00	
Assign From	LIONEL CHUA	Assign Date	09/02/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CITY	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MRHGM26509P020278	Colour	SILVER	
Odometer	175408	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	175/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	175/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	175/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/02/2017	Inspection Date	10/02/2017	
Survey held at	8 KAKI BUKIT AVE 4 #08-46 PREMIER			
Repairer	SK AUTOMOBILE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 9784D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	BUCKLED	898.00	503.70
1	BOOTLID CHROME MOULDING	CRACKED	342.00	96.40
1	BOOTLID LOGO	NECESSARY	55.00	28.80
1	BOOTLID EMBLEM 'VTEC'	NECESSARY	54.00	38.20
1	BOOTLID EMBLEM 'CITY'	NECESSARY	54.00	18.40
1	BOOTLID TOP LOCK	BENT	210.00	189.00
1	BOOTLID LOWER LOCK	BENT	18.30	18.30
1	BOOTLID INSULATOR	TORN	354.00	154.60
1	BOOTLID WEATHER STRIP	TWISTED	215.00	118.50
2	BOOTLID HINGE @\$43.30	BENT	86.60	86.60
2	BOOTLID INNER STOPPER @\$16.00	MISSING	32.00	16.00
1	REAR BUMPER	DEFORMED	652.00	463.70
2	REAR BUMPER SIDE RETAINER @\$54.00	NECESSARY	108.00	43.40
2	REAR BUMPER BRACKET @\$45.00	NOT NECESSARY	90.00	-
2	TAILLAMP @\$486.00	CRACKED	972.00	411.40
2	TAILLAMP PANEL @\$354.00	TO REPAIR SEE LABOUR	708.00	-
1	REAR END PANEL	BUCKLED	548.00	399.50
1	REAR END PANEL TOP GARNISH	DEFORMED	285.00	86.60
1	REAR FENDER AIR VENT	NOT NECESSARY	59.00	-
2	REAR FENDER INNER TRIM @\$489.00	TORN	978.00	357.10
1	REAR WINDSCREEN GLASS	SCRATCHED	1,359.00	739.80
1	REAR WINDSCREEN MOULDING	NECESSARY	214.00	119.80
1	REAR FLOOR PANEL	BUCKLED	857.40	550.00
1	REAR FLOOR PANEL TOP BOARD	CRACKED	214.00	90.80
1	REAR FLOOR TOWING HOOK PANEL	TO REPAIR SEE LABOUR	210.00	-
1	REAR CHASSIS FRAME EXTENSION	TO REPAIR SEE LABOUR	1,264.00	-
1	REAR CHASSIS TOP PANEL	TO REPAIR SEE LABOUR	358.00	-
1	REAR SPARE TYRE BOLT	TO REPAIR SEE LABOUR	25.00	-
1	REAR EXHAUST PIPE	BENT	984.00	457.40
1	REAR EXHAUST PIPE INSULATOR	NOT NECESSARY	189.00	-

Report Ref No. CS/ICS17002736/Gqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR EXHAUST MOUNTING @\$19.00	BENT	38.00	38.00
	LESS 20% DISCOUNT		-2,486.26	-1,005.20
			9,945.04	4,020.80
	<u>SPECIAL NETT ITEMS</u>			
4	TAIL LAMP CLIP @\$8.00 (SN)	NECESSARY	32.00	32.00
1	REAR SPOILER (SN)	CRACKED	1,200.00	500.00
1	REAR WHEEL HOUSE PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
12	REAR FENDER INNER TRIM CLIPS @\$5.00 (SN)	NECESSARY	60.00	30.00
4	REAR END PANEL TOP GARNISH CLIPS @\$10.00 (SN)	NECESSARY	40.00	20.00
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	120.00	-
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NECESSARY	150.00	120.00
1	REAR EXHAUST CHROME PIPE (SN)	NOT NECESSARY	180.00	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	60.00	20.00
1	REVERSE SENSOR (SN)	DAMAGED	200.00	200.00
			2,202.00	962.00
	<u>LABOUR</u>			
	PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL, REAR FLOOR TOWING HOOK PANEL, REAR CHASSIS FRAME EXTENSION, REAR CHASSIS TOP PANEL AND REAR SPARE TYRE BOLT.		1,800.00	1,200.00
	TO SPRAY PAINT AFFECTED AREA.		1,600.00	1,100.00
	TUFF COAT.		250.00	80.00
	WIRING CHECK.		60.00	30.00
	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR.		180.00	60.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	40.00
	REAR CHASSIS ALIGNMENT	NOT NECESSARY	250.00	-
	TRANSFER BOOTLID MECHANISM.		100.00	60.00
	REMOVE AND REFIX REAR WINDSCREEN.		120.00	100.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	100.00	-
	REMOVE AND REFIX REAR EXHAUST PIPE.		180.00	60.00
			4,720.00	2,730.00
GRAND TOTAL			16,867.04	7,712.80

Report Ref No. CS/ICS17002736/Gqbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,150.00
---	--	--	----------

Report Ref No. CS/ICS17002736/Gqbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.