

ASS. REC. BY:

REF:

CS / PC217003453 / R1+h3¹²

Special Instruction:

Surveyor

Raul

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time: 20/2/2017 2:22pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJX12312

Insured:

SHD 4886T

at Workshop m/s

Neng Kee Motor

Tel:

6854 1273

of

Bkt 149 Vishnu Ind Park #01-366

Policy No:

Claim No:

D17001936 MESH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 23/1/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 20/2/2017 2:40pm

Person Contacted:

Victor

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJX12312 - X
	SHD 4886T - CCB / ATG 14024107 / H100362
	DCM: 23/12/2014
20/2/2017 5:50pm	Mr. Victor said vehicle has been repaired. He will send finalization.
	offer \$2000, 4 days, confirm. (Red: 3723.9, 65%)

(08/11/13) wef

REF:

ASS. REC. BY: *Ram*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SJX 12312*at Workshop m/s *Wah Kee*of *BLK 1019, Y12HUN #01-366*Insured: *FCI / PRS*

Policy No: _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SJX 12312* Yr Regn: *2010 / Man*Type: *M.Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *CHEVROLET CAPTIVA* c.c. *2405*Colour: *WHITE* A/C: Insured / Std / NI / NASp. Reading: *94763* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *KL1CD26F19B542418*Gen. Cond: Good / *Fair* / Poor / BurntSteering: *Order* / Jammed / Leaked / Burnt orBrake: *Order* / Jammed / Leaked / Burnt orModi: Nil / *S/Rim* / STD A/Rim orTyre Size: F: *225/65 R17*
R: _____BS / DUN / EXNOVA / GY / FS / LIZA / *MIC* / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. *6* mm R/Bal. *6* mmL/Bal. *6* mm L/Bal. *6* mmD.O.A. *23/01/17* D.O.I. *21/02/17*Survey held at *Wah Kee*Des. of Damages: Frt *Rear* / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 07 FEB 2013

Date/Time, File Pass to?

17/2 Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair: *4*

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

) S + RS.) SI

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$Report Format : *TP*Lump Sum / I.B.I: (\$ *2000*)*140**50**25**215*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS3/FCI17003453/R1th3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-02-2017	
			Code : FCI2	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHD 4886T	Veh. Inspected	SJX 1231Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17001936MFSH	Excess (\$)	0.00	
Assign From	CWS (KAREN TAN)	Assign Date	20/02/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/01/2017	Inspection Date	21/02/2017	
Survey held at	WENG KEE MOTOR BLK 1019 #01-366 YISHUN INDUSTRIAL PARK A SINGAPORE 768761			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

MOTOR SURVEY ASSIGNMENT

Date	17-02-2017	Our Ref No. D17001936MFSH
Accident Date	23-01-2017	Claim Type. Third Party
Insured Vehicle	SHD4886T	Third Party Vehicle. SJX1231Z
Survey Location	BLOCK 1019 YISHUN INDUSTRIAL PARK A#01-366	
Contact Person.	VICTOR	
Contact No.	85431273/ 85431273	Fax No. 00
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WENG KEE MOTOR	Attention. NIL
Cc : TP Solicitor	CK TEO & CO	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/216691)



PRI Documents



Close



PRI Header Details

Claim No	D17001936MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & CK TEO &
Workshop Name	WENG KEE MOTOR (Contact Person : VICTOR)	Survey Location & Contact Details	BLOCK 1019 YISHUN INDUSTRIAL PARK A#01-366 Mobile: 85431273 , Phone: 85431273 , Fax: 00 EmailId: WTUANG@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD4886T	TP Vehicle No	SJX1231Z
PRI Recieved Date	17-02-2017 11:02:55 PM	Surveyor Appointed Date	20-02-2017 02:31:16 PM	Surveyor Accept Date	20-02-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	20-02-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks		Save
Date	Job Remarks	Action

Denise Tay (LKKAuto)

From: Qi zhi Wong <wkmotor@ymail.com>
Sent: Wednesday, 7 February 2018 2:00 PM
To: Denise Tay (LKKAuto)
Subject: Re: SJX 1231Z FIRST CAPITAL

Hi Denise,

I confirmed the amount to be \$2000 with 4 days.

Best Regards,
Victor Wong Qi Zhi

Weng Kee Motor

TEL: 6854 1273	begin_of_the_skype_highlighting	6854 1273	end_of_the_skype_highlighting
HP: 8182 1895	begin_of_the_skype_highlighting	8182 1895	end_of_the_skype_highlighting

On Wed, 7/2/18, Denise Tay (LKKAuto) <denisetay@lkkauto.com> wrote:

Subject: SJX 1231Z FIRST CAPITAL
To: "WKMOTOR@YMAIL.COM" <WKMOTOR@YMAIL.COM>
Date: Wednesday, 7 February, 2018, 1:34 PM

Dear Victor,

As spoken, enclosed
estimate.

We would like to offer
lump sum \$2000, 4days

Best
Regards,
Denise
Tay |
Case Handler
LKK
Auto Consultants Pte Ltd
Phone:
6256-3561 | email:

WENG KEE MOTOR

DATE: 21-02-2017

REPAIR ESTIMATE

VEHICLE: SJX 1231 Z

MODEL: Chevrolet Captiva

S/n	Description of part	Qty	Estimate
1	Rear bumper	1	1,353.00 DE -
2	Rear bumper side retainer LH/RH	2	36.00 X su
3	Rear bumper reinforcement	1	450.00 ? X su
4	Rear tailgate emblem '4WD'	1	39.00 nu -
5	Rear tailgate emblem 'Captiva'	1	42.00 nu -
6	Rear tailgate emblem 'Chevrolet'	1	45.00 nu -
7	Rear bumper reflector LH/RH	2	144.00 X su
8	Rear bumper tow cover	1	56.00 X su
9	Rear exhaust silencer	1	1,506.00 X su

Sub-total 1 3,671.00

Less Discount 10% 3,303.90

10 Reverse sensor

1 200.00 nu -

Sub-total 2 200.00

Parts total 3,503.90

Labour

11	To straighten and panel beating rear frame members, rear end panel. To remove and refit above parts.	900.00 400
12	To putty, re-spray painting and polish affected areas.	900.00 400 500
13	To remove and transfer/refit front rear components.	100.00 60
14	To check and rectify wiring system.	80.00 X nu
15	To replace reverse sensor and check	120.00 60
16	To rust proof affected areas.	120.00 X nu

Labour total 2,220.00

Parts & Labour total 5,723.90

Rasul
Hp 90010068

4 days

HS

21/02/17 @ 1725

Ready after repair

Weng Kee Motor @ Jalan Masjid Chini



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17003453/R1th3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4886T	Veh. Inspected	SJX 1231Z	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17001936MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	20/02/2017	
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET CAPTIVA	c.c	2405	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	KL1CD26F19B542418	Colour	WHITE	
Odometer	94763	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	MICHELIN	6 mm	
L/H Front Tyre	225/65 R17	MICHELIN	6 mm	
R/H Rear Tyre	225/65 R17	MICHELIN	6 mm	
L/H Rear Tyre	225/65 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/01/2017	Inspection Date	21/02/2017	
Survey held at	WENG KEE MOTOR BLK 1019 #01-366 YISHUN INDUSTRIAL PARK A SINGAPORE 768761			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 1231Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	1,353.00	1,353.00
2	REAR BUMPER SIDE RETAINER LH/RH	SERVICEABLE	36.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	450.00	-
1	REAR TAILGATE EMBLEM "4WD"	NECESSARY	39.00	39.00
1	REAR TAILGATE EMBLEM "CAPTIVA"	NECESSARY	42.00	42.00
1	REAR TAILGATE EMBLEM "CHEVROLET"	NECESSARY	45.00	45.00
2	REAR BUMPER REFLECTOR LH/RH	SERVICEABLE	144.00	-
1	REAR BUMPER TOW COVER	SERVICEABLE	56.00	-
1	REAR EXHAUST SILENCER	SERVICEABLE	1,506.00	-
	LESS 10% DISCOUNT		-367.10	-147.90
			3,303.90	1,331.10
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	NOT WORKING	200.00	200.00
			200.00	200.00
	<u>LABOUR</u>			
	TO STRAIGHTEN AND PANEL BEATING REAR FRAME MEMBERS, REAR END PANEL TO REMOVE AND REFIT ABOVE PARTS.		900.00	400.00
	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.		900.00	500.00
	TO REMOVE AND TRANSFER/REFIT FRONT REAR COMPONENTS.		100.00	60.00
	TO CHECK AND RECTIFY WIRING SYSTEM.	NOT NECESSARY	80.00	-
	TO REPLACE REVERSE SENSOR AND CHECK.		120.00	60.00
	TO RUST PROOF AFFECTED AREAS.	NOT NECESSARY	120.00	-
	-		-	-
	-		-	-
	-		-	-
			2,220.00	1,020.00
	GRAND TOTAL		5,723.90	2,551.10



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00
---	--	--	----------

Report Ref No. CS/FCI17003453/R1th3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.