


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB429S
 Ref. No : TAX/02/17/2128
 Reg. Date : 11/02/2015
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : MOHAMMED LATIFF BIN MOHAMMED ALI
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 16/02/2017 08:57:00 AM
 Accident Reported Date / Time : 17/02/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024087984
 Special Instruction to ARC, if any :
 TOS /YP2835P - CHINA TAIPING - LKK
 Prepared Date : 22/02/2017 10:29:39 AM



After Repair photo.

LKK Auto Consultants will notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U305758052

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 936.00	0.00
Total Material Charges	: 4,016.73	4,016.73
Other Charges	: 785.00	0.00
TOTAL	: 6,582.73	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	0.00 <i>2 Days</i>
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 22/02/2017 11:59:01 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 22/02/2017 11:57:36 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 2/22/2017 11:59:21 AM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	845.00	0.00
Total Labour	845.00	0.00 200

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00
TO RESPRAY REAR FENDER RH	378.00	0.00
TO RESPRAY RIM	180.00	0.00
Total Spray Painting & Panel Beating	936.00	0.00 X 400

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 20
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 X
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 X
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 X
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 X
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 X
Total Other Costs	785.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace ☒	No ☒
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace ☒	No ☒
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace ☒	No ☒
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.27	Replace	Replace ☒	No ☒
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace ☒	No ☒
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ☒	No ☒
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace ☒	No ☒
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.02	Replace	Replace ☒	No ☒
81551-47180		6505462	TAIL LAMP RH	1	557.80	10.00	502.02	Replace	Replace ☒	No ☒
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace ☒	No ☒
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ☒	No ☒
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ☒	No ☒
65637-47021		6505480	FENDER LINER RR/RH	1	141.30	25.00	105.97	Replace	Replace ☒	No ☒
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace ☒	No ☒
42611-47140		6505658	WHEEL, DISC	1	1,490.20	25.00	1,117.65	Replace	Replace ☒	No ☒
62710-47130			QUARTER GLASS RR/RH	1	846.50	25.00	634.87	Replace	Replace ☒	No ☒
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace ☒	No ☒
TOTAL MATERIALS								4,016.76	4,016.73	
TOTAL MATERIALS(Discounted)								4,016.73	4,016.73	
Added Spare Parts / Material Usage After Surveyor Signed off										

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Kahe'kka
H 22/2/17