

21/03/2001

ASS. REC. BY:

REF: CS/TCU7004317/Tlrbez

Special Instruction:

Su 12407

Tawfik

ASSIGNMENT (Office)

Date/Time: 02/03/2017 9:13am

From (Person):

CWS May Chua

of

TCL

Bill to:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

Insured:

SHC 2640D

To Inspect Vehicle No:

SLG 9186J

Tel:

6833 6281

at Workshop m/s

Hitachi Capital

of

8 Fourth Lok Yung Road

Claim No:

D17002310M70H

Policy No:

Excess:

Sum Insured:

D.O.A.

25/02/2017

Make of Veh:

(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS 'DS'

Glen

Vehicle IN / OUT

Date/Time: 02/03/2017 9:48am

Person Contacted:

Date/Time Action/Instruction (✓) Estimate

SLG 9186J - X

SHC 2640D - NS / INC12010364 / HIKK3

DUP: 250512

3/3/2017 Sent preli to May

Tawfik confirm \$7882.28 @ 8 days

Red: \$4428.20, 36%.

Surveyor: Tanpin

## ASSIGNMENT

From: \_\_\_\_\_ Date: 02/03/2017

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 9186Jat Workshop m/s Hitachi Capital  
of No. 8 Fourth Lbk Yang Road

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLG 9186J Yr Regn: 2016, outType: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Odyssey c.c. 2356Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / NI / NA

Eng/No: K24W1415017C/No: RC11114604Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/55R17R: 7-1BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6R/Bal. \_\_\_\_\_ mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. \_\_\_\_\_ D.O.I. 2/3/17c 440Survey held at Hitachi CapitalDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/8/18 7882.28, 8 days confirm with w/s.

RECEIVED 27 SEP 2018

Date/Time, File Pass to?

1) tpnt

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Preli. Report☒ : Final ReportDays Of Repair: 8Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I. (\$) 7882.282x5170+30505069369

Reference No.: CS/FCI 17604317/TLrb  
Policy Type: OD/TP/TP RES/TL/EVA

Typist

Admin ( Catherine

C	Reference No.
C	Customer Code
N	Assign From
C	Assign Date
C	Veh No (Inspected)
C	Veh No (Insured)
C	D.O.A
C	Policy No
C	Claim No
C	Insurance Authorisation (CA /REV/REP)
C	Report Type
C	Weekend Charges
N	Survey held at/Repairer
C	Excess

[illegible]

); Case handler to make sure the surveyor completed all required information.

C	Vehicle No
C	Regn Month/Year
N	Vehicle Type
N	Make & Model
C	Engine Capacity. (C.C)
N	Colour
C	Odometer. (Sp.Reading)
C	Chassis No
N	General Condition
N	Steering
N	Brake
N	Modification (Modi)
C	Tyre Size
N	Tyre Make
C	Tyre Balance
C	Date of Inspection
N	Survey held
N	Des.of Damages

[illegible]

System - (Views/Merimen)  
C Damaged Vehicle Photographs Uploaded

N	ALL Parts condition
C	Market Value for OD cases
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C	Days of repair
C	Finalised Amount
C	Re-inspection Cases to Finalize within 5 Days

System - (Views/Merimen)  
C Resurvey photo Uploaded

Case Handler	Date
--------------	------

21/05/20




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17004317/T1rb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-03-2017	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHC 2640D	Veh. Inspected	SLG 9186J
Policy No.		Coverage (\$)	0.00
Claim No.	D17002310MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	02/03/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	25/02/2017	Inspection Date	02/03/2017
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	28-02-2017	<b>Our Ref No.</b> D17002310MFSH
<b>Accident Date</b>	25-02-2017	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHC2640D	<b>Third Party Vehicle.</b> SLG9186J
<b>Survey Location</b>	JUN TAIYO SERVICE CENTRE NO 8 FOURTH LOK YANG ROAD	
<b>Contact Person.</b>	SUN ZHU MEI	
<b>Contact No.</b>	68336281/ 68336281	<b>Fax No.</b> 68966591
<b>Survey Type</b>	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

**Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.**

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	HITACHI CAPITAL ASIA PACIFIC PTE. LTD.	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	MAY CHUA	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/217184)



PRI Documents

Close X

## PRI Header Details

Claim No	D17002310MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & HIT PTE. LT
Workshop Name	HITACHI CAPITAL ASIA PACIFIC PTE. LTD. (Contact Person : SUN ZHU MEI )	Survey Location & Contact Details	JUN TAIYO SERVICE CENTRE NO 8 FOURTH LO Mobile: 68336281 , Phone: 68336281 , Fax: EmailId: SUNZHUMEI@HCSPL.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC2640D	TP Vehicle No	SLG918
PRI Recieved Date	01-03-2017 06:46:53 PM	Surveyor Appointed Date	02-03-2017 09:12:55 AM	Surveyor Accept Date	02-03-

## Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	02-03-2017	Upload Survey Report *:	
-----------------------------	---	----------------------	------------	-------------------------	---

## Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

## Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

## Surveyor Job Remarks

## Janice Lee (LKKAUTO)

---

**From:** Janice Lee (LKKAUTO)  
**Sent:** Friday, 3 March, 2017 4:21 PM  
**To:** 'Claim Workflow System'; MAYCHUA@FIRST-INSURANCE.COM.SG  
**Cc:** SUR; Admin-D (LKKAUTO); assignments  
**Subject:** RE: SURVEY ASSESSMENT - D17002310MFSH/1  
**Attachments:** SLG 9186J.pdf

Dear May,

Enclosed preliminary revised of vehicle **SLG 9186J**.  
Date of survey : 02/03/2017

Thank you.

Best Regards,

**Janice Lee (Ms)** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)

**Sent:** Thursday, 2 March, 2017 9:50 AM

**To:** 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>

**Cc:** MAYCHUA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>

**Subject:** RE: SURVEY ASSESSMENT - D17002310MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]

**Sent:** Thursday, 2 March, 2017 9:13 AM

**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)

**Cc:** [CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG](mailto:CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG); [MAYCHUA@FIRST-INSURANCE.COM.SG](mailto:MAYCHUA@FIRST-INSURANCE.COM.SG)

**Subject:** PRI: SURVEY ASSESSMENT - D17002310MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17002310MFSH  
Our Ref: CS/FCI17004317/T1rb

Date: 03 March 2017

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SLG 9186J**


We thank you for the instruction on 02/03/2017.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 02/03/2017 at the premises of HITACHI CAPITAL (S) PTE LTD have the following to report:-

Workshop Estimate Amount	: S\$ <u>12,310.48</u>
Revised Estimate Amount	: S\$ <u>6,078.28</u>
"Check" Items Amount	: S\$ <u>2,265.20</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

**Description of Damage:**

The vehicle sustained damages at the rear portion.



Comments/ Present Status:  
Damages Consistent.

Yours faithfully

TAUFIKH  
Automotive Assessor

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 0399N

### Vehicle Details

Vehicle No.: SLG9186J

Vehicle to be Exported: Yes

Intended De-registration Date: 07 Mar 2017

Vehicle Make: HONDA

Vehicle Model: ODYSSEY ABSOLUTE 2.4 A

Primary Colour: Black

Manufacturing Year: 2016

Engine No.: K24W1415017

Chassis No.: RC11114604

Maximum Power Output: 140.0 kW (187 bhp)

Open Market Value: \$32,322.00

Original Registration Date: 18 Oct 2016

First Registration Date: 18 Oct 2016

Transfer Count: 0

Actual ARF Paid: \$37,251.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 17 Oct 2026

PARF Rebate Amount: \$27,938.00

### Intended COE Rebate Details

COE Expiry Date: 17 Oct 2026

COE Category: B - Car (above 1600cc or 97kW (130bhp))

COE Period(Years): 10

QP Paid: \$53,001.00

COE Rebate Amount: \$42,400.00

**Total Rebate Amount: \$70,338.00**

The information contained herein is correct as at 07 Mar 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/02/2017 18:57
Date Of Accident	25/02/2017 17:30
Exact Location Of Accident	TRAFFIC JUNCTION AT JEM BOON LAY WAY & JURONG ROAD
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG9186J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HITACHI CAPITAL ASIA PACIFIC PTE LTD
Co Reg No	199400399N
Email Address	JUNTAIYO@HCSPL.COM.SG
Mobile Phone No	
Alternative Phone No	Office-64663022

### Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY-2.4 Absolute (RC1) (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car

### Insurance Company

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	
Cover Note Number	

### Driver

Name of Driver	AMNAH BINTI JANTAN
NRIC No	S1498126H
Date Of Birth	05/02/1961
Occupation	Indoor
Date Of Driving Pass	26/08/2009
Driving Experience	7 Years And 5 Months
Gender	Female
Mobile Number	(Local) +65-97957694
Fax Number	
Contact Number	
Email Address	AMNAH-JANTAN@MOE.EDU.SG

Address  
 Postcode  
 Was driver an employee of the Insured's Company No  
 If No, Relationship of the Driver with the Insured Other - LESSEE  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident Collision- Chain Collision  
 Weather Conditions Clear  
 Road Surface Wet

#### Other Information

Was any foreign vehicle involved in this accident? No  
 Was any body injured in the Accident? No  
 Was any other material or property damaged? Yes  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. No  
 Number of Passengers (Including Driver) 5

#### Details of Police Action

Was the accident reported to the police? No  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? No  
 If Yes, against whom?

#### Circumstances of Accident

PLEASE REFER TO THE ATTACHED.

#### Attachment(s)

Are accident photos available for attachment? Yes  
 Was there any video captured by Car Camera? Yes  
 Was there any audio recorded? No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJS8224A  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Name of Driver GANESH S/O RANALINGAN  
 NRIC/Passport Number S9112650H  
 Contact Number 96723555  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

#### Details of Witness

Name  
 Phone Number  
 Email Address

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHC2640D  
 Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

LIM CHIEW PING

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

### Sketch Plan

A = SLG9186J

B = SHC2640D

C = STS8224A



### Describe Circumstances of the Accident

I was travelling at Borneo Lay Way and stopped at traffic light. When the red light is on. Suddenly, I heard a loud bang from behind. I came out and saw a taxi and a car hit my car. There was a chain collision. The taxi was hit by another car.

### Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

**Hitachi Capital Asia Pacific Pte. Ltd.**

**Jun Taiyo Service Centre**

No. 8 Fourth Lok Yang Road Singapore 629705  
Tel: 64663022 Fax: 68966591  
Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

**VEHICLE ESTIMATE**

M/s : First Capital Insurance Limited  
36 Robinson Rd  
#16-01 City House  
Singapore 068877  
Attn : Motor Claim Dept

Quote No : 00004582  
RevisionNo : 1  
Date : 01/03/2017  
Page : 1 / 3

Dear Sir/Madam,

Accident Repair On : SLG9186J - HONDA ODYSSEY ABSOLUTE 2.4 A  
Insured : Hitachi Capital Asia Pacific Pte Ltd  
Date of Accident : 25/02/2017  
Your Insured Veh No : SHC2640D

*Taughtin 974957461.*  
*OS*  
*Body before paint.*  
*6/3/17. 2/3/17 @ 1740.*

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED :-

*delays.*

		Qty	SSUnit	SSAmt	SSLabor
<b>1. Body Repair</b>	<b>Parts Replacement</b>				
1 Rear Bumper		1.00	558.50	558.50 <i>de</i>	
2 Rear Bumper Clips		10.00	5.50	55.00 <i>de</i>	
3 Rear Bumper Retainer Inner		2.00	25.60	51.20 <i>de</i>	
4 Rear Bumper Retainer Outer - 2pcs				<i>200 SN nm</i>	
5 Reverse Sensor (1set)	S/Nett	1.00	250.00	250.00 <i>nm</i>	
6 Bumper Reflector LH/RH		2.00	45.50	91.00 <i>X nm</i>	
7 Bumper Lower Spoiler LH/RH					
8 Bumper Lower Spoiler Chrome LH/RH		2.00	141.50	283.00 <i>X nm</i>	
9 Tailgate		1.00	1,305.60	1,305.60 <i>de</i>	
10 Tailgate Chrome Moulding Outer		1.00	185.60	185.60 <i>de</i>	
11 Tailgate Lamp LH/RH		2.00	389.60	779.20 <i>nm</i>	
12 Tailgate Centre Moulding Garnish		1.00	201.50	201.50 <i>nm</i>	
13 Tailgate "H" Logo		1.00	38.50	38.50 <i>nm</i>	
14 Number Plate with Casing	S/Nett	1.00	45.00	45.00 <i>X nm</i>	
15 Rear End Panel		1.00	410.50	410.50 <i>? bt</i>	
16 Tail Lamp LH/RH		2.00	821.50	1,643.00 <i>? cut</i>	
17 Rear Bumper Garnish LH/RH					<i>nm</i>
18 Tailgate Lock		1.00	201.50	201.50 <i>jm photo</i>	
19 Rear Fender RH		1.00	978.50	978.50 <i>Rx</i>	
20 Sealant	S/Nett	1.00	45.00	45.00 <i>nm SN</i>	
21 Rear Windscreen Moulding		4.00	38.50	154.00 <i>nm</i>	
22 Spare Tyre Compartment		1.00	1,411.50	1,411.50 <i>Rx</i>	
23 Spare Tyre Sponge					<i>nm</i>
24 Spare Tyre Board					
25 Tailgate Inner Trim Board		1.00	202.50	202.50 <i>? X nm</i>	

*201 3941*



**Hitachi Capital Asia Pacific Pte. Ltd.**  
**Jun Taiyo Service Centre**

No. 8 Fourth Lok Yang Road Singapore 629705  
 Tel: 64663022 Fax: 68966591  
 Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

**VEHICLE ESTIMATE**

M/s : First Capital Insurance Limited  
 36 Robinson Rd  
 #16-01 City House  
 Singapore 068877

Attn: Motor Claim Dept

Quote No : 00004582  
 RevisionNo : 1  
 Date : 01/03/2017  
 Page : 2 / 3

Dear Sir/Madam,

Accident Repair On : SLG9186J - HONDA ODYSSEY ABSOLUTE 2.4 A  
 Insured : Hitachi Capital Asia Pacific Pte Ltd  
 Date of Accident : 25/02/2017  
 Your Insured Veh No : SHC2640D

**2. Labour Charge**

1 Panel beat, cut, weld, re-align and replace damaged parts of REAR portion	1500 2,250.00
2 Spray painting on REAR portion of affected area	<del>1000</del> 1250. 2,000.00
3 Check Wiring and ensure proper function	30 80.00
4 Remove & reinstall bumper sensors	30 120.00
5 Cavity Treatment on New Parts	40 80.00
6 Remove and Replace Tailgate Windscreen	120 180.00
7 Transfer tailgate lock & mechanism to new tailgate	60 120.00
8 Conduct water seepage test	40 120.00
9 Diagnostic Check & Reset	100 180.00

SubTotal : 8,890.60 5,130.00

**Less:**

1 List Items Discount on List Items - 20%

-1,710.12  
 SubTotal : -1,710.12  
 Grand Total : 12,310.48  
 Add 7 % GST : 861.73  
 Net Total After GST : 13,172.21

parts \$ 5584.10 - 20% = \$ 4467.28

SINOT \$ 245 ✓

Labour \$ 3170 ✓

\* Total P/P \$ 7882.28 @ 8 day

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Hitachi Capital Asia Pacific Pte. Ltd.**

**Jun Taiyo Service Centre**

No. 8 Fourth Lok Yang Road Singapore 629705

Tel: 64663022

Fax: 68966591

Co.Reg.No. 199400399N

GST Reg. No. M2-0118999-3

**VEHICLE ESTIMATE**

M/s : First Capital Insurance Limited

36 Robinson Rd

#16-01 City House

Singapore 068877

Attn : Motor Claim Dept

Dear Sir/Madam,

Accident Repair On : SLG9186J - HONDA ODYSSEY ABSOLUTE 2.4 A

Insured : Hitachi Capital Asia Pacific Pte Ltd

Date of Accident : 25/02/2017

Your Insured Veh No : SHC2640D

Quote No : 00004582

RevisionNo : 1

Date : 01/03/2017

Page : 1 / 3

*Tanpin 97495749*

*DS*

*Before part.*

*2/3/17 @ 1740*

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED :-

		Qty	S\$Unit	S\$Amt	S\$Labor
<b>1. Body Repair</b>	<b>Parts Replacement</b>				
1 Rear Bumper		1.00	558.50	558.50 <i>de</i>	✓
2 Rear Bumper Clips		10.00	5.50	55.00 <i>ne</i>	✓
3 Rear Bumper Retainer Inner		2.00	25.60	51.20 <i>ne</i>	✓
4 Rear Bumper Retainer Outer - 2pcs				<i>200</i>	
5 Reverse Sensor (1set)	S/Nett	1.00	250.00	250.00 <i>na</i>	✓
6 Bumper Reflector LH/RH		2.00	45.50	91.00 ?	X
7 Bumper Lower Spoiler LH/RH					
8 Bumper Lower Spoiler Chrome LH/RH		2.00	141.50	283.00 ?	X
9 Tailgate		1.00	1,305.60	1,305.60 <i>bt</i>	✓
10 Tailgate Chrome Moulding Outer		1.00	185.60	185.60 <i>bt</i>	✓
11 Tailgate Lamp LH/RH		2.00	389.60	779.20 <i>cu</i>	✓
12 Tailgate Centre Moulding Garnish		1.00	201.50	201.50 ?	✓
13 Tailgate "H" Logo		1.00	38.50	38.50 <i>ne</i>	✓
14 Number Plate with Casing	S/Nett	1.00	45.00	45.00 X	X
15 Rear End Panel		1.00	410.50	410.50 ?	✓
16 Tail Lamp LH/RH		<u>2.00</u>	821.50	1,643.00 ?	✓
17 Rear Bumper Garnish LH/RH					
18 Tailgate Lock		1.00	201.50	201.50 <i>ju</i>	<i>plate</i> ✓
19 Rear Fender RH		1.00	978.50	978.50 <i>Rx</i>	X
20 Sealant	S/Nett	1.00	45.00	45.00 <i>ne</i>	✓
21 Rear Windscreen Moulding		4.00	38.50	154.00 <i>ne</i>	✓
22 Spare Tyre Compartment		1.00	1,411.50	1,411.50 <i>Rx</i>	X
23 Spare Tyre Sponge					X
24 Spare Tyre Board					X
25 Tailgate Inner Trim Board		1.00	202.50	202.50 ?	X

**Hitachi Capital Asia Pacific Pte. Ltd.**

**Jun Taiyo Service Centre**

No. 8 Fourth Lok Yang Road Singapore 629705

Tel: 64663022

Fax: 68966591

Co.Reg.No. 199400399N

GST Reg. No. M2-0118999-3

**VEHICLE ESTIMATE**

M/s : First Capital Insurance Limited  
36 Robinson Rd  
#16-01 City House  
Singapore 068877  
Attn : Motor Claim Dept

Quote No : 00004582  
RevisionNo : 1  
Date : 01/03/2017  
Page : 2 / 3

Dear Sir/Madam,

Accident Repair On : SLG9186J - HONDA ODYSSEY ABSOLUTE 2.4 A  
Insured : Hitachi Capital Asia Pacific Pte Ltd  
Date of Accident : 25/02/2017  
Your Insured Veh No : SHC2640D

**2. Labour Charge**

1 Panel beat, cut, weld, re-align and replace damaged parts of REAR portion	1500 2,250.00
2 Spray painting on REAR portion of affected area	<del>1000</del> 1250. 2,000.00
3 Check Wiring and ensure proper function	30 80.00
4 Remove & reinstall bumper sensors	30 120.00
5 Cavity Treatment on New Parts	40 80.00
6 Remove and Replace Tailgate Windscreen	120 180.00
7 Transfer tailgate lock & mechanism to new tailgate	60 120.00
8 Conduct water seepage test	40 120.00
9 Diagnostic Check & Reset	100 180.00

SubTotal : 8,890.80 5,130.00

**Less:**

1 List Items Discount on List Items - 20%

-1,710.12  
SubTotal : -1,710.12  
Grand Total : 12,310.48  
Add 7 % GST : 861.73  
Net Total After GST : 13,172.21

parts \$ 5584.10 - 20% = \$ 4467.28

SINOTT \$ 245

Labour \$ 3170

\* Total P/P \$ 7882.28 @ 8 day \*

## Janice Lee (LKKAUTO)

---

**From:** Chong Kean Yap <KeanYap.Chong@hcspl.com.sg>  
**Sent:** Tuesday, 16 May, 2017 5:45 PM  
**To:** Taufikh (LKKAUTO)  
**Cc:** Rasul (LKKAUTO); SUR  
**Subject:** RE: SLG9186J TP/1ST CAPITAL FINALIZATION  
**Attachments:** DSCN6784.JPG; DSCN6771.JPG; DSCN6772.JPG; DSCN6773.JPG; DSCN6776.JPG

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

Hi Taufikh,

Bot Tail lamp also replaced.

Please refer Rasul if got take photo for this case.

Kindly revert this case P/P \$7,882.28 before GST.  
8 day.

Thanks.

Chong Kean Yap  
Motor Claims Advisor  
Auto Servicing Section

Hitachi Capital Asia Pacific Pte. Ltd.  
**Jun Taiyo Service Centre (Automobile Leasing & Workshop)**  
8 Fourth Lok Yang Road, Singapore 629705  
t: 6833 6282  
e: KeanYap.Chong@hcspl.com.sg  
w: [www.hitachi-capital.com.sg](http://www.hitachi-capital.com.sg)

**HITACHI**  
Inspire the Next

---

**NOTE:** Effective **01 April 2015**, Hitachi Capital Singapore Pte. Ltd. has been renamed "**Hitachi Capital Asia Pacific Pte. Ltd.**". However, our main business operation and activities remain unchanged, including our operating address and contact. Kindly assist to address all future correspondences including all issuance of cheques and remittances to "Hitachi Capital Asia Pacific Pte. Ltd.".

We thank you for your attention and cooperation, and we look forward to being of service to you.

**DISCLAIMER:**

This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED. This email is intended solely for the attention and use of the name addressee(s). If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments. If you have received this email in error, please notify the sender immediately by email and delete it from your system.

---

From: "Taufikh (LKK Auto)" <taufikh@lkkauto.com>  
To: "Chong Kean Yap" <KeanYap.Chong@hcspl.com.sg>  
Date: 12/04/2017 03:35 PM  
Subject: RE: SLG9186J TP/1ST CAPITAL FINALIZATION

---

Hi Chong,

If taillamps not replaced, COR is \$6567.80 , 8 days.

Regards  
Taufikh  
Lkk Auto

**From:** Chong Kean Yap [<mailto:KeanYap.Chong@hcspl.com.sg>]  
**Sent:** Tuesday, 11 April 2017 8:23 AM  
**To:** [taufikh@lkkauto.com](mailto:taufikh@lkkauto.com)  
**Cc:** Ai Phing; admin-a; cs-a@lkkauto.com; Jas Khine (LKKAuto); SUR  
**Subject:** SLG9186J TP/1ST CAPITAL FINALIZATION

Hi Taufikh,

Attached with photo for your reference.

Please confirm final repair cost P/P \$7,882.28 before GST.  
8 day

Chong Kean Yap  
Motor Claims Advisor  
Auto Servicing Section

Hitachi Capital Asia Pacific Pte. Ltd.  
**Jun Taiyo Service Centre (Automobile Leasing & Workshop)**  
8 Fourth Lok Yang Road, Singapore 629705  
t: 6833 6282  
e: [KeanYap.Chong@hcspl.com.sg](mailto:KeanYap.Chong@hcspl.com.sg)  
w: [www.hitachi-capital.com.sg](http://www.hitachi-capital.com.sg)

**HITACHI**  
Inspire the Next

**NOTE:** Effective **01 April 2015**, Hitachi Capital Singapore Pte. Ltd. has been renamed "*Hitachi Capital Asia Pacific Pte. Ltd.*". However, our main business operation and activities remain unchanged, including our operating address and contact. Kindly assist to address all future correspondences including all issuance of cheques and remittances to "Hitachi Capital Asia Pacific Pte. Ltd.".

We thank you for your attention and cooperation, and we look forward to being of service to you.

**DISCLAIMER:**

This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED. This email is intended solely for the attention and use of the name addressee(s). If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments. If you have received this email in error, please notify the sender immediately by email and delete it from your system.

**Janice Lee (LKKAUTO)**

**From:** Chong Kean Yap <KeanYap.Chong@hcspl.com.sg>  
**Sent:** Tuesday, 11 April, 2017 8:23 AM  
**To:** Taufikh (LKKAUTO)  
**Cc:** Ai Phing (LKKAUTO); Admin A; CS A Team; Jas Khine (LKKAUTO); SUR  
**Subject:** SLG9186J TP/1ST CAPITAL FINALIZATION  
**Attachments:** juntaiyo@hcspl.com.sg\_20170411\_063141.pdf; DSCN6164.JPG; DSCN6167.JPG; DSCN6168.JPG; DSCN6170.JPG; DSCN6171.JPG; DSCN6172.JPG; DSCN6173.JPG; DSCN6174.JPG; DSCN6771.JPG; DSCN6772.JPG; DSCN6774.JPG; DSCN6775.JPG; DSCN6776.JPG; DSCN6777.JPG; DSCN6778.JPG; DSCN6780.JPG; DSCN6781.JPG; DSCN6782.JPG; DSCN6783.JPG; DSCN6784.JPG

Hi Taufikh,

Attached with photo for your reference.

Please confirm final repair cost P/P \$7,882.28 before GST.  
8 day

Chong Kean Yap  
Motor Claims Advisor  
Auto Servicing Section

Hitachi Capital Asia Pacific Pte. Ltd.  
**Jun Taiyo Service Centre (Automobile Leasing & Workshop)**  
8 Fourth Lok Yang Road, Singapore 629705  
t: 6833 6282  
e: KeanYap.Chong@hcspl.com.sg  
w: [www.hitachi-capital.com.sg](http://www.hitachi-capital.com.sg)


**HITACHI**  
Inspire the Next

---

**NOTE:** Effective **01 April 2015**, Hitachi Capital Singapore Pte. Ltd. has been renamed "**Hitachi Capital Asia Pacific Pte. Ltd.**". However, our main business operation and activities remain unchanged, including our operating address and contact. Kindly assist to address all future correspondences including all issuance of cheques and remittances to "Hitachi Capital Asia Pacific Pte. Ltd.".

We thank you for your attention and cooperation, and we look forward to being of service to you.

**DISCLAIMER:**  
This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED. This email is intended solely for the attention and use of the name addressee(s). If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments. If you have received this email in error, please notify the sender immediately by email and delete it from your system.



# 合興汽車零件私人有限公司

## HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

### TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

ODY

GRANT

NO: HLI9052975

PAGE: 1

DATE: 03/03/2017

A/C CODE: LDHC008

TERMS: CR

VEH NO: SLG9186@J

Part No	Description	Location	Qty	Unit Price	Amount
1	H04715-T6A-900ZZ	RR.BUMPER			HU3-TOP8
2	H91503-SZ3-003 OEM	CLIP BUMPER			HDS
3	H71593-T6A-003	RR.SIDE RETAINER RH			H2K56
4	H71598-T6A-003	RR.SIDE RETAINER LH			H2K56
5	H74891-T6A-003	RR.LIC.GARN.LOW.(CHROME )			H2J
6	H33500-T6A-003	TAIL LAMP ASSY RH			HU3-74
7	H33550-T6A-003	TAIL LAMP ASSY LH			HU3-19
8	H75701-T6A-000	REAR LOGO			HDS
9	H74800-TF0-J01	TAILGATE IN.LOCK			H1A4
10	H73214-T6A-003	RR.W/S.SIDE MLDG.(R&L)			H2K6
11	H73226-SZW-000	RR.W/S.MLDG(TOP & LO)			HDS
12	H73225-TM8-000	RR.W/S. MOULDING LOWER SHORT			H1H3
13	H68100-T6A-Q10ZZ	TRUNK LID			HU3017-6

TOTAL QUANTITY:

O/R:

91998

Inspector	General Manager Approval	Dept Manager Approval

Print / LSK / 3/3/2017 10:09:33 AM

SALESMAN: LSK

This document is computer generated. No signature required.

GOODS S

E. & O. E.

GOODS F






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17004317/T1rbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-10-2018	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 2640D	Veh. Inspected	SLG 9186J	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17002310MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	02/03/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA ODYSSEY	c.c	2356	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RC11114604	Colour	BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	DUNLOP	6 mm	
L/H Front Tyre	215/55 R17	DUNLOP	6 mm	
R/H Rear Tyre	215/55 R17	DUNLOP	6 mm	
L/H Rear Tyre	215/55 R17	DUNLOP	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	25/02/2017	Inspection Date	02/03/2017	
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 9186J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	DEFORMED	558.50	558.50
10	REAR BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
2	REAR BUMPER RETAINER INNER @\$25.60	NECESSARY	51.20	51.20
2	REAR BUMPER RETAINER OUTER (NPA)	NOT NECESSARY	-	-
2	BUMPER REFLECTOR LH / RH @\$45.50	NOT NECESSARY	91.00	-
2	BUMPER LOWER SPOILER LH / RH (NPA)	NOT NECESSARY	-	-
2	BUMPER LOWER SPOILER CHROME LH / RH @\$141.50	NOT NECESSARY	283.00	-
1	TAILGATE	BENT	1,305.60	1,305.60
1	TAILGATE CHROME MOULDING OUTER	CUT	185.60	185.60
2	TAILGATE LAMP LH / RH @\$389.60	CRACKED	779.20	779.20
1	TAILGATE CENTRE MOULDING GARNISH	CRACKED	201.50	201.50
1	TAILGATE "H" LOGO	NECESSARY	38.50	38.50
1	REAR END PANEL	BENT	410.50	410.50
2	TAIL LAMP LH / RH @\$821.50	CUT	1,643.00	1,643.00
2	REAR BUMPER GARNISH LH / RH (NPA)	NOT NECESSARY	-	-
1	TAILGATE LOCK	JAMMED	201.50	201.50
1	REAR FENDER RH	TO REPAIR SEE LABOUR	978.50	-
4	REAR WINDSCREEN MOULDING @\$38.50	NECESSARY	154.00	154.00
1	SPARE TYRE COMPARTMENT	TO REPAIR SEE LABOUR	1,411.50	-
1	SPARE TYRE SPONGE (NPA)	NOT NECESSARY	-	-
1	SPARE TYRE BOARD (NPA)	NOT NECESSARY	-	-
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	202.50	-
	LESS 20% DISCOUNT		-1,710.12	-1,116.82
			6,840.48	4,467.28
<b>SPECIAL NETT ITEMS</b>				
1	SET REVERSE SENSOR (SN)	NOT WORKING	250.00	200.00
1	NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	45.00	-
1	SEALANT (SN)	NECESSARY	45.00	45.00
			340.00	245.00

Report Ref No. CS/FCI17004317/T1rbe2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	PANEL BEAT, CUT, WELD, RE-ALIGN AND REPLACE DAMAGED PARTS OF REAR PORTION. INCLUSIVE OF THE REPAIR OF REAR FENDER RH AND SPARE TYRE COMPARTMENT.		2,250.00	1,500.00
	SPRAY PAINTING ON REAR PORTION OF AFFECTED AREA.		2,000.00	1,250.00
	CHECK WIRING AND ENSURE PROPER FUNCTION.		80.00	30.00
	REMOVE & REINSTALL BUMPER SENSORS.		120.00	30.00
	CAVITY TREATMENT ON NEW PARTS.		80.00	40.00
	REMOVE AND REPLACE TAILGATE WINDSCREEN.		180.00	120.00
	TRANSFER TAILGATE LOCK & MECHANISM TO NEW TAILGATE.		120.00	60.00
	CONDUCT WATER SEEPAGE TEST.		120.00	40.00
	DIAGNOSTIC CHECK & RESET.		180.00	100.00
			5,130.00	3,170.00
	<b>GRAND TOTAL</b>		<b>12,310.48</b>	<b>7,882.28</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>7,882.28</b>

Report Ref No. CS/FCI17004317/T1rbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.