

ASS. REC. BY:

REF:

CS/FCL17004765/RIrb 9

Special Instruction:

Surveyor:

Rahul

ASSIGNMENT (Office)

From (Person):

CWS

Sittara

of

FCL

Date/Time:

09/03/2017

9:08am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 7907K

Insured:

SHR 9312D

at Workshop m/s

Hitachi Capital

Tel:

6633 6281

of

8 Fourth Loke Yang Road.

Policy No:

Claim No:

D17002600MFSM

Sum Insured:

Excess:

Make of Veh:

D.O.A.

06/03/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

09/03/2017 9:29am

Person Contacted:

zhuma

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLB 7907K - X
	SHR 9312D - CS3 / FCL16024310 / Sqham2 D.M: SD1116
10/3/2017	Sent preli to Sittara
	Confirmed \$1137.68, 11 days Red: \$905.17, 45%

ASS. REC. BY: *[Signature]*

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No _____

Claims No _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: 11 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

Veh No: SLB 7907K Yr Regn: 2016 / APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: TOYOTA COROLLA MTRD 1.6 c.c 1598

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 49742 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRO53REH104550165

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal: 6 mm Rear R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 06/03/17 D.O.I. 07/03/17

Survey held at: HIMACH

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 10 APR 2018

Date/Time File Pass to? Preli. Report

1) typist Final Report

Date/Time File Return to?

2) _____

Days Of Repair: 1

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: Site Insp (\$ _____) S + PS \$ _____

Interview (\$ _____) Photos 580

Tech. Invs (\$ _____) Others _____

Weekend (\$ _____) _____

TOTAL

Report Format: TP
Lump Sum / I.B.I: (\$ 1137.68)

10X15 =
10X15
120750
50
50
154
604



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17004765/R1rb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-03-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9342D	Veh. Inspected	SLB 7907K
Policy No.		Coverage (\$)	0.00
Claim No.	D17002600MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	09/03/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/03/2017	Inspection Date	09/03/2017
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	08-03-2017	Our Ref No. D17002600MFSH
Accident Date	06-03-2017	Claim Type. Third Party
Insured Vehicle	SHA9342D	Third Party Vehicle. SLB7907K
Survey Location	JUN TAIYO SERVICE CENTRE NO 8 FOURTH LOK YANG ROAD	
Contact Person.	SUN ZHU MEI	
Contact No.	68336281/ 0	Fax No. 68966591
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT




Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HITACHI CAPITAL ASIA PACIFIC PTE. LTD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/217570)  PRI Documents  Close 

PRI Header Details

Claim No	D17002600MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & HIT PTE. LT
Workshop Name	HITACHI CAPITAL ASIA PACIFIC PTE. LTD. (Contact Person : SUN ZHU MEI)	Survey Location & Contact Details	JUN TAIYO SERVICE CENTRE NO 8 FOURTH LO Mobile: 0 , Phone: 68336281 , Fax: 6896659 EmailId: SUNZHUMEI@HCSPL.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9342D	TP Vehicle No	SLB790
PRI Recieved Date	08-03-2017 08:04:23 PM	Surveyor Appointed Date	09-03-2017 09:07:41 AM	Surveyor Accept Date	09-03-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	09-03-2017	Upload Survey Report *:	
------------------------------------	---	-----------------------------	------------	--------------------------------	---

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

[Upload Multiple Documents](#)

File Name

Action

Surveyor Job Remarks

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Friday, 10 March, 2017 3:36 PM
To: 'Claim Workflow System'; SITHARA@FIRST-INSURANCE.COM.SG
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D17002600MFSH/1
Attachments: SLB 7907K.pdf

Dear Sithara,

Enclosed preliminary revised of vehicle **SLB 7907K**.
Date of survey : 09/03/2017

Thank you.

Best Regards,

Janice Lee (Ms) | Admin

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 9 March, 2017 9:31 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17002600MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Thursday, 9 March, 2017 9:08 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SITHARA@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17002600MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17002600MFSH
Our Ref: CS/FC117004765/R1rb

Date: 10 March 2017

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLB 7907K

We thank you for the instruction on 09/03/2017.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 09/03/2017 at the premises of HITACHI CAPITAL(S) PTE LTD have the following to report:-

Workshop Estimate Amount	: <u>S\$ 20,142.85</u>
Revised Estimate Amount	: <u>S\$ 9,324.13</u>
"Check" Items Amount	: <u>S\$ 4,171.13</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:

The vehicle sustained damages at the front and rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully

RASUL
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/03/2017 18:07
Date Of Accident	06/03/2017 16:40
Exact Location Of Accident	PAYA LEBAR FLYOVER PIE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB7907K
Insured/Policyholder	
Name Of Registered Owner	HITACHI CAPITAL ASIA PACIFIC PTE LTD
Co Reg No	199400399N
Email Address	JUNTAIYO@HCSPL.COM.SG
Mobile Phone No	
Alternative Phone No	Office-64663022

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CLASSIC CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? No

If No, Please state action to be taken Third Party

Vehicle Category Private Car

Insurance Company

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	MSD/VPCP/16-001051-00
Cover Note Number	

Driver

Name of Driver	LIM SWEE CHOON
NRIC No	S1757162A
Date Of Birth	15/09/1966
Occupation	Outdoor
Date Of Driving Pass	16/10/1985
Driving Experience	31 Years And 4 Months
Gender	Male
Mobile Number	(Local) +65-87820493
Fax Number	
Contact Number	
Email Address	ERNESTLIM.2017@GMAIL.COM

Address
 Postcode
 Was driver an employee of the Insured's Company No
 If No, Relationship of the Driver with the Insured Other - LESSEE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident Collision- Chain Collision
 Weather Conditions AFTER RAIN
 Road Surface Wet

Other Information

Was any foreign vehicle involved in this accident? No
 Was any body injured in the Accident? No
 Was any other material or property damaged? Yes
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. Yes
 Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? No
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? No
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE ATTACHED.

Attachment(s)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGY2564L
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver CHOO HENG WEE
 NRIC/Passport Number
 Contact Number 97451927
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHA9342D
 Vehicle Make/Model/Colour

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time




Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan



Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel: 64663022 Fax: 68966591
 Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

VEHICLE ESTIMATE

M/s : First Capital Insurance Limited
 36 Robinson Rd
 #16-01 City House
 Singapore 068877

Quote No : 00004595
 RevisionNo :
 Date : 08/03/2017
 Page : 1 / 4

Attn : Motor Claim Dept

Dear Sir/Madam,

Accident Repair On : SLB7907K - Toyota Altis
 Insured : Hitachi Capital Asia Pacific Pte Ltd
 Date of Accident : 06/03/2017
 Your Insured Veh No : SHA9342D

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED :-

		Qty	S\$Unit	S\$Amt	S\$Labor
1. Body Repair	Parts Replacement				
1 Rear Bumper		1.00	495.80	495.80 DE	/ -
2 Rear Bumper Clips		10.00	5.50	55.00 Re	/ -
3 Rear Bumper Side Retainer Outer		2.00	120.50	241.00 Re	/ -
4 Reverse Sensor Original Set		1.00	281.60	281.60 Re	/ -
5 Rear Reinforcement		1.00	395.60	395.60 Pt	/ -
6 Rear Reinforcement Bracket		2.00	68.50	137.00 X	see
7 Rear Bumper Reflector Lamp		2.00	55.80	111.60 X	8 see
8 End Panel		1.00	590.50	590.50 Pt	/ -
9 End Panel Garnish		1.00	240.50	240.50 DE	/ -
10 Bootlid Weatherstrip		1.00	185.50	185.50 Cut	/ -
11 Bootlid Emblem Logo		1.00	60.60	60.60 Re	/ -
12 Bootlid "COROLLA" Emblem		1.00	35.50	35.50 Re	/ -
13 Bootlid "ALTIS" Emblem		1.00	35.50	35.50 Re	/ -
14 Bootlid		1.00	755.60	755.60 Re	/ -
15 Bootlid Lock		1.00	221.50	221.50 Pt	/ -
16 Bootlid Lamp		2.00	355.60	711.20 X	see
17 Bootlid Hinge		2.00	58.50	117.00 X	see
18 Tail Lamp		2.00	395.60	791.20 ?	X see
19 Tail Lamp Lower Bracket		2.00	80.50	161.00 ?	X see
20 Spare Tyre Compartment	Repair				
21 Spare Tyre Board		1.00	254.50	254.50 X	see
22 Bonnet		1.00	1,050.50	1,050.50 Pt	/ -
23 Bonnet Hinge		2.00	75.80	151.60 X	see
24 Bonnet Lock		1.00	145.50	145.50 Pt	/ -
25 Front Grille with Chrome Moulding		1.00	595.80	595.80 ?	Cat
26 Front Grille Clips		6.00	5.50	33.00 Re	/ -
27 Front Grille Top Cover Garnish		1.00	85.50	85.50 ?	X see

Hitachi Capital Asia Pacific Pte. Ltd.

Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705

Tel: 64663022

Fax: 68966591

Co.Reg.No. 199400399N

GST Reg. No. M2-0118999-3

VEHICLE ESTIMATE

M/s : First Capital Insurance Limited
36 Robinson Rd
#16-01 City House
Singapore 068877

Quote No : 00004595
RevisionNo :
Date : 08/03/2017
Page : 2 / 4

Attn : Motor Claim Dept

Dear Sir/Madam,

Accident Repair On : SLB7907K - Toyota Altis
Insured : Hitachi Capital Asia Pacific Pte Ltd
Date of Accident : 06/03/2017
Your Insured Veh No : SHA9342D

28 Front Bumper		1.00	460.50	460.50	DE
29 Front Bumper Clips		10.00	5.50	55.00	neu
30 Front Bumper Retainer Small Inner		2.00	15.80	31.60	X
31 Front Bumper Side Retainer Outer		2.00	110.80	221.60	X
32 Front Fog Lamp Cover LH/RH		2.00	65.80	131.60	X
33 Front Bumper Centre Lower Grille		1.00	155.60	155.60	?
34 Headlamp		2.00	850.60	1,701.20	CRA
35 Front Reinforcement		1.00	395.60	395.60	?
36 Front Bumper Sponge		1.00	110.50	110.50	?
37 Support Panel Assembly		1.00	985.60	985.60	PT
38 Brace Panel		1.00	155.60	155.60	R
39 Engine Undercover Centre		1.00	178.50	178.50	X
40 Engine Undercover Clips		10.00	5.50	55.00	X
41 Aircon Condenser		1.00	1,475.80	1,475.80	?
42 Radiator		1.00	1,790.50	1,790.50	?
43 Front Number Plate with Casing	S/Nett	1.00	45.00	45.00	PT-35
44 Coolant	S/Nett	1.00	80.00	80.00	neu/60
45 Rear Number Plate with Casing	S/Nett	1.00	45.00	45.00	8: neu

2. Labour Charge

1 Panel beat, cut, weld, re-align and replace damaged parts of FRONT portion	3 days	1,750.00	600
		750	
2 Spray painting work on FRONT portion of affected area	- 750	1,500.00	600
3 Panel beat, cut, weld, re-align and replace damaged parts of REAR portion		2,000.00	600
	4 days	- 1250	
4 Spray painting on REAR portion of affected area		1,500.00	1000
		- 1250	
5 Check Wiring, re-align headlamps and Tail Lamp to ensure proper function.		100.00	30

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel: 64663022 Fax: 68966591
Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

VEHICLE ESTIMATE

M/s : First Capital Insurance Limited
36 Robinson Rd
#16-01 City House
Singapore 068877

Attn : Motor Claim Dept

Quote No : 00004595
RevisionNo :
Date : 08/03/2017
Page : 3 / 4

Dear Sir/Madam,

Accident Repair On : SLB7907K - Toyota Altis
Insured : Hitachi Capital Asia Pacific Pte Ltd
Date of Accident : 06/03/2017
Your Insured Veh No : SHA9342D

6 Refill compressor oil, vacuum and refill aircond gas	80	180.00	100
7 Remove & reinstall bumper sensors		120.00	60
8 Cavity Treatment on New Parts		160.00	100
9 Conduct four wheel alignment / side slip test		180.00	X ^{na}
10 Remove & re-install Rear Trim Compartment to facilitate cutting and repairing work		180.00	80
11 Transfer bootlid lock & mechanism to new bootlid		120.00	X ^{na}
12 Conduct water seepage test		120.00	30
13 Diagnostic Check & Reset		180.00	60

SubTotal : 16,013.80 8,090.00

Less:

1 List Items Discount on List Items - 25%

-3,960.95
SubTotal : -3,960.95

Grand Total : 20,142.85
Add 7 % GST : 1,410.00
Net Total After GST : 21,552.85

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel: 64663022 Fax: 68966591
Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

VEHICLE ESTIMATE

M/s : First Capital Insurance Limited
36 Robinson Rd
#16-01 City House
Singapore 068877

Attn : Motor Claim Dept

Dear Sir/Madam,

Accident Repair On : SLB7907K - Toyota Altis
Insured : Hitachi Capital Asia Pacific Pte Ltd
Date of Accident : 06/03/2017
Your Insured Veh No : SHA9342D

Quote No : 00004595
RevisionNo :
Date : 08/03/2017
Page : 4 / 4

No. of days needed for repair : 16



CUSTOMER SIGNATURE

Hitachi Capital Asia Pacific Pte. Ltd.
(Manager)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Rasul
HP 90010068
11 days
P/P
09/03/17 @ 1530
Resurvey by part
15/3/17.

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel: 64663022 Fax: 68966591
 Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

VEHICLE ESTIMATE

M/s : First Capital Insurance Limited
 36 Robinson Rd
 #16-01 City House
 Singapore 068877

Quote No : 00004595
 RevisionNo :
 Date : 08/03/2017
 Page : 1 / 4

Attn : Motor Claim Dept

Dear Sir/Madam,

Accident Repair On : SLB7907K - Toyota Altis
 Insured : Hitachi Capital Asia Pacific Pte Ltd
 Date of Accident : 06/03/2017
 Your Insured Veh No : SHA9342D

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED :-

		Qty	S\$Unit	S\$Amt	S\$Labor
1. Body Repair	Parts Replacement				
1	Rear Bumper	1.00	495.80	495.80	DE ✓
2	Rear Bumper Clips	10.00	5.50	55.00	DE ✓
3	Rear Bumper Side Retainer Outer	2.00	120.50	241.00	DE ✓
4	Reverse Sensor Original Set	1.00	281.60	281.60	DE ✓
5	Rear Reinforcement	1.00	395.60	395.60	BT ✓
6	Rear Reinforcement Bracket	2.00	88.50	137.00	X
7	Rear Bumper Reflector Lamp	2.00	55.80	111.60	X
8	End Panel	1.00	590.50	590.50	BT ✓
9	End Panel Garnish	1.00	240.50	240.50	DE ✓
10	Bootlid Weatherstrip	1.00	185.50	185.50	DE ✓
11	Bootlid Emblem Logo	1.00	60.60	60.60	DE ✓
12	Bootlid "COROLLA" Emblem	1.00	35.50	35.50	DE ✓
13	Bootlid "ALTIS" Emblem	1.00	35.50	35.50	DE ✓
14	Bootlid	1.00	755.60	755.60	DE ✓
15	Bootlid Lock	1.00	221.50	221.50	BT ✓
16	Bootlid Lamp	2.00	355.60	711.20	X
17	Bootlid Hinge	2.00	58.50	117.00	X
16	Tail Lamp	2.00	395.80	791.20	? X
19	Tail Lamp Lower Bracket	2.00	80.50	161.00	? X
20	Spare Tyre Compartment				X
21	Spare Tyre Board	1.00	254.50	254.50	X
22	Bonnet	1.00	1,050.50	1,050.50	BT ✓
23	Bonnet Hinge	2.00	75.80	151.60	X
24	Bonnet Lock	1.00	145.50	145.50	BT ✓
25	Front Grille with Chrome Moulding	1.00	595.80	595.80	? ✓
26	Front Grille Clips	6.00	5.50	33.00	DE ✓
27	Front Grille Top Cover Garnish	1.00	85.50	85.50	? X

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel: 64663022 Fax: 68966591
 Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

VEHICLE ESTIMATE

M/s : First Capital Insurance Limited
 36 Robinson Rd
 #16-01 City House
 Singapore 068877

Quote No : 00004595
 RevisionNo :
 Date : 08/03/2017
 Page : 2 / 4

Attn : Motor Claim Dept

Dear Sir/Madam,

Accident Repair On : SLB7907K - Toyota Altis
 Insured : Hitachi Capital Asia Pacific Pte Ltd
 Date of Accident : 06/03/2017
 Your Insured Veh No : SHA9342D

28 Front Bumper	1.00	460.50	460.50	DE ✓
29 Front Bumper Clips	10.00	5.50	55.00	new ✓
30 Front Bumper Retainer Small Inner	2.00	15.80	31.80	X
31 Front Bumper Side Retainer Outer	2.00	110.80	221.60	X
32 Front Fog Lamp Cover LH/RH	2.00	65.80	131.80	X
33 Front Bumper Centre Lower Grille	1.00	155.80	155.80	? ✓
34 Headlamp	2.00	850.60	1,701.20	CR ✓
35 Front Reinforcement	1.00	395.60	395.60	? X
36 Front Bumper Sponge	1.00	110.50	110.50	? X
37 Support Panel Assembly	1.00	985.60	985.60	PR ✓
38 Brace Panel	1.00	155.60	155.60	R
39 Engine Undercover Centre	1.00	178.50	178.50	X
40 Engine Undercover Clips	10.00	5.50	55.00	X
41 Aircon Condenser	1.00	1,475.80	1,475.80	? X
42 Radiator	1.00	1,790.50	1,790.50	? X
43 Front Number Plate with Casing	S/Nett	1.00	45.00	PR-35 ✓
44 Coolant	S/Nett	1.00	80.00	new 60 ✓
45 Rear Number Plate with Casing	S/Nett	1.00	45.00	X

2. Labour Charge

1 Panel beat, cut, weld, re-align and replace damaged parts of FRONT portion			1,750.00	600 ✓
2 Spray painting work on FRONT portion of affected area			750 1,500.00	600 ✓
3 Panel beat, cut, weld, re-align and replace damaged parts of REAR portion			2,000.00	600 ✓
4 Spray painting on REAR portion of affected area			1250 1,500.00	600 ✓
5 Check Wiring, re-align headlamps and Tail Lamp to ensure proper function			100.00	30 ✓

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel: 64663022 Fax: 68966591
 Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

VEHICLE ESTIMATE

M/s : First Capital Insurance Limited
 36 Robinson Rd
 #16-01 City House
 Singapore 068877

Quote No : 00004595
 RevisionNo :
 Date : 08/03/2017
 Page : 3 / 4

Attn: Motor Claim Dept

Dear Sir/Madam,

Accident Repair On : SLB7907K - Toyota Altis
 Insured : Hitachi Capital Asia Pacific Pte Ltd
 Date of Accident : 08/03/2017
 Your Insured Veh No : SHA9342D

6 Refill compressor oil, vacuum and refill aircord gas	80 180.00 100✓
7 Remove & reinstall bumper sensors	120.00 60✓
8 Cavity Treatment on New Parts	180.00 100✓
9 Conduct four wheel alignment / side slip test	180.00 X
10 Remove & re-install Rear Trim Compartment to facilitate cutting and repairing work	180.00 80✓
11 Transfer bootlid lock & mechanism to new bootlid	120.00 X
12 Conduct water seepage test	120.00 30✓
13 Diagnostic Check & Reset	180.00 60✓

SubTotal : 16,013.80 8,090.00

Less:

1 List Items Discount on List Items - 25%

-3,960.95
 SubTotal : -3,960.95
 Grand Total : 20,142.85
 Add 7 % GST : 1,410.00
Net Total After GST : 21,552.85

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel: 64863022 Fax: 68966591
Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

VEHICLE ESTIMATE

M/s : First Capital Insurance Limited
38 Robinson Rd
#16-01 City House
Singapore 068877

Attn : Motor Claim Dept

Dear Sir/Madam,

Accident Repair On : SLB7907K - Toyota Allis
Insured : Hitachi Capital Asia Pacific Pte Ltd
Date of Accident : 08/03/2017
Your Insured Veh No : SHA9342D

Quote No : 0004555
RevisionNo :
Date : 08/03/2017
Page : 4 / 4

No. of days needed for repair : 16

CUSTOMER SIGNATURE



Hitachi Capital Asia Pacific Pte. Ltd.
(Manager)

Rasul
HP 90010068

11 days

P/P

09/03/17 @ 1530

Resury 64 part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Parts \$8776.90 - 25% = \$6582.68

stnatt \$95

labour \$4460

* P/P total \$11137.68 @ 11 day *

Janice Lee (LKKAuto)

From: Chong Kean Yap <KeanYap.Chong@hcspl.com.sg>
Sent: Wednesday, August 16, 2017 8:42 AM
To: Rasul (LKKAuto)
Cc: SUR
Subject: SLB7907K TP/1ST CAPITAL FINALIZATION
Attachments: juntaiyo@hcspl.com.sg_20170816_063026.pdf; DSCN7504.JPG; DSCN7480.JPG; DSCN7482.JPG; DSCN7483.JPG; DSCN7484.JPG; DSCN7485.JPG; DSCN7487.JPG; DSCN7489.JPG; DSCN7490.JPG; DSCN7491.JPG; DSCN7492.JPG; DSCN7494.JPG; DSCN7495.JPG; DSCN7496.JPG; DSCN7497.JPG; DSCN7499.JPG; DSCN7500.JPG; DSCN7501.JPG; DSCN7502.JPG; DSCN7503.JPG; DSCN7065.JPG; DSCN7059.JPG; DSCN7061.JPG; DSCN7062.JPG; DSCN7064.JPG

Hi Rasul,

Attached with photo and preliminary report.

Please confirm final repair cost P/P \$11,137.68 before GST.
11 day

Chong Kean Yap
Motor Claims Advisor
Auto Servicing Section

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road, Singapore 629705
t: 6833 6282
e: KeanYap.Chong@hcspl.com.sg
w: www.hitachi-capital.com.sg

HITACHI
Inspire the Next

NOTE: Effective **01 April 2015**, Hitachi Capital Singapore Pte. Ltd. has been renamed "***Hitachi Capital Asia Pacific Pte. Ltd.***". However, our main business operation and activities remain unchanged, including our operating address and contact. Kindly assist to address all future correspondences including all issuance of cheques and remittances to "Hitachi Capital Asia Pacific Pte. Ltd.".

We thank you for your attention and cooperation, and we look forward to being of service to you.

DISCLAIMER:

This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED. This email is intended solely for the attention and use of the name addressee(s). If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments. If you have received this email in error, please notify the sender immediately by email and delete it from your system.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17004765/R1rbq2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-04-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 9342D	Veh. Inspected	SLB 7907K
Policy No.	D-15072702MFSH	Coverage (\$)	0.00
Claim No.	D17002600MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	09/03/2017
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA COROLLA ALTIS 1.6	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104550165	Colour	GREY
Odometer	49742	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/03/2017	Inspection Date	09/03/2017
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 7907K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	495.80	495.80
10	REAR BUMPER SIDE RETAINER OUTER @\$5.50	NECESSARY	55.00	55.00
2	REAR BUMPER SIDE RETAINER OUTER @\$120.50	NECESSARY	241.00	241.00
1	SET REVERSE SENSOR ORIGINAL	NECESSARY	281.60	281.60
1	REAR REINFORCEMENT	BENT	395.60	395.60
2	REAR REINFORCEMENT BRACKET @\$68.50	SERVICEABLE	137.00	-
2	REAR BUMPER REFLECTOR LAMP @\$55.80	SERVICEABLE	111.60	-
1	END PANEL	BENT	590.50	590.50
1	END PANEL GARNISH	DEFORMED	240.50	240.50
1	BOOTLID WEATHERSTRIP	CUT	185.50	185.50
1	BOOTLID EMBLEM LOGO	NECESSARY	60.60	60.60
1	BOOTLID 'COROLLA' EMBLEM	NECESSARY	35.50	35.50
1	BOOTLID 'ALTIS' EMBLEM	NECESSARY	35.50	35.50
1	BOOTLID	NECESSARY	755.60	755.60
1	BOOTLID LOCK	BENT	221.50	221.50
2	BOOTLID LAMP @\$355.60	NOT NECESSARY	711.20	-
2	BOOTLID HINGE @\$58.50	NOT NECESSARY	117.00	-
2	TAIL LAMP @\$395.60	SERVICEABLE	791.20	-
2	TAIL LAMP LOWER BRACKET @\$80.50	SERVICEABLE	161.00	-
1	SPARE TYRE COMPARTMENT (NPA)	TO REPAIR SEE LABOUR	-	-
1	SPARE TYRE BOARD	SERVICEABLE	254.50	-
1	BONNET	BENT	1,050.50	1,050.50
2	BONNET HINGE @\$75.80	SERVICEABLE	151.60	-
1	BONNET LOCK	BENT	145.50	145.50
1	FRONT GRILLE WITH CHROME MOULDING	CRACKED	595.80	595.80
6	FRONT GRILLE CLIPS @\$5.50	NECESSARY	33.00	33.00
1	FRONT GRILLE TOP COVER GARNISH	SERVICEABLE	85.50	-
1	FRONT BUMPER	DEFORMED	460.50	460.50
10	FRONT BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
2	FRONT BUMPER RETAINER SMALL INNER @\$31.60	SERVICEABLE	31.60	-

Report Ref No. CS/FCI17004765/R1rbq2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT BUMPER SIDE RETAINER OUTER @\$110.80	SERVICEABLE	221.60	-
2	FRONT FOG LAMP COVER LH/RH @\$65.80	SERVICEABLE	131.60	-
1	FRONT BUMPER CENTRE LOWER GRILLE	CRACKED	155.60	155.60
2	HEADLAMP @\$850.60	CRACKED	1,701.20	1,701.20
1	FRONT REINFORCEMENT	SERVICEABLE	395.60	-
1	FRONT BUMPER SPONGE	SERVICEABLE	110.50	-
1	SUPPORT PANEL ASSEMBLY	BENT	985.60	985.60
1	BRACE PANEL	TO REPAIR SEE LABOUR	155.60	-
1	ENGINE UNDERCOVER CENTRE	SERVICEABLE	178.50	-
10	ENGINE UNDERCOVER CLIPS @\$5.50	SERVICEABLE	55.00	-
1	AIRCON CONDENSER	SERVICEABLE	1,475.80	-
1	RADIATOR	SERVICEABLE	1,790.50	-
	LESS 25% DISCOUNT		-3,960.95	-2,194.22
			11,882.85	6,582.68
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE WITH CASING (SN)	BENT	45.00	35.00
1	COOLANT (SN)	NECESSARY	80.00	60.00
1	REAR NUMBER PLATE WITH CASING (SN)	SERVICEABLE	45.00	-
			170.00	95.00
	LABOUR			
	PANEL BEAT ,CUT ,WELD ,RE-ALIGN AND REPLACE DAMAGED PARTS OF FRONT PORTION .		1,750.00	750.00
	SPRAY PAINTING WORK ON FRONT PORTION OF AFFECTED AREA.		1,500.00	750.00
	PANEL BEAT ,CUT ,WELD ,RE-ALIGN AND REPLACE DAMAGED PARTS OF REAR PORTION .		2,000.00	1,250.00
	SPRAY PAINTING ON REAR PORTION OF AFFECTED AREA.		1,500.00	1,250.00
	CHECK WIRING ,RE-ALIGN HEADLAMPS AND TAIL LAMP TO ENSURE PROPER FUNCTION .		100.00	30.00
	REFILL COMPRESSOR OIL ,VACUUM AND REFILL AIRCOND GAS.		180.00	100.00
	REMOVE & REINSTALL BUMPER SENSORS .		120.00	60.00
	CAVITY TREATMENT ON NEW PARTS.		160.00	100.00

Report Ref No. CS/FCI17004765/R1rbq2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CONDUCT FOUR WHEEL ALIGNMENT /SIDE SLIP TEST.	NOT NECESSARY	180.00	-
	REMOVE & RE-INSTALL REAR TRIM COMPARTMENT TO FACILITATE CUTTING AND REPAIRING WORK.		180.00	80.00
	TRANSFER BOOTLID LOCK & MECHANISM TO NEW BOOTLID .	NOT NECESSARY	120.00	-
	CONDUCT WATER SEEPAGE TEST.		120.00	30.00
	DIAGNOSTIC CHECK & RESET.		180.00	60.00
			8,090.00	4,460.00
	GRAND TOTAL		20,142.85	11,137.68
RECOMMENDED COST OF REPAIRS				11,137.68

Report Ref No. CS/FC117004765/R1rbq2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.