

12/03/2007

ASS. BY:

REF:

CS/MSC/17005086/PLGH3

Special Instruction:

Surveyor:
menmen

Rdsul

ASSIGNMENT (Office)

From (Person): Kwok Woon Choo

of MSC1

Date/Time: 14/3/2017 11:24am

Estimated Cost:

Bill to:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKL 1034C

Insured:

at Workshop m/s

Diplomat Parts

Tel:

65684501

of

Ava Pandan Gardens

Policy No:

80408303AMX

Claim No:

506796

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A. 8/0/2017

CA / ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Edwin

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKL1034C - CS/MSC/17004809/Avb D.O.A. 8/3/2017
15/3/17 @ 2.18pm	revert to Woon Choo via menmen.
15/3/17 @ 4.08pm	Siew Wei informed C/A via menmen.
16/3/17 @ 9.52am	Informed Edwin C/A to EX: \$500 by email.
22/4/18 @ 3.19pm	2nd revert to Woon Choo via menmen. (Supplementary)
23/4/18 @ 10.58am	Siew Wei informed C/A at \$4612.75 via menmen 26/4.

08/11/13 wef
ASS. REC. BY: *Rahul*

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SKL 1034C*

at Workshop m/s *DI PLUMBS PLUMBS*

of *C&C Pannan WARRS*

Insured: *MSH/ON*

Policy No:

Claims No:

Sum Insured: Excess: *500*

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: *78K*

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: *7* days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: *SKL 1034C* Yr Regn: *2013 / SEP*

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *TOYOTA COROLLA MRS 1.6A c.c 1558*

Colour: *BLUE* A/C: Insured / Std / NI / NA

Sp. Reading: *36935* T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: *MRS3 RCE 104166 358*

Gen. Cond: Good ☒ Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: *P515SR15*

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MID / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: *6* mm R/Bal: *6* mm

L/Bal: *6* mm L/Bal: *6* mm

D.O.A. *08/03/17* D.O.I. *14/03/17*

Survey held at: *C&C (Pg)*

Des. of Damages: ☒ Fr / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Insal ting B4612.75, 2 days (Red #3458.90, 44/10)

RECEIVED 27 APR 2018

Date/Time. File Pass to?

☐ : Prel. Report

Days Of Repair: *7*

1/29/14 10:57

☐ : Final Report

Resurvey No. of Trip: *1*

Date/Time. File Return to?

Survey Fee

Transportation

2)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) \$ - RS \$

) Photos

) Others

)

Report Format : *MEH-00*

Lump Sum / I.B.I. (\$) *46120.75*

TOTAL

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 16 March, 2017 9:52 AM
To: 'edwin.caina@cyclecarriage.com.sg'
Cc: Yusof Bin Hashim; 'Loi Ai Ting'; SUR; Don Bong Kiong Hua; Coco Lu Ting
Subject: VEHICLE SKL 1034C DOA: 08/03/2017

Dear Edwin,

As instructed by our client MSIG Insurance Company, please proceed to repair the insured vehicle SKL 1034C (excess \$500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at : 6741 8434 to arrange our surveyor for inspection.

Any supplementary items are subjected to further approval from our client.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SKL1034C (506796)

OD.

Mar 8 2017 12:00AM

[KAMALAKANNAN S/O SOUNDARARAJAN]

Diplomat Parts Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 15/03/2017 16:08 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5174.85) - SKL1034C - Claim Handler: Kwok Woon Choo

Approved:5174.85:a if c; check items to be confirmed

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 15 Mar 2017

Preliminary Advice

Vehicle No	: SKL1034C	Accident Date	: 08/03/2017
Make	: TOYOTA COROLLA ALTIS	Policy No.	: 80408303QMX
Assignment Date	: 14/03/2017	Excess	: S\$500.00
Date of Inspection	: 14/03/2017	Est. Duration of Repair	: 7.00
Inspection At	: DIPLOMAT PARTS PTE LTD (HQ) 209 PANDAN GARDENS SINGAPORE 609339		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,886.35
Revised Amount	:S\$	3,722.85
Check Items (Estimated)	:S\$	1,452.00
Total	:S\$	5,174.85

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	78,000.00
COE / PARF Rebate	:S\$	61,699.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,301.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. WE HAVE NOT AUTHORISE REPAIR.

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 2446F

Vehicle Details

Vehicle No.: SKL1034C

Vehicle to be Exported: No

Intended De-registration
Date: 15 Mar 2017

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6 A

Primary Colour: Blue

Manufacturing Year: 2013

Engine No.: 1ZR3332205

Chassis No.: MR053REE104166358

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$15,897.00

Original Registration
Date: 27 Sep 2013

First Registration Date: 27 Sep 2013

Transfer Count: 1

Actual ARF Paid: \$15,897.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 26 Sep 2023

PARF Rebate Amount: \$11,922.00

Intended COE Rebate Details

COE Expiry Date: 26 Sep 2023

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$79,223.00

COE Rebate Amount: \$49,777.00

Total Rebate Amount: \$61,699.00

The information contained herein is correct as at 15 Mar 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/03/2017 14:11
Date Of Accident	08/03/2017 08:20
Exact Location Of Accident	ALONG KJE EXPRESSWAY BEFORE PIE CHANGI EXIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL1034C
Insured/Policyholder	
Name Of Registered Owner	KAMALAKANNAN S/O SOUNDARARAJAN
NRIC No	S8632446F
Email Address	KKANNAN114@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92700986
Alternative Phone No	Others-92700986

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	DROPPING OFF SON(GOING TO WORK)
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
If No, Please state action to be taken	
Vehicle Category	Private Car

Insurance Company

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	A80408303QMX
Cover Note Number	

Driver

Name of Driver	KAMALAKANNAN S/O SOUNDARARAJAN
NRIC No	S8632446F
Date Of Birth	09/11/1986
Occupation	Indoor
Date Of Driving Pass	07/11/2006
Driving Experience	10 Years And 4 Months
Gender	Male
Mobile Number	(Local) +65-92700986
Fax Number	
Contact Number	Others-92700986
Email Address	KKANNAN114@GMAIL.COM

Address	BLK 415A FERNVALE LINK #21-40
Postcode	791415
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Owner
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	Collision- Chain Collision
Weather Conditions	Clear
Road Surface	Dry

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	No
Number of Passengers (Including Driver)	3

Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG9306E
Vehicle Make/Model/Colour	BMW 323I BLACK
Details Of Properties	
Name of Driver	LEONG YONG PENG, VAL
NRIC/Passport Number	S8708105B
Contact Number	92379075
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT & BACK BUMPER DAMAGE
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKF8345R
Vehicle Make/Model/Colour	

Details Of Properties

Name of Driver TAN WEILI,WILLI

NRIC/Passport Number

Contact Number 97846520

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "**Purposes**")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


8/3/17

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Car B hit ~~Car C~~ Car C. I hit Car B. Car B had suddenly jam brakes
I did not have enough time to respond. I applied my brakes
as hard as I could but I still hit Car B.

We declare the foregoing particulars are true in every respect.

[Signature]

Driver's Signature (If driver is not the policyholder) / Date & Time

2/10

Witnessed by Reporting Centre
Personnel



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way #21-01 SGX Centre 2 Singapore 068807
Tel: (65) 6827 7888 Fax: (65) 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ORIGINAL

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

MOTOR MAX
Comprehensive

Certificate No. A 80408303 QMX

Excess : SGD500

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SKL1034C

2. Name of Policyholder
KEMALAKANNAN S/O SOUNDARARAJAN

3. Effective Date of the Commencement of Insurance for the purposes of the Act
12/07/2016

4. Date of Expiry of Insurance
11/07/2017

5. Persons or Classes of Persons entitled to drive*

KEMALAKANNAN S/O SOUNDARARAJAN
KAVITHA D/O MEYYAPPAN

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG
AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Jin Li Pte Ltd
2 Kallang Avenue #08-16A
CT Hub S(339407)
Off : 6444 4444
Fax : 6444 0810

Signature / Date

Counter-Signatory:

Jin Li Pte Ltd

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

Amy Lor
Senior Vice President, Agencies

This certificate is not valid unless it is signed for & on behalf of the Company and Counter-Signed by a duly authorised representative of the Counter-Signatory.

XJINLIJL2016071214459373

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. SB632446F

KAMALAKANNAN S/O
SOUNDARARAJAN

சென் கமலகங்கன் ஸ்ரீனி

Race
INDIAN

Date of Birth
09-11-1986

Country of Birth
SINGAPORE

FOR C&C

REPUBLIC OF SINGAPORE DRIVING LICENSE

License Number: S8632446F

Holder:

KAMALAKANNAN S/O
SOUNDARARAJAN

Birth Date: 09 Nov 1986

Issue Date: 07 Nov 2006

USE ONLY

0014574768

AP077537

8B632446F

FOR C&C

09-11-2004

APT BLK 415A FERNVALE LINK #21-40
SINGAPORE 781415

NRIC No: 8B632446F Date: 12/07/2015

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

CLASS DATE

Class 2A Motor cars without clutch pedals (Auto) <= 3000kg, with <= 7 passengers, exclusive of the driver, and other motor vehicles without clutch pedals <= 2500kg

07 Nov 2008

USE ONLY

License No: 58623446

NP 429A

Diplomat Parts Pte Ltd (Co.Reg.No:196400304H)

209 Pandan Gardens

Singapore 609339

Tel: 65684556/65684555 Fax: 65691056 Email: angela.chua@cyclecarriage.com.sg

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	21153
Policy No:	80408303QMX	Date of Loss:	08/03/2017
Vehicle Reg. No.:	SKL1034C	Driveable?	
Driver Age/Info:	30 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KAMALAKANNAN S/O SOUNDARARAJAN	Contact No:	+6592700986
Driver:	KAMALAKANNAN S/O SOUNDARARAJAN		

Make/Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Vehicle Reg. Date:	27/09/2013
Vehicle Colour:	LIGHT BLUE		
Engine No:	1ZRX332205	Chassis No:	MR053REE104166358
Odometer:	36935 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	8

Description of Accident/Loss	REFER TO ATTACHED GIA REPORT
Present Location:	DIPLOMAT PARTS PTE LTD (HQ)

COST OF CLAIMS		Amount
Parts		3,166.35
Miscellaneous Items		110.00
Labour		2,860.00
Paintwork Labour		1,750.00
Towing		0.00
Gross Total (S\$)		7,886.35
+ GST 7.00% (S\$)		552.04
Nett Amount (S\$)		8,438.39

This claim is handled by: EDWIN ABCEDE CAINAGenerated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Mar 2017)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Diplomat Parts Pte Ltd/SKL1034C/10/03/2017 17:00

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET 1	0.00	0.00	*250.00 F BT
2	1		*BONNET LOCK	0.00	0.00	sub *55.00 F BT
3	1		*BONNET HINGE LH	0.00	0.00	sub *30.00 F BT
4	1		*BONNET HINGE RH	0.00	0.00	sub *30.00 F BT
5	7		*BONNET INSULATOR CLIPS 2	0.00	0.00	*10.50 F BT
6	1		*FRT BUMPER 3	0.00	0.00	*210.00 F BT
7	1		*FRT BUMPER REINFORCEMENT 4	0.00	0.00	*140.00 F BT
8	1		*FRT BUMPER BRACKET LH 5	0.00	0.00	*30.00 F BT
9	1		*FRT BUMPER BRACKET RH 6	0.00	0.00	*30.00 F BT
10	1		*FRT BUMPER RETAINER LH 7	0.00	0.00	*25.00 F BT
11	1		*FRT BUMPER RETAINER RH 8	0.00	0.00	*25.00 F BT
12	1		*FRT BUMPER LOWER GRILLE 9	0.00	0.00	*50.00 F BT
13	12		*FRT BUMPER CLIPS 10	0.00	15	*18.00 F BT
14	1		*RADIATOR GRILLE 11	0.00	0.00	*115.00 F BT
15	1		*FRT LOGO 12	0.00	0.00	*35.00 F BT
16	1		*HEADLAMP ASSY LH 13	0.00	0.00	*180.00 F BT
17	1		*HEADLAMP ASSY RH	0.00	0.00	*180.00 F BT
18	1		*FRT FENDER LH	0.00	0.00	*160.00 F BT
19	1		*AIRCON CONDENSER *	0.00	0.00	*300.00 F BT
20	1		*RADIATOR ASSY	0.00	0.00	*420.00 F BT
21	1		*RADIATOR FAN MOTOR	0.00	0.00	*200.00 F BT
22	1		*RADIATOR FAN COWLING	0.00	0.00	*100.00 F BT
23	1		*RADIATOR FAN BLADE	0.00	0.00	*60.00 F BT
24	1		*FRT SUPPORT PNL 14	0.00	15	*225.00 F BT

F=Franchise part.

Sub Total (S\$)	2,878.50
+ Margin on L,N Items 10.00% (S\$)	287.85
Total Parts (S\$)	3,166.35

Diplomat Parts Pte Ltd/SKL1034C/10/03/2017 17:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRT NUMBER PLATE WITH CASING	35 80.00 <i>Bl</i>
2	1	SUNDRIES	20 30.00 <i>Bl</i>
Sub Total (S\$)			110.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	RESPRAY FRT BUMPER , BONNET , FRT SUPPORT PNL , FRT GRILLE , LHF FENDER & RHF FENDER	New	1000 1,750.00
<u>Labour Items</u>			
2	RENEW & RE-ALIGN FRT DAMAGED ACCIDENT PORTION AREAS	New	800 2,450.00
3	RENEW AIRCON CONDENSER & RADIATOR	New	100.00
4	TOP UP AIRCON GAS	New	60 80.00
5	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00
6	CONDUCT DIAGNOSTIC CHECK ON VEHICLE SYSTEM	New	200.00
Gross Labour Cost (S\$)			4,610.00

Diplomat Parts Pte Ltd/SKL1034C/10/03/2017 17:00. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LOK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
Hp 900 100 68

7 days

14/03/17 @ 1530

Excess : 500

Revert

Resurvey by part

Amount to
15/3/17

Diplomat Parts Pte Ltd (Co.Reg.No:196400304H)

209 Pandan Gardens

Singapore 609339

Tel: 65684556/65684555 Fax: 65691056 Email: angela.chua@cyclecarriage.com.sg

(SUPPLEMENTARY)**INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	21153
Policy No:	80408303QMX	Date of Loss:	08/03/2017
Vehicle Reg. No.:	SKL1034C	Driveable?	
Driver Age/Info:	30 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KAMALAKANNAN S/O SOUNDARARAJAN	Contact No:	+6592700986
Driver:	KAMALAKANNAN S/O SOUNDARARAJAN		

Make/Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Vehicle Reg. Date:	27/09/2013
Vehicle Colour:	BLUE		
Engine No:	1ZRX332205	Chassis No:	MR053REE104166358
Odometer:	36935 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	8

Description of Accident/Loss	REFER TO ATTACHED GIA REPORT
Present Location:	DIPLOMAT PARTS PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	185.28
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	185.28
+ GST 7.00% (S\$)	12.97
Nett Amount (S\$)	198.25
+ Previous Estimates (S\$)	8,438.39
Claim Total (S\$)	8,636.64

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 30 Aug 2017)**Parts:** 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Diplomat Parts Pte Ltd/SKL1034C/30/08/2017 11:07**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*PANEL RADIATOR, BRACKET S	0.00	0.00	45 *57.85 F
2	1		*RADIATOR TOP BUSHING S	0.00	0.00	12 *13.09 F
3	1		*ATF - TOYOTA ALTIS S	0.00	0.00	45 *97.50 F
Sub Total (S\$)						168.44
+ Margin on L,N Items 10.00% (S\$)						16.84
Total Parts (S\$)						185.28

F=Franchise part.

Diplomat Parts Pte Ltd/SKL1034C/30/08/2017 11:07. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Diplomat Parts Pte Ltd/SKL1034C/30/08/2017 11:07. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >



FINALIZATION

DATE : 29/12/2017
VEHICLE NO : SKL1031C.
SURVEY BY : RASOL LKK
FINALISE BY : YUSOF
WIP NO : 21153

Materials	:	\$ <u>2367.75</u>
Labour	:	\$ <u>2245.00</u>
Total	:	\$ <u>4612.75</u>
Less Excess	- :	\$ <u>500.00</u>
Sub - Total	:	\$ <u>4112.75</u>
GST	:	\$ <u>287.89</u>
Grand Total	:	\$ <u>4400.64</u>

☒ REVERT BACK WITHIN 7 DAYS
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEY REPORT REQUIRED

REPAIR TOOK _____ DAYS + _____ Days (_____ Weekends)
+ _____ Days (Public Holidays)
+ _____ Days

**Diplomat Parts Pte. Ltd.**Company Reg No. 198400304H
GST Reg No. MR-6500111-X**PRO-FORMA INVOICE****THIS IS NOT AN OFFICIAL TAX INVOICE**

Invoice Name & Address

Mr Kamalakannan S/O Soundararaja
Blk 415a Fernvale Link
#21-40
Singapore 791415

Contact No Mobile: 92700986

Owner Name & Vehicle Info

Reg No/Reg Date SKL1034C / 27/09/2013
Date In/Mileage 16/03/2017/ 36935
Chassis No MR053REE104166358
Engine No 1ZRX32205
Make/Model TOYOTA COROLLA ALTIS 1.6 A

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No					
CSM00061	Cash	29/12/2017/ 09:45		447 / Yusoff	21153					
Description of Goods / Services					Qty	Unit Price	Disc%	Amount		
E	PNT88000	REPLACE DAMAGED PARTS, REPLACE FRONT SUPPORT PANEL, FRONT BONNET, REPAIR RH FRONT FENDER, & LH FRONT FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								800.00 ✓
E	PNT98000	RESPRAY ON FRONT BUMPER, BONNET, FRONT SUPPORT PANEL, FRONT GRILLE, LH FRONT FENDER, RH FRONT FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME								1000.00 ✓
A	25000001	VACUUM & TOP UP A/COND GAS								60.00 ✓
A	54900099	CHECK ELECTRICAL WIRING AND ADJUST HEADLAMP AIM								30.00 ✓
A	54900099	CONDUCT DIAGNOSTIC CHECK ON VEHICLE SYSTEM								200.00 ✓
M	SUNDRY									20.00 ✓
	SUNDRIES									
S	SPECIALISTJOB									35.00 ✓
	SUPPLY & REPLACE FRONT LICENSE PLATE WITH PLASTIC FRAME									
E	PNT88000	REMOVE & INSTALL A/COND CONDENSER AND RADIATOR ASSY TO FACILITATE REPAIR								100.00 ✓
X	EXC	INSURANCE EXCESS								-500.00
X	WFTY5330112A80					1.00	275.00	00.00	275.00 ✓	
	FRT BONNET									
X	WFTY9046709050					7.00	1.65	00.00	11.55 ✓	
	BONNET INSULATOR CLIP									
X	WFTY5211902C80					1.00	231.00	00.00	231.00 ✓	
	FRT BUMPER									
X	WFTY5202102101					1.00	154.00	00.00	154.00 ✓	
	BUMPER REINF FR									
X	WFTY5714212100					1.00	33.00	00.00	33.00 ✓	
	LHF BUMPER BRACKET									

This is not an official tax invoice. This is a computer generated document, no signature is required.



Diplomat Parts Pte. Ltd.

Company Reg No. 196400304H
GST Reg No. MR-6500111-X

PRO-FORMA INVOICE

THIS IS NOT AN OFFICIAL TAX INVOICE

Invoice Name & Address		Owner Name & Vehicle Info	
Mr Kamalakannan S/O Soundararaja Blk 415a Fernvale Link #21-40 Singapore 791415		Reg No/Reg Date SKL1034C / 27/09/2013 Date In/Mileage 16/03/2017/ 36935 Chassis No MR053REE104166358 Engine No 1ZRX32205 Make/Model TOYOTA COROLLA ALTIS 1.6 A	
Contact No	Mobile: 92700986		

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00061	Cash	29/12/2017/ 09:45		447 / YusofH	21153			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
X	WFTY5714212090				1.00	33.00	00.00	33.00
	RHF BUMPER BRACKET				1.00	27.50	00.00	27.50
X	WFTY5211602220				1.00	27.50	00.00	27.50
	LHF BUMPER RETAINER				1.00	55.00	00.00	55.00
X	WFTY5211502220				1.00	1.65	00.00	16.50
	RH BUMPER RETAINER				1.00	126.50	00.00	126.50
X	WFTY5311202330				1.00	38.50	00.00	38.50
	GRILLE RADIATOR LWR				1.00	198.00	00.00	198.00
X	WFTY521610K040				1.00	236.50	00.00	236.50
	CLIP TRIM				1.00	330.00	00.00	330.00
X	WFTY5310002905				1.00	49.50	00.00	49.50
	GRILLE RADIATOR				1.00	13.20	00.00	13.20
X	WFTY7530102050				1.00	462.00	00.00	462.00
	FRT GRILLE EMBLEM				1.00	49.50	00.00	49.50
X	WFTY8117002890				1.00			
	LH HEADLAMP				1.00			
X	WFTY5320102270				1.00			
	SUPPORT PANEL				1.00			
X	WFTY8845002350				1.00			
	A/C CONDENSER				1.00			
X	WFTY5320802120				1.00			
	PANEL RADIATOR, BRACKET				1.00			
X	WFTY165230D060				1.00			
	RADIATOR TOP BUSHING				1.00			
X	WFTY164100D420				1.00			
	RADIATOR				1.00			
X	WFTY0888602305				1.00			
	ATF - TOYOTA ALTIS, WISH, CAMRY				1.00			
Z	TEXT							
	MSG OD CLAIM							
	DOA : 08.03.17							
	SURVEYOR RASUL LKK 14.03.17							
	POLICY NO : AB0408303QMX							

PRICE CHANGE

* PRICE CHANGE

Parts	2,367.75	Nett	4,112.75
Labour	2,190.00	7% GST on	287.89
Standard Menu	0.00		
Specialist Job	35.00		
Others(Lub,etc)	-500.00	Total Payable	4,400.64
Sundry	20.00		
Total(w/o GST)	4,112.75		

This is not an official tax invoice. This is a computer generated document, no signature is required.



"SUPPLEMENTARY"

To : MSIG INSURANCE (S'PORE) PTE LTD
Attn: SURVEYOR RASUL LKK

OWNER NAME : Kamalakannan S/O Soundararajan
REGN : SKL1034C
MODEL : TOYOTA COROLLA ALTIS 1.6 A
CHASSIS NO : MR053REE104166358

PARTS		SS
1	PANEL RADIATOR, BRACKET (CP \$45.00)	49.50 <i>PA</i>
2	RADIATOR TOP BUSHING (CP \$12.00)	13.20 <i>ne</i>
3	ATF (CP \$45.00)	49.50 <i>ne</i>

TOTAL PARTS

112.20

GRAND TOTAL

\$ 112.20

Prepare By : Yusof Hashim



友興汽車零件私人有限公司 YEW HENG AUTO PARTS PTE LTD

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 468708
TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858
Email: yewheng@yewhengauto.sg
Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

record purpose.

M/S: DIPLOMAT PARTS PTE LTD
209 PADAN GARDENS
SINGAPORE 609339

Table to Bill

TAX INVOICE

NO: YLH186199
PAGE: 1
DATE: 18/03/2017
A/C CODE: LYDPM201
TERMS: 60 DAYS
P/O NO: MR.SAZALI

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 T53301-12A80	FRT BONNET	YDS 906.60	1	250.00	250.00
2 T90467-09050	BONNET INSULATOR CLIPS	YDS 4.30x7	7	1.50	10.50
3 T52119-02C80	FRT BUMPER	YDS 486.50	1	210.00	210.00
4 T52021-02101	BUMPER REINF FR	YDS 293.90	1	140.00	140.00
5 T57142-12100	BUMPER BKT FR LH	YDS 55.00	1	30.00	30.00
6 T57142-12090	BUMPER BKT FR RH	YDS 55.00	1	30.00	30.00
7 T52116-02220	BUMPER RETAINER FR LH	YDS 55.00	1	25.00	25.00
8 T52115-02220	RH BUMPER RETAINER	YDS 55.00	1	25.00	25.00
9 T53112-02330	GRILLE,RADIATOR LOWER	YDS 148.61	1	50.00	50.00
10 T52161-0K040	CLIP,TRIM	YDS 0450x10	10	1.50	15.00
11 T53100-02905	GRILLE,RADIATOR	YDS 304.80	1	115.00	115.00
12 T75301-02050	EMBLEM FR GRILLE	YDS 77.60	1	35.00	35.00
13 T81170-02B90	H/LAMP LH	YDS 766.80	1	180.00	180.00
14 T53201-02270	SUPPORT PANEL	YDS 771.30	1	215.00	215.00
TOTAL QUANTITY:			29	TOTAL	SIN 1,330.50
				ADD GST @ 7%	93.14
				GRAND TOTAL	SIN 1,423.64

P/O;
SKL1034C


SALESMAN: TCY

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



4000000
1.07000





友興汽車零件私人有限公司

YEW HENG AUTO PARTS PTE LTD

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708

TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858

Email: yewheng@yewhengauto.sg

Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

TAX INVOICE

M/S: DIPLOMAT PARTS PTE LTD

209 PADAN GARDENS

SINGAPORE 609339

NO: YLI1186463

PAGE: 1

DATE: 22/03/2017

A/C CODE: LYDPM201

TERMS: 60 DAYS

P/O NO: MR.SAZALI

Part No	Description	Location	Qty	Unit Price	Amount	
				SIN	SIN	
1	T88450-02350	CONDENSER - A/C	YDS	1	300.00	300.00
2	T53208-02120	PANEL-RADIATOR, BRACKET	YDS	1	45.00	45.00
3	T16523-0D060	RADIATOR TOP BUSHING	YDS	1	12.00	12.00
4	T32943-02180	OIL COOLER HOSE	YDS	1	18.00	18.00
5	T16410-0D420	RADIATOR	YDS	1	420.00	420.00
TOTAL QUANTITY:			5	TOTAL	SIN 795.00	
				ADD GST @ 7%	55.65	
				GRAND TOTAL	SIN 850.65	

P/O:646411

Check goods received & services rendered quote & collection		Initials	Date
		EA	2017
Passed for payment			29/3
Description	Price		
Int. Parts - GIS	2100		
Kia Parts - GIS	2200		
Oil Parts - GIS	200		
OPS Parts - GIS	200		
Ma Lubricant Cost	2200		
Kia Lubricant Cost	2400		
GST Control - 7%	3.000	80907001	65 65

Reprint: 1 / GTB / 22/03/2017 4:20:56 PM

SALESMAN: GTB

This document is computer generated. No signature required.

DIPLOMAT PARTS PTE LTD
GOODS SOLD ARE NOT RETURNABLE

Goods Received

Received By - Signature





友興汽車零件私人有限公司

YEW HENG AUTO PARTS PTE LTD

record purpose

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708

TEL: 6743 8858 A/C: 6392 0830 FAX: 6749 0858

Email: yewheng@yewhengauto.sg

Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

21153

M/S: DIPLOMAT PARTS PTE LTD

209 PADAN GARDENS

SINGAPORE 609339

TAX INVOICE

NO: YLH1186542
 PAGE: 1
 DATE: 23/03/2017
 A/C CODE: LYDPM201
 TERMS: 60 DAYS
 P/O NO: MR.SAZALI

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 T08886-02305	AUTO FLUID,WS 4L S	YR3017	1	45.00	195.00 45.00

TOTAL QUANTITY:

1 TOTAL

SIN.45.00

ADD GST @ 7% 3.15

GRAND TOTAL SIN 48.15
To Bill

P/O:
SKL1034C

Toyota
Toyota
21153

Print / GTB / 23/03/2017 4:16:41 PM

SALESMAN: GTB

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Mar 2017 18:26 Sendback Est	10 Mar 2017 17:00 \$57,886.35	14 Mar 2017 11:34 Edit Adj Rpt	\$54,612.75 Edit Estimates	\$54,612.75 View Rpt		Pending for Survey Report Cancel Case
Supp #1	29 Aug 2017 18:34	30 Aug 2017 11:07 \$5185.28	30 Aug 2017 11:07			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	KAMALAKANNAN S/O SOUNDARARAJAN, ID: S8632446F, Tel: +6592700986		
Vehicle Reg. No.:	SKL1034C	Date of Loss:	08/03/2017 00:00 - :59 [41 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 506796	Policy/Cover Note No.:	80408303QMX (Comprehensive) Coverage: 12/07/2016 - 11/07/2017
		Excess:	\$500.00
Repairer:	Diplomat Parts Pte Ltd (HQ) 209 Pandan Gardens, 609339 West Coast - Tel: 65684556/65684555		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/04/2017]		
Driver/Custodian:	KAMALAKANNAN S/O SOUNDARARAJAN (30 / Male), NRIC: S8632446F, Tel: +6592700986		
Adj Asg. Remarks:	TO REVERT		

ASSOCIATED MAIL RECEIVED

View All	Compose Case Mail
- MSIG_SG (23/04/2018): Alert - Adj Mandate Approved (\$54612.75) - SKL1034C - Claim Handler: Kwok Woon C... - MSIG_SG (15/03/2017): Alert - Adj Mandate Approved (\$5174.85) - SKL1034C - Claim Handler: Kwok Woon C...	

ALL ASSOCIATED TASKS

View All	Search Tasks	Create New Task	Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKL1034C (506796)
 OD
 Mar 8 2017 12:00AM
 [KAMALAKANNAN S/O SOUNDARARAJAN]
 Diplomat Parts Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser v	
Assessment Reports				1 per page v	☒
No	Finalized On	Diplomat Parts Pte Ltd (HQ)		Thumbnail	Print
1	10/03/17 17:00	Repairer Estimates		Load HTM	
2	30/08/17 11:07	Repairer Estimates Suppl. #1		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/03/17 14:15	Adjuster Immediate Advice		Load HTM	
2	20/04/18 15:18	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page v	☒
No	Finalized On	Diplomat Parts Pte Ltd (HQ)		Thumbnail	Print
1	10/03/17 16:58	Front View		Load JPG	☒
2	10/03/17 16:58	Front View Left		Load JPG	☒
3	10/03/17 16:58	Front View Right		Load JPG	☒
4	10/03/17 16:58	Accident Photo		Load JPG	☒
5	10/03/17 16:58	Accident Photo		Load JPG	☒
6	10/03/17 16:58	Accident Photo		Load JPG	☒
7	29/12/17 10:32	Photos - Before		Load JPG	☒
8	29/12/17 10:32	Photos - Before		Load JPG	☒
9	29/12/17 10:32	Photos - Before		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/03/17 14:17	Odometer Reading		Load JPG	☒
2	15/03/17 14:17	Chassis Number		Load JPG	☒
3	15/03/17 14:17	General View		Load JPG	☒
4	15/03/17 14:17	General View		Load JPG	☒
5	15/03/17 14:17	General View		Load JPG	☒
6	15/03/17 14:17	General View		Load JPG	☒
7	15/03/17 14:17	General View		Load JPG	☒
8	15/03/17 14:17	General View		Load JPG	☒
9	15/03/17 14:17	General View		Load JPG	☒
10	15/03/17 14:17	General View		Load JPG	☒
11	15/03/17 14:17	General View		Load JPG	☒
12	15/03/17 14:17	General View		Load JPG	☒
13	15/03/17 14:17	General View		Load JPG	☒
14	15/03/17 14:17	General View		Load JPG	☒
15	15/03/17 14:17	General View		Load JPG	☒
16	15/03/17 14:17	General View		Load JPG	☒
17	15/03/17 14:17	General View		Load JPG	☒
18	15/03/17 14:17	General View		Load JPG	☒
19	15/03/17 14:17	General View		Load JPG	☒
20	15/03/17 14:17	General View		Load JPG	☒
21	15/03/17 14:17	General View		Load JPG	☒
22	15/03/17 14:17	General View		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Diplomat Parts Pte Ltd (HQ)	Thumbnail	Print
23	15/03/17 14:17	General View		☒
24	15/03/17 14:17	General View		☒
25	15/03/17 14:17	General View		☒
26	15/03/17 14:17	General View		☒
27	15/03/17 14:17	General View		☒
28	15/03/17 14:17	General View		☒
29	15/03/17 14:17	General View		☒
30	15/03/17 14:17	General View		☒
31	15/03/17 14:17	General View		☒
32	15/03/17 14:17	General View		☒
33	15/03/17 14:17	General View		☒
34	15/03/17 14:17	General View		☒
35	15/03/17 14:17	General View		☒
36	15/03/17 14:17	General View		☒
37	15/03/17 14:17	General View		☒
38	15/03/17 14:17	General View		☒
39	15/03/17 14:17	General View		☒
40	15/03/17 14:17	General View		☒
41	15/03/17 14:17	General View		☒
42	15/03/17 14:17	General View		☒
43	15/03/17 14:17	General View		☒
44	15/03/17 14:17	General View		☒
45	15/03/17 14:17	General View		☒
46	15/03/17 14:17	General View		☒
47	15/03/17 14:17	General View		☒
48	15/03/17 14:17	General View		☒
49	15/03/17 14:17	General View		☒
50	15/03/17 14:17	General View		☒
51	20/04/18 15:14	Reinspection Photo		☒
52	20/04/18 15:14	Reinspection Photo		☒
53	20/04/18 15:14	Reinspection Photo		☒
54	20/04/18 15:14	Reinspection Photo		☒
55	20/04/18 15:14	Reinspection Photo		☒
56	20/04/18 15:14	Reinspection Photo		☒
57	20/04/18 15:14	Reinspection Photo		☒
58	20/04/18 15:14	Reinspection Photo		☒
59	20/04/18 15:14	Reinspection Photo		☒
60	20/04/18 15:14	Reinspection Photo		☒
61	20/04/18 15:14	Reinspection Photo		☒
62	20/04/18 15:14	Reinspection Photo		☒
63	20/04/18 15:14	Reinspection Photo		☒
64	20/04/18 15:14	Reinspection Photo		☒
65	20/04/18 15:14	Reinspection Photo		☒
66	20/04/18 15:14	Reinspection Photo		☒
67	20/04/18 15:14	Reinspection Photo		☒
68	20/04/18 15:14	Reinspection Photo		☒
69	20/04/18 15:14	Reinspection Photo		☒
70	20/04/18 15:14	Reinspection Photo		☒
71	20/04/18 15:14	Reinspection Photo		☒
72	20/04/18 15:14	Reinspection Photo		☒

Assessment Reports				1 per page	☒
No	Finalized On	Diplomat Parts Pte Ltd (HQ)		Thumbnail	Print
Documentation				1 per page	☒
No	Finalized On	Diplomat Parts Pte Ltd (HQ)		Thumbnail	Print
1	10/03/17 16:57	E-filed GIA report		Load PDF	
2	29/12/17 10:31	Supplier's Bill		Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	14/03/17 11:23	Email - Survey Appt		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/04/18 10:26	SUPPLEMENTARY LIST		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17005086/R1QH3Q2

Date: 27/04/2018

REFERENCE

Insured/Claimant: KAMALAKANNAN S/O SOUNDARARAJAN
Date of Loss: 08/03/2017

Policy No: 80408303QMX
Nature of Claim: OD Claim No: 506796

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKL1034C**
Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 1ZRX332205
Reg. Date: 27/09/2013 (Man. Year: 2013) Chassis No: MR053REE104166358
Colour: Blue Odometer: 36935 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$78,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,351.63	2,367.75	983.88	29.36
Miscellaneous Items	110.00	55.00	55.00	50.00
Labour	2,860.00	1,190.00	1,670.00	58.39
Paintwork Labour	1,750.00	1,000.00	750.00	42.86
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,071.63	4,612.75	3,458.88	42.85
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	8,071.63	4,112.75	3,958.88	49.05
+ GST 7.00/7.00% (S\$)	565.01	287.89	277.12	49.05
Nett Amount (S\$)	8,636.64	4,400.64	4,236.00	49.05

INSPECTION

Date of Assignment: 14/03/2017 Present Location: Diplomat Parts Pte Ltd (HQ)
Date Inspected: 14/03/2017 Inspected At: Diplomat Parts Pte Ltd (HQ)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Apr 2018)
Parts: 143	TOYOTA COROLLA ALTIS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKL1034C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Bent	250.00 F	*250.00 F
2	1		*BONNET LOCK (WCP)	Serviceable	55.00 F	*- F
3	1		*BONNET HINGE LH (WCP)	Serviceable	30.00 F	*- F
4	1		*BONNET HINGE RH (WCP)	Serviceable	30.00 F	*- F
5	7		*BONNET INSULATOR CLIPS (WCP)	Necessary	10.50 F	*10.50 F
6	1		*FRT BUMPER (WCP)	Torn	210.00 F	*210.00 F
7	1		*FRT BUMPER REINFORCEMENT (WCP)	Bent	140.00 F	*140.00 F
8	1		*FRT BUMPER BRACKET LH (WCP)	Necessary	30.00 F	*30.00 F
9	1		*FRT BUMPER BRACKET RH (WCP)	Necessary	30.00 F	*30.00 F
10	1		*FRT BUMPER RETAINER LH (WCP)	Necessary	25.00 F	*25.00 F
11	1		*FRT BUMPER RETAINER RH (WCP)	Necessary	25.00 F	*25.00 F
12	1		*FRT BUMPER LOWER GRILLE (WCP)	Distorted	50.00 F	*50.00 F
13	12		*FRT BUMPER CLIPS (WCP)	Necessary	18.00 F	*15.00 F
14	1		*RADIATOR GRILLE (WCP)	Cracked	115.00 F	*115.00 F
15	1		*FRT LOGO (WCP)	Necessary	35.00 F	*35.00 F
16	1		*HEADLAMP ASSY LH (WCP)	Cracked	180.00 F	*180.00 F
17	1		*HEADLAMP ASSY RH (WCP)	Serviceable	180.00 F	*- F
18	1		*FRT FENDER LH (WCP)	Repair	160.00 F	*- F
19	1		*AIRCON CONDENSER (WCP)	Bent	300.00 F	*300.00 F
20	1		*RADIATOR ASSY (WCP)	Bent	420.00 F	*420.00 F
21	1		*RADIATOR FAN MOTOR (WCP)	Serviceable	200.00 F	*- F
22	1		*RADIATOR FAN COWLING (WCP)	Serviceable	100.00 F	*- F
23	1		*RADIATOR FAN BLADE (WCP)	Serviceable	60.00 F	*- F
24	1			Bent	225.00 F	*215.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
*FRT SUPPORT PNL						
(WCP)						
Supplementary #1						
25	1		*PANEL RADIATOR, BRACKET	Bent	57.85 F	*45.00 F
(WCP)						
26	1		*RADIATOR TOP BUSHING	Necessary	13.09 F	*12.00 F
(WCP)						
27	1		*ATF - TOYOTA ALTIS	Necessary	97.50 F	*45.00 F
(WCP)						
F=Franchise part.						
Sub Total (S\$)					3,046.94	2,152.50
+ Margin on L,N Items 10.00/10.00% (S\$)					304.69	215.25
Total Parts (S\$)					3,351.63	2,367.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	FRT NUMBER PLATE WITH CASING (BENT)	80.00	35.00
2	1	SUNDRIES (NECESSARY)	30.00	20.00
Sub Total (S\$)			110.00	55.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	RESPRAY FRT BUMPER , BONNET , FRT SUPPORT PNL , FRT GRILLE , LHF FENDER & RHF FENDER	New	1,750.00	1,000.00
<u>Labour Items</u>				
2	RENEW & RE-ALIGN FRT DAMAGED ACCIDENT PORTION AREAS	New	2,450.00	800.00
3	RENEW AIRCON CONDENSER & RADIATOR	New	100.00	100.00
4	TOP UP AIRCON GAS	New	80.00	60.00
5	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
6	CONDUCT DIAGNOSTIC CHECK ON VEHICLE SYSTEM	New	200.00	200.00
Gross Labour Cost (S\$)			4,610.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >