

ASS. REC. BY:

REF: CS/7CL17005166/11/bn2 Special Instruction:

Survivor:

ASSIGNMENT (Office)From (Person): CNS Luren Jaw of FCL Date/Time: 15/03/2017 913am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GZ 8470D Insured: SHB 3309Kat Workshop m/s Sin Sheng Tel: 6863 9595of 3 Tech Park Crescent Tugay Tech ParkPolicy No: _____ Claim No: 019002774MTJH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 09/03/2017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement: _____

Date/Time: 15/03/2017 920am Person Contacted: Susan Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	<u>GZ 8470D - CS/7CL14015345/Kabu2</u>	<u>DOA: 11/03/2014</u>
	<u>SHB 3309K - NS/INC11021042/Hlvn</u>	<u>DOA: 11/10/2011</u>
<u>16/10/17 @ 510pm</u>	<u>According to Susan, Vehicle Not In Yet.</u>	
<u>30/12/17 210pm</u>	<u>Email to FCL temporary dose file</u>	
	<u>lump sum \$3500, 2days Cred: 534.50, 60%</u>	

REF: FCI

ASSIGNMENT

2021 Aug

From:

Date: 26/09/2018

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

GZ 8470D

at Workshop m/s

Sin Sheng

of

3 Tuas Park Crescent

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Mitsubishi

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GZ 8470D

Yr Regn:

2006 Sep

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi L300

c.c

2477

Colour:

white

A/C

Insured / Std / NI / NA

Sp. Reading:

367536

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM HJNP15V6A001694

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

26/7/18 @ 1730

Survey held at

Sin Sheng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rear.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 17 SEP 2018

Date/Time, File Pass to?

1) 14/9 Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

90

50

50

28

218

Report Format: TP

Lump Sum / I.B.I: (\$

350/-

Catherine Chong (LKK Auto)

From: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Sent: Saturday, 30 December, 2017 2:12 PM
To: 'Claim Workflow System'; 'ASSIGNMENTS@LKKAUTO.COM'
Cc: 'LURENEJAW@FIRST-INSURANCE.COM.SG'
Subject: RE: SURVEY ASSESSMENT - D17002774MFSH/1

Dear Sir / Madam,

Please be informed that we are unable to conduct the inspection after some attempts to inform the workshop to present the vehicle.

This case has been pending for a long time due to the unavailability of the owner, therefore we decided to temporarily close this case.

Kindly advise us if there is any arrangement made and will be glad to re-open the case accordingly.

"Wishes you a Happy New Year 2018"

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 15 March, 2017 9:22 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; sur@lkkauto.com
Subject: RE: SURVEY ASSESSMENT - D17002774MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@first-insurance.com.sg]
Sent: Wednesday, 15 March, 2017 9:13 AM
To: ASSIGNMENTS@LKKAUTO.COM

MOTOR SURVEY ASSIGNMENT

Date	14-03-2017	Our Ref No. D17002774MFSH
Accident Date	09-03-2017	Claim Type. Third Party
Insured Vehicle	SHB3309K	Third Party Vehicle. GZ8470D
Survey Location	3 TECH PARK CRESCENT TUAS TECH PARK	
Contact Person.	SUSAN	
Contact No.	68639595/ 0	Fax No. 68636477
Survey Type	WITHOUT PREJUDICE: PENDING ID'S VIDEO FOOTAGE TO DETERMINE LIABILITY	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIN SHENG ENGINEERING SERVICES	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/217813)


PRI Documents

Close X

PRI Header Details

Claim No	D17002774MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & SIN SERVICE
Workshop Name	SIN SHENG ENGINEERING SERVICES (Contact Person : SUSAN)	Survey Location & Contact Details	3 TECH PARK CRESCENT TUAS TECH PARK Mobile: 0 , Phone: 68639595 , Fax: 6863647 EmailId: SINSHENG1981@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: PENDING ID'S VIDEO F LIABILITY		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB3309K	TP Vehicle No	GZ8470
PRI Recieved Date	14-03-2017 07:26:06 PM	Surveyor Appointed Date	15-03-2017 09:13:04 AM	Surveyor Accept Date	15-03-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	15-03-2017	Upload Survey Report *:	<input type="text"/>
-----------------------------	---	----------------------	------------	-------------------------	----------------------

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Denise Tay (LKKAUTO)

From: sinsheng engineering services <sinsheng1981@gmail.com>
Sent: Thursday, 13 September 2018 1:28 PM
To: Denise Tay (LKKAUTO)
Cc: SUR; Taufikh (LKKAUTO); Admin A; Shu Pei (LKKAUTO)
Subject: Re: FW: Accident Involving GZ8470D with SHB3309K on 09/03/2017

Hi Ms Denise,

We are agreed.

*Thank You
Regards*

*Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477*

On 13 September 2018 at 10:49, Denise Tay (LKKAUTO) <denisetay@lkkauto.com> wrote:

Dear Susan,

Offer at lump sum 350,2days

Please check and revert

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle
Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 1195N

Vehicle Details

Vehicle No.: GZ8470D

Vehicle to be Exported: No

Intended De-registration
Date: 31 Dec 2017

Vehicle Make: MITSUBISHI

Vehicle Model: L300 HR M

Primary Colour: White

Manufacturing Year: 2006

Engine No.: 4D56LC5466

Chassis No.: JMAJNP15V6A001694

Maximum Power Output:-

Open Market Value: \$11,987.00

Original Registration
Date: 27 Sep 2006

First Registration Date: 27 Sep 2006

Transfer Count: 0

Actual ARF Paid: \$600.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Aug 2021

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

PQP Paid: \$23,127.00

COE Rebate Amount: \$16,959.00

Total Rebate Amount: \$16,959.00**Message**

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 14 Mar 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002547

Date : 24/07/2018

Vehicle Num. : GZ8470D

Make/Model : MITSUBISHI L300-2006

Chassis/Eng# : JMAJNP15V6A001694/4D56LC5466

Accident Date : 09/03/2017

Claim No. :

Reference : SHB3309K

Policy No. : D-16085361 MFCV

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	NETT ITEMS :		
2.	1	BUMPER SIDE		55.00 <i>est</i>
3.	1	REFLECTOR		55.00 <i>x nn</i>
3.	1	MUDFLAP, RH		95.00 <i>x nn</i>

Nett Total S\$:

205.00

10.00% Discount S\$:

20.50

184.50

LABOUR :

TO PANEL BEAT/REPAIR RH BODY

250.00

TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS

SPRAY PAINTING

450.00

LOSS OF USE : 3 DAYS @ \$ 120/DAY

Labour Total S\$:

700.00

Total S\$: 884.50

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17005166/T1tbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 21-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3309K	Veh. Inspected	GZ 8470D	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17002774MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	15/03/2017	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI L300	c.c	2477	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JMAJNP15V6A001694	Colour	WHITE	
Odometer	367536	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R14	BRIDGESTONE	6 mm	
L/H Front Tyre	185/60 R14	BRIDGESTONE	6 mm	
R/H Rear Tyre	185/60 R14	BRIDGESTONE	6 mm	
L/H Rear Tyre	185/60 R14	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/03/2017	Inspection Date	26/07/2018	
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GZ 8470D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER SIDE (N)	CUT	55.00	55.00
1	REFLECTOR (N)	NOT NECESSARY	55.00	-
1	MUDFLAP, RH (N)	NOT NECESSARY	95.00	-
	LESS 10% DISCOUNT		-20.50	-5.50
			184.50	49.50
LABOUR				
	TO PANEL BEAT/REPAIR RH BODY TO		250.00	200.00
	DISMANTLE/REPLACE ABOVEMENTIONED PARTS.		450.00	200.00
	SPRAY PAINTING.		700.00	400.00
GRAND TOTAL			884.50	449.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				350.00

Report Ref No. CS/FCI17005166/T1tbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.